

**NATIONAL TRANSPORTATION SAFETY BOARD
MATERIALS LABORATORY DIVISION
RECEIPT OF RETURNED PARTS**

ACCIDENT/INCIDENT IDENTIFICATION	
PLACE	Fitchburg, Massachusetts
DATE / VEHICLE	November 6, 2010 North American T-6
NTSB NO: / IIC	ERA11LA050 Ralph Hicks, AS-ERA
THE FOLLOWING PARTS, PIECES OR COMPONENTS FROM THE ABOVE ACCIDENT/INCIDENT	
Carburetor from Pratt and Whitney R-1340 radial engine	
ARE BEING RETURNED VIA U.S REGISTERED MAIL NO.	
OR BY OTHER CARRIER (NAMED)	
WHICH HAS BEEN ADDRESSED TO:	
NAME	Scott Anglin
COMPANY	Anglin Aircraft Recovery Services
ADDRESS	[REDACTED]
	Clayton, DE 19938

RECIPIENTS PLEASE VERIFY THAT THE COMPONENTS, AS ITEMIZED, HAVE BEEN RECEIVED BY PRINTING LEGIBLE YOUR NAME, SIGNING, AND DATING THIS FORM BELOW, AND RETURNING THIS DOCUMENT TO: MICHAEL BUDINSKI, CHIEF, MATERIALS LABORATORY DIVISION, (RE-30), NATIONAL TRANSPORTATION SAFETY BOARD, 490 L'ENFANT PLAZA EAST, WASHINGTON, D.C. 20594. ATTACHED IS A SELF-ADDRESSED, STAMPED ENVELOPE FOR YOUR CONVENIENCE. IF ANY DISCREPANCIES ARE FOUND, IMMEDIATELY CALL (202) 314-6516.

WRITER'S NAME AND INITIALS	Michael Budinski [REDACTED]	DATE	30 NOV 2011
NTSB REPRESENTATIVE PACKING PARTS	Michael Budinski [REDACTED]	DATE	30 NOV 2011
NAME AND SIGNATURE OF RECIPIENT OR RECIPIENT'S REPRESENTATIVE	Print STACIE ROBINSON. Sign [REDACTED]	DATE	12-1-11

Part Return Form.doc (Word Template)