



Photo 5 Left Engine and Propeller-No.3 propeller blade taper bore and pitch change pin