


SHERIDAN COUNTY SHERIFF

Sheriff Brian K. Fenner
940.8th Street P.O. Box 899
Hoxie, Kansas 67740
Office: (785) 675-3481 Fax: (785) 675-2294

Undersheriff Hessel M. Anderson

Send to: <i>FAA</i>	From: <i>SHERIFF FENNER</i>
Attention: <i>CALVIN CLARK</i>	Date: <i>4/27/2013</i>
Office location:	Office location: <i>HOXIE, KS.</i>
Fax number: <i>316-941-1276</i>	Phone number: 

- Urgent
 Reply ASAP
 Please comment
 Please review
 For your information

Total pages, including cover: *2*

Comments:

SHERIDAN COUNTY SHERIFF'S DEPARTMENT

Case# _____

Brian K. Fenner, Sheriff

Hessel M. Anderson, Undersheriff

CASE STATEMENT

NAME Gregory Scott Trays DATE OF BIRTH [REDACTED]

SS# [REDACTED] or DL# _____

ADDRESS [REDACTED] PHONE [REDACTED]

Departed APA Airport in Denver. Flying @ 11,000 FT to TXD
Engine began to start running rough & vibrating, & losing
power. Prop rpm decreased & aircraft began to descend.
Turned boost pump on switched fuel tanks, no
improvement in the power loss. Tried to make the
Rocky Airport but had to land in a field 3 miles
away

Went through complete engine checklist.
Boost pump, switched tanks, checked mags, mixture rich
Pulled prop back to idle to reduce descent rate.

N222GL
BEECHCRAFT BONANZA

SIGNATURE [REDACTED] DATE 4/26/13