

RECORD OF CONVERSATION

James F. Struhsaker Senior Air Safety Investigator Western Pacific Region

Date: July 12, 2012

Person Contacted: Tom Little, NTSB investigator

NTSB Accident Number: WPR12FA297

Narrative:

During a telephone conversation Tom reported that he examined the engine of M20L, N137MP, at Air Transport, Phoenix, with the technical assistance of a representative from Continental Motors. They found no anomalies with the engine that would have precluded normal operation. He said that the Continental representative would send a complete report in the near future.

James F. Struhsaker, Senior Air Safety Investigator