



RECORD OF CONVERSATION

Samantha Link
Aviation Accident Investigator
Western Pacific Region

Date: January 15, 2019
Person Contacted: Mr. Reed Jarmin (Air Transport – Aircraft Recovery)
NTSB Accident Number: WPR19FA263

Narrative:

During a conversation with Mr. Jarmin he reported the following:

- Due to weather conditions, the airplane was recovered from the mountain side early October 2019.
- The airplane impacted a section of boulders just below the top of the ridgeline.
 - Fragments of the forward fuselage were located in this area. These consisted of the nose wheel, propeller hub, and cowling pieces.
- The main wreckage came to rest slightly downhill from the section of boulders, about 100 yards from the top of the ridge.
- The last major piece of debris was the engine, which was about 300 yards down the ridge from the main wreckage.
 - Engine fragments and components were scattered between the main wreckage and the engine.

END.

Submitted by: Samantha Link