



RECORD OF CONVERSATION

Eleazar Nepomuceno
Air Safety Investigator
General Aviation Accident Division

Date: 12/13/2018
Person Contacted: Jim Cook (FAA Inspector)
NTSB Accident Number: GAA19CA

Narrative:

The following is a synopsis of the information provided by Jim Cook in a telephone conversation on the date specified above:

- The pilot had a hard landing after catching a gust of wind. He lost control and exited the runway on to the grass adjacent the runway.
- The mechanic he interviewed stated the outboard rib was damaged and needs to be replaced.