



RECORD OF CORRESPONDENCE

**Michael J. Folkerts
Aviation Accident Investigator
Central Region**

NTSB Accident Number: CEN20CA146

During his examination of the airplane, the FAA inspector David Mikolajewski noted about 1 gallon of fuel remained in the fuel tank and there were no breaches or leaks observed.