NATIONAL TRANSPORTATION SAFETY BOARD

ACCIDENT NUMBER:

RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ►

ENG11IA051

For Use In All Modal Investigations				
REGISTERED OWNER (name and address)			IDENTIFICATION NUMBER	
United Air Lines				
233 South Wacker Drive			MAKE	
Chicago IL 60606			Boeing	
LOCATION DATE OF ACCIDENT			MODEL	
Denver International Airport	9/26/11		757-222	
RETAINED BY NTSB REPRESENTATIVE		TITL		DATE
Jean-Pierre Scarfo		Pov	werplant Lead 12/8/11	
The National Transportation Safety Board has ⊠ has not □ completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control form(s) is hereby released.				
NO PARTS RETAINED				
RELEASED BY NTSB REPRESENTATIVE		TITL	TITLE DATE	
Jean-Pierre Scarfo		Pov	verplant Lead	12/8/11
(This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.)				
I HEREBY ACKNOWLEDGE:				
Receipt of the above described wreckage.				
Removal of the parts, if any, listed in the evidence control form(s).				
PERSON MAKING ACKNOWLEDGEMENT		TITL	E	DATE
Steve Cloud		Unit	ed Air Safety Investigator	9/29/11
ADDRESS		PHONE NUMBER & EMAIL		
		872	872 825 5613 //steven.l.cloud@united.com	
REMARKS:				
Engine SN P727118 (PW2037 Turbofan) and all its partr pieces are now released back to United Air Lines. The NTSB will not be retaining any parts for further examination.				