## NATIONAL TRANSPORTATION SAFETY BOARD

ACCIDENT NUMBER:

RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ▶ WPR17LA202

REGISTERE	For Use In All I	Modal Invi	estigations		
TOISTERED OWNER (name and address)			IDENTIFICATION NUMBER		
Lawrence D. Frick			N9798L		
	Same of the		MAKE	44	
			Beech		
LOCATION DATE OF ADDITION					
	DATE OF ACCIDEN	П	MODEL		
Roy, Utah	9/12/2017		A24R		
RETAINED BY NTSB REPRES	SENTATIVE	TITL	E	DATE	
Samantha Link		Avi	Aviation Aviation Investigato 9/12/2017		
The National Transportation Safety	Board has  has not  completed	its investig	ation of the wreckage described above. A	I recovered wreckage	
except trial listed in the evidence co	ontrol form(s) is hereby released.				
□ NO PARTS RETAINED	The Section of				
RELEASED BY NTSB REPRESENTATIVE			E	DATE	
Samantha Link			ation Accident Investigate	9/21/2017	
PERSON MAKING ACKNOWLEDGEMENT		TITI		DATE	
Removal of the parts, if an	y, listed in the evidence control	form(s).			
PERSON MAKING ACKNOWLEDGEMENT			E		
Lawrence 1	2 Frick	1 3	DWNen	9-24-11	
ADDRESS	1. 111010	PH	ONE NUMBER & EMAIL		
PLODI CLOS					
REMARKS:	1 the following item	e for fi	uther examination		
The NTSB has retain	ned the following item	15 101 11	artifici cadiminati		
~ Fuel Manifold					
~ Fuel Pump ~ Upper spark plug	for the #4 cylinder				
~ Upper spark plug ~ A fuel injection lin	P				
~ A fuel injection in					