

NATIONAL TRANSPORTATION SAFETY BOARD
RECEIPT OF PARTS

ACCIDENT/INCIDENT
IDENTIFICATION NUMBER
FR1116A240

PART II - RELEASE OF PARTS

REGISTRATION NUMBER

N3547C

MAKE

Piper

MODEL

PA-31-350

DATE OF ACCIDENT/INCIDENT

02/11/11

LOCATION

Richmond, VA

The National Transportation Safety Board has retained, for further examination, those parts, pieces, or components listed below. When the examination is complete, they will be returned to:

OWNER OR OWNER'S REPRESENTATIVE -

Anglin Aircraft Recovery

ADDRESS

[REDACTED]
Clayton, DE 19938

PARTS, PIECES, OR COMPONENTS RETAINED:

Right Engine Fuel Servo

SIGNATURE OF NTSB REPRESENTATIVE

[REDACTED SIGNATURE]

TITLE

ASI

DATE

12/14/11

The registered owner or owner's representative will acknowledge receipt of the materials by signing this form in the spaces designated below.

SIGNATURE OF OWNER OR OWNER'S REPRESENTATIVE

[REDACTED SIGNATURE]

TITLE

Admin Asst

DATE

12-14-11