


NATIONAL TRANSPORTATION SAFETY BOARD
RELEASE OF AIRCRAFT WRECKAGE

ACCIDENT IDENTIFICATION
NUMBER
NYC03MA183

PART I—RELEASE OF AIRCRAFT WRECKAGE

REGISTERED OWNER (name and address) Raytheon Aircraft Credit Corp 9709 E Central Wichita, KS 67206		REGISTRATION NUMBER—N 24005
MODEL 1900D		MAKE Beechcraft
DATE OF ACCIDENT 8/26/03	LOCATION Yarmouth, MA	


The National Transportation Safety Board has has not completed its investigation of the aircraft wreckage described above. All wreckage except that listed on the reverse side is hereby released to the registered owner, or owner's representative, for appropriate disposition. (If no parts are retained, insert NONE.)

SIGNATURE OF NTSB REPRESENTATIVE 	TITLE ASI	DATE 8/31/03
---	--------------	-----------------

(This section may be signed by a person, not the owner or owner's representative, who has knowledge of the disposition of the aircraft wreckage and its parts. Such signature does not place a responsibility for disposition of the wreckage upon that person.)

I HEREBY ACKNOWLEDGE:

- Receipt of the above described aircraft wreckage.
- Removal of the parts, if any, listed on the reverse side of this form.

SIGNATURE 	TITLE Aviation Adjuster X	DATE AUG 31 2003 X
--	---------------------------------	--------------------------

REM.
Ryan Insurance Services, Inc.
Biddeford Municipal Airport
87 Landry Street
Biddeford, Maine 04005-4332

NATIONAL TRANSPORTATION SAFETY BOARD
RECEIPT OF AIRCRAFT PARTS

ACCIDENT IDENTIFICATION
NUMBER

NYC03MA183

PART II - RELEASE OF AIRCRAFT PARTS

REGISTRATION NUMBER

N240CS

MAKE

Beechcraft

MODEL

1900D

DATE OF ACCIDENT

8/26/03

LOCATION

Yarmouth, MA

The National Transportation Safety Board has retained, for further examination, those parts, pieces, or components listed below. When the examination is complete, they will be returned to:

OWNER OR OWNER'S REPRESENTATIVE - Ryan Insurance
ADDRESS Biddeford, ME

PARTS, PIECES, OR COMPONENTS RETAINED:

Throttle Quadrant

• Electric TRIM System (elevator)

2 TRIM ACTUATORS (elevator)

2 Control Yokes

Flight & Engine Instruments (some unrecusable)

SIGNATURE OF NTSB REPRESENTATIVE

TITLE

ASI

DATE

6/17/04

The registered owner or owner's representative will acknowledge receipt of the materials by signing this form in the spaces designated below.

SIGNATURE OF OWNER OR OWNER'S REPRESENTATIVE

ADDRESS

Ryan Insurance Services, Inc.
Biddeford Municipal Airport
87 Landry Street
Biddeford, Maine 04005-4332

TITLE

Aviation Adjuster
for
AIG Aviation, Inc.

DATE

JUN 23 2004