
### Volusia County Sheriff's Office Supplementary Report

### Original Report () Yes 🖔 No

Zone:			
		$\Box$	





Incident Type	Incident Location	Incident Number	
Police Information, Assist Other	Deland, FL.	99-38889	
Agency			

#### Narrative:

On 12-03-99, Inv. Dewees was dispatched to the listed location in reference to an aircraft crash. Inv. Dewees responded and arrived on scene at 1130 hours. Upon arrival Inv. Dewees was briefed by Lt. D. Hudson. Hudson advised that the incident involved two aircraft, both of which were down. Hudson advised that one of the aircraft was located in the wooded area close to the intersection of Marsh Road and Matt Fair Blvd. The second aircraft was located in a wooded/marsh area next to the east end runway of the Deland Airport.

Lt. Hudson advised Dewees to standby for possible assistance to the Deland Police Department and the Federal Aviation Administration. At approximately 1200 hours, Inv. Dewees was assigned to conduct aerial photographs of the scene via VCSO Air One. Inv. Dewees conducted photographs of both crash sites and the debris between the two sites.

After the aerial photographs were completed, Inv. Dewees was assigned to assist Deland Police Department with photography/ video of the two crash sites. Inv. Dewees conducted video taping of both scenes. 35mm photographs of the scenes were conducted by Evelyn Paterno of the Deland Police Department.

Inv. Dewees observed the aircraft at the Marsh Road scene to be a single engine airplane bearing the Emory Riddle logo on the tail section. The plane's tail number was recorded as N153ER. A white male and a white female victim were recovered from this aircraft by Fire Service personnel.

The aircraft located next to the airport runway was a twin engine airplane bearing tail number N3038N. This aircraft was removed from the wooded/marsh area by Lewis Wrecker Service. The bodies of two white males were removed from this aircraft by Fire Service personnel. Inv. Dewees completed his documentation of the scene at 1720 hours.

Copies of the aerial photographs and video tapes of the scene will be forwarded to the following persons.

Dale Nodorft - Federal Aviation Administration Evelyn Paterno- Deland Police Department

Reporting Officer: Inv. Day	vid Dewees	<b>DID:</b> 2242	Date: 12-08-99
Approved By: So T		DID: 2012	Date: 1928 99

 $\sim 11$ 

## Volusia County Sheriff's Office Supplementary Report

# Original Report ( ) Yes (No

|--|

Zone:	
25	

Incident Type	Incident Location	Incident Number
Police Information, Assist Other Agency	Deland, FL.	99-38889

Inv. Dewees will forward the 35mm negatives of the aerial photographs and copies of the video tapes to:

Timothy Monville - National Transportation Safety Board

Case Status: Closed

Inv. Time: 9 hours

Reporting Officer:	Inv. David Dewees		<b>DID:</b> 2242	<b>Date:</b> 12-08-99
Approved By:	CATRICA	ALLX/	<b>DID:</b> 2092	Date: 12 6 0.5

110

COMPLAINT HISTORY DETAIL: V993370118 Page 12/04/99 TIBURON C A D VOLUSIA COUNTY SHERIFF 08:09 CALL NUMBER: VO118 INITIATE: 10:22:53 12/03/99 (10:23:09 ENTRY CURRENT STATUS: CLOSED (DISPATCH EXCEPTION) DISPATCH: 10:23:40 PRIMARY UNIT: C25 VP99038889 ONSCENE: 10:33:59 CASE NUMBER: CLOSE: . 17:40:45 DISPOSITION: INC LOCATION: 2324 MARSH RD, DEL (NEAR PALM AV) 02 DAREA: INIT.: 96 25 TYPE: INFORMATION BEAT: 1.4 247 PRIORITY: E RDIST: FIRE ZONE:247 MAP: 39 :D3 MB:39 :03\TX:2 PLANES JUST CRASHED IN MID AIR 10:23:09 E491 ENTRY 10:23:10 E491 BOUNDARY 10:23:40 E307 SUGGEST C25 C22 10:23:40 E307 DISP ENR C25/002124-ROBINETT.EVERETT 10:24:06 E307 BACK ENR C24/001457-HARVEY, DARIC 10:24:18 E307 BACK ENR 222/002122-FURSE,GEORGE 225/002332-MORGAN,MICHAEL J 10:24:29 E307 BACK ENR C12/002038-DAVIS, MICHAEL 10:24:41 E430 MISC 10-39 DELAND PD 10:24:55 E430 MISC 10-39 STEVENS TX:10-39 TO DAYTONA TOWER, DAN SHAY.HE'LL NEED MORE S/14 10:25:11 E353 SUPP WHEN WE GET IT. 10:27:04 E302 MISC 10-39 TO AVIATION 10:27:25 E484 BACK ENR AIR1/002081-FENNELL,ANDREW 001510-MARKOVICH,MICHAEL R 10:27:35 E450 MISC 10-39 202 L20 10:27:39 E307 INSRVICE C24 10:28:45 E450 MISC 10-39 EM 10:28:59 E302 MISC C14 ADVISED OF CALL WILL MONITOR CHANEL I WILL ASSIST WITH MAN POWER IF NEEDED C12, THRU SKYDIVE DELAND..AT THE END OF THE RUNWAY 10:29:14 E307 MISC 10:29:21 E307 BACK ENR L20/002220-COFFIN, MCKINLEY 10:29:30 E307 BACK ENR 202/002080-SZAROLETA, JOHN 10:29:57 E450 MISC 10-39 PIO 10:30:20 E307 MISC C12, THRU THE SPORTS COMPLEX..ON STERLING 10:30:37 E307 MISC C12, MAKE THAT SPERLING 10:33:59 E307 ONSCENE C25, MULTIPLE UNITS 10-97..DPD AND FIRE RESCUE UNITS PER DELAND PD ..THIS OCC NEAR THE NE CORNER OF THE 10:34:08 E450 MISC DELAND AIRFIELD. MORE THAN LIKELY IN THE CITY OF DELAND TX: COMP IN THE WOODS WITH THE DOWNED AIRPLANE..CLOSER TO 10:35:08 E451 SUPP MARSH RD .. THE PLANE IS NOT SMOKING OR ON FIRE. CANNOT LOCATE ANY VICTIMS.. 10:35:23 E430 ONSCENE AIRL TX: THE PERSON I AM TALKING TO IS WITH THE 2ND PLANE 10:35:36 E451 SUPP 10:35:38 E307 MISC C25, 1 AIRCRAFT LOCATED... 10:35:56 E302 MISC PLEASE LET 201 .. CPT BURNSED KNOW SIG 14 ASAP 10:36:14 E307 BACK ONS C22/002377-MADDOX,GEORGE C22, 1-LOCATED IN THE SPERLING COMPLEX.. CANNOT FIND THE 10:36:56 E307 MISC PILOT.. 10:36:56 E451 SUPP TX:PER EVAC..ONE SIG 7..IN THE PLANE NEAR MARSH RD IN THE WOODS.. 10:37:04 E307 ONSCENE 222 10:37:12 E307 ONSCENE 1.20 10:37:28 E307 BACK ONS E22/002362-CHANG,JOSE E

TX:N3038N..TAIL NUMBER ON THE PLANE NEAR MARSH RD IN TH

AIR1, THE OTHER PLANE NEAR THE ENTRANCE TO SPURLING

10:37:41 E451 SUPP

10:37:55 E430 MISC

woods..

```
3 mai 2 mai 2
                COMPLAINT HISTORY DETAIL: V993370118
                                                    Page
TIBURÓN
                                                             รี้
วังอาการ
 C A DETERM
                  VOLUSIA COUNTY SHERIFF
SPORTS COMPLEX, HAVE THE DEP NEAR HERE COME UP ON AIR1
                      CHANNEL
                      222, 10-33 EMBRY RIDDLE PLANE. TAIL NUMBER 153ER . BLU
10:38:29 E307 MISC
                      WHI IN COLOR. CANNOT FIND PILOT
                      TX:EM IS CALLING STATE WARNING POINT
10:38:37 E451 SUPP
10:38:44 E307 MISC.
                      222, 10-98 10-33
10:38:53 E307 ONSCENE
                      225
                      222, PILOT MAY BE FOLDED UP INSIDE THE PLANE.. 10-23 FOR
10:40:30 E307 MISC
                      FIRE RESCUE TO ADV. ON TAC1...
                      10-39 201/BURNSED VIA PX AT OPS .. HE IS 10-51..
10:40:55 E307 MISC
10:41:04 E307 ONSCENE
                     202
10:41:15 E307 BACK ENR 201/002061-BURNSED, RANDALL
                      AIR1, 2ND PLANE IS WITH 222 ENTRANCE TO SPERLING COMPLEX
10:41:53 E307 MISC
                      THEN GO SOUTH...
                      BODY ON AIRPORT PROPERTY PER TACL
10:42:55 E307 MISC
10:43:25 E307 MISC
                      AIR1, GREAT BIG RED PK...
                      TX:10-39 DAYTONA TOWER REF ADD SIG 14 AND TAIL NUMBERS
10:43:45 E451 SUPP
10:44:39 E307 BACK ENR C24/001457-HARVEY, DARIC
10:44:41 E307 ONSCENE C24
10:44:41 E307 ONSCENE C12
                       PER EVAC THEY HAVE 2 UNITS 10-97 ...
10:45:18 E307 MISC
10:45:42 E307 BACK ONS E24/002344-HAVENNER,MICHAEL TYR
10:46:03 E307 MISC C12, ALL UNITS TO AIR1 CHANNEL..
10:46:19 E450 MISC
                      I AM CALLING SWP
10:46:41 E307 MISC
                      222, BODY UNDER DEBRIS
10:46:47 E307 MISC
                      C12, 1 CONF S/7
                      THE CONF'D S/7 IS PER FIRE RESCUE THAT IS 10-97 W/222 ...
10:47:48 E307 MISC
10:48:36 E450 MISC
                      10-39 SPW
                      PER EVAC. 2 CONFIRMED S/7
10:48:56 E430 MISC
                       222, CONTACT EMBRY RIDDLE. ASCERTAIN HOW MANY SUBJ'S
10:49:36 E307 MISC
                       WERE ON THE PLANE, THEY HAVE ONLY LOCATED ONLY LOCATED
                       ONE BODY REF THE PLANE HE IS OUT WITH...
                       10-39 4016/CANTRELL .. SHE IS CONTACTING EMBRY RIDDLE AT
10:50:01 E307 MISC
                       THIS TIME ..
                       222, N153ER..CORRECT TAIL NUMBER OF PLANE..
10:51:06 E307 MISC
10:51:17 E484 CODE 4
                       012
10:51:18 E484 CODE 4
                      022
10:51:18 E484 CODE 4
                      024
                     C25
10:51:18 E484 COOE 4
10:51:18 E484 CODE 4
                      E22
                      I AM 10-25 WITH EMBRY RIDDLE .. THEY ARE CKING ON THE
10:51:39 E450 MISC
                       NUMBER OF OCCUPANTS
10:52:15 E484 CODE 4
                     E24
10:52:15 E484 CODE 4
                     L20
10:52:15 E484 CODE 4
                       202
10:52:16 E484 CODE 4
                       222
10:52:16 E484 CODE 4
                       AIRI
10:53:09 E307 CODE 4
                       225
                       222, PER 222, THERE ARE STILL 2 PEOPLE MISSING, POSS ONE
10:54:42 E450 MISC
                       FROM EACH PLANE ..
                       222, THERE WERE TWO SUBJ'S ON BOARD EACH PLANE..
10:54:53 E307 MISC
10:55:47 E307 MISC
                     AIR1, LANDING AT 1ST CRASH SITE...
                       LAND UNITS ARE STARTING A GROUND SEARCH
10:56:33 E450 MISC
                       C22, GROUND UNITS EXPANDING SEARCH AREA IN WOODED AREA..
10:57:08 E307 MISC
10:58:00 E484 BACK ENR E65/002265-DAVIS,DONNA K
```

10:59:11 E450 MISC

10-39 FAA

10:59:17-E307 BACK ONS 424/002183-ROHM, CAROL

TIBURON	COMPLA	INT HISTORY DETAIL: V993370118 Page 3 12/04/99 VOLUSIA COUNTY SHERIFF 08:09
C A 0		VOLUSIA COUNTY SHERIFF
	****	**************************************
		C25, SW OF 2ND CRASH SITE FRESH BONES DEEP IN THE WOODS
11.00.00	113,434	ON TAC1. 6 RESCUE UNITS IN IMMEDIATE AREA.
erigg	22 T (*) (*)	C25, MARKED WHAT HE FOUND WITH CRIME SCENE TAPE
11:04:01 E450		TRYING TO CALL DB WEATHER 7. ITS 10-6
11:06:44 E484		
11:06:50 E450		I AM CALLING THE CO THAT OWNS THE 2ND PLANE TO FIND OUT
*		HOW MANY PEOPLE WERE ABOARD IT PHOENIX EAST AVIATION
11:07:05 E307	MISC	C12, IN THE WOODS AT THE SCENE. ADV C14 AND SEE IF HE
		CAN MONITOR 02 RADIOALSO NOTIFY C18 REF 27 ZONE
11:07:44 E450	MISC	PER PHOENIX EAST AVIATIONTHERE WERE TWO FOLKS ON
		THEIR PLANE
11:08:33 E307	MISC	222, 10-22 S/14 FROM EMBRY RIDDLE2 PEOPLE FROM EMBRY
The state of the s	1 1 14 14 14	RIDDLE 10-97 NOW.
11:09:51 E307	MIGE	C14 IS GOING TO MONITOR D2 RADIOC18 WILL MONITOR D4
11.00.01 0000	114.00	
aa,ays.am maxaan	CODE A	RADIO PER C14
11:10:17 E307		EAS
11:10:17 E307		424
11:11:34 E450	MISC	10-39 EM REF UPDATES
11:12:19 E450	MISC	DB WEATHER PX STILL 10-6
11:16:50 E307	MISC	PER C14C18 IS GOING TO MOITOR D2 RADIO AMD C14 WILL
		STAY IN DELTONA
11:17:04 E355	SUPP	TX:COMP IS LINDA IAUCH, PX, SAW CRASH, HAS S/14
		WHERE WHAT SHE SAI D IS A BODY 10-20
11:18:00 E307	MISC	C12, 2ND BODY LOCATED. THINKS IT IS FROM THE 1ST CRASH
		SITE WHICH IS THE EMBRY RIDDLE PLANE
11:18:58 E307	MIGC	AIR1, WEST END OF FIELD IN DELAND GETTING FUEL
11:21:36 E307		CALL LINDA IAUCHASCERATIN ADD'L S/14HER ADDRESS.
asiasiao maov	MIDC	
المعاور بسراسي بدريسرا فسريس الراز	Carpe and an	WHERE SHE POSS THINKS THERE IS A BODY
11:25:28 E307	MISU	PER RP LINDA TAUCHLIVES TA
		THAT SITS BACK OFF INTO THE WOODSWHI BRONCO IN DRIVE.
		SHE WITNESSES THE CRASHIF LOOKING OUT
11:26:24 E307	MISC	IF LOOKING OUT OVER HER FRONT PORCH FROM INSIDE HER RES
		.SHE SAW SOMETHING LEAVE THE PLANEWAS NOT A WING OR
		PLANE PARTTHINKS IT WAS A BODY
11:26:49 E307	MISC	THINKS IS MAY BE IN THE WATER NEAR WHERE THE PPLANE THAT
		IS UPSIDE DOWN IN THE WATER
11:27:59 E307	MISC	10-39 222HE WILL ADV DELAND FIRE RESCUE UNITSHE IS
The second of th		10-51 TO SPEAK WITH THE RP LINDA LAUCH
11:28:11 E450	MICO	PAGED WHITTET TO PUT THE DIVE TEAM ON STAND BY
11:28:14 E307		
		TC3/CANTRELL NOTIFYING DIVE TEAM TO STAND BY
11:29:35 E450	mioc	TRYING TO ASCERTAIN IF THERE IS ANY FUEL SPILLAGE IN THE
did in the district of the second of	52.00.25.20	WATERPER 22210-23
11:31:09 E307	misu -	222, 10-25 W/RP. WILL ASCERTAIN REF FUEL SPILLAGE INTO
		WATER IN A FEW
11:34:05 E307		C12
11:34:34 E450		PER DB WEATHERNOTIFY MELBOURNE WEATHER
11:35:25 E450	MISC	10-39 MELBOURNE WEATHER
11:36:11 E307		222, THE ONE IN THE WATER IS THE PHOENIX AVIATION PLANE.
11:38:18 E307		AIR1, 10-98 FUELING. BACK AT CRASH SITE
		C12/002038-DAVIS,MICHAEL, WAS NEVER 10-8 FROM THIS CALL.
		CP1/004010-LOPEZ,GLENN
11:45:08 E307		
11:51:26 E307		CP1, WAS 10-8 10-51 AT 1135 HRS
		C12
11:53:40 E307		CP1
10.07 48 E450	MISC	PAGED DIVE TEAM AGAIN
ニュアミリム・白泉 提及誓合	(v) 1 (v) 1	4A-GO BUTTTET

10-39 WHITTET

222, LOOKING FOR 2 BODIES. ONLY 1 CONF S/7...

12:06:08 E450 MISC 12:10:10 E307 MISC

	7.		
TIBURON		COMPLA	NINT HISTORY DETAIL: V993370118 Page 1949 1941 12/04/99
CAD		4 (1874)	VOLUSIA COUNTY SHERIFF
***** <b>***</b>	****	******	NINT HISTORY DETAIL: V993370118 Page 4 12/04/99 VOLUSIA COUNTY SHERIFF . 08:09
12:11:21	E307	MISC	L20, S/7 X2. STILL LOOKING FOR 2
40.10.14	EASA	Mich	THERE ARE POSS 2 BODIES IN THE EMBRY RIDDLE PLANE THEY
42214244	L. 7.5 V		
			CANT MOVE IT AT THIS TIME
12:15:47	E307	MISU	L20, THERE IS FUEL IN THE WATER10-39 TO TC3/CANTRELL
			REF NOTIFICATIONS.,
12:19:09	E307	BACK ENR	260/002245-WHITTET, JAMES
12:20:56	E450	BACK ENR	262/001431-WILLETTS,GARFIELD 263/001405-SCOFIELD,FRANCIS
			E 264/002339-LEE, DANIEL 267/002249-JONES, JOHN 268/001359
			MEEKS, LARRY A
12:22:04	F* C) (A **)	TAIN OLD TON	·
12:22:49	E307	WIRC	10-25 EVAC THEY ARE GOING TO CK WITH THEIR UNITS ON
			SCENE AND CALL US BACK REF TO FUEL IN WATER 10-39 SWP REF THE FUEL IN THE WATERAND THEY WILL
12:24:05	E450	MISC	10-39 SWP REF THE FUEL IN THE WATERAND THEY WILL
			NOTIFY DEP
12:25:56	E307	INSRVICE	
10,00,05	CASA	MTOC	10-39 EM REF THE FUEL IN THE WATER ITS A POND AT THE NE SECTION OF THE AIRPORT
-3.210V120 -40.40.00	L 19 DW	TELEVIERA	ATO M CUND HE THE NE DELITION OF THE BIRMURE
		INSRVICE	
12:44:15			C25 ***** VP99038889 002124 **
		FINALTYP	
12:46:30	E307	INSRVICE	C24
12:47:57	E307	INSRVICE	022
12:48:16	E307	INSRVICE	225
		INSRVICE	
		INSRVICE	
		INSRVICE	
13:04:31	VOAL.	SUPP	TX:D.E.P. IS 10-51 AS WELL AS THE BUREAU OF EMERGENCY
			RESPONSE. PER INV JEFFRIES
the state of the s			
13:05:21	VSAL.	SUPP	TX:IF FOR SOME REASON WE NEED TO CONTACT INV JEFFRIES.
13:05:21	VSAL.	SUPP	TX:IF FOR SOME REASON WE NEED TO CONTACT INV JEFFRIES. WE CAN DO SO THRU FM P DISPATCH
13:05:21	VSAL.	SUPP	TX:IF FOR SOME REASON WE NEED TO CONTACT INV JEFFRIES. WE CAN DO SO THRU FM P DISPATCH C25 INC. INCIDENT REPORT
13:12:49	VSAL E307	SUPP CLEAR	C25 INC, INCIDENT REPORT
13:12:49	VSAL E307	SUPP CLEAR SUPP	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN
13:12:49	VSAL E307	SUPP CLEAR SUPP	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT
13:12:49	VSAL E307	SUPP CLEAR SUPP	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS
13:12:49 13:15:27	VSAL E307 VSAL	SUPP CLEAR SUPP	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING
13:12:49 13:15:27	VSAL E307 VSAL	SUPP CLEAR SUPP	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO
13:12:49 13:15:27	VSAL E307 VSAL	SUPP CLEAR SUPP	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS
13:12:49 13:15:27	VSAL E307 VSAL	SUPP CLEAR SUPP	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO
13:12:49 13:15:27	VSAL VSAL VSAL	SUPP CLEAR SUPP	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS
13:12:49 13:15:27 13:18:17	VSAL VSAL VSAL	SUPP CLEAR SUPP SUPP ONSCENE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262
13:12:49 13:15:27 13:18:17 13:22:41 13:34:25	VSAL VSAL VSAL	SUPP CLEAR SUPP SUPP ONSCENE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF
13:12:49 13:15:27 13:18:17 13:22:41 13:34:25 13:34:38	VSAL VSAL VSAL E450 E450	SUPP CLEAR SUPP SUPP ONSCENE INSRVICE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF
13:12:49 13:15:27 13:18:17 13:22:41 13:34:25 13:34:38	VSAL VSAL VSAL E450 E450 E450	SUPP  CLEAR SUPP  SUPP  ONSCENE INSRVICE INSRVICE INSRVICE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263
13:12:49 13:15:27 13:18:17 13:22:41 13:34:25 13:34:38 13:34:38	VSAL VSAL VSAL E450 E450 E450 E450	SUPP CLEAR SUPP SUPP ONSCENE INSRVICE INSRVICE INSRVICE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263 264
13:12:49 13:15:27 13:18:17 13:22:41 13:34:25 13:34:38 13:34:38	VSAL VSAL VSAL E450 E450 E450 E450	SUPP  CLEAR SUPP  SUPP  ONSCENE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 263 264 267
13:12:49 13:15:27 13:18:17 13:22:41 13:34:25 13:34:38 13:34:38 13:34:39 13:34:39	VSAL VSAL VSAL E450 E450 E450 E450 E450	SUPP  CLEAR SUPP  SUPP  ONSCENE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263 264 267 268
13:12:49 13:15:27 13:18:17 13:22:41 13:34:25 13:34:38 13:34:38 13:34:39 13:34:39	VSAL VSAL VSAL E450 E450 E450 E450 E450 E450	SUPP  CLEAR SUPP  SUPP  ONSCENE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263 264 267 268 201
13:12:49 13:15:27 13:18:17 13:22:41 13:34:25 13:34:38 13:34:38 13:34:39 13:34:40 13:35:05 13:37:00	VSAL VSAL VSAL VSAL E450 E450 E450 E450 E450 E450 E307	SUPP  CLEAR SUPP  SUPP  ONSCENE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263 264 267 268 201 E65
13:12:49 13:15:27 13:18:17 13:22:41 13:34:25 13:34:38 13:34:38 13:34:39 13:34:40 13:35:05 13:37:00	VSAL VSAL VSAL VSAL E450 E450 E450 E450 E450 E450 E307	SUPP  CLEAR SUPP  SUPP  ONSCENE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263 264 267 268 201 E65
13:12:49 13:15:27 13:18:17 13:22:41 13:34:25 13:34:38 13:34:38 13:34:39 13:34:40 13:35:05 13:37:00	VSAL E307 VSAL VSAL E450 E450 E450 E450 E450 E450 E307	SUPP  CLEAR SUPP  SUPP  ONSCENE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263 264 267 268 201 E65
13:12:49 13:15:27 13:15:27 13:18:17 13:34:25 13:34:38 13:34:38 13:34:39 13:34:39 13:34:40 13:35:05 13:37:00 14:46:23 15:53:15	VSAL VSAL VSAL VSAL E450 E450 E450 E450 E450 E307 E307 VSAL	SUPP  CLEAR SUPP  SUPP  ONSCENE INSRVICE CATCH UP	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263 264 267 268 201 E65
13:12:49 13:15:27 13:15:27 13:18:17 13:22:41 13:34:25 13:34:36 13:34:38 13:34:39 13:34:39 13:34:39 13:34:40 13:35:05 13:35:05 13:35:05	VSAL VSAL VSAL VSAL E450 E450 E450 E450 E450 E450 E450 E450	SUPP  CLEAR SUPP  SUPP  SUPP  ONSCENE INSRVICE CATCH UP CASE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263 264 267 268 201 E65 202 ****** ****** UP99038911
13:12:49 13:15:27  13:18:17  13:22:41 13:34:25 13:34:38 13:34:39 13:34:39 13:34:40 13:35:05 13:37:00 14:46:23 15:53:16 15:53:16	VSAL VSAL VSAL VSAL E450 E450 E450 E450 E450 E450 E307 VSAL VSAL VSAL VSAL	SUPP  CLEAR SUPP  SUPP  ONSCENE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263 264 267 268 201 E65 202 ****** ****** VP99038911 SGT WHITTET WANTED 10-40 FOR S/65B
13:12:49 13:15:27  13:18:17  13:22:41 13:34:25 13:34:38 13:34:38 13:34:39 13:34:40 13:35:05 13:37:00 14:46:23 15:53:16 15:53:16 17:40:20	VSAL VSAL VSAL VSAL E450 E450 E450 E450 E450 E450 E450 E450	SUPP  CLEAR SUPP  SUPP  ONSCENE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263 264 267 268 201 E65 202 ****** ****** VP99038911 SGT WHITTET WANTED 10-40 FOR S/65B E24
13:12:49 13:15:27  13:18:17  13:22:41 13:34:25 13:34:38 13:34:39 13:34:39 13:34:40 13:35:05 13:37:00 14:46:23 15:53:16 15:53:16 17:40:20 17:40:46	VSAL VSAL VSAL E450 E450 E450 E450 E450 E450 E450 E307 VSAL VSAL VSAL VSAL E307	SUPP  CLEAR SUPP  SUPP  SUPP  ONSCENE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263 264 267 268 201 E65 202 ****** ****** VP99038911 SGT WHITTET WANTED 10-40 FOR S/65B E24
13:12:49 13:15:27  13:18:17  13:22:41 13:34:25 13:34:38 13:34:38 13:34:39 13:34:40 13:35:05 13:37:00 14:46:23 15:53:16 15:53:16 17:40:20	VSAL VSAL VSAL E450 E450 E450 E450 E450 E450 E450 E307 VSAL VSAL VSAL VSAL E307	SUPP  CLEAR SUPP  SUPP  SUPP  ONSCENE INSRVICE	C25 INC, INCIDENT REPORT TX:PER EVACTHERE IS 30-40 GALLONS OF AVIATION FUEL IN THE WATER ONE TANK CAME OFF THE AIRCRAFT AND IS NOT LEAKINGTHE OTHER TANK IS UNDER WA TERUNK IF IT IS STILL LEAKING TX:NO LARGER BODY OF WATER THAT THE POND LEADS TO COMMAND POST IS SENT UP AT THE ENTRANCE TO THE SPORTS COMPLEX 262 260, WITH NO ACTION.PER THE DELAND CHIEF 262 263 264 267 268 201 E65 202 ****** ****** VP99038911 SGT WHITTET WANTED 10-40 FOR S/65B E24

E491 004016 CANTRELL, PATTI E307 004026 FRANZ, ROBIN

OPERATOR ASSIGNMENTS:

TIBURON	COMPLAINT HISTORY DETAIL: V993370118 Page 5(LAST) 12/04/99
CAD	VOLUSIA COUNTY SHERIFF 08:09
***********	**************************************

engende for vertigen in de la de la

			E430	004016	CANTRELL, PATTI	
					MCDONNELL, THOMAS	V JR
			E302	004039	BROWN, RODERICK	
17 <del>4</del> 1.5			E484	004021	GOFF,GREGG	
			E450	004016	CANTRELL, PATTI	
AS	OF.	10:33:59:	E307	004078	CHAPMAN,MYRA	
			E451	004016	CANTRELL, PATTI	
AS	OF	10:35:23:	E430	004084	MCDONNELL, THOMAS	V JR
AS	OF	10:35:56:	E302	004026	FRANZ,ROBIN	
AS	() F	10:58:00:	E484	004026	FRANZ,ROBIN	
			E355	004122	LEVECK,DOUGLAS	
AS	OF.	12:56:07:	E307	004084	MCDONNELL, THOMAS	V JR
			VSAL.	004016	CANTRELL, PATTI	

AS OF 13:39:00: E307 004026 FRANZ, ROBIN

1510W