

**PACIFIC GAS AND ELECTRIC COMPANY
San Bruno Gas Transmission Line Incident
Data Response**

PG&E Data Request No.:	NTSB_058-008		
PG&E File Name:	San Bruno GT Line Incident_DR_NTSB_058-008		
Request Date:	March 31, 2011	Requesting Party:	NTSB
Date Sent:	April 6, 2011	Requestor:	Operations (Chhatre/Nicholson)

QUESTION 8

SCADA

Provide operator command log that shows setpoint changes.

ANSWER 8

Please see the attached SCADA alarm log (which has been exported into an Excel file). The SCADA alarm log is for September 9, 2010 from 15:00:00 to 22:59:42. Gas system operator commands, including set point changes, are memorialized in this log.

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 15:00:31.0	ON	ACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		1	BDMh	CTSF00P3
09/09/10 15:01:19.1	OFF	ACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		0		
09/09/10 15:02:33.0	OFF	CLEAR	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		0	J1Gw	CTSF00P4
09/09/10 15:02:37.8	ON	UNACK	ALI_Y0009_BRT	Lodi-Field Sulfur Analyzer Trbl		1		
09/09/10 15:02:37.8	OFF	ACK	ALI_ES0008_BRT	Lodi-Field Sul Anlyzr Comm Fail		0		
09/09/10 15:02:56.0	OFF	CLEAR	ALI_ES0008_BRT	Lodi-Field Sul Anlyzr Comm Fail		0	BDMh	CTSF00P3
09/09/10 15:02:56.0	ON	ACK	ALI_Y0009_BRT	Lodi-Field Sulfur Analyzer Trbl		1	BDMh	CTSF00P3
09/09/10 15:04:08.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 15:06:12.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	J1Gw	CTSF00P4
09/09/10 15:06:24.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 15:06:24.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 15:06:47.0		Insert	KH2_Y0001	Insert Removed			J1Gw	CTSF00P4
09/09/10 15:06:47.5	ON	UNACK	KH2_Y0001_RUNNG_BRT	Hinkley1 K1 Compressor Status -Runng		1		
09/09/10 15:06:50.0	LOW	UNACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW			
09/09/10 15:07:08.0	LOW	UNACK	SSA_FI0001_AA_BRT	Sac-Glc 20-In L108 Flow Calculated	LOW	0		
09/09/10 15:07:14.0	OFF	CLEAR	KH2_Y0001_RUNNG_BRT	Hinkley1 K1 Compressor Status -Runng		0	J1Gw	CTSF00P4
09/09/10 15:07:14.0	ON	ACK	KH2_Y0001_RUNNG_BRT	Hinkley1 K1 Compressor Status -Runng		0	J1Gw	CTSF00P4
09/09/10 15:07:14.0	OFF	UNACK	KH2_Y0001_RUNNG_BRT	Hinkley1 K1 Compressor Status -Runng		0		
09/09/10 15:07:15.0	OFF	CLEAR	KH2_Y0001_RUNNG_BRT	Hinkley1 K1 Compressor Status -Runng		0		
09/09/10 15:07:16.0	LOW	ACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW		J1Gw	CTSF00P4
09/09/10 15:07:17.0	LOW	ACK	SSA_FI0001_AA_BRT	Sac-Glc 20-In L108 Flow Calculated	LOW	0	J1Gw	CTSF00P4
09/09/10 15:07:31.7	ON	UNACK	K5A_ZT_01A_00R	PLS-5A M1 V299.01A Pct Op Out of Range		1		
09/09/10 15:07:37.0	ON	ACK	K5A_ZT_01A_00R	PLS-5A M1 V299.01A Pct Op Out of Range		1	J1Gw	CTSF00P4
09/09/10 15:07:52.0		RTU	RYAN_SLOUGH	Demand Scan			KLM7	CTSF00P5
09/09/10 15:07:59.0		RTU	RYAN_SLOUGH	On Scan			KLM7	CTSF00P5
09/09/10 15:08:08.0	OFF	CLEAR	Ryan_Slough_Timeout	Ryan_Slough RTU Failed		0		
09/09/10 15:08:08.0	OFF	ACK	Ryan_Slough_Timeout	Ryan_Slough RTU Failed		0		
09/09/10 15:08:08.5	ON	UNACK	MMT_Y0006_BRT	Mil-Plt Front Gate Status		1		
09/09/10 15:08:30.0		Insert	GGN_Temp_On_Sendout	Insert Applied		62.3	mgc4	CTSF00P1
09/09/10 15:08:31.0	ON	UNACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		1		
09/09/10 15:08:53.6	OFF	UNACK	MMT_Y0006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 15:09:09.0	ON	ACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		1	MFV2	CTSF00P2
09/09/10 15:09:10.0	OFF	CLEAR	MMT_Y0006_BRT	Mil-Plt Front Gate Status		0	MFV2	CTSF00P2
09/09/10 15:09:10.0	ON	ACK	MMT_Y0006_BRT	Mil-Plt Front Gate Status		0	MFV2	CTSF00P2
09/09/10 15:10:20.0	ON	UNACK	Humboldt_PP_Timeout	Humboldt_PP RTU Failed		1		
09/09/10 15:10:25.5	OFF	ACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		0		
09/09/10 15:10:27.0	ON	UNACK	Rio_Dell_Scotia_Timeout	Rio_Dell_Scotia RTU Failed		1		
09/09/10 15:10:32.0	ON	UNACK	Tomkins_Hill_Timeout	Tomkins_Hill RTU Failed		1		
09/09/10 15:10:36.0	ON	UNACK	Union_Sta_Eureka_Timeout	Union_Sta_Eureka RTU Failed		1		
09/09/10 15:10:40.0	ON	UNACK	Humboldt_PP_MM_Timeout	Humboldt_PP_MM RTU Failed		1		
09/09/10 15:11:03.0	ON	ACK	Humboldt_PP_MM_Timeout	Humboldt_PP_MM RTU Failed		1	MFV2	CTSF00P2
09/09/10 15:11:04.0	ON	ACK	Rio_Dell_Scotia_Timeout	Rio_Dell_Scotia RTU Failed		1	MFV2	CTSF00P2
09/09/10 15:11:04.0	ON	ACK	Tomkins_Hill_Timeout	Tomkins_Hill RTU Failed		1	MFV2	CTSF00P2
09/09/10 15:11:04.0	ON	ACK	Union_Sta_Eureka_Timeout	Union_Sta_Eureka RTU Failed		1	MFV2	CTSF00P2
09/09/10 15:11:05.0	OFF	CLEAR	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		0	MFV2	CTSF00P2
09/09/10 15:11:05.0	ON	ACK	Humboldt_PP_Timeout	Humboldt_PP RTU Failed		1	MFV2	CTSF00P2
09/09/10 15:11:14.0		RTU	RYAN_SLOUGH	Off Scan			KLM7	CTSF00P5
09/09/10 15:11:15.0		RTU	RYAN_SLOUGH	Demand Scan			KLM7	CTSF00P5
09/09/10 15:11:17.0		RTU	RYAN_SLOUGH	Interleave RTU			KLM7	CTSF00P5
09/09/10 15:11:42.0	ON	UNACK	Ryan_Slough_Timeout	Ryan_Slough RTU Failed		1		
09/09/10 15:11:55.0	ON	ACK	Ryan_Slough_Timeout	Ryan_Slough RTU Failed		1	KLM7	CTSF00P5
09/09/10 15:12:29.0		RTU	SANTA_CRUZ_HLDR	On Scan			KLM7	CTSF00P5
09/09/10 15:12:36.0	OFF	CLEAR	Humboldt_PP_Timeout	Humboldt_PP RTU Failed		0		
09/09/10 15:12:36.0	OFF	ACK	Humboldt_PP_Timeout	Humboldt_PP RTU Failed		0		
09/09/10 15:12:46.0	OFF	CLEAR	Rio_Dell_Scotia_Timeout	Rio_Dell_Scotia RTU Failed		0		
09/09/10 15:12:46.0	OFF	ACK	Rio_Dell_Scotia_Timeout	Rio_Dell_Scotia RTU Failed		0		
09/09/10 15:12:48.0	OFF	CLEAR	Tomkins_Hill_Timeout	Tomkins_Hill RTU Failed		0		
09/09/10 15:12:48.0	OFF	ACK	Tomkins_Hill_Timeout	Tomkins_Hill RTU Failed		0		
09/09/10 15:12:54.0	OFF	ACK	Union_Sta_Eureka_Timeout	Union_Sta_Eureka RTU Failed		0		
09/09/10 15:12:55.0	OFF	CLEAR	Union_Sta_Eureka_Timeout	Union_Sta_Eureka RTU Failed		0		
09/09/10 15:12:58.0	OFF	CLEAR	Humboldt_PP_MM_Timeout	Humboldt_PP_MM RTU Failed		0		
09/09/10 15:12:58.0	OFF	ACK	Humboldt_PP_MM_Timeout	Humboldt_PP_MM RTU Failed		0		
09/09/10 15:13:09.0	OFF	CLEAR	Santa_Cruz_Hldr_Timeout	Santa_Cruz_Hldr RTU Failed		0		
09/09/10 15:13:09.0	OFF	ACK	Santa_Cruz_Hldr_Timeout	Santa_Cruz_Hldr RTU Failed		0		
09/09/10 15:14:16.9	ON	UNACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		1		
09/09/10 15:15:11.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 15:15:15.0		RTU	SANTA_CRUZ_HLDR	Off Scan			KLM7	CTSF00P5
09/09/10 15:15:18.0		RTU	SANTA_CRUZ_HLDR	Demand Scan			KLM7	CTSF00P5
09/09/10 15:15:35.6	OFF	UNACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		0		
09/09/10 15:16:55.0	ON	UNACK	Santa_Cruz_Hldr_Timeout	Santa_Cruz_Hldr RTU Failed		1		
09/09/10 15:17:14.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	mgc4	CTSF00P1
09/09/10 15:17:14.0	ON	ACK	Santa_Cruz_Hldr_Timeout	Santa_Cruz_Hldr RTU Failed		1	mgc4	CTSF00P1
09/09/10 15:17:15.0	OFF	CLEAR	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		0	mgc4	CTSF00P1

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 15:17:15.0	ON	ACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		0	mgc4	CTSF00P1
09/09/10 15:18:45.5	ON	UNACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		1		
09/09/10 15:19:54.8	OFF	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW LOW			
09/09/10 15:19:57.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 15:19:57.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 15:20:48.6	OFF	UNACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		0		
09/09/10 15:22:08.0	OFF	CLEAR	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	OFF		KLM7	CTSF00P5
09/09/10 15:22:08.0	OFF	CLEAR	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		0	KLM7	CTSF00P5
09/09/10 15:22:08.0	ON	ACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		0	KLM7	CTSF00P5
09/09/10 15:23:00.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 15:23:25.3	OFF	ACK	ALI_Y0009_BRT	Lodi-Field Sulfur Analyzer Trbl		0		
09/09/10 15:23:33.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	J1Gw	CTSF00P4
09/09/10 15:23:33.0	OFF	CLEAR	ALI_Y0009_BRT	Lodi-Field Sulfur Analyzer Trbl		0	J1Gw	CTSF00P4
09/09/10 15:25:18.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 15:25:18.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 15:26:53.5	LL	UNACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW LOW			
09/09/10 15:27:06.0	LL	ACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW LOW		J1Gw	CTSF00P4
09/09/10 15:27:46.0	ON	UNACK	Orinda_Timeout	Orinda RTU Failed		1		
09/09/10 15:28:08.0	HH	UNACK	SSA_FI0001_AA_BRT	Sac-Glc 20-In L108 Flow Calculated	HIGH HIGH	8.21		
09/09/10 15:28:46.0	ON	UNACK	Potrero_Meter_Timeout	Potrero_Meter RTU Failed		1		
09/09/10 15:29:40.0	ON	ACK	Potrero_Meter_Timeout	Potrero_Meter RTU Failed		1	J1Gw	CTSF00P4
09/09/10 15:29:41.0	ON	ACK	Orinda_Timeout	Orinda RTU Failed		1	J1Gw	CTSF00P4
09/09/10 15:29:46.0	HH	ACK	SSA_FI0001_AA_BRT	Sac-Glc 20-In L108 Flow Calculated	HIGH HIGH	8.18	KLM7	CTSF00P5
09/09/10 15:29:49.5	ON	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		1		
09/09/10 15:30:01.0	ON	ACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		1	J1Gw	CTSF00P4
09/09/10 15:30:02.0	OFF	CLEAR	Orinda_Timeout	Orinda RTU Failed		0		
09/09/10 15:30:02.0	OFF	ACK	Orinda_Timeout	Orinda RTU Failed		0		
09/09/10 15:30:12.7	OFF	ACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0		
09/09/10 15:31:02.0	OFF	CLEAR	Potrero_Meter_Timeout	Potrero_Meter RTU Failed		0		
09/09/10 15:31:02.0	OFF	ACK	Potrero_Meter_Timeout	Potrero_Meter RTU Failed		0		
09/09/10 15:31:19.3	ON	UNACK	JCZ_ZS9998_BRT	Sn-Cruz-Hr Rtu Door Alarm		1		
09/09/10 15:31:22.0	OFF	CLEAR	Santa_Cruz_Hldr_Timeout	Santa_Cruz_Hldr RTU Failed		0		
09/09/10 15:31:22.0	OFF	ACK	Santa_Cruz_Hldr_Timeout	Santa_Cruz_Hldr RTU Failed		0		
09/09/10 15:31:55.0	ON	ACK	JCZ_ZS9998_BRT	Sn-Cruz-Hr Rtu Door Alarm		1	J1Gw	CTSF00P4
09/09/10 15:32:32.8	ON	UNACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		1		
09/09/10 15:32:53.0	ON	ACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		1	J1Gw	CTSF00P4
09/09/10 15:32:53.0	OFF	CLEAR	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0	J1Gw	CTSF00P4
09/09/10 15:33:45.4	ON	UNACK	SSA_FT0001B_00R	Sac-Glc 20 Inch L108 Hi Orf Dp Out of Range		1		
09/09/10 15:33:49.0	ON	ACK	SSA_FT0001B_00R	Sac-Glc 20 Inch L108 Hi Orf Dp Out of Range		1	MFV2	CTSF00P2
09/09/10 15:33:57.0	OFF	ACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		0		
09/09/10 15:34:05.1	OFF	ACK	SSA_FT0001B_00R	Sac-Glc 20 Inch L108 Hi Orf Dp Out of Range		0		
09/09/10 15:34:05.1	OFF	UNACK	SSA_FT0001B_00R	Sac-Glc 20 Inch L108 Hi Orf Dp Out of Range		0		
09/09/10 15:34:08.0	LOW	UNACK	SSA_FI0001_AA_BRT	Sac-Glc 20-In L108 Flow Calculated	LOW	0		
09/09/10 15:34:11.0	OFF	CLEAR	SSA_FT0001B_00R	Sac-Glc 20 Inch L108 Hi Orf Dp Out of Range		0		
09/09/10 15:34:15.0	LOW	ACK	SSA_FI0001_AA_BRT	Sac-Glc 20-In L108 Flow Calculated	LOW	0	MFV2	CTSF00P2
09/09/10 15:34:16.0	OFF	CLEAR	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		0	MFV2	CTSF00P2
09/09/10 15:34:17.6	OFF	ACK	JCZ_ZS9998_BRT	Sn-Cruz-Hr Rtu Door Alarm		0		
09/09/10 15:34:31.0	OFF	CLEAR	JCZ_ZS9998_BRT	Sn-Cruz-Hr Rtu Door Alarm		0	MFV2	CTSF00P2
09/09/10 15:35:08.0	HH	UNACK	SSA_FI0001_AA_BRT	Sac-Glc 20-In L108 Flow Calculated	HIGH HIGH	8.26		
09/09/10 15:35:16.0	HH	ACK	SSA_FI0001_AA_BRT	Sac-Glc 20-In L108 Flow Calculated	HIGH HIGH	8.26	J1Gw	CTSF00P4
09/09/10 15:36:08.0	OFF	ACK	SSA_FI0001_AA_BRT	Sac-Glc 20-In L108 Flow Calculated	HIGH HIGH	1.04		
09/09/10 15:36:41.0	OFF	CLEAR	SSA_FI0001_AA_BRT	Sac-Glc 20-In L108 Flow Calculated	OFF	1.04	MFV2	CTSF00P2
09/09/10 15:37:28.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 15:37:37.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	J1Gw	CTSF00P4
09/09/10 15:39:48.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 15:39:49.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 15:40:42.0	ON	UNACK	CoCo_PP_Meter_Timeout	CoCo_PP_Meter RTU Failed		1		
09/09/10 15:40:49.0	ON	ACK	CoCo_PP_Meter_Timeout	CoCo_PP_Meter RTU Failed		1	J1Gw	CTSF00P4
09/09/10 15:43:04.0	OFF	CLEAR	CoCo_PP_Meter_Timeout	CoCo_PP_Meter RTU Failed		0		
09/09/10 15:43:04.0	OFF	ACK	CoCo_PP_Meter_Timeout	CoCo_PP_Meter RTU Failed		0		
09/09/10 15:44:44.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 15:47:04.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 15:47:12.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	J1Gw	CTSF00P4
09/09/10 15:47:12.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	J1Gw	CTSF00P4
09/09/10 15:51:24.6	ON	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		1		
09/09/10 15:51:40.1	ON	UNACK	MMT_Y0006_BRT	Mil-Plt Front Gate Status		1		
09/09/10 15:52:12.5	OFF	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0		
09/09/10 15:52:25.9	OFF	UNACK	MMT_Y0006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 15:52:30.0	OFF	CLEAR	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0	MFV2	CTSF00P2
09/09/10 15:52:30.0	ON	ACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0	MFV2	CTSF00P2
09/09/10 15:52:30.0	OFF	CLEAR	MMT_Y0006_BRT	Mil-Plt Front Gate Status		0	MFV2	CTSF00P2
09/09/10 15:52:30.0	ON	ACK	MMT_Y0006_BRT	Mil-Plt Front Gate Status		0	MFV2	CTSF00P2
09/09/10 15:52:48.9	ON	UNACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm		1		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 15:53:30.7	LOW	UNACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	LOW			
09/09/10 15:53:42.2	ON	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai			1	
09/09/10 15:53:49.0	OFF	UNACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	LOW			
09/09/10 15:54:03.2	ON	UNACK	BMD_YS0004_AVAIL_BRT	Mcdnld-Is K4 Compressor Status -Avail			1	
09/09/10 15:54:08.4	OFF	UNACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0	
09/09/10 15:54:46.0	ON	UNACK	LRCV_71A_Timeout	LRCV_71A RTU Failed			1	
09/09/10 15:55:01.3	LOW	UNACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	LOW			
09/09/10 15:56:00.3	OFF	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai			0	
09/09/10 15:56:10.0	ON	UNACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			1	
09/09/10 15:56:45.0	ON	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai			1	
09/09/10 15:57:02.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			1	
09/09/10 15:57:06.0	OFF	UNACK	LRCV_71A_Timeout	LRCV_71A RTU Failed			0	
09/09/10 15:57:28.3	OFF	UNACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0	
09/09/10 15:57:34.1	OFF	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai			0	
09/09/10 15:57:54.2	ON	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai			1	
09/09/10 15:58:38.6	OFF	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai			0	
09/09/10 15:59:21.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0	
09/09/10 15:59:59.4	ON	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm			1	
09/09/10 16:00:21.3	OFF	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm			0	
09/09/10 16:02:22.0	ON	ACK	BMD_YS0004_AVAIL_BRT	Mcdnld-Is K4 Compressor Status -Avail			1	
09/09/10 16:02:22.0	LOW	ACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	LOW		MFV2	CTSF00P2
09/09/10 16:02:23.0	OFF	ACK	BMD_YS0004_AVAIL_BRT	Mcdnld-Is K4 Compressor Status -Avail			0	
09/09/10 16:02:23.0	OFF	CLEAR	BTY_ES0002_BRT	Tracy-Sta Gate Alm			0 MFV2	CTSF00P2
09/09/10 16:02:23.0	ON	ACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm			0 MFV2	CTSF00P2
09/09/10 16:02:23.0	OFF	CLEAR	BMD_YS0004_AVAIL_BRT	Mcdnld-Is K4 Compressor Status -Avail			0 MFV2	CTSF00P2
09/09/10 16:02:23.0	ON	ACK	BMD_YS0004_AVAIL_BRT	Mcdnld-Is K4 Compressor Status -Avail			0 MFV2	CTSF00P2
09/09/10 16:02:23.0	OFF	UNACK	BMD_YS0004_AVAIL_BRT	Mcdnld-Is K4 Compressor Status -Avail			0	
09/09/10 16:02:24.0	OFF	CLEAR	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai			0 MFV2	CTSF00P2
09/09/10 16:02:24.0	ON	ACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai			0 MFV2	CTSF00P2
09/09/10 16:02:25.0	OFF	CLEAR	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0 MFV2	CTSF00P2
09/09/10 16:02:25.0	ON	ACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0 MFV2	CTSF00P2
09/09/10 16:02:25.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0 MFV2	CTSF00P2
09/09/10 16:02:25.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0 MFV2	CTSF00P2
09/09/10 16:02:26.0	OFF	CLEAR	LRCV_71A_Timeout	LRCV_71A RTU Failed			0 MFV2	CTSF00P2
09/09/10 16:02:26.0	ON	ACK	LRCV_71A_Timeout	LRCV_71A RTU Failed			0 MFV2	CTSF00P2
09/09/10 16:05:03.7	LOW	UNACK	SAE_PT0002_BRT	Antelope Rsvl-Feed Press	LOW			
09/09/10 16:06:42.7	LOW	UNACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW			
09/09/10 16:06:58.0		Insert	GGN_FQI008_PD	Insert Applied		727.181 mgc4	J1Gw	CTSF00P1
09/09/10 16:07:01.0	LOW	ACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW		J1Gw	CTSF00P4
09/09/10 16:07:02.0	LOW	ACK	SAE_PT0002_BRT	Antelope Rsvl-Feed Press	LOW		J1Gw	CTSF00P4
09/09/10 16:07:49.0		Setpoint	K5A_PIC_01A_CMD0	Pls-5A D/S Press Sp		500 MFV2		CTSF00P2
09/09/10 16:08:17.0		Insert	GGN_FQI038_PD	Insert Applied		2.175 mgc4		CTSF00P1
09/09/10 16:09:50.2	OFF	ACK	K5A_ZT_01A_00R	PLS-5A M1 V299.01A Pct Op Out of Range		0		
09/09/10 16:09:53.0	OFF	CLEAR	K5A_ZT_01A_00R	PLS-5A M1 V299.01A Pct Op Out of Range		0		
09/09/10 16:09:59.3	ON	UNACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			1	
09/09/10 16:10:39.7	OFF	ACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	LOW		0	
09/09/10 16:11:18.6	OFF	UNACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0	
09/09/10 16:11:37.0		Insert	GGN_FI0038_AA	Insert Applied		0.090625 mgc4		CTSF00P1
09/09/10 16:11:41.0		Insert	GGN_FI0038_AA	Insert Applied		0.090625 mgc4		CTSF00P1
09/09/10 16:11:58.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			1	
09/09/10 16:12:44.0	OFF	CLEAR	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0 J1Gw	CTSF00P4
09/09/10 16:12:44.0	ON	ACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0 J1Gw	CTSF00P4
09/09/10 16:12:45.0	OFF	CLEAR	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	OFF		J1Gw	CTSF00P4
09/09/10 16:12:46.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			1 J1Gw	CTSF00P4
09/09/10 16:13:57.6	ON	UNACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			1	
09/09/10 16:14:16.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0	
09/09/10 16:14:16.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0	
09/09/10 16:15:00.6	ON	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm			1	
09/09/10 16:15:15.9	OFF	UNACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0	
09/09/10 16:15:23.5	OFF	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm			0	
09/09/10 16:16:04.2	HIGH	UNACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	HIGH			
09/09/10 16:16:22.2	OFF	UNACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	HIGH			
09/09/10 16:16:34.0	OFF	CLEAR	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0 J1Gw	CTSF00P4
09/09/10 16:16:34.0	ON	ACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0 J1Gw	CTSF00P4
09/09/10 16:16:34.0	OFF	CLEAR	BTY_ES0002_BRT	Tracy-Sta Gate Alm			0 J1Gw	CTSF00P4
09/09/10 16:16:34.0	ON	ACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm			0 J1Gw	CTSF00P4
09/09/10 16:16:35.0	OFF	CLEAR	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	OFF		J1Gw	CTSF00P4
09/09/10 16:16:35.0	HIGH	ACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	HIGH		J1Gw	CTSF00P4
09/09/10 16:16:38.0	ON	UNACK	Orinda_Timeout	Orinda RTU Failed			1	
09/09/10 16:16:40.2	HIGH	UNACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	HIGH			
09/09/10 16:17:11.1	ON	UNACK	MMT_HS0010RC_BRT	Mil-Ter V10R Controller Con/Loc			1	
09/09/10 16:17:11.1	ON	UNACK	MMT_HS0010RA_BRT	Mil-Ter V10R Controller Aut/Man			1	
09/09/10 16:17:40.0	HIGH	ACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	HIGH		J1Gw	CTSF00P4

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:17:40.0	ON	ACK	MMT_HS0010RA_BRT	Mil-Ter V10R Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:17:41.0	ON	ACK	Orinda_Timeout	Orinda RTU Failed		1	J1Gw	CTSF00P4
09/09/10 16:17:41.0	ON	ACK	MMT_HS0010RC_BRT	Mil-Ter V10R Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0007RC_BRT	Mil-Ter V7R Controller Con/Loc		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0007RA_BRT	Mil-Ter V7R Controller Aut/Man		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0008RC_BRT	Mil-Ter V8R Controller Con/Loc		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0008RA_BRT	Mil-Ter V8R Controller Aut/Man		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0009RC_BRT	Mil-Ter V9R Controller Con/Loc		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0009RA_BRT	Mil-Ter V9R Controller Aut/Man		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0007C_BRT	Mil-Ter V7 Controller Con/Loc		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0007A_BRT	Mil-Ter V7 Controller Aut/Man		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0008C_BRT	Mil-Ter V8 Controller Con/Loc		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0008A_BRT	Mil-Ter V8 Controller Aut/Man		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0009C_BRT	Mil-Ter V9 Controller Con/Loc		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0009A_BRT	Mil-Ter V9 Controller Aut/Man		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0010C_BRT	Mil-Ter V10 Controller Con/Loc		1		
09/09/10 16:17:56.3	ON	UNACK	MMT_HS0010A_BRT	Mil-Ter V10 Controller Aut/Man		1		
09/09/10 16:18:02.0	ON	ACK	MMT_HS0010A_BRT	Mil-Ter V10 Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:18:03.0	ON	ACK	MMT_HS0009A_BRT	Mil-Ter V9 Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:18:03.0	ON	ACK	MMT_HS0010C_BRT	Mil-Ter V10 Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:18:04.0	ON	ACK	MMT_HS0008A_BRT	Mil-Ter V8 Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:18:04.0	ON	ACK	MMT_HS0009C_BRT	Mil-Ter V9 Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:18:05.0	ON	ACK	MMT_HS0007A_BRT	Mil-Ter V7 Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:18:05.0	ON	ACK	MMT_HS0008C_BRT	Mil-Ter V8 Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:18:06.0	ON	ACK	MMT_HS0009RA_BRT	Mil-Ter V9R Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:18:06.0	ON	ACK	MMT_HS0007C_BRT	Mil-Ter V7 Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:18:07.0	ON	ACK	MMT_HS0008RC_BRT	Mil-Ter V8R Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:18:07.0	ON	ACK	MMT_HS0008RA_BRT	Mil-Ter V8R Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:18:07.0	ON	ACK	MMT_HS0009RC_BRT	Mil-Ter V9R Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:18:08.0	ON	ACK	MMT_HS0007RC_BRT	Mil-Ter V7R Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:18:08.0	ON	ACK	MMT_HS0007RA_BRT	Mil-Ter V7R Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0011RC_BRT	Mil-Ter V11R Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0011RA_BRT	Mil-Ter V11R Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0012RC_BRT	Mil-Ter V12R Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0012RA_BRT	Mil-Ter V12R Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0013RC_BRT	Mil-Ter V13R Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0013RA_BRT	Mil-Ter V13R Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0014RC_BRT	Mil-Ter V14R Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0014RA_BRT	Mil-Ter V14R Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0029C_BRT	Mil-Ter V29 Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0029A_BRT	Mil-Ter V29 Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0017RC_BRT	Mil-Ter V17R Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0017RA_BRT	Mil-Ter V17R Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0021RC_BRT	Mil-Ter V21R Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0021RA_BRT	Mil-Ter V21R Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS00C_BRT	Mil-Ter V27R Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS00A_BRT	Mil-Ter V27R Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0038C_BRT	Mil-Ter V38 Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0038A_BRT	Mil-Ter V38 Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0011C_BRT	Mil-Ter V11 Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0011A_BRT	Mil-Ter V11 Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0012C_BRT	Mil-Ter V12 Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0012A_BRT	Mil-Ter V12 Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0013C_BRT	Mil-Ter V13 Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0013A_BRT	Mil-Ter V13 Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0014C_BRT	Mil-Ter V14 Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0014A_BRT	Mil-Ter V14 Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0017C_BRT	Mil-Ter V17 Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0017A_BRT	Mil-Ter V17 Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0021C_BRT	Mil-Ter V21 Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0021A_BRT	Mil-Ter V21 Controller Aut/Man		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0027C_BRT	Mil-Ter V27 Controller Con/Loc		1		
09/09/10 16:18:41.3	ON	UNACK	MMT_HS0027A_BRT	Mil-Ter V27 Controller Aut/Man		1		
09/09/10 16:18:57.0	OFF	CLEAR	Orinda_Timeout	Orinda RTU Failed		0		
09/09/10 16:18:57.0	OFF	ACK	Orinda_Timeout	Orinda RTU Failed		0		
09/09/10 16:19:14.0		Login	ODN\FHS2Admin	AutoLogin			System	CTBRT0P6
09/09/10 16:19:15.0		System	Status	Citect USA - 2009/10/22 - C14 - 9/8/2010 09:00:00			System	CTBRT0P6
09/09/10 16:19:26.2	ON	UNACK	MMT_HS0040C_BRT	Mil-Ter V40 Controller Con/Loc		1		
09/09/10 16:19:26.2	ON	UNACK	MMT_HS0040A_BRT	Mil-Ter V40 Controller Aut/Man		1		
09/09/10 16:19:26.2	ON	UNACK	MMT_HS0062C_BRT	Mil-Ter V62 Controller Con/Loc		1		
09/09/10 16:19:26.2	ON	UNACK	MMT_HS0062A_BRT	Mil-Ter V62 Controller Aut/Man		1		
09/09/10 16:19:37.9	LL	UNACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW LOW			
09/09/10 16:19:50.0	LL	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW LOW			

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:19:51.0	ON	ACK	MMT_HS0062C_BRT	Mil-Ter V62 Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:19:51.0	ON	ACK	MMT_HS0062A_BRT	Mil-Ter V62 Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:19:52.0	ON	ACK	MMT_HS0027A_BRT	Mil-Ter V27 Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:19:52.0	ON	ACK	MMT_HS0040C_BRT	Mil-Ter V40 Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:19:52.0	ON	ACK	MMT_HS0040A_BRT	Mil-Ter V40 Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:19:53.0	ON	ACK	MMT_HS0021A_BRT	Mil-Ter V21 Controller Aut/Man		1		
09/09/10 16:19:53.0	ON	ACK	MMT_HS0027C_BRT	Mil-Ter V27 Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:19:54.0	ON	ACK	MMT_HS0021C_BRT	Mil-Ter V21 Controller Con/Loc		1		
09/09/10 16:20:00.0	ON	ACK	MMT_HS0017A_BRT	Mil-Ter V17 Controller Aut/Man		1		
09/09/10 16:20:01.0	ON	ACK	MMT_HS0017C_BRT	Mil-Ter V17 Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:20:02.0	ON	ACK	MMT_HS0014A_BRT	Mil-Ter V14 Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:20:03.0	ON	ACK	MMT_HS0013A_BRT	Mil-Ter V13 Controller Aut/Man		1	J1Gw	CTSF00P4
09/09/10 16:20:04.0	ON	ACK	MMT_HS0014C_BRT	Mil-Ter V14 Controller Con/Loc		1	J1Gw	CTSF00P4
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0008A_BRT	Mil-Ter V8 Controller Aut/Man		0		
09/09/10 16:20:10.9	ON	UNACK	MMT_ES0008_BRT	Mil-Ter V8 Controller Error		1		
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0009C_BRT	Mil-Ter V9 Controller Con/Loc		0		
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0009A_BRT	Mil-Ter V9 Controller Aut/Man		0		
09/09/10 16:20:10.9	ON	UNACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		1		
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0010C_BRT	Mil-Ter V10 Controller Con/Loc		0		
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0010A_BRT	Mil-Ter V10 Controller Aut/Man		0		
09/09/10 16:20:10.9	ON	UNACK	MMT_ES0010_BRT	Mil-Ter V10 Controller Error		1		
09/09/10 16:20:10.9	OFF	UNACK	MMT_HS0011C_BRT	Mil-Ter V11 Controller Con/Loc		0		
09/09/10 16:20:10.9	OFF	UNACK	MMT_HS0011A_BRT	Mil-Ter V11 Controller Aut/Man		0		
09/09/10 16:20:10.9	ON	UNACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ES0013_BRT	Mil-Ter V13 Controller Error		1		
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0014C_BRT	Mil-Ter V14 Controller Con/Loc		0		
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0014A_BRT	Mil-Ter V14 Controller Aut/Man		0		
09/09/10 16:20:10.9	ON	UNACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error		1		
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0017C_BRT	Mil-Ter V17 Controller Con/Loc		0		
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0017A_BRT	Mil-Ter V17 Controller Aut/Man		0		
09/09/10 16:20:10.9	ON	UNACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		1		
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0021C_BRT	Mil-Ter V21 Controller Con/Loc		0		
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0021A_BRT	Mil-Ter V21 Controller Aut/Man		0		
09/09/10 16:20:10.9	ON	UNACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		1		
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0027C_BRT	Mil-Ter V27 Controller Con/Loc		0		
09/09/10 16:20:10.9	OFF	ACK	MMT_HS0027A_BRT	Mil-Ter V27 Controller Aut/Man		0		
09/09/10 16:20:10.9	ON	UNACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0071_0_BRT	Mil-Ter Mon V71 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0070_0_BRT	Mil-Ter Mon V70 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0067_0_BRT	Mil-Ter Mon V67 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0066_0_BRT	Mil-Ter Mon V66 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0063_0_BRT	Mil-Ter V63 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0039_0_BRT	Mil-Ter V39 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0037_0_BRT	Mil-Ter V37 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0028_0_BRT	Mil-Ter Byp Mon V28 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0026_0_BRT	Mil-Ter Mon V26 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0020_0_BRT	Mil-Ter Mon V20 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0016_0_BRT	Mil-Ter Mon V16 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0006_0_BRT	Mil-Ter Mon V6 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0005_0_BRT	Mil-Ter Mon V5 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0004_0_BRT	Mil-Ter Mon V4 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ZS0003_0_BRT	Mil-Ter Mon V3 Not Open		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ES0105_BRT	Mil-Ter Air Comprsr 2 Shutdown		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_ES0104_BRT	Mil-Ter Air Comprsr 1 Shutdown		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_PS0002_BRT	Mil-Ter Air Tank 2 Press Lo Lo		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_PS0001_BRT	Mil-Ter Air Tank 1 Press Lo Lo		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_YS0005_BRT	Mil-Plt Operation Bldng Entry		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_YS0004_BRT	Mil-Plt Control Room Entry		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_YS0003_BRT	Mil-Plt Telecom & Vax Room		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_YS0002_BRT	Mil-Plt Shop Building Entry		1		
09/09/10 16:20:10.9	ON	UNACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		1		
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0007RC_BRT	Mil-Ter V7R Controller Con/Loc		0		
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0007RA_BRT	Mil-Ter V7R Controller Aut/Man		0		
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		1		
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0008RC_BRT	Mil-Ter V8R Controller Con/Loc		0		
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0008RA_BRT	Mil-Ter V8R Controller Aut/Man		0		
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error		1		
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0009RC_BRT	Mil-Ter V9R Controller Con/Loc		0		
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0009RA_BRT	Mil-Ter V9R Controller Aut/Man		0		
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		1		
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0010RC_BRT	Mil-Ter V10R Controller Con/Loc		0		
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0010RA_BRT	Mil-Ter V10R Controller Aut/Man		0		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error			1	
09/09/10 16:20:11.0	OFF	UNACK	MMT_HS0011RC_BRT	Mil-Ter V11R Controller Con/Loc			0	
09/09/10 16:20:11.0	OFF	UNACK	MMT_HS0011RA_BRT	Mil-Ter V11R Controller Aut/Man			0	
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error			1	
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error			1	
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error			1	
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error			1	
09/09/10 16:20:11.0	OFF	UNACK	MMT_HS0029C_BRT	Mil-Ter V29 Controller Con/Loc			0	
09/09/10 16:20:11.0	OFF	UNACK	MMT_HS0029A_BRT	Mil-Ter V29 Controller Aut/Man			0	
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error			1	
09/09/10 16:20:11.0	OFF	UNACK	MMT_HS0017RC_BRT	Mil-Ter V17R Controller Con/Loc			0	
09/09/10 16:20:11.0	OFF	UNACK	MMT_HS0017RA_BRT	Mil-Ter V17R Controller Aut/Man			0	
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error			1	
09/09/10 16:20:11.0	OFF	UNACK	MMT_HS0021RC_BRT	Mil-Ter V21R Controller Con/Loc			0	
09/09/10 16:20:11.0	OFF	UNACK	MMT_HS0021RA_BRT	Mil-Ter V21R Controller Aut/Man			0	
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0021R_BRT	Mil-Ter V21R Controller Error			1	
09/09/10 16:20:11.0	OFF	UNACK	MMT_HS00C_BRT	Mil-Ter V27R Controller Con/Loc			0	
09/09/10 16:20:11.0	OFF	UNACK	MMT_HS00A_BRT	Mil-Ter V27R Controller Aut/Man			0	
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error			1	
09/09/10 16:20:11.0	OFF	UNACK	MMT_HS0038C_BRT	Mil-Ter V38 Controller Con/Loc			0	
09/09/10 16:20:11.0	OFF	UNACK	MMT_HS0038A_BRT	Mil-Ter V38 Controller Aut/Man			0	
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0038_BRT	Mil-Ter V38 Controller Error			1	
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0040C_BRT	Mil-Ter V40 Controller Con/Loc			0	
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0040A_BRT	Mil-Ter V40 Controller Aut/Man			0	
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0040_BRT	Mil-Ter V40 Controller Error			1	
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0062C_BRT	Mil-Ter V62 Controller Con/Loc			0	
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0062A_BRT	Mil-Ter V62 Controller Aut/Man			0	
09/09/10 16:20:11.0	ON	UNACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error			1	
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0007C_BRT	Mil-Ter V7 Controller Con/Loc			0	
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0007A_BRT	Mil-Ter V7 Controller Aut/Man			0	
09/09/10 16:20:11.0	OFF	ACK	MMT_HS0008C_BRT	Mil-Ter V8 Controller Con/Loc			0	
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0062_BRT	Mlpts-Ter Sta Bypass Press	LOW LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0001_BRT	Mil-Ter Instr Air Press	LOW LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_TT0001_BRT	MIL-PLT ATM TEMP	LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0008_BRT	Mlpts-Ter L300B Press	LOW LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0034A_BRT	Mlpts-Ter M34 D/S Press	LOW LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0050_BRT	Mlpts-Ter Sjdfm V50 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0049_BRT	Mlpts-Ter L132 V49 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0048_BRT	Mlpts-Ter L101 V48 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0045_BRT	Mlpts-Ter L109 V45 Pct Op	LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0087_BRT	Mlpts-Ter L100 Press	LOW LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0084_BRT	Mlpts-Ter L101 Press	LOW LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0083_BRT	Mlpts-Ter L132 Press	LOW LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0063_BRT	Mlpts-Ter Mon V63 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0071_BRT	Mlpts-Ter L131 Mon V71 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0070_BRT	Mlpts-Ter L131 Mon V70 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0067_BRT	Mlpts-Ter L107 Mon V67 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0066_BRT	Mlpts-Ter L107 Mon V66 Pct Op	LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0040_BRT	Mlpts-Ter L109 Press	LOW LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0009_BRT	Mlpts-Ter Sjdfm Press	LOW LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0028_BRT	Mlpts-Ter Byp Mon V28 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0026_BRT	Mlpts-Ter Mixer Mon V26 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0016_BRT	Mlpts-Ter Mixer Mon V16 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0006_BRT	Mlpts-Ter M7 Mon V6 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0005_BRT	Mlpts-Ter M8 Mon V5 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0004_BRT	Mlpts-Ter M9 Mon V4 Pct Op	LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_ZT0003_BRT	Mlpts-Ter M10 Mon V3 Pct Op	LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0038A_BRT	Mlpts-Ter M38 D/S Press	LOW LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0032_BRT	Mlpts-Ter M32 D/S Press	LOW LOW			
09/09/10 16:20:12.9	LOW	UNACK	MMT_PT0031_BRT	Mlpts-Ter M31 D/S Press	LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0030_BRT	Mlpts-Ter M30 D/S Press	LOW LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0029B_BRT	Mlpts-Ter Mixer D/S Press	LOW LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0017_BRT	Mlpts-Ter Mixer D/S Press	LOW LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0007_BRT	Mlpts-Ter L107 Press	LOW LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0012_BRT	Mlpts-Ter L131 Press	LOW LOW			
09/09/10 16:20:12.9	LL	UNACK	MMT_PT0010_BRT	Mlpts-Ter L300A Press	LOW LOW			
09/09/10 16:20:16.9	OFF	ACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	HIGH			
09/09/10 16:20:30.0	LL	ACK	MMT_PT0062_BRT	Mlpts-Ter Sta Bypass Press	LOW LOW			
09/09/10 16:20:31.0	LL	ACK	MMT_PT0010_BRT	Mlpts-Ter L300A Press	LOW LOW			
09/09/10 16:20:52.9	HIGH	UNACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	HIGH			
09/09/10 16:20:53.0	LL	ACK	MMT_PT0012_BRT	Mlpts-Ter L131 Press	LOW LOW		J1Gw	CTSF00P4
09/09/10 16:20:54.0	HIGH	ACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	HIGH		J1Gw	CTSF00P4
09/09/10 16:20:54.0	OFF	CLEAR	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	OFF		J1Gw	CTSF00P4

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:20:54.0	LL	ACK	MMT_PT0007_BRT	Mlpts-Ter L107 Press	LOW LOW		J1Gw	CTSF00P4
09/09/10 16:20:55.0	LL	ACK	MMT_PT0030_BRT	Mlpts-Ter M30 D/S Press	LOW LOW		J1Gw	CTSF00P4
09/09/10 16:20:55.0	LL	ACK	MMT_PT0029B_BRT	Mlpts-Ter Mixer D/S Press	LOW LOW		J1Gw	CTSF00P4
09/09/10 16:20:55.0	LL	ACK	MMT_PT0017_BRT	Mlpts-Ter Mixer D/S Press	LOW LOW		J1Gw	CTSF00P4
09/09/10 16:20:55.0	OFF	CLEAR	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	OFF			
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0040A_BRT	Mil-Ter V40 Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0040_BRT	Mil-Ter V40 Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0062C_BRT	Mil-Ter V62 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0062A_BRT	Mil-Ter V62 Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0007C_BRT	Mil-Ter V7 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0007A_BRT	Mil-Ter V7 Controller Aut/Man		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0008C_BRT	Mil-Ter V8 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0008A_BRT	Mil-Ter V8 Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0008_BRT	Mil-Ter V8 Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0009C_BRT	Mil-Ter V9 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0009A_BRT	Mil-Ter V9 Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0010C_BRT	Mil-Ter V10 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0007RC_BRT	Mil-Ter V7R Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0007RA_BRT	Mil-Ter V7R Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0008RC_BRT	Mil-Ter V8R Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0008RA_BRT	Mil-Ter V8R Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0009RC_BRT	Mil-Ter V9R Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0009RA_BRT	Mil-Ter V9R Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0010RC_BRT	Mil-Ter V10R Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0010RA_BRT	Mil-Ter V10R Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0011RC_BRT	Mil-Ter V11R Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0011RA_BRT	Mil-Ter V11R Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error		0		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		0		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		0		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0029C_BRT	Mil-Ter V29 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0029A_BRT	Mil-Ter V29 Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0017RC_BRT	Mil-Ter V17R Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0017RA_BRT	Mil-Ter V17R Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0021RC_BRT	Mil-Ter V21R Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0021RA_BRT	Mil-Ter V21R Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0021R_BRT	Mil-Ter V21R Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS00C_BRT	Mil-Ter V27R Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS00A_BRT	Mil-Ter V27R Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0038C_BRT	Mil-Ter V38 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0038A_BRT	Mil-Ter V38 Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0038_BRT	Mil-Ter V38 Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0040C_BRT	Mil-Ter V40 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0010A_BRT	Mil-Ter V10 Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0010_BRT	Mil-Ter V10 Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0011C_BRT	Mil-Ter V11 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0011A_BRT	Mil-Ter V11 Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		0		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error		0		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0013_BRT	Mil-Ter V13 Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0014C_BRT	Mil-Ter V14 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0014A_BRT	Mil-Ter V14 Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0017C_BRT	Mil-Ter V17 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0017A_BRT	Mil-Ter V17 Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0021C_BRT	Mil-Ter V21 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0021A_BRT	Mil-Ter V21 Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0027C_BRT	Mil-Ter V27 Controller Con/Loc		1		
09/09/10 16:20:55.8	ON	UNACK	MMT_HS0027A_BRT	Mil-Ter V27 Controller Aut/Man		1		
09/09/10 16:20:55.8	OFF	UNACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		0		
09/09/10 16:20:55.8	ON	UNACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:20:56.0	LL	ACK	MMT_PT0038A_BRT	Mlpts-Ter M38 D/S Press	LOW LOW		J1Gw	CTSF00P4
09/09/10 16:20:56.0	LOW	ACK	MMT_ZT0004_BRT	Mlpts-Ter M9 Mon V4 Pct Op	LOW		J1Gw	CTSF00P4
09/09/10 16:20:56.0	LOW	ACK	MMT_ZT0003_BRT	Mlpts-Ter M10 Mon V3 Pct Op	LOW		J1Gw	CTSF00P4
09/09/10 16:20:56.0	LOW	ACK	MMT_PT0031_BRT	Mlpts-Ter M31 D/S Press	LOW		J1Gw	CTSF00P4
09/09/10 16:20:57.0	LOW	ACK	MMT_ZT0005_BRT	Mlpts-Ter M8 Mon V5 Pct Op	LOW		J1Gw	CTSF00P4
09/09/10 16:20:57.0	LL	ACK	MMT_PT0032_BRT	Mlpts-Ter M32 D/S Press	LOW LOW		J1Gw	CTSF00P4
09/09/10 16:20:58.0	ON	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo			1 J1Gw	CTSF00P4
09/09/10 16:20:58.0	ON	ACK	MMT_HS0027A_BRT	Mil-Ter V27 Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:20:59.0	ON	ACK	MMT_HS0027C_BRT	Mil-Ter V27 Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:00.0	ON	ACK	MMT_HS0021C_BRT	Mil-Ter V21 Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:00.0	ON	ACK	MMT_HS0021A_BRT	Mil-Ter V21 Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:00.0	ON	ACK	MMT_HS0017A_BRT	Mil-Ter V17 Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:01.0	ON	ACK	MMT_HS0014A_BRT	Mil-Ter V14 Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:01.0	ON	ACK	MMT_HS0017C_BRT	Mil-Ter V17 Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:02.0	ON	ACK	MMT_HS0014C_BRT	Mil-Ter V14 Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:04.0	LL	UNACK	MMT_FI0903_AA_BRT	Mlpts-Ter Penin Tot Flow Calculated	LOW LOW		0	
09/09/10 16:21:10.9	OFF	ACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	HIGH			
09/09/10 16:21:10.9	OFF	UNACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	HIGH			
09/09/10 16:21:12.0	LL	ACK	MMT_FI0903_AA_BRT	Mlpts-Ter Penin Tot Flow Calculated	LOW LOW		0 J1Gw	CTSF00P4
09/09/10 16:21:13.0	ON	ACK	MMT_HS0011C_BRT	Mil-Ter V11 Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:13.0	ON	ACK	MMT_HS0011A_BRT	Mil-Ter V11 Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:14.0		Login	ODN\FHS2Admin	AutoLogin			System	CTSF0Admin2
09/09/10 16:21:14.0	ON	ACK	MMT_HS0010A_BRT	Mil-Ter V10 Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:15.0		System	Status	Citect USA - 2009/10/22 - C14 - 9/8/2010 09:00:00			System	CTSF0Admin2
09/09/10 16:21:26.0	ON	ACK	MMT_HS0010C_BRT	Mil-Ter V10 Controller Con/Loc			1	
09/09/10 16:21:27.0	ON	ACK	MMT_HS0008A_BRT	Mil-Ter V8 Controller Aut/Man			1	
09/09/10 16:21:27.0	ON	ACK	MMT_HS0009C_BRT	Mil-Ter V9 Controller Con/Loc			1	
09/09/10 16:21:28.0	ON	ACK	MMT_HS0062C_BRT	Mil-Ter V62 Controller Con/Loc			1	
09/09/10 16:21:28.0	ON	ACK	MMT_HS0007A_BRT	Mil-Ter V7 Controller Aut/Man			1	
09/09/10 16:21:28.0	ON	ACK	MMT_HS0008C_BRT	Mil-Ter V8 Controller Con/Loc			1	
09/09/10 16:21:28.0	ON	ACK	MMT_HS0009A_BRT	Mil-Ter V9 Controller Aut/Man			1	
09/09/10 16:21:29.0	ON	ACK	MMT_HS0062A_BRT	Mil-Ter V62 Controller Aut/Man			1	
09/09/10 16:21:30.0	ON	ACK	MMT_HS0007C_BRT	Mil-Ter V7 Controller Con/Loc			1	
09/09/10 16:21:31.0	ON	ACK	MMT_HS0038A_BRT	Mil-Ter V38 Controller Aut/Man			1	
09/09/10 16:21:31.0	ON	ACK	MMT_HS0038C_BRT	Mil-Ter V38 Controller Con/Loc			1	
09/09/10 16:21:31.0	ON	ACK	MMT_HS0040C_BRT	Mil-Ter V40 Controller Con/Loc			1	
09/09/10 16:21:32.0	ON	ACK	MMT_HS00C_BRT	Mil-Ter V27R Controller Con/Loc			1	
09/09/10 16:21:32.0	ON	ACK	MMT_HS0040A_BRT	Mil-Ter V40 Controller Aut/Man			1	
09/09/10 16:21:33.0	ON	ACK	MMT_HS00A_BRT	Mil-Ter V27R Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:34.0	ON	ACK	MMT_HS0021RC_BRT	Mil-Ter V21R Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:34.0	ON	ACK	MMT_HS0017RC_BRT	Mil-Ter V17R Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:34.0	ON	ACK	MMT_HS0017RA_BRT	Mil-Ter V17R Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:34.0	ON	ACK	MMT_HS0021RA_BRT	Mil-Ter V21R Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:35.0	ON	ACK	MMT_HS0029A_BRT	Mil-Ter V29 Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:36.0	ON	ACK	MMT_HS0011RA_BRT	Mil-Ter V11R Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:48.0	ON	ACK	MMT_HS0029C_BRT	Mil-Ter V29 Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:49.0	ON	ACK	MMT_HS0009RC_BRT	Mil-Ter V9R Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:49.0	ON	ACK	MMT_HS0010RC_BRT	Mil-Ter V10R Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:49.0	ON	ACK	MMT_HS0010RA_BRT	Mil-Ter V10R Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:50.0	ON	ACK	MMT_HS0009RA_BRT	Mil-Ter V9R Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:50.0	ON	ACK	MMT_HS0008RA_BRT	Mil-Ter V8R Controller Aut/Man			1	
09/09/10 16:21:51.0	ON	ACK	MMT_HS0008RC_BRT	Mil-Ter V8R Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:51.0	ON	ACK	MMT_HS0011RC_BRT	Mil-Ter V11R Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:52.0	LOW	ACK	MMT_ZT0006_BRT	Mlpts-Ter M7 Mon V6 Pct Op	LOW		J1Gw	CTSF00P4
09/09/10 16:21:52.0	ON	ACK	MMT_HS0007RC_BRT	Mil-Ter V7R Controller Con/Loc			1 J1Gw	CTSF00P4
09/09/10 16:21:52.0	ON	ACK	MMT_HS0007RA_BRT	Mil-Ter V7R Controller Aut/Man			1 J1Gw	CTSF00P4
09/09/10 16:21:53.0	LOW	ACK	MMT_ZT0016_BRT	Mlpts-Ter Mixer Mon V16 Pct Op	LOW			
09/09/10 16:22:01.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			1	
09/09/10 16:22:04.0	LL	UNACK	MMT_FI0904_AA_BRT	Mlpts-Ter Pen+Sjo Tot Flow Calculated	LOW LOW		0	
09/09/10 16:22:04.0	LL	UNACK	MMT_FI0901_AA_BRT	Mlpts-Ter Stn Tot Flow In Calculated	LOW LOW		0	
09/09/10 16:24:15.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0	
09/09/10 16:24:15.0	ON	UNACK	L101_Meter_Timeout	L101_Meter RTU Failed			1	
09/09/10 16:24:19.0	ON	UNACK	L109_Meter_Timeout	L109_Meter RTU Failed			1	
09/09/10 16:24:43.0	ON	ACK	L101_Meter_Timeout	L101_Meter RTU Failed			1	
09/09/10 16:24:43.0	ON	ACK	L109_Meter_Timeout	L109_Meter RTU Failed			1 BDMh	CTSF00P3
09/09/10 16:24:44.0	LOW	ACK	MMT_ZT0026_BRT	Mlpts-Ter Mixer Mon V26 Pct Op	LOW		1 BDMh	CTSF00P3
09/09/10 16:24:44.0	LL	ACK	MMT_FI0904_AA_BRT	Mlpts-Ter Pen+Sjo Tot Flow Calculated	LOW LOW		0 BDMh	CTSF00P3
09/09/10 16:24:44.0	LL	ACK	MMT_FI0901_AA_BRT	Mlpts-Ter Stn Tot Flow In Calculated	LOW LOW		0 BDMh	CTSF00P3
09/09/10 16:24:45.0	LL	ACK	MMT_PT0009_BRT	Mlpts-Ter Sjdfm Press	LOW LOW		BDMh	CTSF00P3
09/09/10 16:24:45.0	LOW	ACK	MMT_ZT0028_BRT	Mlpts-Ter Byp Mon V28 Pct Op	LOW		BDMh	CTSF00P3
09/09/10 16:24:46.0	LOW	ACK	MMT_ZT0066_BRT	Mlpts-Ter L107 Mon V66 Pct Op	LOW		BDMh	CTSF00P3
09/09/10 16:24:46.0	LL	ACK	MMT_PT0040_BRT	Mlpts-Ter L109 Press	LOW LOW		BDMh	CTSF00P3
09/09/10 16:24:47.0	LOW	ACK	MMT_ZT0071_BRT	Mlpts-Ter L131 Mon V71 Pct Op	LOW		BDMh	CTSF00P3

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:24:47.0	LOW	ACK	MMT_ZT0070_BRT	MLpts-Ter L131 Mon V70 Pct Op	LOW		BDMh	CTSF00P3
09/09/10 16:24:47.0	LOW	ACK	MMT_ZT0067_BRT	MLpts-Ter L107 Mon V67 Pct Op	LOW		BDMh	CTSF00P3
09/09/10 16:24:48.0	LL	ACK	MMT_PT0083_BRT	MLpts-Ter L132 Press	LOW LOW		BDMh	CTSF00P3
09/09/10 16:24:48.0	LOW	ACK	MMT_ZT0063_BRT	MLpts-Ter Mon V63 Pct Op	LOW		BDMh	CTSF00P3
09/09/10 16:24:49.0	LOW	ACK	MMT_ZT0045_BRT	MLpts-Ter L109 V45 Pct Op	LOW		BDMh	CTSF00P3
09/09/10 16:24:49.0	LL	ACK	MMT_PT0087_BRT	MLpts-Ter L100 Press	LOW LOW		BDMh	CTSF00P3
09/09/10 16:24:49.0	LL	ACK	MMT_PT0084_BRT	MLpts-Ter L101 Press	LOW LOW		BDMh	CTSF00P3
09/09/10 16:24:50.0	LOW	ACK	MMT_ZT0049_BRT	MLpts-Ter L132 V49 Pct Op	LOW		BDMh	CTSF00P3
09/09/10 16:24:50.0	LOW	ACK	MMT_ZT0048_BRT	MLpts-Ter L101 V48 Pct Op	LOW		BDMh	CTSF00P3
09/09/10 16:24:51.0	LL	ACK	MMT_PT0034A_BRT	MLpts-Ter M34 D/S Press	LOW LOW		BDMh	CTSF00P3
09/09/10 16:24:51.0	LOW	ACK	MMT_ZT0050_BRT	MLpts-Ter Sjdfrm V50 Pct Op	LOW		BDMh	CTSF00P3
09/09/10 16:24:52.0	ON	ACK	MMT_YS0003_BRT	Mil-Plt Telecom & Vax Room			1	
09/09/10 16:24:52.0	ON	ACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status			1 BDMh	CTSF00P3
09/09/10 16:24:52.0	LL	ACK	MMT_PT0001_BRT	Mil-Ter Instr Air Press	LOW LOW		BDMh	CTSF00P3
09/09/10 16:24:52.0	LOW	ACK	MMT_TT0001_BRT	MIL-PLT ATM TEMP	LOW		BDMh	CTSF00P3
09/09/10 16:24:52.0	LL	ACK	MMT_PT0008_BRT	MLpts-Ter L300B Press	LOW LOW		BDMh	CTSF00P3
09/09/10 16:24:53.0	ON	ACK	MMT_YS0004_BRT	Mil-Plt Control Room Entry			1 BDMh	CTSF00P3
09/09/10 16:24:53.0	ON	ACK	MMT_YS0002_BRT	Mil-Plt Shop Building Entry			1 J1Gw	CTSF00P4
09/09/10 16:24:54.0	ON	ACK	MMT_PS0001_BRT	Mil-Ter Air Tank 1 Press Lo Lo			1 BDMh	CTSF00P3
09/09/10 16:24:54.0	ON	ACK	MMT_PS0002_BRT	Mil-Ter Air Tank 2 Press Lo Lo			1 J1Gw	CTSF00P4
09/09/10 16:24:54.0	ON	ACK	MMT_YS0005_BRT	Mil-Plt Operation Bldng Entry			1 BDMh	CTSF00P3
09/09/10 16:24:55.0	ON	ACK	MMT_ZS0003_0_BRT	Mil-Ter Mon V3 Not Open			1 BDMh	CTSF00P3
09/09/10 16:24:55.0	ON	ACK	MMT_ES0104_BRT	Mil-Ter Air Comprsr 1 Shutdown			1 BDMh	CTSF00P3
09/09/10 16:24:55.0	ON	ACK	MMT_ES0105_BRT	Mil-Ter Air Comprsr 2 Shutdown			1 J1Gw	CTSF00P4
09/09/10 16:24:56.0	ON	ACK	MMT_ZS0005_0_BRT	Mil-Ter Mon V5 Not Open			1 J1Gw	CTSF00P4
09/09/10 16:24:56.0	ON	ACK	MMT_ZS0004_0_BRT	Mil-Ter Mon V4 Not Open			1 BDMh	CTSF00P3
09/09/10 16:24:57.0	ON	ACK	MMT_ZS0016_0_BRT	Mil-Ter Mon V16 Not Open			1 BDMh	CTSF00P3
09/09/10 16:24:57.0	ON	ACK	MMT_ZS0006_0_BRT	Mil-Ter Mon V6 Not Open			1	
09/09/10 16:24:58.0	ON	ACK	MMT_ZS0028_0_BRT	Mil-Ter Byp Mon V28 Not Open			1 BDMh	CTSF00P3
09/09/10 16:24:58.0	ON	ACK	MMT_ZS0026_0_BRT	Mil-Ter Mon V26 Not Open			1 BDMh	CTSF00P3
09/09/10 16:24:58.0	ON	ACK	MMT_ZS0020_0_BRT	Mil-Ter Mon V20 Not Open			1 BDMh	CTSF00P3
09/09/10 16:24:59.0	ON	ACK	MMT_ZS0063_0_BRT	Mil-Ter V63 Not Open			1 BDMh	CTSF00P3
09/09/10 16:24:59.0	ON	ACK	MMT_ZS0039_0_BRT	Mil-Ter V39 Not Open			1 BDMh	CTSF00P3
09/09/10 16:24:59.0	ON	ACK	MMT_ZS0037_0_BRT	Mil-Ter V37 Not Open			1 BDMh	CTSF00P3
09/09/10 16:25:00.0	ON	ACK	MMT_ZS0067_0_BRT	Mil-Ter Mon V67 Not Open			1 BDMh	CTSF00P3
09/09/10 16:25:00.0	OFF	CLEAR	MMT_ES0038_BRT	Mil-Ter V38 Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:00.0	ON	ACK	MMT_ES0038_BRT	Mil-Ter V38 Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:00.0	ON	ACK	MMT_ZS0066_0_BRT	Mil-Ter Mon V66 Not Open			1 BDMh	CTSF00P3
09/09/10 16:25:00.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0 J1Gw	CTSF00P4
09/09/10 16:25:00.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0 J1Gw	CTSF00P4
09/09/10 16:25:01.0	ON	ACK	MMT_HS0013C_BRT	Mil-Ter V13 Controller Con/Loc			1 BDMh	CTSF00P3
09/09/10 16:25:01.0	ON	ACK	MMT_ZS0071_0_BRT	Mil-Ter Mon V71 Not Open			1	
09/09/10 16:25:01.0	OFF	CLEAR	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:01.0	ON	ACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:01.0	OFF	CLEAR	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:01.0	ON	ACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:01.0	ON	ACK	MMT_ZS0070_0_BRT	Mil-Ter Mon V70 Not Open			1 BDMh	CTSF00P3
09/09/10 16:25:01.0	OFF	CLEAR	MMT_ES0021R_BRT	Mil-Ter V21R Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:01.0	ON	ACK	MMT_ES0021R_BRT	Mil-Ter V21R Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:02.0	OFF	CLEAR	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:02.0	ON	ACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:02.0	ON	ACK	MMT_HS0012A_BRT	Mil-Ter V12 Controller Aut/Man			1 BDMh	CTSF00P3
09/09/10 16:25:02.0	OFF	CLEAR	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:02.0	ON	ACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:02.0	ON	ACK	MMT_HS0012C_BRT	Mil-Ter V12 Controller Con/Loc			1 BDMh	CTSF00P3
09/09/10 16:25:02.0	OFF	CLEAR	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:02.0	ON	ACK	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:03.0	ON	ACK	MMT_HS0013RC_BRT	Mil-Ter V13R Controller Con/Loc			1 BDMh	CTSF00P3
09/09/10 16:25:03.0	OFF	CLEAR	MMT_ES0012_BRT	Mil-Ter V12 Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:03.0	ON	ACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:03.0	ON	ACK	MMT_HS0013RA_BRT	Mil-Ter V13R Controller Aut/Man			1 BDMh	CTSF00P3
09/09/10 16:25:03.0	OFF	CLEAR	MMT_ES0014_BRT	Mil-Ter V14 Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:03.0	ON	ACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:03.0	ON	ACK	MMT_HS0014RC_BRT	Mil-Ter V14R Controller Con/Loc			1 BDMh	CTSF00P3
09/09/10 16:25:03.0	OFF	CLEAR	MMT_ES0027_BRT	Mil-Ter V27 Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:03.0	ON	ACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error			0	
09/09/10 16:25:03.0	ON	ACK	MMT_HS0014RA_BRT	Mil-Ter V14R Controller Aut/Man			1 BDMh	CTSF00P3
09/09/10 16:25:04.0	OFF	CLEAR	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	OFF		BDMh	CTSF00P3
09/09/10 16:25:04.0	ON	ACK	MMT_HS0012RC_BRT	Mil-Ter V12R Controller Con/Loc			1 BDMh	CTSF00P3
09/09/10 16:25:04.0	OFF	CLEAR	MMT_ES0008_BRT	Mil-Ter V8 Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:04.0	ON	ACK	MMT_ES0008_BRT	Mil-Ter V8 Controller Error			0 J1Gw	CTSF00P4
09/09/10 16:25:04.0	ON	ACK	MMT_HS0012RA_BRT	Mil-Ter V12R Controller Aut/Man			1 BDMh	CTSF00P3
09/09/10 16:25:04.0	OFF	CLEAR	MMT_ES0010_BRT	Mil-Ter V10 Controller Error			0 J1Gw	CTSF00P4

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:25:04.0	ON	ACK	MMT_ES0010_BRT	Mil-Ter V10 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:05.0	OFF	CLEAR	MMT_ES0040_BRT	Mil-Ter V40 Controller Error		0		
09/09/10 16:25:05.0	ON	ACK	MMT_ES0040_BRT	Mil-Ter V40 Controller Error		0		
09/09/10 16:25:05.0	OFF	CLEAR	MMT_ES0013_BRT	Mil-Ter V13 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:05.0	ON	ACK	MMT_ES0013_BRT	Mil-Ter V13 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:05.0	OFF	CLEAR	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		0		
09/09/10 16:25:05.0	ON	ACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		0		
09/09/10 16:25:06.0	OFF	CLEAR	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:06.0	ON	ACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:06.0	OFF	CLEAR	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:06.0	ON	ACK	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:06.0	OFF	CLEAR	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		0	BDMh	CTSF00P3
09/09/10 16:25:06.0	ON	ACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		0	BDMh	CTSF00P3
09/09/10 16:25:06.0	OFF	CLEAR	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		0	BDMh	CTSF00P3
09/09/10 16:25:06.0	ON	ACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		0	BDMh	CTSF00P3
09/09/10 16:25:07.0	ON	ACK	Bethany_K_Timeout	Bethany_K RTU Failed		1	BDMh	CTSF00P3
09/09/10 16:25:07.0	ON	UNACK	Bethany_K_Timeout	Bethany_K RTU Failed		1		
09/09/10 16:25:07.0	OFF	CLEAR	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:07.0	ON	ACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:07.0	OFF	CLEAR	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:07.0	ON	ACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:07.0	OFF	CLEAR	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:07.0	ON	ACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:07.0	OFF	CLEAR	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		0	BDMh	CTSF00P3
09/09/10 16:25:07.0	ON	ACK	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		0	BDMh	CTSF00P3
09/09/10 16:25:08.0	OFF	CLEAR	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		0	BDMh	CTSF00P3
09/09/10 16:25:08.0	ON	ACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		0	BDMh	CTSF00P3
09/09/10 16:25:08.0	OFF	CLEAR	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:08.0	ON	ACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:25:22.0	OFF	CLEAR	HEARTBEAT0_11	SERVER DOWN	BRTGasScada2	0		
09/09/10 16:25:22.0	ON	ACK	HEARTBEAT0_11	SERVER DOWN	BRTGasScada2	0		
09/09/10 16:25:22.5	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 16:25:25.0	OFF	CLEAR	HEARTBEAT0_15	SERVER DOWN	SFGOGasSCADA2	0		
09/09/10 16:25:25.0	ON	ACK	HEARTBEAT0_15	SERVER DOWN	SFGOGasSCADA2	0		
09/09/10 16:25:26.0	OFF	CLEAR	HEARTBEAT0_14	SERVER DOWN	SFGOGasSCADA1	0		
09/09/10 16:25:26.0	ON	ACK	HEARTBEAT0_14	SERVER DOWN	SFGOGasSCADA1	0		
09/09/10 16:25:27.0	OFF	CLEAR	AGE_Y0003_BRT	Gerber-K Sta Ent		0	FHS2Admin	CTBRT0P6
09/09/10 16:25:28.0	OFF	CLEAR	HEARTBEAT0_10	SERVER DOWN	BRTGasScada1	0		
09/09/10 16:25:29.0	ON	ACK	HEARTBEAT0_10	SERVER DOWN	BRTGasScada1	0		
09/09/10 16:25:31.0	OFF	CLEAR	CAL_A_to_CAL_B_CommFail	CAL A to CAL B	Communication Failure	0		
09/09/10 16:25:31.0	ON	ACK	CAL_A_to_CAL_B_CommFail	CAL A to CAL B	Communication Failure	0		
09/09/10 16:25:35.0	OFF	CLEAR	AMPLA1HEARTBEAT	SfgoGasIIM1 Ampla Service Fail		0	FHS2Admin	CTBRT0P6
09/09/10 16:25:35.0	ON	ACK	AMPLA1HEARTBEAT	SfgoGasIIM1 Ampla Service Fail		0	FHS2Admin	CTBRT0P6
09/09/10 16:25:37.0	OFF	CLEAR	HEARTBEAT0_20	SERVER DOWN	SfgoGasIim2	0		
09/09/10 16:25:37.0	ON	ACK	HEARTBEAT0_20	SERVER DOWN	SfgoGasIim2	0		
09/09/10 16:25:38.0	OFF	CLEAR	HEARTBEAT0_8	SERVER DOWN	SANJOSEGasFEP1	0		
09/09/10 16:25:38.0	ON	ACK	HEARTBEAT0_8	SERVER DOWN	SANJOSEGasFEP1	0		
09/09/10 16:25:39.0	OFF	CLEAR	HEARTBEAT0_3	SERVER DOWN	CHICOGasFEP2	0		
09/09/10 16:25:39.0	ON	ACK	HEARTBEAT0_3	SERVER DOWN	CHICOGasFEP2	0		
09/09/10 16:25:41.0	OFF	CLEAR	HEARTBEAT0_7	SERVER DOWN	SactoGasFEP1	0		
09/09/10 16:25:41.0	ON	ACK	HEARTBEAT0_7	SERVER DOWN	SactoGasFEP1	0		
09/09/10 16:25:42.0	OFF	CLEAR	HEARTBEAT0_13	SERVER DOWN	EASTBAYGasFEP2	0		
09/09/10 16:25:42.0	ON	ACK	HEARTBEAT0_13	SERVER DOWN	EASTBAYGasFEP2	0		
09/09/10 16:25:43.0	OFF	CLEAR	HEARTBEAT0_5	SERVER DOWN	FRESNOGasFEP1	0		
09/09/10 16:25:44.0	ON	UNACK	Half_Moon_Bay_Timeout	Half_Moon_Bay RTU Failed		1		
09/09/10 16:25:44.0	OFF	CLEAR	HEARTBEAT0_0	SERVER DOWN	BrGasFEP1	0		
09/09/10 16:25:44.0	ON	ACK	HEARTBEAT0_0	SERVER DOWN	BrGasFEP1	0		
09/09/10 16:25:44.0	ON	ACK	HEARTBEAT0_5	SERVER DOWN	FRESNOGasFEP1	0		
09/09/10 16:25:46.0	OFF	CLEAR	M6A_PT0003_BRT	PLS-6A D/S PRESS	OFF			
09/09/10 16:25:46.0	HIGH	ACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 16:25:47.0	OFF	CLEAR	HEARTBEAT0_9	SERVER DOWN	SANJOSEGasFEP2	0		
09/09/10 16:25:47.0	ON	ACK	HEARTBEAT0_9	SERVER DOWN	SANJOSEGasFEP2	0		
09/09/10 16:25:49.0	OFF	CLEAR	HEARTBEAT0_12	SERVER DOWN	SactoGasFEP2	0		
09/09/10 16:25:49.0	ON	ACK	HEARTBEAT0_12	SERVER DOWN	SactoGasFEP2	0		
09/09/10 16:25:50.0	OFF	CLEAR	HEARTBEAT0_6	SERVER DOWN	FRESNOGasFEP2	0		
09/09/10 16:25:50.0	ON	ACK	HEARTBEAT0_6	SERVER DOWN	FRESNOGasFEP2	0		
09/09/10 16:25:52.0	OFF	CLEAR	HEARTBEAT0_4	SERVER DOWN	EASTBAYGasFEP1	0		
09/09/10 16:25:52.0	ON	ACK	HEARTBEAT0_4	SERVER DOWN	EASTBAYGasFEP1	0		
09/09/10 16:25:53.0	ON	UNACK	L132_Meter_Timeout	L132_Meter RTU Failed		1		
09/09/10 16:25:54.0	OFF	CLEAR	HEARTBEAT0_2	SERVER DOWN	CHICOGasFEP1	0		
09/09/10 16:25:54.0	ON	ACK	HEARTBEAT0_2	SERVER DOWN	CHICOGasFEP1	0		
09/09/10 16:25:55.0	OFF	CLEAR	HEARTBEAT0_1	SERVER DOWN	BrGasFEP2	0		
09/09/10 16:25:55.0	ON	ACK	HEARTBEAT0_1	SERVER DOWN	BrGasFEP2	0		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:25:57.0	OFF	CLEAR	HEARTBEAT0_19	SERVER DOWN	SfgoGasiim1	0		
09/09/10 16:25:57.0	ON	ACK	HEARTBEAT0_19	SERVER DOWN	SfgoGasiim1	0		
09/09/10 16:26:00.0	OFF	UNACK	Bethany_K_Timeout	Bethany_K RTU Failed		0		
09/09/10 16:26:01.0	OFF	CLEAR	Bethany_K_Timeout	Bethany_K RTU Failed		0		
09/09/10 16:26:01.0	OFF	ACK	Bethany_K_Timeout	Bethany_K RTU Failed		0		
09/09/10 16:26:03.0	ON	UNACK	Miramontes_Timeout	Miramontes RTU Failed		1		
09/09/10 16:26:17.9	LOW	UNACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	LOW			
09/09/10 16:26:31.0	OFF	ACK	L101_Meter_Timeout	L101_Meter RTU Failed		0		
09/09/10 16:26:33.0	OFF	CLEAR	L101_Meter_Timeout	L101_Meter RTU Failed		0		
09/09/10 16:26:37.0	OFF	CLEAR	L109_Meter_Timeout	L109_Meter RTU Failed		0		
09/09/10 16:26:37.0	OFF	ACK	L109_Meter_Timeout	L109_Meter RTU Failed		0		
09/09/10 16:26:47.7	LL	UNACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW LOW			
09/09/10 16:27:10.9	OFF	UNACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	LOW			
09/09/10 16:27:28.9	LOW	UNACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	LOW			
09/09/10 16:27:46.9	OFF	UNACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	LOW			
09/09/10 16:27:58.0	ON	ACK	Half_Moon_Bay_Timeout	Half_Moon_Bay RTU Failed		1		
09/09/10 16:27:58.0	ON	ACK	L132_Meter_Timeout	L132_Meter RTU Failed		1		
09/09/10 16:27:58.0	ON	ACK	Miramontes_Timeout	Miramontes RTU Failed		1		
09/09/10 16:27:58.0	LL	ACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW LOW			
09/09/10 16:27:59.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		MFV2	CTSF00P2
09/09/10 16:28:00.0	OFF	CLEAR	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	OFF		MFV2	CTSF00P2
09/09/10 16:28:00.0	LOW	ACK	KKN_FI0001_BRT	Kern-Rvr Pge To Socal Flow Rate	LOW		MFV2	CTSF00P2
09/09/10 16:28:01.0	OFF	CLEAR	Half_Moon_Bay_Timeout	Half_Moon_Bay RTU Failed		0		
09/09/10 16:28:01.0	OFF	ACK	Half_Moon_Bay_Timeout	Half_Moon_Bay RTU Failed		0		
09/09/10 16:28:11.0	OFF	CLEAR	L132_Meter_Timeout	L132_Meter RTU Failed		0		
09/09/10 16:28:11.0	OFF	ACK	L132_Meter_Timeout	L132_Meter RTU Failed		0		
09/09/10 16:28:19.0	OFF	CLEAR	Miramontes_Timeout	Miramontes RTU Failed		0		
09/09/10 16:28:19.0	OFF	ACK	Miramontes_Timeout	Miramontes RTU Failed		0		
09/09/10 16:28:56.2	ON	UNACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm		1		
09/09/10 16:30:12.4	OFF	UNACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm		0		
09/09/10 16:30:39.9	ON	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		1		
09/09/10 16:31:00.1	OFF	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		0		
09/09/10 16:31:09.1	ON	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		1		
09/09/10 16:31:21.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 16:31:31.9	OFF	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0		
09/09/10 16:31:40.0	OFF	CLEAR	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0	J1Gw	CTSF00P4
09/09/10 16:31:40.0	ON	ACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0	J1Gw	CTSF00P4
09/09/10 16:31:40.0	OFF	CLEAR	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		0	J1Gw	CTSF00P4
09/09/10 16:31:40.0	ON	ACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		0	J1Gw	CTSF00P4
09/09/10 16:31:41.0	OFF	CLEAR	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm		0	J1Gw	CTSF00P4
09/09/10 16:31:41.0	ON	ACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm		0	J1Gw	CTSF00P4
09/09/10 16:31:48.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	J1Gw	CTSF00P4
09/09/10 16:32:11.1	ON	UNACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm		1		
09/09/10 16:32:11.9	OFF	ACK	MMT_YS0005_BRT	Mil-Plt Operation Bldng Entry		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_YS0004_BRT	Mil-Plt Control Room Entry		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_YS0003_BRT	Mil-Plt Telecom & Vax Room		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_YS0002_BRT	Mil-Plt Shop Building Entry		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0021R_BRT	Mil-Ter V21R Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0038_BRT	Mil-Ter V38 Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0040_BRT	Mil-Ter V40 Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0010_BRT	Mil-Ter V10 Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0013_BRT	Mil-Ter V13 Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		1		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0071_ERROR_SF0	Mil-Ter Mon V71 Error		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0071_ERROR_BRT	Mil-Ter Mon V71 Error		0		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0071_0_BRT	Mil-Ter Mon V71 Not Open		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0071_ERROR_SF0	Mil-Ter Mon V71 Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0071_ERROR_BRT	Mil-Ter Mon V71 Error		1		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0070_ERROR_SF0	Mil-Ter Mon V70 Error		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0070_ERROR_BRT	Mil-Ter Mon V70 Error		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0070_0_BRT	Mil-Ter Mon V70 Not Open		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0070_ERROR_SF0	Mil-Ter Mon V70 Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0070_ERROR_BRT	Mil-Ter Mon V70 Error		1		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0067_ERROR_SF0	Mil-Ter Mon V67 Error		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0067_ERROR_BRT	Mil-Ter Mon V67 Error		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0067_0_BRT	Mil-Ter Mon V67 Not Open		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0067_ERROR_SF0	Mil-Ter Mon V67 Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0067_ERROR_BRT	Mil-Ter Mon V67 Error		1		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0066_ERROR_SF0	Mil-Ter Mon V66 Error		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0066_ERROR_BRT	Mil-Ter Mon V66 Error		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0066_0_BRT	Mil-Ter Mon V66 Not Open		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0066_ERROR_SF0	Mil-Ter Mon V66 Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0066_ERROR_BRT	Mil-Ter Mon V66 Error		1		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0063_0_BRT	Mil-Ter V63 Not Open		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0039_0_BRT	Mil-Ter V39 Not Open		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0037_0_BRT	Mil-Ter V37 Not Open		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0028_ERROR_SF0	Mil-Ter Mon V28 Error		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0028_ERROR_BRT	Mil-Ter Mon V28 Error		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0028_0_BRT	Mil-Ter Byp Mon V28 Not Open		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0028_ERROR_SF0	Mil-Ter Mon V28 Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0028_ERROR_BRT	Mil-Ter Mon V28 Error		1		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0026_ERROR_SF0	Mil-Ter Mon V26 Error		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0026_ERROR_BRT	Mil-Ter Mon V26 Error		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0026_0_BRT	Mil-Ter Mon V26 Not Open		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0026_ERROR_SF0	Mil-Ter Mon V26 Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0026_ERROR_BRT	Mil-Ter Mon V26 Error		1		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0020_ERROR_SF0	Mil-Ter Mon V20 Error		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0020_ERROR_BRT	Mil-Ter Mon V20 Error		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0020_0_BRT	Mil-Ter Mon V20 Not Open		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0020_ERROR_SF0	Mil-Ter Mon V20 Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0020_ERROR_BRT	Mil-Ter Mon V20 Error		1		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0016_ERROR_SF0	Mil-Ter Mon V16 Error		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0016_ERROR_BRT	Mil-Ter Mon V16 Error		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0016_0_BRT	Mil-Ter Mon V16 Not Open		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0016_ERROR_SF0	Mil-Ter Mon V16 Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0016_ERROR_BRT	Mil-Ter Mon V16 Error		1		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0006_ERROR_SF0	Mil-Ter Mon V6 Error		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0006_ERROR_BRT	Mil-Ter Mon V6 Error		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0006_0_BRT	Mil-Ter Mon V6 Not Open		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0006_ERROR_SF0	Mil-Ter Mon V6 Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0006_ERROR_BRT	Mil-Ter Mon V6 Error		1		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0005_ERROR_SF0	Mil-Ter Mon V5 Error		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0005_ERROR_BRT	Mil-Ter Mon V5 Error		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0005_0_BRT	Mil-Ter Mon V5 Not Open		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0005_ERROR_SF0	Mil-Ter Mon V5 Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0005_ERROR_BRT	Mil-Ter Mon V5 Error		1		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0004_ERROR_SF0	Mil-Ter Mon V4 Error		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0004_ERROR_BRT	Mil-Ter Mon V4 Error		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0004_0_BRT	Mil-Ter Mon V4 Not Open		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0004_ERROR_SF0	Mil-Ter Mon V4 Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0004_ERROR_BRT	Mil-Ter Mon V4 Error		1		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0003_ERROR_SF0	Mil-Ter Mon V3 Error		0		
09/09/10 16:32:11.9	OFF	UNACK	MMT_ZS0003_ERROR_BRT	Mil-Ter Mon V3 Error		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ZS0003_0_BRT	Mil-Ter Mon V3 Not Open		0		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0003_ERROR_SF0	Mil-Ter Mon V3 Error		1		
09/09/10 16:32:11.9	ON	UNACK	MMT_ZS0003_ERROR_BRT	Mil-Ter Mon V3 Error		1		
09/09/10 16:32:11.9	OFF	ACK	MMT_ES0105_BRT	Mil-Ter Air Comprsr 2 Shutdown		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_ES0104_BRT	Mil-Ter Air Comprsr 1 Shutdown		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_PS0002_BRT	Mil-Ter Air Tank 2 Press Lo Lo		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_PS0001_BRT	Mil-Ter Air Tank 1 Press Lo Lo		0		
09/09/10 16:32:11.9	OFF	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0		
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0001_BRT	Mil-Ter Instr Air Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_TT0001_BRT	MIL-PLT ATM TEMP	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0008_BRT	Mlpts-Ter L300B Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0034A_BRT	Mlpts-Ter M34 D/S Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0050_BRT	Mlpts-Ter Sjdfm V50 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0049_BRT	Mlpts-Ter L132 V49 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0048_BRT	Mlpts-Ter L101 V48 Pct Op	LOW			

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0045_BRT	Mlpts-Ter L109 V45 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0087_BRT	Mlpts-Ter L100 Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0084_BRT	Mlpts-Ter L101 Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0083_BRT	Mlpts-Ter L132 Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0063_BRT	Mlpts-Ter Mon V63 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0071_BRT	Mlpts-Ter L131 Mon V71 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0070_BRT	Mlpts-Ter L131 Mon V70 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0067_BRT	Mlpts-Ter L107 Mon V67 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0066_BRT	Mlpts-Ter L107 Mon V66 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0040_BRT	Mlpts-Ter L109 Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0009_BRT	Mlpts-Ter Sjdfrm Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0028_BRT	Mlpts-Ter Byp Mon V28 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0026_BRT	Mlpts-Ter Mixer Mon V26 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0016_BRT	Mlpts-Ter Mixer Mon V16 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0006_BRT	Mlpts-Ter M7 Mon V6 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0005_BRT	Mlpts-Ter M8 Mon V5 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0004_BRT	Mlpts-Ter M9 Mon V4 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_ZT0003_BRT	Mlpts-Ter M10 Mon V3 Pct Op	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0038A_BRT	Mlpts-Ter M38 D/S Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0032_BRT	Mlpts-Ter M32 D/S Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0031_BRT	Mlpts-Ter M31 D/S Press	LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0030_BRT	Mlpts-Ter M30 D/S Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0029B_BRT	Mlpts-Ter Mixer D/S Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0017_BRT	Mlpts-Ter Mixer D/S Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0007_BRT	Mlpts-Ter L107 Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0012_BRT	Mlpts-Ter L131 Press	LOW LOW			
09/09/10 16:32:12.9	OFF	ACK	MMT_PT0010_BRT	Mlpts-Ter L300A Press	LOW LOW			
09/09/10 16:32:13.9	OFF	ACK	MMT_PT0062_BRT	Mlpts-Ter Sta Bypass Press	LOW LOW			
09/09/10 16:32:16.2	ON	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm			1	
09/09/10 16:32:17.0	ON	UNACK	Sullivan_Ave_Timeout	Sullivan_Ave RTU Failed			1	
09/09/10 16:32:22.0	ON	ACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:22.0	ON	ACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:22.0	ON	ACK	Sullivan_Ave_Timeout	Sullivan_Ave RTU Failed			1 BDMh	CTSF00P3
09/09/10 16:32:23.0	ON	ACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:24.0	ON	ACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:24.0	ON	ACK	MMT_ES0013_BRT	Mil-Ter V13 Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:24.0	ON	ACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:25.0	ON	ACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:25.0	ON	ACK	MMT_ES0010_BRT	Mil-Ter V10 Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:25.0	ON	ACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:26.0	ON	ACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:26.0	ON	ACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm			1 BDMh	CTSF00P3
09/09/10 16:32:27.0	OFF	CLEAR	MMT_ZS0006_ERROR_SF0	Mil-Ter Mon V6 Error			0 J1Gw	CTSF00P4
09/09/10 16:32:27.0	OFF	CLEAR	MMT_ZS0006_ERROR_SF0	Mil-Ter Mon V6 Error			0 J1Gw	CTSF00P4
09/09/10 16:32:27.0	OFF	CLEAR	MMT_ZS0006_ERROR_BRT	Mil-Ter Mon V6 Error			0 J1Gw	CTSF00P4
09/09/10 16:32:27.0	ON	ACK	MMT_ZS0006_ERROR_BRT	Mil-Ter Mon V6 Error			0 J1Gw	CTSF00P4
09/09/10 16:32:27.0	ON	ACK	MMT_ES0038_BRT	Mil-Ter V38 Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:27.0	OFF	CLEAR	MMT_ZS0005_ERROR_BRT	Mil-Ter Mon V5 Error			0 J1Gw	CTSF00P4
09/09/10 16:32:27.0	ON	ACK	MMT_ZS0005_ERROR_BRT	Mil-Ter Mon V5 Error			0 J1Gw	CTSF00P4
09/09/10 16:32:27.0	ON	ACK	MMT_ES0040_BRT	Mil-Ter V40 Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:28.0	ON	ACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error			1	
09/09/10 16:32:28.0	OFF	CLEAR	MMT_ZS0020_ERROR_SF0	Mil-Ter Mon V20 Error			0	
09/09/10 16:32:28.0	ON	ACK	MMT_ZS0020_ERROR_SF0	Mil-Ter Mon V20 Error			0 J1Gw	CTSF00P4
09/09/10 16:32:28.0	ON	ACK	MMT_ES0021R_BRT	Mil-Ter V21R Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:28.0	OFF	CLEAR	MMT_ZS0016_ERROR_SF0	Mil-Ter Mon V16 Error			0 J1Gw	CTSF00P4
09/09/10 16:32:28.0	ON	ACK	MMT_ZS0016_ERROR_SF0	Mil-Ter Mon V16 Error			0 J1Gw	CTSF00P4
09/09/10 16:32:28.0	ON	ACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error			1 BDMh	CTSF00P3
09/09/10 16:32:29.0	OFF	CLEAR	MMT_ZS0066_ERROR_BRT	Mil-Ter Mon V66 Error			0	
09/09/10 16:32:29.0	ON	ACK	MMT_ZS0066_ERROR_BRT	Mil-Ter Mon V66 Error			0	
09/09/10 16:32:29.0	ON	ACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error			1	
09/09/10 16:32:29.0	OFF	CLEAR	MMT_ZS0028_ERROR_BRT	Mil-Ter Mon V28 Error			0	
09/09/10 16:32:29.0	ON	ACK	MMT_ZS0028_ERROR_BRT	Mil-Ter Mon V28 Error			0	
09/09/10 16:32:29.0	OFF	CLEAR	MMT_ZS0026_ERROR_SF0	Mil-Ter Mon V26 Error			0	
09/09/10 16:32:29.0	ON	ACK	MMT_ZS0026_ERROR_SF0	Mil-Ter Mon V26 Error			0	
09/09/10 16:32:30.0	OFF	CLEAR	MMT_ZS0067_ERROR_SF0	Mil-Ter Mon V67 Error			0	
09/09/10 16:32:30.0	ON	ACK	MMT_ZS0067_ERROR_SF0	Mil-Ter Mon V67 Error			0	
09/09/10 16:32:30.0	OFF	CLEAR	MMT_ZS0067_ERROR_BRT	Mil-Ter Mon V67 Error			0	
09/09/10 16:32:30.0	ON	ACK	MMT_ZS0067_ERROR_BRT	Mil-Ter Mon V67 Error			0	
09/09/10 16:32:30.0	OFF	CLEAR	MMT_ZS0066_ERROR_SF0	Mil-Ter Mon V66 Error			0	
09/09/10 16:32:30.0	ON	ACK	MMT_ZS0066_ERROR_SF0	Mil-Ter Mon V66 Error			0	
09/09/10 16:32:31.0	ON	ACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error			1	
09/09/10 16:32:31.0	OFF	CLEAR	MMT_ZS0071_ERROR_SF0	Mil-Ter Mon V71 Error			0	
09/09/10 16:32:31.0	ON	ACK	MMT_ZS0071_ERROR_SF0	Mil-Ter Mon V71 Error			0	

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:32:31.0	ON	ACK	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		1		
09/09/10 16:32:31.0	OFF	CLEAR	MMT_ZS0070_ERROR_BRT	Mil-Ter Mon V70 Error		0		
09/09/10 16:32:31.0	ON	ACK	MMT_ZS0070_ERROR_BRT	Mil-Ter Mon V70 Error		0		
09/09/10 16:32:31.0	ON	ACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error		1		
09/09/10 16:32:32.0	OFF	CLEAR	MMT_ZS0004_ERROR_SF0	Mil-Ter Mon V4 Error		0	J1Gw	CTSF00P4
09/09/10 16:32:32.0	ON	ACK	MMT_ZS0004_ERROR_SF0	Mil-Ter Mon V4 Error		0	J1Gw	CTSF00P4
09/09/10 16:32:32.0	ON	ACK	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		1	BDMh	CTSF00P3
09/09/10 16:32:32.0	OFF	CLEAR	MMT_ZS0026_ERROR_BRT	Mil-Ter Mon V26 Error		0	J1Gw	CTSF00P4
09/09/10 16:32:32.0	ON	ACK	MMT_ZS0026_ERROR_BRT	Mil-Ter Mon V26 Error		0	J1Gw	CTSF00P4
09/09/10 16:32:32.0	ON	ACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error		1	BDMh	CTSF00P3
09/09/10 16:32:32.0	OFF	CLEAR	MMT_ZS0028_ERROR_SF0	Mil-Ter Mon V28 Error		0	J1Gw	CTSF00P4
09/09/10 16:32:32.0	ON	ACK	MMT_ZS0028_ERROR_SF0	Mil-Ter Mon V28 Error		0	J1Gw	CTSF00P4
09/09/10 16:32:33.0	OFF	CLEAR	MMT_ZS0070_ERROR_SF0	Mil-Ter Mon V70 Error		0	J1Gw	CTSF00P4
09/09/10 16:32:33.0	ON	ACK	MMT_ZS0070_ERROR_SF0	Mil-Ter Mon V70 Error		0	J1Gw	CTSF00P4
09/09/10 16:32:33.0	ON	ACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm		1	BDMh	CTSF00P3
09/09/10 16:32:33.0	OFF	CLEAR	MMT_ZS0020_ERROR_BRT	Mil-Ter Mon V20 Error		0	J1Gw	CTSF00P4
09/09/10 16:32:33.0	ON	ACK	MMT_ZS0020_ERROR_BRT	Mil-Ter Mon V20 Error		0	J1Gw	CTSF00P4
09/09/10 16:32:33.0	ON	ACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		1	BDMh	CTSF00P3
09/09/10 16:32:33.0	ON	ACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		1	BDMh	CTSF00P3
09/09/10 16:32:33.0	OFF	CLEAR	MMT_ZS0016_ERROR_BRT	Mil-Ter Mon V16 Error		0	J1Gw	CTSF00P4
09/09/10 16:32:33.0	ON	ACK	MMT_ZS0016_ERROR_BRT	Mil-Ter Mon V16 Error		0	J1Gw	CTSF00P4
09/09/10 16:32:34.0	OFF	CLEAR	MMT_ZS0003_ERROR_SF0	Mil-Ter Mon V3 Error		0	BDMh	CTSF00P3
09/09/10 16:32:34.0	ON	ACK	MMT_ZS0003_ERROR_SF0	Mil-Ter Mon V3 Error		0	BDMh	CTSF00P3
09/09/10 16:32:34.0	OFF	CLEAR	MMT_ZS0003_ERROR_BRT	Mil-Ter Mon V3 Error		0	BDMh	CTSF00P3
09/09/10 16:32:34.0	ON	ACK	MMT_ZS0003_ERROR_BRT	Mil-Ter Mon V3 Error		0	BDMh	CTSF00P3
09/09/10 16:32:35.0	OFF	CLEAR	MMT_ZT0026_BRT	Mlpts-Ter Mixer Mon V26 Pct Op	OFF	J1Gw		CTSF00P4
09/09/10 16:32:35.0	OFF	CLEAR	MMT_ZS0071_ERROR_BRT	Mil-Ter Mon V71 Error		0	BDMh	CTSF00P3
09/09/10 16:32:35.0	ON	ACK	MMT_ZS0071_ERROR_BRT	Mil-Ter Mon V71 Error		0	BDMh	CTSF00P3
09/09/10 16:32:35.0	OFF	CLEAR	MMT_ZT0006_BRT	Mlpts-Ter M7 Mon V6 Pct Op	OFF	J1Gw		CTSF00P4
09/09/10 16:32:35.0	OFF	CLEAR	MMT_ZS0005_ERROR_SF0	Mil-Ter Mon V5 Error		0	BDMh	CTSF00P3
09/09/10 16:32:35.0	ON	ACK	MMT_ZS0005_ERROR_SF0	Mil-Ter Mon V5 Error		0	BDMh	CTSF00P3
09/09/10 16:32:35.0	OFF	CLEAR	MMT_PT0032_BRT	Mlpts-Ter M32 D/S Press	OFF	J1Gw		CTSF00P4
09/09/10 16:32:35.0	OFF	CLEAR	MMT_ZS0004_ERROR_BRT	Mil-Ter Mon V4 Error		0	BDMh	CTSF00P3
09/09/10 16:32:35.0	ON	ACK	MMT_ZS0004_ERROR_BRT	Mil-Ter Mon V4 Error		0	BDMh	CTSF00P3
09/09/10 16:32:36.0	OFF	CLEAR	MMT_PT0012_BRT	Mlpts-Ter L131 Press	OFF	J1Gw		CTSF00P4
09/09/10 16:32:36.0	OFF	CLEAR	MMT_PT0062_BRT	Mlpts-Ter Sta Bypass Press	OFF	BDMh		CTSF00P3
09/09/10 16:32:36.0	OFF	CLEAR	MMT_PT0030_BRT	Mlpts-Ter M30 D/S Press	OFF	J1Gw		CTSF00P4
09/09/10 16:32:36.0	OFF	CLEAR	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0	BDMh	CTSF00P3
09/09/10 16:32:36.0	OFF	CLEAR	MMT_ZT0005_BRT	Mlpts-Ter M8 Mon V5 Pct Op	OFF	J1Gw		CTSF00P4
09/09/10 16:32:37.0	OFF	CLEAR	MMT_PT0007_BRT	Mlpts-Ter L107 Press	OFF	BDMh		CTSF00P3
09/09/10 16:32:37.0	OFF	CLEAR	MMT_PT0010_BRT	Mlpts-Ter L300A Press	OFF	BDMh		CTSF00P3
09/09/10 16:32:38.0	OFF	CLEAR	MMT_PT0031_BRT	Mlpts-Ter M31 D/S Press	OFF	BDMh		CTSF00P3
09/09/10 16:32:38.0	OFF	CLEAR	MMT_ZT0071_BRT	Mlpts-Ter L131 Mon V71 Pct Op	OFF	J1Gw		CTSF00P4
09/09/10 16:32:38.0	OFF	CLEAR	MMT_PT0029B_BRT	Mlpts-Ter Mixer D/S Press	OFF	BDMh		CTSF00P3
09/09/10 16:32:38.0	OFF	CLEAR	MMT_YS0003_BRT	Mil-Plt Telecom & Vax Room		0	J1Gw	CTSF00P4
09/09/10 16:32:38.0	OFF	CLEAR	MMT_PT0017_BRT	Mlpts-Ter Mixer D/S Press	OFF	BDMh		CTSF00P3
09/09/10 16:32:39.0	OFF	ACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0		
09/09/10 16:32:39.0	OFF	CLEAR	MMT_ZT0003_BRT	Mlpts-Ter M10 Mon V3 Pct Op	OFF	BDMh		CTSF00P3
09/09/10 16:32:39.0	OFF	CLEAR	MMT_YS0005_BRT	Mil-Plt Operation Bldng Entry		0	J1Gw	CTSF00P4
09/09/10 16:32:39.0	OFF	CLEAR	MMT_PT0038A_BRT	Mlpts-Ter M38 D/S Press	OFF	BDMh		CTSF00P3
09/09/10 16:32:40.0	OFF	CLEAR	MMT_ES0105_BRT	Mil-Ter Air Comprsr 2 Shutdown		0	J1Gw	CTSF00P4
09/09/10 16:32:40.0	OFF	CLEAR	MMT_ZT0016_BRT	Mlpts-Ter Mixer Mon V16 Pct Op	OFF	BDMh		CTSF00P3
09/09/10 16:32:40.0	OFF	CLEAR	MMT_PT0087_BRT	Mlpts-Ter L100 Press	OFF	J1Gw		CTSF00P4
09/09/10 16:32:40.0	OFF	CLEAR	MMT_ZT0004_BRT	Mlpts-Ter M9 Mon V4 Pct Op	OFF	BDMh		CTSF00P3
09/09/10 16:32:40.0	OFF	CLEAR	MMT_PT0008_BRT	Mlpts-Ter L300B Press	OFF	J1Gw		CTSF00P4
09/09/10 16:32:41.0	OFF	CLEAR	MMT_PT0009_BRT	Mlpts-Ter Sjdfrm Press	OFF	BDMh		CTSF00P3
09/09/10 16:32:41.0	OFF	CLEAR	MMT_PS0001_BRT	Mil-Ter Air Tank 1 Press Lo Lo		0	J1Gw	CTSF00P4
09/09/10 16:32:41.0	OFF	CLEAR	MMT_ZS0004_O_BRT	Mil-Ter Mon V4 Not Open		0	J1Gw	CTSF00P4
09/09/10 16:32:41.0	OFF	CLEAR	MMT_ZT0028_BRT	Mlpts-Ter Byp Mon V28 Pct Op	OFF	BDMh		CTSF00P3
09/09/10 16:32:41.0	OFF	CLEAR	MMT_ES0104_BRT	Mil-Ter Air Comprsr 1 Shutdown		0	J1Gw	CTSF00P4
09/09/10 16:32:42.0	OFF	CLEAR	MMT_ZS0026_O_BRT	Mil-Ter Mon V26 Not Open		0	J1Gw	CTSF00P4
09/09/10 16:32:42.0	OFF	CLEAR	MMT_ZS0020_O_BRT	Mil-Ter Mon V20 Not Open		0	J1Gw	CTSF00P4
09/09/10 16:32:42.0	OFF	CLEAR	MMT_ZT0066_BRT	Mlpts-Ter L107 Mon V66 Pct Op	OFF	BDMh		CTSF00P3
09/09/10 16:32:42.0	OFF	CLEAR	MMT_ZS0006_O_BRT	Mil-Ter Mon V6 Not Open		0	J1Gw	CTSF00P4
09/09/10 16:32:42.0	OFF	CLEAR	MMT_PT0040_BRT	Mlpts-Ter L109 Press	OFF	BDMh		CTSF00P3
09/09/10 16:32:42.0	OFF	CLEAR	MMT_ZS0003_O_BRT	Mil-Ter Mon V3 Not Open		0	J1Gw	CTSF00P4
09/09/10 16:32:43.0	OFF	CLEAR	MMT_ZS0028_O_BRT	Mil-Ter Byp Mon V28 Not Open		0	J1Gw	CTSF00P4
09/09/10 16:32:44.0	OFF	CLEAR	MMT_ZS0039_O_BRT	Mil-Ter V39 Not Open		0	J1Gw	CTSF00P4
09/09/10 16:32:44.0	OFF	CLEAR	MMT_ZS0037_O_BRT	Mil-Ter V37 Not Open		0	J1Gw	CTSF00P4
09/09/10 16:32:44.0	OFF	CLEAR	MMT_ZS0016_O_BRT	Mil-Ter Mon V16 Not Open		0	J1Gw	CTSF00P4
09/09/10 16:32:45.0	OFF	CLEAR	MMT_ZT0067_BRT	Mlpts-Ter L107 Mon V67 Pct Op	OFF	BDMh		CTSF00P3
09/09/10 16:32:45.0	OFF	CLEAR	MMT_ZS0067_O_BRT	Mil-Ter Mon V67 Not Open		0	J1Gw	CTSF00P4
09/09/10 16:32:45.0	OFF	CLEAR	MMT_ZT0063_BRT	Mlpts-Ter Mon V63 Pct Op	OFF	BDMh		CTSF00P3

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:32:45.0	OFF	CLEAR	MMT_ZT0070_BRT	Mlpts-Ter L131 Mon V70 Pct Op	OFF		BDMh	CTSF00P3
09/09/10 16:32:45.0	OFF	CLEAR	MMT_ZS0063_O_BRT	Mil-Ter V63 Not Open		0	J1Gw	CTSF00P4
09/09/10 16:32:46.0	OFF	CLEAR	MMT_PT0083_BRT	Mlpts-Ter L132 Press	OFF		BDMh	CTSF00P3
09/09/10 16:32:46.0	OFF	CLEAR	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0	BDMh	CTSF00P3
09/09/10 16:32:47.0	OFF	CLEAR	MMT_ZT0049_BRT	Mlpts-Ter L132 V49 Pct Op	OFF		BDMh	CTSF00P3
09/09/10 16:32:47.0	OFF	CLEAR	MMT_ZT0048_BRT	Mlpts-Ter L101 V48 Pct Op	OFF		BDMh	CTSF00P3
09/09/10 16:32:47.0	OFF	CLEAR	MMT_ZT0045_BRT	Mlpts-Ter L109 V45 Pct Op	OFF		BDMh	CTSF00P3
09/09/10 16:32:47.0	OFF	CLEAR	MMT_PT0084_BRT	Mlpts-Ter L101 Press	OFF		BDMh	CTSF00P3
09/09/10 16:32:48.0	OFF	CLEAR	MMT_ZT0050_BRT	Mlpts-Ter Sjdfrm V50 Pct Op	OFF		BDMh	CTSF00P3
09/09/10 16:32:48.0	OFF	CLEAR	MMT_ZT0049_BRT	Mlpts-Ter L132 V49 Pct Op	OFF			
09/09/10 16:32:48.8	OFF	ACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm		0		
09/09/10 16:32:49.0	OFF	CLEAR	MMT_PT0001_BRT	Mil-Ter Instr Air Press	OFF		BDMh	CTSF00P3
09/09/10 16:32:49.0	OFF	CLEAR	MMT_TT0001_BRT	MIL-PLT ATM TEMP	OFF		J1Gw	CTSF00P4
09/09/10 16:32:49.0	OFF	CLEAR	MMT_PT0034A_BRT	Mlpts-Ter M34 D/S Press	OFF		BDMh	CTSF00P3
09/09/10 16:32:49.0	OFF	CLEAR	MMT_ZT0050_BRT	Mlpts-Ter Sjdfrm V50 Pct Op	OFF		J1Gw	CTSF00P4
09/09/10 16:32:50.0	OFF	CLEAR	MMT_PS0002_BRT	Mil-Ter Air Tank 2 Press Lo Lo		0	BDMh	CTSF00P3
09/09/10 16:32:50.0	OFF	CLEAR	MMT_YS0004_BRT	Mil-Plt Control Room Entry		0	J1Gw	CTSF00P4
09/09/10 16:32:50.0	OFF	CLEAR	MMT_YS0002_BRT	Mil-Plt Shop Building Entry		0	J1Gw	CTSF00P4
09/09/10 16:32:50.0	OFF	CLEAR	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0	BDMh	CTSF00P3
09/09/10 16:32:51.0	OFF	CLEAR	MMT_ZS0066_O_BRT	Mil-Ter Mon V66 Not Open		0	BDMh	CTSF00P3
09/09/10 16:32:51.0	OFF	CLEAR	MMT_ZS0005_O_BRT	Mil-Ter Mon V5 Not Open		0	BDMh	CTSF00P3
09/09/10 16:32:51.0	OFF	CLEAR	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm		0	BDMh	CTSF00P3
09/09/10 16:32:52.0	OFF	CLEAR	MMT_ZS0071_O_BRT	Mil-Ter Mon V71 Not Open		0	BDMh	CTSF00P3
09/09/10 16:32:52.0	OFF	CLEAR	MMT_ZS0070_O_BRT	Mil-Ter Mon V70 Not Open		0	BDMh	CTSF00P3
09/09/10 16:32:56.8	OFF	ACK	MMT_HS0062C_BRT	Mil-Ter V62 Controller Con/Loc		0		
09/09/10 16:32:56.8	OFF	ACK	MMT_HS0062A_BRT	Mil-Ter V62 Controller Aut/Man		0		
09/09/10 16:33:02.0	OFF	CLEAR	MMT_HS0062C_BRT	Mil-Ter V62 Controller Con/Loc		0	MFV2	CTSF00P2
09/09/10 16:33:02.0	OFF	CLEAR	MMT_HS0062A_BRT	Mil-Ter V62 Controller Aut/Man		0	MFV2	CTSF00P2
09/09/10 16:33:05.0	OFF	ACK	MMT_FI0903_AA_BRT	Mlpts-Ter Penin Tot Flow Calculated	LOW LOW	8.4		
09/09/10 16:33:09.0	OFF	CLEAR	MMT_FI0903_AA_BRT	Mlpts-Ter Penin Tot Flow Calculated	OFF	8.4	J1Gw	CTSF00P4
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0021R_BRT	Mil-Ter V21R Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_HS0038C_BRT	Mil-Ter V38 Controller Con/Loc		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_HS0038A_BRT	Mil-Ter V38 Controller Aut/Man		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0038_BRT	Mil-Ter V38 Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_HS0040C_BRT	Mil-Ter V40 Controller Con/Loc		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_HS0040A_BRT	Mil-Ter V40 Controller Aut/Man		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0040_BRT	Mil-Ter V40 Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0010_BRT	Mil-Ter V10 Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0013_BRT	Mil-Ter V13 Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		0		
09/09/10 16:33:42.1	OFF	ACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		0		
09/09/10 16:33:45.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 16:33:45.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 16:33:47.0	OFF	CLEAR	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:48.0	OFF	CLEAR	MMT_ES0014_BRT	Mil-Ter V14 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:48.0	OFF	CLEAR	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:48.0	OFF	CLEAR	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:49.0	OFF	CLEAR	MMT_ES0012_BRT	Mil-Ter V12 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:49.0	OFF	CLEAR	MMT_ES0013_BRT	Mil-Ter V13 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:50.0	OFF	CLEAR	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:50.0	OFF	CLEAR	MMT_ES0010_BRT	Mil-Ter V10 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:50.0	OFF	CLEAR	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:51.0	OFF	CLEAR	MMT_ES0040_BRT	Mil-Ter V40 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:51.0	OFF	CLEAR	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:52.0	OFF	CLEAR	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:52.0	OFF	CLEAR	MMT_ES0038_BRT	Mil-Ter V38 Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:53.0	OFF	CLEAR	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		0	J1Gw	CTSF00P4

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:33:53.0	OFF	CLEAR	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:53.0	OFF	CLEAR	MMT_ES0021R_BRT	Mil-Ter V21R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:54.0	OFF	CLEAR	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:54.0	OFF	CLEAR	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:54.0	OFF	CLEAR	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:54.0	OFF	CLEAR	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:55.0	OFF	CLEAR	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:56.0	OFF	CLEAR	MMT_HS0040C_BRT	Mil-Ter V40 Controller Con/Loc		0	J1Gw	CTSF00P4
09/09/10 16:33:56.0	OFF	CLEAR	MMT_HS0040A_BRT	Mil-Ter V40 Controller Aut/Man		0	J1Gw	CTSF00P4
09/09/10 16:33:56.0	OFF	CLEAR	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:56.0	OFF	CLEAR	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		0	J1Gw	CTSF00P4
09/09/10 16:33:58.0	OFF	CLEAR	MMT_HS0038C_BRT	Mil-Ter V38 Controller Con/Loc		0	J1Gw	CTSF00P4
09/09/10 16:33:58.0	OFF	CLEAR	MMT_HS0038A_BRT	Mil-Ter V38 Controller Aut/Man		0	J1Gw	CTSF00P4
09/09/10 16:34:05.0	OFF	ACK	MMT_FI0904_AA_BRT	Mlpts-Ter Pen+Sjo Tot Flow Calculated	LOW LOW	10.1		
09/09/10 16:34:05.0	OFF	ACK	MMT_FI0901_AA_BRT	Mlpts-Ter Stn Tot Flow In Calculated	LOW LOW	10.1		
09/09/10 16:34:09.0	OFF	CLEAR	MMT_FI0904_AA_BRT	Mlpts-Ter Pen+Sjo Tot Flow Calculated	OFF	10.1	J1Gw	CTSF00P4
09/09/10 16:34:09.0	OFF	CLEAR	MMT_FI0901_AA_BRT	Mlpts-Ter Stn Tot Flow In Calculated	OFF	10.1	J1Gw	CTSF00P4
09/09/10 16:34:17.8	ON	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		1		
09/09/10 16:34:27.5	OFF	ACK	MMT_HS00C_BRT	Mil-Ter V27R Controller Con/Loc		0		
09/09/10 16:34:27.5	OFF	ACK	MMT_HS00A_BRT	Mil-Ter V27R Controller Aut/Man		0		
09/09/10 16:34:27.5	OFF	ACK	MMT_HS0021C_BRT	Mil-Ter V21 Controller Con/Loc		0		
09/09/10 16:34:27.5	OFF	ACK	MMT_HS0021A_BRT	Mil-Ter V21 Controller Aut/Man		0		
09/09/10 16:34:27.5	OFF	ACK	MMT_HS0027C_BRT	Mil-Ter V27 Controller Con/Loc		0		
09/09/10 16:34:27.5	OFF	ACK	MMT_HS0027A_BRT	Mil-Ter V27 Controller Aut/Man		0		
09/09/10 16:34:31.0	OFF	CLEAR	MMT_HS0027A_BRT	Mil-Ter V27 Controller Aut/Man		0		
09/09/10 16:34:32.0	OFF	CLEAR	MMT_HS0021A_BRT	Mil-Ter V21 Controller Aut/Man		0		
09/09/10 16:34:32.0	OFF	CLEAR	MMT_HS0027C_BRT	Mil-Ter V27 Controller Con/Loc		0		
09/09/10 16:34:33.0	OFF	CLEAR	Sullivan_Ave_Timeout	Sullivan_Ave RTU Failed		0		
09/09/10 16:34:33.0	OFF	ACK	Sullivan_Ave_Timeout	Sullivan_Ave RTU Failed		0		
09/09/10 16:34:33.0	OFF	CLEAR	MMT_HS00A_BRT	Mil-Ter V27R Controller Aut/Man		0		
09/09/10 16:34:33.0	OFF	CLEAR	MMT_HS0021C_BRT	Mil-Ter V21 Controller Con/Loc		0		
09/09/10 16:34:34.0	OFF	CLEAR	MMT_HS00C_BRT	Mil-Ter V27R Controller Con/Loc		0	J1Gw	CTSF00P4
09/09/10 16:34:35.0	ON	ACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		1	J1Gw	CTSF00P4
09/09/10 16:35:03.4	OFF	ACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0		
09/09/10 16:35:11.9	OFF	ACK	MMT_HS0029C_BRT	Mil-Ter V29 Controller Con/Loc		0		
09/09/10 16:35:11.9	OFF	ACK	MMT_HS0029A_BRT	Mil-Ter V29 Controller Aut/Man		0		
09/09/10 16:35:11.9	OFF	ACK	MMT_HS0017RC_BRT	Mil-Ter V17R Controller Con/Loc		0		
09/09/10 16:35:11.9	OFF	ACK	MMT_HS0017RA_BRT	Mil-Ter V17R Controller Aut/Man		0		
09/09/10 16:35:11.9	OFF	ACK	MMT_HS0021RC_BRT	Mil-Ter V21R Controller Con/Loc		0		
09/09/10 16:35:11.9	OFF	ACK	MMT_HS0021RA_BRT	Mil-Ter V21R Controller Aut/Man		0		
09/09/10 16:35:11.9	OFF	ACK	MMT_HS0014C_BRT	Mil-Ter V14 Controller Con/Loc		0		
09/09/10 16:35:11.9	OFF	ACK	MMT_HS0014A_BRT	Mil-Ter V14 Controller Aut/Man		0		
09/09/10 16:35:11.9	OFF	ACK	MMT_HS0017C_BRT	Mil-Ter V17 Controller Con/Loc		0		
09/09/10 16:35:11.9	OFF	ACK	MMT_HS0017A_BRT	Mil-Ter V17 Controller Aut/Man		0		
09/09/10 16:35:20.0	OFF	CLEAR	MMT_HS0017A_BRT	Mil-Ter V17 Controller Aut/Man		0	J1Gw	CTSF00P4
09/09/10 16:35:20.0	OFF	CLEAR	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0	J1Gw	CTSF00P4
09/09/10 16:35:21.0	OFF	CLEAR	MMT_HS0014A_BRT	Mil-Ter V14 Controller Aut/Man		0	J1Gw	CTSF00P4
09/09/10 16:35:21.0	OFF	CLEAR	MMT_HS0017C_BRT	Mil-Ter V17 Controller Con/Loc		0		
09/09/10 16:35:22.0	OFF	CLEAR	MMT_HS0021RA_BRT	Mil-Ter V21R Controller Aut/Man		0	J1Gw	CTSF00P4
09/09/10 16:35:22.0	OFF	CLEAR	MMT_HS0014C_BRT	Mil-Ter V14 Controller Con/Loc		0	J1Gw	CTSF00P4
09/09/10 16:35:23.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	J1Gw	CTSF00P4
09/09/10 16:35:23.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 16:35:23.0	OFF	CLEAR	MMT_HS0021RC_BRT	Mil-Ter V21R Controller Con/Loc		0	J1Gw	CTSF00P4
09/09/10 16:35:24.0	OFF	CLEAR	MMT_HS0017RA_BRT	Mil-Ter V17R Controller Aut/Man		0		
09/09/10 16:35:25.0	OFF	CLEAR	MMT_HS0017RC_BRT	Mil-Ter V17R Controller Con/Loc		0		
09/09/10 16:35:27.2	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 16:35:30.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF			
09/09/10 16:35:31.0	OFF	CLEAR	MMT_HS0029A_BRT	Mil-Ter V29 Controller Aut/Man		0		
09/09/10 16:35:32.0	OFF	CLEAR	MMT_HS0029C_BRT	Mil-Ter V29 Controller Con/Loc		0		
09/09/10 16:35:57.1	OFF	ACK	MMT_HS0013RC_BRT	Mil-Ter V13R Controller Con/Loc		0		
09/09/10 16:35:57.1	OFF	ACK	MMT_HS0013RA_BRT	Mil-Ter V13R Controller Aut/Man		0		
09/09/10 16:35:57.1	OFF	ACK	MMT_HS0014RC_BRT	Mil-Ter V14R Controller Con/Loc		0		
09/09/10 16:35:57.1	OFF	ACK	MMT_HS0014RA_BRT	Mil-Ter V14R Controller Aut/Man		0		
09/09/10 16:35:57.1	OFF	ACK	MMT_HS0012C_BRT	Mil-Ter V12 Controller Con/Loc		0		
09/09/10 16:35:57.1	OFF	ACK	MMT_HS0012A_BRT	Mil-Ter V12 Controller Aut/Man		0		
09/09/10 16:35:57.1	OFF	ACK	MMT_HS0013C_BRT	Mil-Ter V13 Controller Con/Loc		0		
09/09/10 16:35:57.1	OFF	ACK	MMT_HS0013A_BRT	Mil-Ter V13 Controller Aut/Man		0		
09/09/10 16:36:09.0	OFF	CLEAR	MMT_HS0012A_BRT	Mil-Ter V12 Controller Aut/Man		0	J1Gw	CTSF00P4
09/09/10 16:36:09.0	OFF	CLEAR	MMT_HS0013C_BRT	Mil-Ter V13 Controller Con/Loc		0	J1Gw	CTSF00P4
09/09/10 16:36:09.0	OFF	CLEAR	MMT_HS0013A_BRT	Mil-Ter V13 Controller Aut/Man		0	J1Gw	CTSF00P4
09/09/10 16:36:10.0	OFF	CLEAR	MMT_HS0012C_BRT	Mil-Ter V12 Controller Con/Loc		0	J1Gw	CTSF00P4
09/09/10 16:36:11.0	OFF	CLEAR	MMT_HS0013RA_BRT	Mil-Ter V13R Controller Aut/Man		0	J1Gw	CTSF00P4
09/09/10 16:36:11.0	OFF	CLEAR	MMT_HS0014RC_BRT	Mil-Ter V14R Controller Con/Loc		0	J1Gw	CTSF00P4

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:36:11.0	OFF	CLEAR	MMT_HS0014RA_BRT	Mil-Ter V14R Controller Aut/Man		0	J1Gw	CTSF00P4
09/09/10 16:36:12.0	OFF	CLEAR	MMT_HS0013RC_BRT	Mil-Ter V13R Controller Con/Loc		0	J1Gw	CTSF00P4
09/09/10 16:36:42.3	OFF	ACK	MMT_HS0007RC_BRT	Mil-Ter V7R Controller Con/Loc		0		
09/09/10 16:36:42.3	OFF	ACK	MMT_HS0007RA_BRT	Mil-Ter V7R Controller Aut/Man		0		
09/09/10 16:36:42.3	OFF	ACK	MMT_HS0011RC_BRT	Mil-Ter V11R Controller Con/Loc		0		
09/09/10 16:36:42.3	OFF	ACK	MMT_HS0011RA_BRT	Mil-Ter V11R Controller Aut/Man		0		
09/09/10 16:36:42.3	OFF	ACK	MMT_HS0012RC_BRT	Mil-Ter V12R Controller Con/Loc		0		
09/09/10 16:36:42.3	OFF	ACK	MMT_HS0012RA_BRT	Mil-Ter V12R Controller Aut/Man		0		
09/09/10 16:36:42.3	OFF	ACK	MMT_HS0007C_BRT	Mil-Ter V7 Controller Con/Loc		0		
09/09/10 16:36:42.3	OFF	ACK	MMT_HS0007A_BRT	Mil-Ter V7 Controller Aut/Man		0		
09/09/10 16:36:42.3	OFF	ACK	MMT_HS0008C_BRT	Mil-Ter V8 Controller Con/Loc		0		
09/09/10 16:36:42.3	OFF	ACK	MMT_HS0008A_BRT	Mil-Ter V8 Controller Aut/Man		0		
09/09/10 16:36:42.3	OFF	ACK	MMT_HS0011C_BRT	Mil-Ter V11 Controller Con/Loc		0		
09/09/10 16:36:42.3	OFF	ACK	MMT_HS0011A_BRT	Mil-Ter V11 Controller Aut/Man		0		
09/09/10 16:36:57.0	OFF	CLEAR	MMT_HS0011C_BRT	Mil-Ter V11 Controller Con/Loc		0	BDMh	CTSF00P3
09/09/10 16:36:57.0	OFF	CLEAR	MMT_HS0011A_BRT	Mil-Ter V11 Controller Aut/Man		0	BDMh	CTSF00P3
09/09/10 16:36:58.0	OFF	CLEAR	MMT_HS0008C_BRT	Mil-Ter V8 Controller Con/Loc		0	BDMh	CTSF00P3
09/09/10 16:36:58.0	OFF	CLEAR	MMT_HS0008A_BRT	Mil-Ter V8 Controller Aut/Man		0	BDMh	CTSF00P3
09/09/10 16:36:59.0	OFF	CLEAR	MMT_HS0007C_BRT	Mil-Ter V7 Controller Con/Loc		0	BDMh	CTSF00P3
09/09/10 16:36:59.0	OFF	CLEAR	MMT_HS0007A_BRT	Mil-Ter V7 Controller Aut/Man		0	BDMh	CTSF00P3
09/09/10 16:37:00.0	OFF	CLEAR	MMT_HS0011RC_BRT	Mil-Ter V11R Controller Con/Loc		0	BDMh	CTSF00P3
09/09/10 16:37:00.0	OFF	CLEAR	MMT_HS0011RA_BRT	Mil-Ter V11R Controller Aut/Man		0	BDMh	CTSF00P3
09/09/10 16:37:01.0	OFF	CLEAR	MMT_HS0007RC_BRT	Mil-Ter V7R Controller Con/Loc		0	BDMh	CTSF00P3
09/09/10 16:37:01.0	OFF	CLEAR	MMT_HS0007RA_BRT	Mil-Ter V7R Controller Aut/Man		0	BDMh	CTSF00P3
09/09/10 16:37:22.0	OFF	CLEAR	MMT_HS0012RC_BRT	Mil-Ter V12R Controller Con/Loc		0		
09/09/10 16:37:22.0	OFF	CLEAR	MMT_HS0012RA_BRT	Mil-Ter V12R Controller Aut/Man		0	BDMh	CTSF00P3
09/09/10 16:37:27.2	OFF	ACK	MMT_HS0008RC_BRT	Mil-Ter V8R Controller Con/Loc		0		
09/09/10 16:37:27.2	OFF	ACK	MMT_HS0008RA_BRT	Mil-Ter V8R Controller Aut/Man		0		
09/09/10 16:37:27.2	OFF	ACK	MMT_HS0009RC_BRT	Mil-Ter V9R Controller Con/Loc		0		
09/09/10 16:37:27.2	OFF	ACK	MMT_HS0009RA_BRT	Mil-Ter V9R Controller Aut/Man		0		
09/09/10 16:37:27.2	OFF	ACK	MMT_HS0010RC_BRT	Mil-Ter V10R Controller Con/Loc		0		
09/09/10 16:37:27.2	OFF	ACK	MMT_HS0010RA_BRT	Mil-Ter V10R Controller Aut/Man		0		
09/09/10 16:37:27.2	OFF	ACK	MMT_HS0009C_BRT	Mil-Ter V9 Controller Con/Loc		0		
09/09/10 16:37:27.2	OFF	ACK	MMT_HS0009A_BRT	Mil-Ter V9 Controller Aut/Man		0		
09/09/10 16:37:27.2	OFF	ACK	MMT_HS0010C_BRT	Mil-Ter V10 Controller Con/Loc		0		
09/09/10 16:37:27.2	OFF	ACK	MMT_HS0010A_BRT	Mil-Ter V10 Controller Aut/Man		0		
09/09/10 16:37:28.9	ON	UNACK	ALI_Y00004_BRT	Lodi-Field Building Entry Alarm		1		
09/09/10 16:37:41.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 16:37:41.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 16:37:42.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 16:38:21.0	OFF	CLEAR	MMT_HS0010C_BRT	Mil-Ter V10 Controller Con/Loc		0	MFV2	CTSF00P2
09/09/10 16:38:21.0	OFF	CLEAR	MMT_HS0010A_BRT	Mil-Ter V10 Controller Aut/Man		0	MFV2	CTSF00P2
09/09/10 16:38:21.0	ON	ACK	ALI_Y00004_BRT	Lodi-Field Building Entry Alarm		1	MFV2	CTSF00P2
09/09/10 16:38:22.0	OFF	CLEAR	MMT_HS0009C_BRT	Mil-Ter V9 Controller Con/Loc		0	MFV2	CTSF00P2
09/09/10 16:38:22.0	OFF	CLEAR	MMT_HS0009A_BRT	Mil-Ter V9 Controller Aut/Man		0	MFV2	CTSF00P2
09/09/10 16:38:23.0	OFF	CLEAR	MMT_HS0009RA_BRT	Mil-Ter V9R Controller Aut/Man		0	MFV2	CTSF00P2
09/09/10 16:38:23.0	OFF	CLEAR	MMT_HS0010RC_BRT	Mil-Ter V10R Controller Con/Loc		0	MFV2	CTSF00P2
09/09/10 16:38:23.0	OFF	CLEAR	MMT_HS0010RA_BRT	Mil-Ter V10R Controller Aut/Man		0	MFV2	CTSF00P2
09/09/10 16:38:24.0	OFF	CLEAR	MMT_HS0008RA_BRT	Mil-Ter V8R Controller Aut/Man		0	MFV2	CTSF00P2
09/09/10 16:38:24.0	OFF	CLEAR	MMT_HS0009RC_BRT	Mil-Ter V9R Controller Con/Loc		0	MFV2	CTSF00P2
09/09/10 16:38:25.0	OFF	CLEAR	MMT_HS0008RC_BRT	Mil-Ter V8R Controller Con/Loc		0	MFV2	CTSF00P2
09/09/10 16:38:44.2	OFF	ACK	ALI_Y00004_BRT	Lodi-Field Building Entry Alarm		0		
09/09/10 16:38:56.0	OFF	CLEAR	ALI_Y00004_BRT	Lodi-Field Building Entry Alarm		0	BDMh	CTSF00P3
09/09/10 16:40:10.7	ON	UNACK	ALI_Y00004_BRT	Lodi-Field Building Entry Alarm		1		
09/09/10 16:40:47.8	OFF	UNACK	ALI_Y00004_BRT	Lodi-Field Building Entry Alarm		0		
09/09/10 16:41:30.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 16:43:47.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 16:44:16.0	OFF	CLEAR	ALI_Y00004_BRT	Lodi-Field Building Entry Alarm		0	BDMh	CTSF00P3
09/09/10 16:44:16.0	ON	ACK	ALI_Y00004_BRT	Lodi-Field Building Entry Alarm		0	BDMh	CTSF00P3
09/09/10 16:44:16.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	BDMh	CTSF00P3
09/09/10 16:44:16.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	BDMh	CTSF00P3
09/09/10 16:44:41.3	ON	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		1		
09/09/10 16:45:05.0	OFF	UNACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0		
09/09/10 16:45:12.0	OFF	CLEAR	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0	MFV2	CTSF00P2
09/09/10 16:45:12.0	ON	ACK	BTY_ES0002_BRT	Tracy-Sta Gate Alm		0	MFV2	CTSF00P2
09/09/10 16:45:54.0		System	Status	Citect USA - 2009/10/22 - C14 - 9/8/2010 09:00:00			System	CTSF0Admin4
09/09/10 16:45:54.0		System	Login	ODN\wahbAdmin			System	CTSF0Admin4
09/09/10 16:47:42.0		System	Status	User Shutdown			mwh7admin	CTSF0Admin3
09/09/10 16:47:43.0	OFF	CLEAR	SRR_ES9997_BRT	Rtr-Rd RTU Battery Charger Fail		0	FHS2Admin	CTBRTOP6
09/09/10 16:48:07.0	OFF	CLEAR	SSA_FT0001B_OOR	Sac-Glc 20 Inch L108 Hi Orf Dp Out of Range		0	FHS2Admin	CTBRTOP6
09/09/10 16:48:07.0	ON	ACK	SSA_FT0001B_OOR	Sac-Glc 20 Inch L108 Hi Orf Dp Out of Range		0	FHS2Admin	CTBRTOP6
09/09/10 16:48:15.0		System	Status	User Shutdown			FHS2Admin	CTBRTOP6
09/09/10 16:50:57.3	ON	UNACK	MMT_Y00006_BRT	Mil-Plt Front Gate Status		1		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 16:51:42.2	OFF	UNACK	MMT_Y0006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 16:51:53.0		System	Status	User Shutdown		1	JxF2Admin	CTSF00Admin1
09/09/10 16:51:55.0	OFF	CLEAR	MMT_Y0006_BRT	Mil-Plt Front Gate Status		0	J1Gw	CTSF00P4
09/09/10 16:51:55.0	ON	ACK	MMT_Y0006_BRT	Mil-Plt Front Gate Status		0	J1Gw	CTSF00P4
09/09/10 16:52:04.6	ON	UNACK	ASQ_HS0001_BRT	Shingl-401 L401 Control Auto/Man		1		
09/09/10 16:52:35.0	ON	ACK	ASQ_HS0001_BRT	Shingl-401 L401 Control Auto/Man		1	J1Gw	CTSF00P4
09/09/10 16:52:46.0	ON	UNACK	BMD_Y0004_RUNNG_BRT	Mcdnld-Is K4 Compressor Status -Runng		1		
09/09/10 16:52:50.0	OFF	ACK	BMD_Y0004_RUNNG_BRT	Mcdnld-Is K4 Compressor Status -Runng		0		
09/09/10 16:52:50.0	ON	ACK	BMD_Y0004_RUNNG_BRT	Mcdnld-Is K4 Compressor Status -Runng		1		
09/09/10 16:52:50.0	OFF	CLEAR	BMD_Y0004_RUNNG_BRT	Mcdnld-Is K4 Compressor Status -Runng		0	J1Gw	CTSF00P4
09/09/10 16:52:50.0	ON	ACK	BMD_Y0004_RUNNG_BRT	Mcdnld-Is K4 Compressor Status -Runng		0	J1Gw	CTSF00P4
09/09/10 16:52:50.0	OFF	UNACK	BMD_Y0004_RUNNG_BRT	Mcdnld-Is K4 Compressor Status -Runng		0		
09/09/10 16:54:11.0	ON	UNACK	Dublin_DFM_Timeout	Dublin_DFM RTU Failed		1		
09/09/10 16:54:13.0	ON	UNACK	Fowler_Nees_Timeout	Fowler_Nees RTU Failed		1		
09/09/10 16:55:47.0	ON	ACK	Fowler_Nees_Timeout	Fowler_Nees RTU Failed		1	BDMh	CTSF00P3
09/09/10 16:55:48.0	ON	ACK	Dublin_DFM_Timeout	Dublin_DFM RTU Failed		1	BDMh	CTSF00P3
09/09/10 16:56:27.0	OFF	ACK	Fowler_Nees_Timeout	Fowler_Nees RTU Failed		0		
09/09/10 16:56:29.0	OFF	CLEAR	Fowler_Nees_Timeout	Fowler_Nees RTU Failed		0		
09/09/10 16:56:45.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 16:57:11.0	ON	UNACK	Orinda_Timeout	Orinda RTU Failed		1		
09/09/10 16:59:04.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 16:59:19.0	ON	ACK	Orinda_Timeout	Orinda RTU Failed		1		
09/09/10 16:59:19.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 16:59:19.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	J1Gw	CTSF00P4
09/09/10 16:59:20.7	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 16:59:20.7	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 16:59:26.0	OFF	CLEAR	Orinda_Timeout	Orinda RTU Failed		0		
09/09/10 16:59:26.0	OFF	ACK	Orinda_Timeout	Orinda RTU Failed		0		
09/09/10 16:59:38.5	OFF	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 16:59:38.5	OFF	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 16:59:45.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF		MFV2	CTSF00P2
09/09/10 16:59:45.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH		MFV2	CTSF00P2
09/09/10 16:59:46.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF		MFV2	CTSF00P2
09/09/10 16:59:46.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH		MFV2	CTSF00P2
09/09/10 16:59:56.5	OFF	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW LOW			
09/09/10 17:01:22.0	OFF	CLEAR	Dublin_DFM_Timeout	Dublin_DFM RTU Failed		0		
09/09/10 17:01:22.0	OFF	ACK	Dublin_DFM_Timeout	Dublin_DFM RTU Failed		0		
09/09/10 17:01:26.3	ON	UNACK	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		1		
09/09/10 17:01:26.3	ON	UNACK	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		1		
09/09/10 17:01:26.3	ON	UNACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		1		
09/09/10 17:01:26.3	ON	UNACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error		1		
09/09/10 17:01:26.3	ON	UNACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		1		
09/09/10 17:01:26.3	ON	UNACK	MMT_ES0038_BRT	Mil-Ter V38 Controller Error		1		
09/09/10 17:01:26.3	ON	UNACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		1		
09/09/10 17:01:26.3	ON	UNACK	MMT_ES0010_BRT	Mil-Ter V10 Controller Error		1		
09/09/10 17:01:26.3	ON	UNACK	MMT_ES0013_BRT	Mil-Ter V13 Controller Error		1		
09/09/10 17:01:26.3	ON	UNACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		1		
09/09/10 17:01:26.3	ON	UNACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		1		
09/09/10 17:01:42.0	ON	ACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		1	MFV2	CTSF00P2
09/09/10 17:01:42.0	ON	ACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		1	MFV2	CTSF00P2
09/09/10 17:01:43.0	ON	ACK	MMT_ES0013_BRT	Mil-Ter V13 Controller Error		1	MFV2	CTSF00P2
09/09/10 17:01:43.0	ON	ACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		1	MFV2	CTSF00P2
09/09/10 17:01:43.0	ON	ACK	MMT_ES0010_BRT	Mil-Ter V10 Controller Error		1	MFV2	CTSF00P2
09/09/10 17:01:44.0	ON	ACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		1	MFV2	CTSF00P2
09/09/10 17:01:44.0	ON	ACK	MMT_ES0038_BRT	Mil-Ter V38 Controller Error		1	MFV2	CTSF00P2
09/09/10 17:01:45.0	ON	ACK	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		1	MFV2	CTSF00P2
09/09/10 17:01:45.0	ON	ACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		1	MFV2	CTSF00P2
09/09/10 17:01:45.0	ON	ACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error		1	MFV2	CTSF00P2
09/09/10 17:01:46.0	OFF	CLEAR	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	OFF		MFV2	CTSF00P2
09/09/10 17:01:46.0	ON	ACK	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		1	MFV2	CTSF00P2
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		1		
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error		1		
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		1		
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error		1		
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		1		
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error		1		
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0021R_BRT	Mil-Ter V21R Controller Error		1		
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0040_BRT	Mil-Ter V40 Controller Error		1		
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0008_BRT	Mil-Ter V8 Controller Error		1		
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		1		
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		1		
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error		1		
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error		1		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 17:02:11.4	ON	UNACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error			1	
09/09/10 17:02:24.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			1	
09/09/10 17:03:41.4	OFF	UNACK	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error			0	
09/09/10 17:03:41.4	OFF	UNACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error			0	
09/09/10 17:03:41.4	OFF	ACK	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error			0	
09/09/10 17:03:41.4	OFF	UNACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error			0	
09/09/10 17:03:41.4	OFF	ACK	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error			0	
09/09/10 17:03:41.4	OFF	UNACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error			0	
09/09/10 17:03:41.4	OFF	ACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error			0	
09/09/10 17:03:41.4	OFF	ACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error			0	
09/09/10 17:03:41.4	OFF	ACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error			0	
09/09/10 17:03:41.4	OFF	ACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error			0	
09/09/10 17:03:41.4	OFF	UNACK	MMT_ES0008_BRT	Mil-Ter V8 Controller Error			0	
09/09/10 17:03:41.4	OFF	UNACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error			0	
09/09/10 17:03:41.4	OFF	ACK	MMT_ES0010_BRT	Mil-Ter V10 Controller Error			0	
09/09/10 17:03:41.4	OFF	UNACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error			0	
09/09/10 17:03:41.4	OFF	ACK	MMT_ES0013_BRT	Mil-Ter V13 Controller Error			0	
09/09/10 17:03:41.4	OFF	UNACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error			0	
09/09/10 17:03:41.4	OFF	ACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error			0	
09/09/10 17:03:41.4	OFF	UNACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error			0	
09/09/10 17:03:41.4	OFF	ACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error			0	
09/09/10 17:03:42.0	ON	UNACK	LRCV_71B_Timeout	LRCV_71B RTU Failed			1	
09/09/10 17:04:26.6	OFF	UNACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error			0	
09/09/10 17:04:26.6	OFF	UNACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error			0	
09/09/10 17:04:26.6	OFF	UNACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error			0	
09/09/10 17:04:46.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0	
09/09/10 17:05:51.4	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:05:58.0	OFF	UNACK	LRCV_71B_Timeout	LRCV_71B RTU Failed			0	
09/09/10 17:06:11.2	OFF	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:06:51.9	ON	UNACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			1	
09/09/10 17:07:32.5	OFF	UNACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0	
09/09/10 17:08:54.6	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:09:09.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:09:10.0	ON	ACK	MMT_ES0021R_BRT	Mil-Ter V21R Controller Error			BDMh	CTSF00P3
09/09/10 17:09:10.0	ON	ACK	MMT_ES0040_BRT	Mil-Ter V40 Controller Error			1 BDMh	CTSF00P3
09/09/10 17:09:11.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0 BDMh	CTSF00P3
09/09/10 17:09:11.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0 BDMh	CTSF00P3
09/09/10 17:09:11.0	OFF	CLEAR	LRCV_71B_Timeout	LRCV_71B RTU Failed			0 BDMh	CTSF00P3
09/09/10 17:09:11.0	ON	ACK	LRCV_71B_Timeout	LRCV_71B RTU Failed			0 BDMh	CTSF00P3
09/09/10 17:09:11.0	OFF	CLEAR	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0 BDMh	CTSF00P3
09/09/10 17:09:11.0	ON	ACK	ALI_YS0004_BRT	Lodi-Field Building Entry Alarm			0 BDMh	CTSF00P3
09/09/10 17:09:12.0	OFF	CLEAR	MMT_ES0021_BRT	Mil-Ter V21 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:12.0	ON	ACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:13.0	OFF	CLEAR	MMT_ES0009_BRT	Mil-Ter V9 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:13.0	ON	ACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:13.0	OFF	CLEAR	MMT_ES0011_BRT	Mil-Ter V11 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:13.0	ON	ACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:13.0	OFF	CLEAR	MMT_ES0014_BRT	Mil-Ter V14 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:13.0	ON	ACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:14.0	OFF	CLEAR	MMT_ES0008_BRT	Mil-Ter V8 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:14.0	ON	ACK	MMT_ES0008_BRT	Mil-Ter V8 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:14.0	OFF	CLEAR	MMT_ES0009_BRT	Mil-Ter V9 Controller Error			0	
09/09/10 17:09:15.0	OFF	CLEAR	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:15.0	ON	ACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:15.0	OFF	CLEAR	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:15.0	ON	ACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:16.0	OFF	CLEAR	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:16.0	ON	ACK	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:16.0	OFF	CLEAR	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:16.0	ON	ACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:17.0	OFF	CLEAR	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:17.0	ON	ACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:17.0	OFF	CLEAR	MMT_ES0012_BRT	Mil-Ter V12 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:17.0	ON	ACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:18.0	OFF	CLEAR	MMT_ES0027_BRT	Mil-Ter V27 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:18.0	OFF	CLEAR	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:18.0	ON	ACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:19.0	OFF	CLEAR	MMT_ES0010_BRT	Mil-Ter V10 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:19.0	OFF	CLEAR	MMT_ES0013_BRT	Mil-Ter V13 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:19.0	OFF	CLEAR	MMT_ES0017_BRT	Mil-Ter V17 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:20.0	OFF	CLEAR	MMT_ES0062_BRT	Mil-Ter V62 Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:21.0	OFF	CLEAR	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error			0 BDMh	CTSF00P3
09/09/10 17:09:21.0	OFF	CLEAR	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error			0 BDMh	CTSF00P3

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 17:09:22.0	OFF	CLEAR	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		0	BDMh	CTSF00P3
09/09/10 17:09:22.0	OFF	CLEAR	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		0	BDMh	CTSF00P3
09/09/10 17:09:22.0	OFF	CLEAR	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		0	BDMh	CTSF00P3
09/09/10 17:09:35.5	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:10:13.0	ON	UNACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm			1	
09/09/10 17:10:15.3	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:10:27.3	ON	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai			1	
09/09/10 17:10:34.9	OFF	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:10:51.6	OFF	UNACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm			0	
09/09/10 17:11:31.6	ON	UNACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm			1	
09/09/10 17:11:39.0	ON	ACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm			1	BDMh CTSF00P3
09/09/10 17:11:40.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		BDMh	CTSF00P3
09/09/10 17:11:40.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		BDMh	CTSF00P3
09/09/10 17:11:40.0	ON	ACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai			1	BDMh CTSF00P3
09/09/10 17:11:55.1	OFF	ACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai			0	
09/09/10 17:12:15.4	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:12:35.3	OFF	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:12:49.5	OFF	ACK	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm			0	
09/09/10 17:12:55.2	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:13:14.9	OFF	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:13:34.5	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:13:54.2	OFF	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:14:24.5	OFF	ACK	OC2_Y0025_BRT	Alstn-Wy L105 Pres Data Old			0	
09/09/10 17:15:53.4	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:16:33.9	OFF	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:16:54.0	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:17:33.3	OFF	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:17:58.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		BDMh	CTSF00P3
09/09/10 17:17:58.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		BDMh	CTSF00P3
09/09/10 17:17:59.0	OFF	CLEAR	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai			0	BDMh CTSF00P3
09/09/10 17:17:59.0	OFF	CLEAR	ALI_Y0004_BRT	Lodi-Field Building Entry Alarm			0	BDMh CTSF00P3
09/09/10 17:18:00.0	OFF	CLEAR	OC2_Y0025_BRT	Alstn-Wy L105 Pres Data Old			0	BDMh CTSF00P3
09/09/10 17:19:20.9	OFF	ACK	ASQ_HS0001_BRT	Shingl-401 L401 Control Auto/Man			0	
09/09/10 17:19:46.0	OFF	CLEAR	ASQ_HS0001_BRT	Shingl-401 L401 Control Auto/Man			0	MFV2 CTSF00P2
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_FA0014R_BRT	Mil-Ter M14 Backflow Alarm			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0071_0_BRT	Mil-Ter Mon V71 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0070_0_BRT	Mil-Ter Mon V70 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0067_0_BRT	Mil-Ter Mon V67 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0066_0_BRT	Mil-Ter Mon V66 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0063_0_BRT	Mil-Ter V63 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0039_0_BRT	Mil-Ter V39 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0037_0_BRT	Mil-Ter V37 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0028_0_BRT	Mil-Ter Byp Mon V28 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0026_0_BRT	Mil-Ter Mon V26 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0020_0_BRT	Mil-Ter Mon V20 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0016_0_BRT	Mil-Ter Mon V16 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0006_0_BRT	Mil-Ter Mon V6 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0005_0_BRT	Mil-Ter Mon V5 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0004_0_BRT	Mil-Ter Mon V4 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_ZS0003_0_BRT	Mil-Ter Mon V3 Not Open			1	
09/09/10 17:21:41.9	ON	UNACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo			1	
09/09/10 17:21:42.9	LOW	UNACK	MMT_PT0010BR_BRT	Mil-Ter Uic 10R U/S Pres	LOW			
09/09/10 17:21:42.9	LOW	UNACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW			
09/09/10 17:21:42.9	ON	UNACK	MMT_PT0021D_00R	Mil-Ter V21R D/S Pres Out of Range			1	
09/09/10 17:21:43.3	ON	UNACK	MMT_PT0008_00R	Mlpts-Ter L300B Press Out of Range			1	

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 17:21:43.3	ON	UNACK	MMT_LT0001B_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_LT0001A_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_PT0087_OOR	Mlpts-Ter L100 Press Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_PT0040_OOR	Mlpts-Ter L109 Press Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_PT0009_OOR	Mlpts-Ter Sjdfm Press Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_PT0017_OOR	Mlpts-Ter Mixer D/S Press Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_PT0007_OOR	Mlpts-Ter L107 Press Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_PT0012_OOR	Mlpts-Ter L131 Press Out of Range		1		
09/09/10 17:21:43.3	ON	UNACK	MMT_PT0010_OOR	Mlpts-Ter L300A Press Out of Range		1		
09/09/10 17:21:44.3	ON	UNACK	MMT_PT0062_OOR	Mlpts-Ter Sta Bypass Press Out of Range		1		
09/09/10 17:22:06.0	ON	ACK	MMT_PT0010_OOR	Mlpts-Ter L300A Press Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:06.0	ON	ACK	MMT_PT0062_OOR	Mlpts-Ter Sta Bypass Press Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:07.0	ON	ACK	MMT_PT0007_OOR	Mlpts-Ter L107 Press Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:07.0	ON	ACK	MMT_PT0012_OOR	Mlpts-Ter L131 Press Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:08.0	ON	ACK	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:08.0	ON	ACK	MMT_PT0017_OOR	Mlpts-Ter Mixer D/S Press Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:09.0	ON	ACK	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:09.0	ON	ACK	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:10.0	ON	ACK	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:10.0	ON	ACK	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:10.0	ON	ACK	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:11.0	ON	ACK	MMT_PT0009_OOR	Mlpts-Ter Sjdfm Press Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:12.0	ON	ACK	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:12.0	ON	ACK	MMT_PT0040_OOR	Mlpts-Ter L109 Press Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:13.0	ON	ACK	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:13.0	ON	ACK	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:13.0	ON	ACK	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:14.0	ON	ACK	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:15.0	ON	ACK	MMT_LT0001B_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:15.0	ON	ACK	MMT_LT0001A_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:15.0	ON	ACK	MMT_PT0087_OOR	Mlpts-Ter L100 Press Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:16.0	ON	ACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:16.0	ON	ACK	MMT_PT0008_OOR	Mlpts-Ter L300B Press Out of Range		1 MFV2		CTSF00P2
09/09/10 17:22:17.0	LOW	ACK	MMT_PT0010BR_BRT	Mil-Ter Uic 10R U/S Pres	LOW	MFV2		CTSF00P2
09/09/10 17:22:17.0	LOW	ACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW	MFV2		CTSF00P2
09/09/10 17:22:18.0	ON	ACK	MMT_ZS0003_O_BRT	Mil-Ter Mon V3 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:18.0	ON	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1 MFV2		CTSF00P2
09/09/10 17:22:19.0	ON	ACK	MMT_ZS0005_O_BRT	Mil-Ter Mon V5 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:19.0	ON	ACK	MMT_ZS0004_O_BRT	Mil-Ter Mon V4 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:20.0	ON	ACK	MMT_ZS0016_O_BRT	Mil-Ter Mon V16 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:20.0	ON	ACK	MMT_ZS0006_O_BRT	Mil-Ter Mon V6 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:21.0	ON	ACK	MMT_ZS0028_O_BRT	Mil-Ter Byp Mon V28 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:21.0	ON	ACK	MMT_ZS0026_O_BRT	Mil-Ter Mon V26 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:21.0	ON	ACK	MMT_ZS0020_O_BRT	Mil-Ter Mon V20 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:22.0	ON	ACK	MMT_ZS0037_O_BRT	Mil-Ter V37 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:23.0	ON	ACK	MMT_ZS0063_O_BRT	Mil-Ter V63 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:23.0	ON	ACK	MMT_ZS0039_O_BRT	Mil-Ter V39 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:24.0	ON	ACK	MMT_ZS0067_O_BRT	Mil-Ter Mon V67 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:24.0	ON	ACK	MMT_ZS0066_O_BRT	Mil-Ter Mon V66 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:25.0	ON	ACK	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		1 MFV2		CTSF00P2
09/09/10 17:22:25.0	ON	ACK	MMT_ZS0071_O_BRT	Mil-Ter Mon V71 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:25.0	ON	ACK	MMT_ZS0070_O_BRT	Mil-Ter Mon V70 Not Open		1 MFV2		CTSF00P2
09/09/10 17:22:26.0	ON	ACK	MMT_FA0014R_BRT	Mil-Ter M14 Backflow Alarm		1		
09/09/10 17:22:26.9	OFF	UNACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		0		
09/09/10 17:22:26.9	OFF	UNACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		0		
09/09/10 17:22:26.9	OFF	UNACK	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error		0		
09/09/10 17:22:26.9	OFF	UNACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		0		
09/09/10 17:22:26.9	OFF	UNACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error		0		
09/09/10 17:22:26.9	OFF	UNACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		0		
09/09/10 17:22:26.9	OFF	UNACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error		0		
09/09/10 17:22:26.9	OFF	UNACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		0		
09/09/10 17:22:26.9	OFF	UNACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error		0		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 17:22:26.9	OFF	UNACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		0		
09/09/10 17:22:26.9	OFF	UNACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		0		
09/09/10 17:22:26.9	OFF	ACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		0		
09/09/10 17:22:26.9	OFF	ACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		0		
09/09/10 17:22:26.9	OFF	ACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error		0		
09/09/10 17:22:26.9	OFF	ACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error		0		
09/09/10 17:22:26.9	OFF	ACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		0		
09/09/10 17:22:26.9	OFF	ACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		0		
09/09/10 17:22:26.9	OFF	ACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		0		
09/09/10 17:22:26.9	OFF	ACK	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		0		
09/09/10 17:22:26.9	ON	UNACK	MMT_FA0008R_BRT	Mil-Ter M8 Backflow Alarm		1		
09/09/10 17:22:26.9	ON	UNACK	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm		1		
09/09/10 17:22:27.0	ON	ACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		1		
09/09/10 17:22:27.0	ON	ACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		1		
09/09/10 17:22:27.0	ON	ACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		1		
09/09/10 17:22:28.0	ON	ACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		1 MFV2		CTSF00P2
09/09/10 17:22:28.0	ON	ACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error		1 MFV2		CTSF00P2
09/09/10 17:22:28.0	ON	ACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error		1 MFV2		CTSF00P2
09/09/10 17:22:28.2	HIGH	UNACK	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	HIGH			
09/09/10 17:22:28.2	HIGH	UNACK	MMT_FT0012_BRT	Mil-Ter M12 Diff Pressure	HIGH			
09/09/10 17:22:29.0	ON	ACK	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm		1 MFV2		CTSF00P2
09/09/10 17:22:29.0	ON	ACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:29.0	ON	ACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		1 MFV2		CTSF00P2
09/09/10 17:22:30.0	OFF	CLEAR	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		0 MFV2		CTSF00P2
09/09/10 17:22:30.0	ON	ACK	MMT_FA0008R_BRT	Mil-Ter M8 Backflow Alarm		1 MFV2		CTSF00P2
09/09/10 17:22:31.0	HIGH	ACK	MMT_FT0012_BRT	Mil-Ter M12 Diff Pressure	HIGH	MFV2		CTSF00P2
09/09/10 17:22:31.0	OFF	CLEAR	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:31.0	OFF	CLEAR	MMT_FT0012_BRT	Mil-Ter M12 Diff Pressure	HIGH			
09/09/10 17:22:31.0	OFF	CLEAR	MMT_FT0012_BRT	Mil-Ter M12 Diff Pressure	OFF	MFV2		CTSF00P2
09/09/10 17:22:32.0	OFF	CLEAR	MMT_ES0014_BRT	Mil-Ter V14 Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:32.0	OFF	CLEAR	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:32.0	OFF	CLEAR	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:33.0	OFF	CLEAR	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:33.0	OFF	CLEAR	MMT_ES0012_BRT	Mil-Ter V12 Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:34.0	HIGH	ACK	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	HIGH	MFV2		CTSF00P2
09/09/10 17:22:34.0	OFF	CLEAR	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:34.0	ON	ACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:34.0	OFF	CLEAR	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:34.0	ON	ACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:34.0	OFF	CLEAR	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	OFF	MFV2		CTSF00P2
09/09/10 17:22:35.0	OFF	CLEAR	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:35.0	ON	ACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:35.0	OFF	CLEAR	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:35.0	ON	ACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:36.0	OFF	CLEAR	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:36.0	ON	ACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:36.0	OFF	CLEAR	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:36.0	ON	ACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:37.0	OFF	CLEAR	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:37.0	OFF	CLEAR	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:37.0	ON	ACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:38.0	OFF	CLEAR	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:38.0	ON	ACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:38.0	OFF	CLEAR	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:38.0	ON	ACK	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:38.0	OFF	CLEAR	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:22:38.0	ON	ACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		0 MFV2		CTSF00P2
09/09/10 17:23:02.4	HIGH	UNACK	MLE_PT0001_BRT	Los-Esteros Tot Flow Meter Press	HIGH			
09/09/10 17:23:11.8	ON	UNACK	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		1		
09/09/10 17:23:12.9	HH	UNACK	MMT_PT0038A_BRT	Mlpts-Ter M38 D/S Press	HIGH HIGH			
09/09/10 17:23:12.9	HH	UNACK	MMT_PT0032_BRT	Mlpts-Ter M32 D/S Press	HIGH HIGH			
09/09/10 17:23:12.9	HH	UNACK	MMT_PT0031_BRT	Mlpts-Ter M31 D/S Press	HIGH HIGH			
09/09/10 17:23:14.0	HIGH	ACK	MLE_PT0001_BRT	Los-Esteros Tot Flow Meter Press	HIGH	MFV2		CTSF00P2
09/09/10 17:23:15.0	HH	ACK	MMT_PT0032_BRT	Mlpts-Ter M32 D/S Press	HIGH HIGH	MFV2		CTSF00P2
09/09/10 17:23:15.0	HH	ACK	MMT_PT0031_BRT	Mlpts-Ter M31 D/S Press	HIGH HIGH	MFV2		CTSF00P2
09/09/10 17:23:16.0	ON	ACK	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		1 MFV2		CTSF00P2
09/09/10 17:23:16.0	HH	ACK	MMT_PT0038A_BRT	Mlpts-Ter M38 D/S Press	HIGH HIGH	MFV2		CTSF00P2
09/09/10 17:23:27.3	HH	UNACK	MLE_PT0001_BRT	Los-Esteros Tot Flow Meter Press	HIGH HIGH			
09/09/10 17:23:58.9	OFF	UNACK	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	HIGH			
09/09/10 17:23:58.9	OFF	ACK	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	HIGH			
09/09/10 17:24:04.0	LL	UNACK	MMT_FI0901_AA_BRT	Mlpts-Ter Stn Tot Flow In Calculated	LOW LOW	0.4		
09/09/10 17:24:13.0	HIGH	UNACK	M7A_PT0100_BRT	SILVER CREEK L100 PRESS	HIGH			
09/09/10 17:24:21.0	HH	ACK	MLE_PT0001_BRT	Los-Esteros Tot Flow Meter Press	HIGH HIGH	MFV2		CTSF00P2

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 17:24:21.0	LL	ACK	MMT_FI0901_AA_BRT	Mlpts-Ter Stn Tot Flow In Calculated	LOW LOW	0.4	MFV2	CTSF00P2
09/09/10 17:24:21.0	HIGH	ACK	M7A_PT0100_BRT	SILVER CREEK L100 PRESS	HIGH		MFV2	CTSF00P2
09/09/10 17:24:22.0	OFF	CLEAR	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	OFF			
09/09/10 17:24:32.9	HH	UNACK	M7A_PT0100_BRT	SILVER CREEK L100 PRESS	HIGH HIGH			
09/09/10 17:24:34.5	HIGH	UNACK	JAW_PT0001_BRT	Aborn & White L100 Press	HIGH			
09/09/10 17:24:35.6	HIGH	UNACK	JTL_PT0004_BRT	Tully Rd Inlet Pressure	HIGH			
09/09/10 17:24:35.6	HIGH	UNACK	JTL_PT0001_BRT	Tully Rd L100 Pressure	HIGH			
09/09/10 17:24:43.2	HIGH	UNACK	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	HIGH			
09/09/10 17:24:50.5	HIGH	UNACK	JNR_PT0002_BRT	N-Rngstrf L101 D-S Press	HIGH			
09/09/10 17:24:54.4	HH	UNACK	JAW_PT0001_BRT	Aborn & White L100 Press	HIGH HIGH			
09/09/10 17:24:56.0	HH	UNACK	JTL_PT0001_BRT	Tully Rd L100 Pressure	HIGH HIGH			
09/09/10 17:24:57.0	HIGH	ACK	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	HIGH		J1Gw	CTSF00P4
09/09/10 17:24:58.0	HIGH	ACK	JAW_PT0001_BRT	Aborn & White L100 Press	HIGH		J1Gw	CTSF00P4
09/09/10 17:24:58.0	HIGH	ACK	JTL_PT0004_BRT	Tully Rd Inlet Pressure	HIGH		J1Gw	CTSF00P4
09/09/10 17:24:58.6	HIGH	UNACK	MIR_FI0003_AA_BRT	IRVING-STA M-3 FLOW	HIGH			
09/09/10 17:24:59.0	HH	ACK	M7A_PT0100_BRT	SILVER CREEK L100 PRESS	HIGH HIGH		J1Gw	CTSF00P4
09/09/10 17:24:59.0	HIGH	ACK	JTL_PT0001_BRT	Tully Rd L100 Pressure	HIGH		J1Gw	CTSF00P4
09/09/10 17:25:13.3	HH	UNACK	JNR_PT0002_BRT	N-Rngstrf L101 D-S Press	HIGH HIGH			
09/09/10 17:25:22.3	HIGH	UNACK	JSI_PT0004_BRT	Sr-Vst-X L109 Press	HIGH			
09/09/10 17:25:23.0	HH	ACK	JTL_PT0001_BRT	Tully Rd L100 Pressure	HIGH HIGH		J1Gw	CTSF00P4
09/09/10 17:25:23.0	HIGH	ACK	MIR_FI0003_AA_BRT	IRVING-STA M-3 FLOW	HIGH		J1Gw	CTSF00P4
09/09/10 17:25:24.0	HH	ACK	JAW_PT0001_BRT	Aborn & White L100 Press	HIGH HIGH		J1Gw	CTSF00P4
09/09/10 17:25:24.0	HH	ACK	JNR_PT0002_BRT	N-Rngstrf L101 D-S Press	HIGH HIGH		J1Gw	CTSF00P4
09/09/10 17:25:27.2	OFF	ACK	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm		0		
09/09/10 17:25:27.2	OFF	ACK	MMT_FA0008R_BRT	Mil-Ter M8 Backflow Alarm		0		
09/09/10 17:25:27.2	OFF	UNACK	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm		0		
09/09/10 17:25:28.3	OFF	ACK	MMT_FT0012_BRT	Mil-Ter M12 Diff Pressure	HIGH			
09/09/10 17:25:28.3	OFF	ACK	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	HIGH			
09/09/10 17:25:28.3	OFF	UNACK	MMT_FT0012_BRT	Mil-Ter M12 Diff Pressure	HIGH			
09/09/10 17:25:32.0	ON	UNACK	Potrero_Meter_Timeout	Potrero_Meter RTU Failed		1		
09/09/10 17:25:48.0	ON	ACK	Potrero_Meter_Timeout	Potrero_Meter RTU Failed		1	MFV2	CTSF00P2
09/09/10 17:25:49.0	OFF	CLEAR	MMT_FT0012_BRT	Mil-Ter M12 Diff Pressure	OFF		MFV2	CTSF00P2
09/09/10 17:25:49.0	OFF	CLEAR	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	OFF		MFV2	CTSF00P2
09/09/10 17:25:49.0	HIGH	ACK	JSI_PT0004_BRT	Sr-Vst-X L109 Press	HIGH		MFV2	CTSF00P2
09/09/10 17:25:50.0	OFF	CLEAR	MMT_FA0008R_BRT	Mil-Ter M8 Backflow Alarm		0	MFV2	CTSF00P2
09/09/10 17:25:50.0	OFF	CLEAR	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm		0	MFV2	CTSF00P2
09/09/10 17:25:57.7	HIGH	UNACK	JNR_PT0002_BRT	N-Rngstrf L101 D-S Press	HIGH			
09/09/10 17:26:06.0	ON	UNACK	Orinda_Timeout	Orinda RTU Failed		1		
09/09/10 17:26:06.0		Login	ODN\SMGb	AutoLogin			System	CTBRT0P4
09/09/10 17:26:07.0		System	Status	Citect USA - 2009/10/22 - C14 - 9/8/2010 09:00:00			System	CTBRT0P4
09/09/10 17:26:10.0	ON	ACK	Orinda_Timeout	Orinda RTU Failed		1	MFV2	CTSF00P2
09/09/10 17:26:12.3	OFF	ACK	MMT_FA0014R_BRT	Mil-Ter M14 Backflow Alarm		0		
09/09/10 17:26:13.1	HIGH	UNACK	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	HIGH			
09/09/10 17:26:13.1	HIGH	UNACK	MMT_FT0012_BRT	Mil-Ter M12 Diff Pressure	HIGH			
09/09/10 17:26:13.6	HIGH	UNACK	JAW_PT0001_BRT	Aborn & White L100 Press	HIGH			
09/09/10 17:26:16.0	HIGH	ACK	JNR_PT0002_BRT	N-Rngstrf L101 D-S Press	HIGH		MFV2	CTSF00P2
09/09/10 17:26:16.4	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:26:17.0	HIGH	ACK	MMT_FT0012_BRT	Mil-Ter M12 Diff Pressure	HIGH		MFV2	CTSF00P2
09/09/10 17:26:18.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		MFV2	CTSF00P2
09/09/10 17:26:18.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		MFV2	CTSF00P2
09/09/10 17:26:18.0	OFF	CLEAR	MMT_FA0014R_BRT	Mil-Ter M14 Backflow Alarm		0	MFV2	CTSF00P2
09/09/10 17:26:18.0	HIGH	ACK	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	HIGH		KLM7	CTSF00P5
09/09/10 17:26:19.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		MFV2	CTSF00P2
09/09/10 17:26:19.0	OFF	CLEAR	MMT_FA0014R_BRT	Mil-Ter M14 Backflow Alarm		0	KLM7	CTSF00P5
09/09/10 17:26:20.0	HIGH	ACK	JAW_PT0001_BRT	Aborn & White L100 Press	HIGH		MFV2	CTSF00P2
09/09/10 17:26:37.6	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:26:37.6	OFF	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:26:40.8	HH	UNACK	JNR_PT0002_BRT	N-Rngstrf L101 D-S Press	HIGH HIGH			
09/09/10 17:26:52.0	HH	ACK	JNR_PT0002_BRT	N-Rngstrf L101 D-S Press	HIGH HIGH		BDMh	CTSF00P3
09/09/10 17:26:52.9	HH	UNACK	JAW_PT0001_BRT	Aborn & White L100 Press	HIGH HIGH			
09/09/10 17:26:53.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		BDMh	CTSF00P3
09/09/10 17:26:57.0	HH	ACK	JAW_PT0001_BRT	Aborn & White L100 Press	HIGH HIGH		MFV2	CTSF00P2
09/09/10 17:26:58.5	OFF	ACK	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	HIGH			
09/09/10 17:27:05.0	OFF	CLEAR	MMT_FT0011_BRT	Mil-Ter M11 Diff Pressure	OFF		J1Gw	CTSF00P4
09/09/10 17:27:42.2	ON	UNACK	MMT_FA0008R_BRT	Mil-Ter M8 Backflow Alarm		1		
09/09/10 17:27:42.2	ON	UNACK	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm		1		
09/09/10 17:27:43.2	OFF	ACK	MMT_FT0012_BRT	Mil-Ter M12 Diff Pressure	HIGH			
09/09/10 17:27:48.0	ON	ACK	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm		1	BDMh	CTSF00P3
09/09/10 17:27:48.0	OFF	CLEAR	Potrero_Meter_Timeout	Potrero_Meter RTU Failed		0		
09/09/10 17:27:48.0	OFF	ACK	Potrero_Meter_Timeout	Potrero_Meter RTU Failed		0		
09/09/10 17:27:49.0	ON	ACK	MMT_FA0008R_BRT	Mil-Ter M8 Backflow Alarm		1	BDMh	CTSF00P3
09/09/10 17:27:50.0	OFF	CLEAR	MMT_FT0012_BRT	Mil-Ter M12 Diff Pressure	OFF			
09/09/10 17:28:24.0	OFF	CLEAR	Orinda_Timeout	Orinda RTU Failed		0		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 17:28:24.0	OFF	ACK	Orinda_Timeout	Orinda RTU Failed		0		
09/09/10 17:28:29.6	HIGH	UNACK	MMT_FT0009_BRT	Mil-Ter M9 Diff Pressure	HIGH			
09/09/10 17:28:39.0	HIGH	ACK	MMT_FT0009_BRT	Mil-Ter M9 Diff Pressure	HIGH		J1Gw	CTSF00P4
09/09/10 17:29:22.0		Setpoint	ADE_ZIC222_CMD0	Delevan-K L400 Spill V222 Pct Op Sp		4	MFV2	CTSF00P2
09/09/10 17:29:37.3	HH	UNACK	JSI_PT0004_BRT	Sr-Vst-X L109 Press	HIGH HIGH			
09/09/10 17:29:37.3	HH	UNACK	JSI_PT0001_BRT	Sr-Vst-X L132 Press	HIGH HIGH			
09/09/10 17:29:59.2	OFF	ACK	MMT_FT0009_BRT	Mil-Ter M9 Diff Pressure	HIGH			
09/09/10 17:30:01.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		exl8	CTBRTOP1
09/09/10 17:30:01.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		exl8	CTBRTOP1
09/09/10 17:30:11.0	OFF	CLEAR	MMT_FT0009_BRT	Mil-Ter M9 Diff Pressure	OFF		exl8	CTBRTOP1
09/09/10 17:30:12.0	HH	ACK	JSI_PT0001_BRT	Sr-Vst-X L132 Press	HIGH HIGH		MFV2	CTSF00P2
09/09/10 17:30:12.0	HH	ACK	JSI_PT0004_BRT	Sr-Vst-X L109 Press	HIGH HIGH		MFV2	CTSF00P2
09/09/10 17:30:16.9	ON	UNACK	OC2_Y50025_BRT	Alstn-Wy L105 Pres Data Old		1		
09/09/10 17:30:24.0		Setpoint	ADE_ZIC222_CMD0	Delevan-K L400 Spill V222 Pct Op Sp		3	MFV2	CTSF00P2
09/09/10 17:31:09.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 17:31:15.6	OFF	UNACK	OC2_Y50025_BRT	Alstn-Wy L105 Pres Data Old		0		
09/09/10 17:31:28.0		Setpoint	ADE_ZIC222_CMD0	Delevan-K L400 Spill V222 Pct Op Sp		0	MFV2	CTSF00P2
09/09/10 17:31:43.0	OFF	CLEAR	OC2_Y50025_BRT	Alstn-Wy L105 Pres Data Old		0	MFV2	CTSF00P2
09/09/10 17:31:43.0	ON	ACK	OC2_Y50025_BRT	Alstn-Wy L105 Pres Data Old		0	MFV2	CTSF00P2
09/09/10 17:31:44.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 17:32:57.5	ON	UNACK	MMT_HS0029C_BRT	Mil-Ter V29 Controller Con/Loc		1		
09/09/10 17:32:57.5	ON	UNACK	MMT_HS0029A_BRT	Mil-Ter V29 Controller Aut/Man		1		
09/09/10 17:33:12.0	ON	ACK	MMT_HS0029A_BRT	Mil-Ter V29 Controller Aut/Man		1	BDMh	CTSF00P3
09/09/10 17:33:13.0	ON	ACK	MMT_HS0029C_BRT	Mil-Ter V29 Controller Con/Loc		1	BDMh	CTSF00P3
09/09/10 17:33:27.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 17:33:27.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 17:34:32.0	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 17:34:32.0	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 17:34:50.1	OFF	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 17:34:50.1	OFF	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 17:35:20.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF			
09/09/10 17:35:21.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF			
09/09/10 17:35:21.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 17:35:21.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH		MFV2	CTSF00P2
09/09/10 17:37:19.1	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:37:27.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:37:55.0		Login	ODN\mbma	AutoLogin			System	CTBRTOP2
09/09/10 17:37:56.0		System	Status	Citect USA - 2009/10/22 - C14 - 9/8/2010 09:00:00			System	CTBRTOP2
09/09/10 17:37:58.4	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:38:04.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		J1Gw	CTSF00P4
09/09/10 17:38:39.7	HIGH	UNACK	NSF_PT0003_BRT	San-Crlos L147 Press	HIGH			
09/09/10 17:38:50.0	HIGH	ACK	NSF_PT0003_BRT	San-Crlos L147 Press	HIGH			
09/09/10 17:38:58.5	OFF	ACK	NSF_PT0003_BRT	San-Crlos L147 Press	HIGH			
09/09/10 17:39:05.0	OFF	CLEAR	NSF_PT0003_BRT	San-Crlos L147 Press	OFF		MFV2	CTSF00P2
09/09/10 17:39:06.0	OFF	CLEAR	NSF_PT0003_BRT	San-Crlos L147 Press	OFF		MFV2	CTSF00P2
09/09/10 17:39:18.1	HIGH	UNACK	NSF_PT0003_BRT	San-Crlos L147 Press	HIGH			
09/09/10 17:39:26.0	HIGH	ACK	NSF_PT0003_BRT	San-Crlos L147 Press	HIGH		MFV2	CTSF00P2
09/09/10 17:39:36.9	LL	UNACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW LOW			
09/09/10 17:39:37.6	HIGH	UNACK	NSF_PT0009_BRT	Brngme L101 Press	HIGH			
09/09/10 17:39:44.0	LOW	UNACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	LOW			
09/09/10 17:39:47.0	HIGH	ACK	NSF_PT0009_BRT	Brngme L101 Press	HIGH			
09/09/10 17:39:48.0	LL	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW LOW		J1Gw	CTSF00P4
09/09/10 17:40:12.0	LOW	ACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	LOW		J1Gw	CTSF00P4
09/09/10 17:40:18.3	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:40:24.2	HIGH	UNACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 17:40:27.0	HIGH	ACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH		J1Gw	CTSF00P4
09/09/10 17:40:28.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		J1Gw	CTSF00P4
09/09/10 17:40:38.9	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:40:45.7	HIGH	UNACK	NHF_PT0001_BRT	Hlf-Mn-By L132 Press	HIGH			
09/09/10 17:40:46.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		J1Gw	CTSF00P4
09/09/10 17:40:49.0	HIGH	ACK	NHF_PT0001_BRT	Hlf-Mn-By L132 Press	HIGH			
09/09/10 17:41:23.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 17:41:38.3	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:41:44.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		MFV2	CTSF00P2
09/09/10 17:41:45.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	MFV2	CTSF00P2
09/09/10 17:41:55.8	HIGH	UNACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	HIGH			
09/09/10 17:42:04.0	HIGH	ACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	HIGH		J1Gw	CTSF00P4
09/09/10 17:42:19.5	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:42:28.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		J1Gw	CTSF00P4
09/09/10 17:42:39.1	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:42:48.9	LOW	UNACK	SWG_AT0031_BRT	Wild-Goose Tot Odorant (Tbm+Tht)	LOW			
09/09/10 17:42:58.7	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF			
09/09/10 17:42:58.7	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 17:43:00.0	LOW	ACK	SWG_AT0031_BRT	Wild-Goose Tot Odorant (Tbm+Tht)	LOW		J1Gw	CTSF00P4
09/09/10 17:43:00.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		J1Gw	CTSF00P4
09/09/10 17:43:01.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		J1Gw	CTSF00P4
09/09/10 17:43:04.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		J1Gw	CTSF00P4
09/09/10 17:43:45.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 17:43:45.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 17:43:57.9	HIGH	UNACK	NLP_PT0102_BRT	Lmita-Prk L101 U/S Press	HIGH			
09/09/10 17:44:18.6	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:44:30.0	HIGH	ACK	NLP_PT0102_BRT	Lmita-Prk L101 U/S Press	HIGH			
09/09/10 17:44:30.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:44:58.8	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:45:01.3	HH	UNACK	NSF_PT0003_BRT	San-Crlos L147 Press	HIGH HIGH			
09/09/10 17:45:13.0	HH	ACK	NSF_PT0003_BRT	San-Crlos L147 Press	HIGH HIGH		J1Gw	CTSF00P4
09/09/10 17:45:14.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		J1Gw	CTSF00P4
09/09/10 17:45:17.0		System	Status	User Shutdown			wahbAdmin	CTSF0Admin4
09/09/10 17:45:18.5	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:45:53.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		J1Gw	CTSF00P4
09/09/10 17:45:58.8	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:46:03.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		J1Gw	CTSF00P4
09/09/10 17:46:04.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		MFV2	CTSF00P2
09/09/10 17:46:39.0	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:46:44.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		J1Gw	CTSF00P4
09/09/10 17:46:46.3	OFF	ACK	MIR_FI0003_AA_BRT	IRVING-STA M-3 FLOW	HIGH			
09/09/10 17:46:58.0	OFF	CLEAR	MIR_FI0003_AA_BRT	IRVING-STA M-3 FLOW	OFF		BDMh	CTSF00P3
09/09/10 17:46:58.6	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:47:06.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		J1Gw	CTSF00P4
09/09/10 17:47:29.9	HIGH	UNACK	JMB_PT0001_BRT	Mabury Upstream Pressure	HIGH			
09/09/10 17:48:09.0	HIGH	ACK	JMB_PT0001_BRT	Mabury Upstream Pressure	HIGH		J1Gw	CTSF00P4
09/09/10 17:48:12.5	HIGH	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH			
09/09/10 17:48:18.5	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:48:33.0	OFF	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH			
09/09/10 17:48:43.2	OFF	ACK	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm		0		
09/09/10 17:48:52.7	HIGH	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH			
09/09/10 17:49:10.3	HH	UNACK	NHF_PT0001_BRT	Hlf-Mn-By L132 Press	HIGH HIGH			
09/09/10 17:49:28.6	OFF	ACK	MMT_FA0008R_BRT	Mil-Ter M8 Backflow Alarm		0		
09/09/10 17:49:30.8	HH	UNACK	NSF_PT0009_BRT	BrIngme L101 Press	HIGH HIGH			
09/09/10 17:49:52.4	OFF	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH			
09/09/10 17:50:07.4	HH	UNACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	HIGH HIGH			
09/09/10 17:50:12.2	HIGH	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH			
09/09/10 17:50:13.4	ON	UNACK	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm		1		
09/09/10 17:50:21.0	HH	ACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	HIGH HIGH		J1Gw	CTSF00P4
09/09/10 17:50:22.0	ON	ACK	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm		1	J1Gw	CTSF00P4
09/09/10 17:50:22.0	HIGH	ACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH		J1Gw	CTSF00P4
09/09/10 17:50:23.0	HH	ACK	NSF_PT0009_BRT	BrIngme L101 Press	HIGH HIGH		J1Gw	CTSF00P4
09/09/10 17:50:27.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 17:50:29.0	HH	ACK	NHF_PT0001_BRT	Hlf-Mn-By L132 Press	HIGH HIGH		J1Gw	CTSF00P4
09/09/10 17:50:30.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	J1Gw	CTSF00P4
09/09/10 17:50:30.4	LOW	UNACK	ADE_PT0002B_BRT	Delevan-K L401 Disch Press	LOW			
09/09/10 17:50:31.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		J1Gw	CTSF00P4
09/09/10 17:50:32.0	OFF	CLEAR	MMT_FA0008R_BRT	Mil-Ter M8 Backflow Alarm		0	J1Gw	CTSF00P4
09/09/10 17:50:47.0	LOW	ACK	ADE_PT0002B_BRT	Delevan-K L401 Disch Press	LOW		J1Gw	CTSF00P4
09/09/10 17:50:48.5	OFF	ACK	ADE_PT0002B_BRT	Delevan-K L401 Disch Press	LOW			
09/09/10 17:51:02.0	OFF	CLEAR	ADE_PT0002B_BRT	Delevan-K L401 Disch Press	OFF		J1Gw	CTSF00P4
09/09/10 17:51:39.8	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:51:50.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		J1Gw	CTSF00P4
09/09/10 17:51:52.0		Setpoint	M7B_PIC_92B_CMD0	Pls-7B D/S Press Sp		370	BDMh	CTSF00P3
09/09/10 17:51:58.9	HIGH	UNACK	MIR_PT0012_BRT	IRVING-STA MIXER PRESS	HIGH			
09/09/10 17:51:59.6	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:52:03.0		Setpoint	M7A_PIC_65A_CMD0	Pls-7A D/S Press Sp		370	BDMh	CTSF00P3
09/09/10 17:52:18.0	HIGH	ACK	MIR_PT0012_BRT	IRVING-STA MIXER PRESS	HIGH		MFV2	CTSF00P2
09/09/10 17:52:19.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		MFV2	CTSF00P2
09/09/10 17:52:37.2	LOW	UNACK	ADE_PT0002B_BRT	Delevan-K L401 Disch Press	LOW			
09/09/10 17:52:39.0		Setpoint	MSH_PIC001_CMD0	Sherid-Rd V1 Press Sp		370	BDMh	CTSF00P3
09/09/10 17:52:47.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 17:52:47.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 17:52:50.4	HH	UNACK	NLP_PT0102_BRT	Lmita-Prk L101 U/S Press	HIGH HIGH			
09/09/10 17:52:54.0		Setpoint	MSH_PIC002_CMD0	Sherid-Rd V2 Press Sp		350	BDMh	CTSF00P3
09/09/10 17:52:56.9	OFF	ACK	ASQ_ZS9998_BRT	Shingl-401 RTU Door Alarm		0		
09/09/10 17:52:59.6	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:53:13.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		J1Gw	CTSF00P4
09/09/10 17:53:14.0	OFF	CLEAR	ASQ_ZS9998_BRT	Shingl-401 RTU Door Alarm		0	J1Gw	CTSF00P4
09/09/10 17:53:14.0	LOW	ACK	ADE_PT0002B_BRT	Delevan-K L401 Disch Press	LOW		J1Gw	CTSF00P4
09/09/10 17:53:19.3	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 17:53:42.3	ON	UNACK	K15_FS0001A_BRT	Panoche L2 To L300A Backflow			1	
09/09/10 17:54:12.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		mbma	CTBRTOP2
09/09/10 17:54:12.0	ON	ACK	K15_FS0001A_BRT	Panoche L2 To L300A Backflow			1 mbma	CTBRTOP2
09/09/10 17:54:18.6	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 17:54:42.0	HH	ACK	NLP_PT0102_BRT	Lmita-Prk L101 U/S Press	HIGH HIGH		MFV2	CTSF00P2
09/09/10 17:54:42.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		MFV2	CTSF00P2
09/09/10 17:54:43.4	OFF	ACK	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm			0	
09/09/10 17:54:47.0	OFF	CLEAR	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm			0 MFV2	CTSF00P2
09/09/10 17:54:48.0	OFF	CLEAR	MMT_FA0007R_BRT	Mil-Ter M7 Backflow Alarm			0	
09/09/10 17:55:33.3	HH	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH HIGH			
09/09/10 17:55:41.0	HH	ACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH HIGH		MFV2	CTSF00P2
09/09/10 17:55:57.0		Login	ODN\axa1	AutoLogin			System	CTBRTOP3
09/09/10 17:55:58.0		System	Status	Citect USA - 2009/10/22 - C14 - 9/8/2010 09:00:00			System	CTBRTOP3
09/09/10 17:56:14.6	HIGH	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH			
09/09/10 17:56:33.8	HH	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH HIGH			
09/09/10 17:56:53.0	HH	ACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH HIGH			
09/09/10 17:57:08.2	ON	UNACK	OC2_Y50025_BRT	Alstn-Wy L105 Pres Data Old			1	
09/09/10 17:57:13.4	HIGH	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH			
09/09/10 17:57:27.6	OFF	UNACK	OC2_Y50025_BRT	Alstn-Wy L105 Pres Data Old			0	
09/09/10 17:57:46.9	ON	UNACK	OC2_Y50025_BRT	Alstn-Wy L105 Pres Data Old			1	
09/09/10 17:57:55.0	HIGH	ACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH		J1Gw	CTSF00P4
09/09/10 17:57:56.0	OFF	CLEAR	OC2_Y50025_BRT	Alstn-Wy L105 Pres Data Old			0 J1Gw	CTSF00P4
09/09/10 17:57:56.0	ON	ACK	OC2_Y50025_BRT	Alstn-Wy L105 Pres Data Old			0 J1Gw	CTSF00P4
09/09/10 17:58:14.5	HH	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH HIGH			
09/09/10 17:58:25.0	HH	ACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH HIGH		J1Gw	CTSF00P4
09/09/10 17:58:28.0	ON	ACK	OC2_Y50025_BRT	Alstn-Wy L105 Pres Data Old			1 exl8	CTBRTOP1
09/09/10 17:59:52.4	OFF	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW LOW			
09/09/10 18:00:35.0	ON	UNACK	AMPLA1HEARTBEAT	SfgoGasIIM1 Ampla Service Fail			1	
09/09/10 18:00:37.0	OFF	UNACK	AMPLA1HEARTBEAT	SfgoGasIIM1 Ampla Service Fail			0	
09/09/10 18:01:17.0	OFF	CLEAR	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	OFF		exl8	CTBRTOP1
09/09/10 18:01:17.0	OFF	CLEAR	AMPLA1HEARTBEAT	SfgoGasIIM1 Ampla Service Fail			0 exl8	CTBRTOP1
09/09/10 18:01:17.0	ON	ACK	AMPLA1HEARTBEAT	SfgoGasIIM1 Ampla Service Fail			0 exl8	CTBRTOP1
09/09/10 18:01:18.0	OFF	CLEAR	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	OFF			
09/09/10 18:02:32.0	ON	UNACK	Orinda_Timeout	Orinda RTU Failed			1	
09/09/10 18:02:45.6	LOW	UNACK	M7A_PT0003_BRT	PLS-7A D/S PRESS	LOW			
09/09/10 18:02:59.7	OFF	ACK	SWG_AT0031_BRT	Wild-Goose Tot Odorant (Tbm+Tht)	LOW			
09/09/10 18:03:56.5	OFF	ACK	OC2_Y50025_BRT	Alstn-Wy L105 Pres Data Old			0	
09/09/10 18:04:27.5	OFF	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo			0	
09/09/10 18:04:28.3	OFF	ACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range			0	
09/09/10 18:04:28.3	HIGH	UNACK	MMT_ZT0029_BRT	Mlpts-Ter Mix Bypass V29 Pct Op	HIGH			
09/09/10 18:04:28.3	OFF	ACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW			
09/09/10 18:04:28.7	OFF	ACK	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range			0	
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0066_BRT	Mlpts-Ter L107 Mon V66 Pct Op	LOW			
09/09/10 18:04:28.7	OFF	ACK	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range			0	
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0050_BRT	Mlpts-Ter Sjdfm V50 Pct Op	LOW			
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0049_BRT	Mlpts-Ter L132 V49 Pct Op	LOW			
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0048_BRT	Mlpts-Ter L101 V48 Pct Op	LOW			
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0045_BRT	Mlpts-Ter L109 V45 Pct Op	LOW			
09/09/10 18:04:28.7	OFF	ACK	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range			0	
09/09/10 18:04:28.7	OFF	ACK	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range			0	
09/09/10 18:04:28.7	OFF	ACK	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range			0	
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0003_BRT	Mlpts-Ter M10 Mon V3 Pct Op	LOW			
09/09/10 18:04:28.7	OFF	ACK	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range			0	
09/09/10 18:04:28.7	LL	UNACK	MMT_PT0040_BRT	Mlpts-Ter L109 Press	LOW LOW			
09/09/10 18:04:28.7	OFF	ACK	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range			0	
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0070_BRT	Mlpts-Ter L131 Mon V70 Pct Op	LOW			
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0067_BRT	Mlpts-Ter L107 Mon V67 Pct Op	LOW			
09/09/10 18:04:28.7	OFF	ACK	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range			0	
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0063_BRT	Mlpts-Ter Mon V63 Pct Op	LOW			
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0071_BRT	Mlpts-Ter L131 Mon V71 Pct Op	LOW			
09/09/10 18:04:28.7	OFF	ACK	MMT_PT0040_OOR	Mlpts-Ter L109 Press Out of Range			0	
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0028_BRT	Mlpts-Ter Byp Mon V28 Pct Op	LOW			
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0026_BRT	Mlpts-Ter Mixer Mon V26 Pct Op	LOW			
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0016_BRT	Mlpts-Ter Mixer Mon V16 Pct Op	LOW			
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0006_BRT	Mlpts-Ter M7 Mon V6 Pct Op	LOW			
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0005_BRT	Mlpts-Ter M8 Mon V5 Pct Op	LOW			
09/09/10 18:04:28.7	LOW	UNACK	MMT_ZT0004_BRT	Mlpts-Ter M9 Mon V4 Pct Op	LOW			
09/09/10 18:04:28.7	OFF	ACK	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range			0	
09/09/10 18:04:28.7	OFF	ACK	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range			0	
09/09/10 18:04:28.7	OFF	ACK	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range			0	
09/09/10 18:04:29.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			1	
09/09/10 18:04:32.0	OFF	CLEAR	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range			0	
09/09/10 18:04:32.0	OFF	CLEAR	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range			0	

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 18:04:32.0	OFF	CLEAR	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		0		
09/09/10 18:04:33.0	OFF	CLEAR	MMT_ZT0071_00R	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		0		
09/09/10 18:04:33.0	OFF	CLEAR	MMT_ZT0067_00R	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		0		
09/09/10 18:04:33.0	OFF	CLEAR	MMT_PT0040_00R	Mlpts-Ter L109 Press Out of Range		0		
09/09/10 18:04:33.0	OFF	CLEAR	MMT_ZT0003_00R	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		0		
09/09/10 18:04:33.0	OFF	CLEAR	MMT_LT0003_00R	Mlpts-Ter Storage Tank Lvl Out of Range		0		
09/09/10 18:04:33.0	OFF	CLEAR	MMT_LT0002A_00R	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		0		
09/09/10 18:04:33.0	OFF	CLEAR	MMT_ZT0004_00R	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		0		
09/09/10 18:04:33.0	OFF	CLEAR	MMT_PT0084_00R	Mlpts-Ter L101 Press Out of Range		0		
09/09/10 18:04:33.0	OFF	CLEAR	MMT_PT0083_00R	Mlpts-Ter L132 Press Out of Range		0		
09/09/10 18:04:33.0	OFF	CLEAR	MMT_ZT0066_00R	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		0		
09/09/10 18:04:44.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	exl8	CTBRTOP1
09/09/10 18:04:45.0	LOW	ACK	MMT_ZT0006_BRT	Mlpts-Ter M7 Mon V6 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:45.0	LOW	ACK	MMT_ZT0005_BRT	Mlpts-Ter M8 Mon V5 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:45.0	LOW	ACK	MMT_ZT0004_BRT	Mlpts-Ter M9 Mon V4 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:45.0	LOW	ACK	MMT_ZT0003_BRT	Mlpts-Ter M10 Mon V3 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:46.0	LOW	ACK	MMT_ZT0028_BRT	Mlpts-Ter Byp Mon V28 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:46.0	LOW	ACK	MMT_ZT0016_BRT	Mlpts-Ter Mixer Mon V16 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:46.0	LOW	ACK	MMT_ZT0026_BRT	Mlpts-Ter Mixer Mon V26 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:47.0	OFF	UNACK	Orinda_Timeout	Orinda RTU Failed		0		
09/09/10 18:04:47.0	LOW	ACK	MMT_ZT0070_BRT	Mlpts-Ter L131 Mon V70 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:47.0	LOW	ACK	MMT_ZT0066_BRT	Mlpts-Ter L107 Mon V66 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:47.0	LL	ACK	MMT_PT0040_BRT	Mlpts-Ter L109 Press	LOW LOW		exl8	CTBRTOP1
09/09/10 18:04:48.0	LOW	ACK	MMT_ZT0063_BRT	Mlpts-Ter Mon V63 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:48.0	LOW	ACK	MMT_ZT0071_BRT	Mlpts-Ter L131 Mon V71 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:49.0	LOW	ACK	MMT_ZT0048_BRT	Mlpts-Ter L101 V48 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:49.0	LOW	ACK	MMT_ZT0045_BRT	Mlpts-Ter L109 V45 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:50.0	LOW	ACK	MMT_ZT0050_BRT	Mlpts-Ter Sjdfm V50 Pct Op	LOW			
09/09/10 18:04:50.0	LOW	ACK	MMT_ZT0049_BRT	Mlpts-Ter L132 V49 Pct Op	LOW		exl8	CTBRTOP1
09/09/10 18:04:51.0	LOW	ACK	M7A_PT0003_BRT	PLS-7A D/S PRESS	LOW			
09/09/10 18:04:51.0	HIGH	ACK	MMT_ZT0029_BRT	Mlpts-Ter Mix Bypass V29 Pct Op	HIGH			
09/09/10 18:04:52.0	OFF	CLEAR	OC2_Y50025_BRT	Alstn-Wy L105 Pres Data Old		0	exl8	CTBRTOP1
09/09/10 18:04:52.0	OFF	CLEAR	Orinda_Timeout	Orinda RTU Failed		0		
09/09/10 18:04:52.0	ON	ACK	Orinda_Timeout	Orinda RTU Failed		0		
09/09/10 18:04:53.0	OFF	CLEAR	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	OFF		exl8	CTBRTOP1
09/09/10 18:04:53.0	OFF	CLEAR	SWG_AT0031_BRT	Wild-Goose Tot Odorant (Tbm+Tht)	OFF		exl8	CTBRTOP1
09/09/10 18:04:54.0	OFF	CLEAR	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0	exl8	CTBRTOP1
09/09/10 18:05:13.2	ON	UNACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		1		
09/09/10 18:05:13.2	OFF	ACK	MMT_ZT0029_BRT	Mlpts-Ter Mix Bypass V29 Pct Op	HIGH			
09/09/10 18:05:13.2	LOW	UNACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW			
09/09/10 18:05:13.7	ON	UNACK	MMT_ZT0066_00R	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		1		
09/09/10 18:05:13.7	OFF	ACK	MMT_PT0040_BRT	Mlpts-Ter L109 Press	LOW LOW			
09/09/10 18:05:13.7	LL	UNACK	MMT_PT0009_BRT	Mlpts-Ter Sjdfm Press	LOW LOW			
09/09/10 18:05:13.7	OFF	ACK	MMT_PT0009_00R	Mlpts-Ter Sjdfm Press Out of Range		0		
09/09/10 18:05:13.7	LL	UNACK	MMT_PT0029B_BRT	Mlpts-Ter Mixer D/S Press	LOW LOW			
09/09/10 18:05:13.7	LL	UNACK	MMT_PT0084_BRT	Mlpts-Ter L101 Press	LOW LOW			
09/09/10 18:05:13.7	LL	UNACK	MMT_PT0083_BRT	Mlpts-Ter L132 Press	LOW LOW			
09/09/10 18:05:19.0	OFF	CLEAR	MMT_PT0009_00R	Mlpts-Ter Sjdfm Press Out of Range		0		
09/09/10 18:05:43.0	ON	ACK	MMT_ZT0066_00R	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		1	MFV2	CTSF00P2
09/09/10 18:05:44.0	LL	ACK	MMT_PT0083_BRT	Mlpts-Ter L132 Press	LOW LOW		MFV2	CTSF00P2
09/09/10 18:05:44.0	LL	ACK	MMT_PT0029B_BRT	Mlpts-Ter Mixer D/S Press	LOW LOW		MFV2	CTSF00P2
09/09/10 18:05:44.0	LL	ACK	MMT_PT0009_BRT	Mlpts-Ter Sjdfm Press	LOW LOW		MFV2	CTSF00P2
09/09/10 18:05:45.0	LOW	ACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW		MFV2	CTSF00P2
09/09/10 18:05:45.0	LL	ACK	MMT_PT0084_BRT	Mlpts-Ter L101 Press	LOW LOW		MFV2	CTSF00P2
09/09/10 18:05:46.0	LOW	ACK	MMT_ZT0067_BRT	Mlpts-Ter L107 Mon V67 Pct Op	LOW		MFV2	CTSF00P2
09/09/10 18:05:46.0	ON	ACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		1	MFV2	CTSF00P2
09/09/10 18:05:47.0	OFF	CLEAR	MMT_PT0040_BRT	Mlpts-Ter L109 Press	OFF		MFV2	CTSF00P2
09/09/10 18:05:48.0	OFF	CLEAR	MMT_ZT0029_BRT	Mlpts-Ter Mix Bypass V29 Pct Op	OFF		MFV2	CTSF00P2
09/09/10 18:05:57.8	OFF	ACK	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		0		
09/09/10 18:05:58.7	OFF	ACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		0		
09/09/10 18:05:58.7	OFF	ACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW			
09/09/10 18:05:59.7	OFF	ACK	MMT_LT0001B_00R	Mlpts-Ter L300A Sep Liq Lvl Out of Range		0		
09/09/10 18:05:59.7	OFF	ACK	MMT_LT0001A_00R	Mlpts-Ter L300A Sep Liq Lvl Out of Range		0		
09/09/10 18:05:59.7	HH	UNACK	MMT_PT0084_BRT	Mlpts-Ter L101 Press	HIGH HIGH			
09/09/10 18:05:59.7	HH	UNACK	MMT_PT0083_BRT	Mlpts-Ter L132 Press	HIGH HIGH			
09/09/10 18:05:59.7	OFF	ACK	MMT_ZT0066_00R	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		0		
09/09/10 18:05:59.7	ON	UNACK	MMT_PT0009_00R	Mlpts-Ter Sjdfm Press Out of Range		1		
09/09/10 18:05:59.7	HH	UNACK	MMT_PT0029B_BRT	Mlpts-Ter Mixer D/S Press	HIGH HIGH			
09/09/10 18:06:04.0	OFF	CLEAR	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		0		
09/09/10 18:06:04.0	OFF	CLEAR	MMT_ZT0066_00R	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		0		
09/09/10 18:06:05.0	HH	ACK	MMT_PT0083_BRT	Mlpts-Ter L132 Press	HIGH HIGH		MFV2	CTSF00P2
09/09/10 18:06:05.0	ON	ACK	MMT_PT0009_00R	Mlpts-Ter Sjdfm Press Out of Range		1		
09/09/10 18:06:05.0	HH	ACK	MMT_PT0029B_BRT	Mlpts-Ter Mixer D/S Press	HIGH HIGH		MFV2	CTSF00P2

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 18:06:06.0	HH	ACK	MMT_PT0084_BRT	Mlpts-Ter L101 Press	HIGH HIGH		MFV2	CTSF00P2
09/09/10 18:06:07.0	OFF	CLEAR	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	OFF		MFV2	CTSF00P2
09/09/10 18:06:07.0	OFF	CLEAR	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		0	MFV2	CTSF00P2
09/09/10 18:06:07.0	OFF	CLEAR	MMT_LT0001B_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range		0		
09/09/10 18:06:07.0	OFF	CLEAR	MMT_LT0001A_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range		0		
09/09/10 18:06:12.5	ON	UNACK	OC2_Y0025_BRT	Alstn-Wy L105 Pres Data Old		1		
09/09/10 18:06:18.0	ON	ACK	OC2_Y0025_BRT	Alstn-Wy L105 Pres Data Old		1		
09/09/10 18:06:20.0	HH	ACK	MMT_PT0084_BRT	Mlpts-Ter L101 Press	HIGH HIGH		MFV2	CTSF00P2
09/09/10 18:06:43.3	OFF	ACK	MMT_PT0010BR_BRT	Mil-Ter Uic 10R U/S Pres	LOW			
09/09/10 18:06:43.9	LL	UNACK	MMT_PT0087_BRT	Mlpts-Ter L100 Press	LOW LOW			
09/09/10 18:06:43.9	OFF	ACK	MMT_PT0087_OOR	Mlpts-Ter L100 Press Out of Range		0		
09/09/10 18:06:43.9	HH	UNACK	MMT_PT0040_BRT	Mlpts-Ter L109 Press	HIGH HIGH			
09/09/10 18:06:49.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 18:06:50.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 18:06:51.5	LOW	UNACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW			
09/09/10 18:06:56.0	OFF	CLEAR	MMT_PT0010BR_BRT	Mil-Ter Uic 10R U/S Pres	OFF		ex18	CTBRTOP1
09/09/10 18:06:57.0	OFF	CLEAR	MMT_PT0087_OOR	Mlpts-Ter L100 Press Out of Range		0		
09/09/10 18:07:02.0	HH	ACK	MMT_PT0040_BRT	Mlpts-Ter L109 Press	HIGH HIGH		MFV2	CTSF00P2
09/09/10 18:07:02.0	LOW	ACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW		MFV2	CTSF00P2
09/09/10 18:07:03.0	LL	ACK	MMT_PT0087_BRT	Mlpts-Ter L100 Press	LOW LOW		MFV2	CTSF00P2
09/09/10 18:07:27.5	ON	UNACK	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		1		
09/09/10 18:07:27.5	ON	UNACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1		
09/09/10 18:07:28.6	ON	UNACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		1		
09/09/10 18:07:28.6	LOW	UNACK	MMT_PT0010BR_BRT	Mil-Ter Uic 10R U/S Pres	LOW			
09/09/10 18:07:28.6	LOW	UNACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW			
09/09/10 18:07:29.2	ON	UNACK	MMT_LT0001B_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_LT0001A_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_PT0087_OOR	Mlpts-Ter L100 Press Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_PT0040_OOR	Mlpts-Ter L109 Press Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		1		
09/09/10 18:07:29.2	ON	UNACK	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		1		
09/09/10 18:07:50.0	ON	ACK	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		1	MFV2	CTSF00P2
09/09/10 18:07:50.0	ON	ACK	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		1	MFV2	CTSF00P2
09/09/10 18:07:51.0	ON	ACK	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		1		
09/09/10 18:07:51.0	ON	ACK	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		1		
09/09/10 18:07:51.0	ON	ACK	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		1	MFV2	CTSF00P2
09/09/10 18:07:52.0	ON	ACK	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		1		
09/09/10 18:07:54.0	ON	ACK	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		1		
09/09/10 18:07:54.0	ON	ACK	MMT_PT0040_OOR	Mlpts-Ter L109 Press Out of Range		1		
09/09/10 18:07:55.0	ON	ACK	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		1		
09/09/10 18:07:55.0	ON	ACK	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		1		
09/09/10 18:07:56.0	ON	ACK	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		1		
09/09/10 18:08:01.0	ON	ACK	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		1	MFV2	CTSF00P2
09/09/10 18:08:02.0	ON	ACK	MMT_LT0001A_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range		1	MFV2	CTSF00P2
09/09/10 18:08:02.0	ON	ACK	MMT_PT0087_OOR	Mlpts-Ter L100 Press Out of Range		1	MFV2	CTSF00P2
09/09/10 18:08:03.0	LOW	ACK	MMT_PT0010BR_BRT	Mil-Ter Uic 10R U/S Pres	LOW		MFV2	CTSF00P2
09/09/10 18:08:03.0	LOW	ACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW		MFV2	CTSF00P2
09/09/10 18:08:03.0	ON	ACK	MMT_LT0001B_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range		1	MFV2	CTSF00P2
09/09/10 18:08:04.0	ON	ACK	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		1	MFV2	CTSF00P2
09/09/10 18:08:04.0	ON	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1	MFV2	CTSF00P2
09/09/10 18:08:04.0	ON	ACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		1	MFV2	CTSF00P2
09/09/10 18:09:38.0	ON	UNACK	Bethany_K_Timeout	Bethany_K RTU Failed		1		
09/09/10 18:09:46.5	OFF	ACK	OC2_Y0025_BRT	Alstn-Wy L105 Pres Data Old		0		
09/09/10 18:10:08.0	ON	ACK	Bethany_K_Timeout	Bethany_K RTU Failed		1	MFV2	CTSF00P2
09/09/10 18:10:09.0	OFF	CLEAR	OC2_Y0025_BRT	Alstn-Wy L105 Pres Data Old		0	MFV2	CTSF00P2
09/09/10 18:10:21.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 18:10:25.8	OFF	ACK	SAE_PT0002_BRT	Antelope Rsvl-Feed Press	LOW			
09/09/10 18:10:30.0	OFF	CLEAR	Bethany_K_Timeout	Bethany_K RTU Failed		0		
09/09/10 18:10:30.0	OFF	ACK	Bethany_K_Timeout	Bethany_K RTU Failed		0		
09/09/10 18:10:33.0	OFF	CLEAR	SAE_PT0002_BRT	Antelope Rsvl-Feed Press	OFF		ex18	CTBRTOP1
09/09/10 18:10:59.9	OFF	ACK	JMB_PT0001_BRT	Mabury Upstream Pressure	HIGH			
09/09/10 18:11:23.3	ON	UNACK	OC2_Y0025_BRT	Alstn-Wy L105 Pres Data Old		1		
09/09/10 18:11:46.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	MFV2	CTSF00P2
09/09/10 18:11:46.0	ON	ACK	OC2_Y0025_BRT	Alstn-Wy L105 Pres Data Old		1	MFV2	CTSF00P2

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 18:11:47.0	OFF	CLEAR	JMB_PT0001_BRT	Mabury Upstream Pressure	OFF		MFV2	CTSF00P2
09/09/10 18:11:50.9	OFF	ACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	HIGH HIGH			
09/09/10 18:12:00.0	OFF	CLEAR	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	OFF		J1Gw	CTSF00P4
09/09/10 18:12:03.9	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 18:12:19.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		J1Gw	CTSF00P4
09/09/10 18:12:23.7	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 18:12:35.2	HIGH	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 18:12:37.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		J1Gw	CTSF00P4
09/09/10 18:12:44.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 18:12:44.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 18:13:06.0	OFF	CLEAR	M6A_PT0003_BRT	PLS-6A D/S PRESS	OFF		exl8	CTBRTOP1
09/09/10 18:13:06.0	HIGH	ACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH		exl8	CTBRTOP1
09/09/10 18:13:07.0	OFF	CLEAR	M6A_PT0003_BRT	PLS-6A D/S PRESS	OFF		axa1	CTBRTOP3
09/09/10 18:13:08.0	OFF	CLEAR	M6A_PT0003_BRT	PLS-6A D/S PRESS	OFF		exl8	CTBRTOP1
09/09/10 18:13:20.0	OFF	CLEAR	M6A_PT0003_BRT	PLS-6A D/S PRESS	OFF		axa1	CTBRTOP3
09/09/10 18:13:39.5	OFF	ACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 18:13:59.0	OFF	CLEAR	M6A_PT0003_BRT	PLS-6A D/S PRESS	OFF		exl8	CTBRTOP1
09/09/10 18:14:36.7	HIGH	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH			
09/09/10 18:14:58.1	HH	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH HIGH			
09/09/10 18:15:17.7	HIGH	UNACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH			
09/09/10 18:15:19.0	HH	ACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH HIGH		J1Gw	CTSF00P4
09/09/10 18:15:35.1	HIGH	UNACK	NLP_PT0102_BRT	Lmita-Prk L101 U/S Press	HIGH			
09/09/10 18:15:36.3	LOW	UNACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	LOW			
09/09/10 18:15:45.0	HIGH	ACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH		axa1	CTBRTOP3
09/09/10 18:15:45.0	HIGH	ACK	NLP_PT0102_BRT	Lmita-Prk L101 U/S Press	HIGH		axa1	CTBRTOP3
09/09/10 18:15:45.0	LOW	ACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	LOW		axa1	CTBRTOP3
09/09/10 18:15:49.6	HIGH	UNACK	NSF_PT0009_BRT	Brngme L101 Press	HIGH			
09/09/10 18:15:56.0	HIGH	ACK	NSF_PT0009_BRT	Brngme L101 Press	HIGH		axa1	CTBRTOP3
09/09/10 18:15:56.6	LL	UNACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	LOW LOW			
09/09/10 18:16:12.8	HIGH	UNACK	NSF_PT0003_BRT	San-Crlos L147 Press	HIGH			
09/09/10 18:16:19.9	OFF	ACK	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	HIGH			
09/09/10 18:16:26.0	HIGH	ACK	NSF_PT0003_BRT	San-Crlos L147 Press	HIGH		J1Gw	CTSF00P4
09/09/10 18:16:28.0	LL	ACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	LOW LOW		J1Gw	CTSF00P4
09/09/10 18:16:29.0	OFF	CLEAR	NSU_PT0001_BRT	Slvn-Ave L109 U/S Press	OFF		J1Gw	CTSF00P4
09/09/10 18:16:46.8	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 18:16:58.1	LOW	UNACK	NMA_PT0011_BRT	Mrtin-Sta L132 D/S Press	LOW			
09/09/10 18:17:06.6	OFF	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 18:17:17.3	OFF	ACK	NLP_PT0102_BRT	Lmita-Prk L101 U/S Press	HIGH			
09/09/10 18:17:18.5	LL	UNACK	NMA_PT0011_BRT	Mrtin-Sta L132 D/S Press	LOW LOW			
09/09/10 18:17:29.0	LOW	ACK	NMA_PT0011_BRT	Mrtin-Sta L132 D/S Press	LOW			
09/09/10 18:17:30.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		MFV2	CTSF00P2
09/09/10 18:17:30.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		MFV2	CTSF00P2
09/09/10 18:17:31.4	OFF	ACK	NSF_PT0003_BRT	San-Crlos L147 Press	HIGH			
09/09/10 18:17:34.0	OFF	CLEAR	NLP_PT0102_BRT	Lmita-Prk L101 U/S Press	OFF		MFV2	CTSF00P2
09/09/10 18:17:34.0	LL	ACK	NMA_PT0011_BRT	Mrtin-Sta L132 D/S Press	LOW LOW		MFV2	CTSF00P2
09/09/10 18:17:38.2	ON	UNACK	NMA_PS0006_BRT	Mrtin-Sta Gas Sup Rack2 Press Lo		1		
09/09/10 18:17:53.0	ON	ACK	NMA_PS0006_BRT	Mrtin-Sta Gas Sup Rack2 Press Lo		1		
09/09/10 18:17:53.0	OFF	CLEAR	NSF_PT0003_BRT	San-Crlos L147 Press	OFF			
09/09/10 18:18:06.6	LOW	UNACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 18:18:12.4	OFF	ACK	NSF_PT0009_BRT	Brngme L101 Press	HIGH			
09/09/10 18:18:23.0	LOW	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW		J1Gw	CTSF00P4
09/09/10 18:18:24.0	OFF	CLEAR	NSF_PT0009_BRT	Brngme L101 Press	OFF		J1Gw	CTSF00P4
09/09/10 18:18:30.9	OFF	ACK	OC2_YS0025_BRT	Alstn-Wy L105 Pres Data Old		0		
09/09/10 18:18:40.0	OFF	CLEAR	OC2_YS0025_BRT	Alstn-Wy L105 Pres Data Old		0	J1Gw	CTSF00P4
09/09/10 18:18:41.0	OFF	CLEAR	OC2_YS0025_BRT	Alstn-Wy L105 Pres Data Old		0		
09/09/10 18:18:44.7	HIGH	UNACK	MMT_PT0031_BRT	Mlpts-Ter M31 D/S Press	HIGH			
09/09/10 18:18:46.2	ON	UNACK	K15_FY0026_00R	Panoche L300B/Cee Flo Ratio Out of Range		1		
09/09/10 18:18:57.0	ON	ACK	K15_FY0026_00R	Panoche L300B/Cee Flo Ratio Out of Range		1	axa1	CTBRTOP3
09/09/10 18:18:58.0	HIGH	ACK	MMT_PT0031_BRT	Mlpts-Ter M31 D/S Press	HIGH		axa1	CTBRTOP3
09/09/10 18:19:09.7	OFF	ACK	K15_FY0026_00R	Panoche L300B/Cee Flo Ratio Out of Range		0		
09/09/10 18:19:10.3	ON	UNACK	OC2_YS0025_BRT	Alstn-Wy L105 Pres Data Old		1		
09/09/10 18:19:13.0	OFF	CLEAR	K15_FY0026_00R	Panoche L300B/Cee Flo Ratio Out of Range		0		
09/09/10 18:19:17.6	HIGH	UNACK	JAW_PT0001_BRT	Aborn & White L100 Press	HIGH			
09/09/10 18:19:25.7	HIGH	UNACK	JSI_PT0004_BRT	Sr-Vst-X L109 Press	HIGH			
09/09/10 18:19:25.7	OFF	ACK	JSI_PT0001_BRT	Sr-Vst-X L132 Press	HIGH HIGH			
09/09/10 18:19:29.6	HIGH	UNACK	MMT_PT0038A_BRT	Mlpts-Ter M38 D/S Press	HIGH			
09/09/10 18:19:29.7	OFF	UNACK	OC2_YS0025_BRT	Alstn-Wy L105 Pres Data Old		0		
09/09/10 18:20:05.3	HIGH	UNACK	JNR_PT0002_BRT	N-Rngstrf L101 D-S Press	HIGH			
09/09/10 18:20:13.4	HIGH	UNACK	MLE_PT0001_BRT	Los-Esteros Tot Flow Meter Press	HIGH			
09/09/10 18:20:14.9	HIGH	UNACK	MMT_PT0032_BRT	Mlpts-Ter M32 D/S Press	HIGH			
09/09/10 18:20:14.9	OFF	ACK	MMT_PT0031_BRT	Mlpts-Ter M31 D/S Press	HIGH			
09/09/10 18:20:25.1	HIGH	UNACK	JTL_PT0001_BRT	Tully Rd L100 Pressure	HIGH			
09/09/10 18:20:52.3	OFF	UNACK	JSI_PT0004_BRT	Sr-Vst-X L109 Press	HIGH			

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 18:21:00.3	OFF	UNACK	MMT_PT0038A_BRT	Mlpts-Ter M38 D/S Press	HIGH			
09/09/10 18:21:00.3	OFF	UNACK	MMT_PT0032_BRT	Mlpts-Ter M32 D/S Press	HIGH			
09/09/10 18:21:03.0	HIGH	ACK	JNR_PT0002_BRT	N-Rngstrf L101 D-S Press	HIGH		J1Gw	CTSF00P4
09/09/10 18:21:03.0	HIGH	ACK	MLE_PT0001_BRT	Los-Esteros Tot Flow Meter Press	HIGH		J1Gw	CTSF00P4
09/09/10 18:21:03.0	HIGH	ACK	JTL_PT0001_BRT	Tully Rd L100 Pressure	HIGH		J1Gw	CTSF00P4
09/09/10 18:21:04.0	HIGH	ACK	JAW_PT0001_BRT	Aborn & White L100 Press	HIGH		J1Gw	CTSF00P4
09/09/10 18:21:04.0	OFF	CLEAR	MMT_PT0032_BRT	Mlpts-Ter M32 D/S Press	OFF		J1Gw	CTSF00P4
09/09/10 18:21:04.0	HIGH	ACK	MMT_PT0032_BRT	Mlpts-Ter M32 D/S Press	HIGH		J1Gw	CTSF00P4
09/09/10 18:21:05.0	OFF	CLEAR	MMT_PT0038A_BRT	Mlpts-Ter M38 D/S Press	OFF		J1Gw	CTSF00P4
09/09/10 18:21:05.0	HIGH	ACK	MMT_PT0038A_BRT	Mlpts-Ter M38 D/S Press	HIGH		J1Gw	CTSF00P4
09/09/10 18:21:06.0	OFF	CLEAR	OC2_YS0025_BRT	Alstn-Wy L105 Pres Data Old			0 J1Gw	CTSF00P4
09/09/10 18:21:06.0	ON	ACK	OC2_YS0025_BRT	Alstn-Wy L105 Pres Data Old			0 J1Gw	CTSF00P4
09/09/10 18:21:06.0	OFF	CLEAR	JSI_PT0004_BRT	Sr-Vst-X L109 Press	OFF		J1Gw	CTSF00P4
09/09/10 18:21:06.0	HIGH	ACK	JSI_PT0004_BRT	Sr-Vst-X L109 Press	HIGH		J1Gw	CTSF00P4
09/09/10 18:21:07.0	OFF	CLEAR	JSI_PT0001_BRT	Sr-Vst-X L132 Press	OFF		J1Gw	CTSF00P4
09/09/10 18:21:07.0	OFF	CLEAR	MMT_PT0031_BRT	Mlpts-Ter M31 D/S Press	OFF		J1Gw	CTSF00P4
09/09/10 18:21:08.5	HIGH	UNACK	M7A_PT0100_BRT	SILVER CREEK L100 PRESS	HIGH			
09/09/10 18:21:24.0	OFF	ACK	JTL_PT0004_BRT	Tully Rd Inlet Pressure	HIGH			
09/09/10 18:21:24.0	OFF	ACK	JTL_PT0001_BRT	Tully Rd L100 Pressure	HIGH			
09/09/10 18:21:27.0	HIGH	ACK	M7A_PT0100_BRT	SILVER CREEK L100 PRESS	HIGH		axa1	CTBRTOP3
09/09/10 18:21:33.0	OFF	ACK	JNR_PT0002_BRT	N-Rngstrf L101 D-S Press	HIGH			
09/09/10 18:21:36.0	OFF	CLEAR	JTL_PT0001_BRT	Tully Rd L100 Pressure	OFF		J1Gw	CTSF00P4
09/09/10 18:21:36.4	OFF	ACK	JAW_PT0001_BRT	Aborn & White L100 Press	HIGH			
09/09/10 18:21:37.0	OFF	CLEAR	JTL_PT0004_BRT	Tully Rd Inlet Pressure	OFF		J1Gw	CTSF00P4
09/09/10 18:21:42.6	OFF	ACK	MLE_PT0001_BRT	Los-Esteros Tot Flow Meter Press	HIGH			
09/09/10 18:21:55.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			1	
09/09/10 18:22:01.0	OFF	CLEAR	JAW_PT0001_BRT	Aborn & White L100 Press	OFF		J1Gw	CTSF00P4
09/09/10 18:22:01.0	OFF	CLEAR	MLE_PT0001_BRT	Los-Esteros Tot Flow Meter Press	OFF		J1Gw	CTSF00P4
09/09/10 18:22:01.0	OFF	CLEAR	JNR_PT0002_BRT	N-Rngstrf L101 D-S Press	OFF		J1Gw	CTSF00P4
09/09/10 18:22:29.1	OFF	ACK	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm			0	
09/09/10 18:22:31.6	OFF	ACK	M7A_PT0100_BRT	SILVER CREEK L100 PRESS	HIGH			
09/09/10 18:22:36.0	OFF	CLEAR	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm			0 J1Gw	CTSF00P4
09/09/10 18:22:36.0	OFF	CLEAR	M7A_PT0100_BRT	SILVER CREEK L100 PRESS	OFF		J1Gw	CTSF00P4
09/09/10 18:22:45.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			1 axa1	CTBRTOP3
09/09/10 18:23:40.5	HIGH	UNACK	NHF_PT0001_BRT	Hlf-Mn-By L132 Press	HIGH			
09/09/10 18:24:11.0	HIGH	ACK	NHF_PT0001_BRT	Hlf-Mn-By L132 Press	HIGH		axa1	CTBRTOP3
09/09/10 18:24:18.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0	
09/09/10 18:24:18.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0	
09/09/10 18:25:29.2	OFF	ACK	MIR_PT0012_BRT	IRVING-STA MIXER PRESS	HIGH			
09/09/10 18:25:36.1	OFF	ACK	K15_FS0001A_BRT	Panoche L2 To L300A Backflow			0	
09/09/10 18:26:13.0	OFF	CLEAR	MIR_PT0012_BRT	IRVING-STA MIXER PRESS	OFF		mbma	CTBRTOP2
09/09/10 18:26:13.0	OFF	CLEAR	K15_FS0001A_BRT	Panoche L2 To L300A Backflow			0 mbma	CTBRTOP2
09/09/10 18:26:34.3	LOW	UNACK	NSF_PT0106_BRT	Potrero-RTU Trans Hdr Press	LOW			
09/09/10 18:26:38.0	LL	UNACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW LOW			
09/09/10 18:26:59.0	LL	ACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW LOW		exl8	CTBRTOP1
09/09/10 18:27:00.0	LOW	ACK	NSF_PT0106_BRT	Potrero-RTU Trans Hdr Press	LOW		exl8	CTBRTOP1
09/09/10 18:27:31.7	OFF	ACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 18:27:50.0	ON	UNACK	NMA_PS0005_BRT	Mrtin-Sta Gas Sup Rack1 Press Lo			1	
09/09/10 18:27:52.2	HIGH	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 18:28:25.0	ON	ACK	NMA_PS0005_BRT	Mrtin-Sta Gas Sup Rack1 Press Lo			1 BDMh	CTSF00P3
09/09/10 18:28:25.0	OFF	CLEAR	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	OFF			
09/09/10 18:28:34.6	OFF	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 18:29:40.0	OFF	CLEAR	M6A_PT0003_BRT	PLS-6A D/S PRESS	OFF		mbma	CTBRTOP2
09/09/10 18:29:40.0	HIGH	ACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH		mbma	CTBRTOP2
09/09/10 18:29:59.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			1	
09/09/10 18:30:02.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			1 MFV2	CTSF00P2
09/09/10 18:30:46.9	OFF	ACK	NHF_PT0001_BRT	Hlf-Mn-By L132 Press	HIGH			
09/09/10 18:30:54.0	OFF	CLEAR	NHF_PT0001_BRT	Hlf-Mn-By L132 Press	OFF			
09/09/10 18:31:21.6	ON	UNACK	BMD_YS0002_STRTG_BRT	Mcdnld-Is K2 Compressor Status -Strtg			1	
09/09/10 18:31:31.5	OFF	ACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	LOW			
09/09/10 18:31:46.0	OFF	CLEAR	BMD_YS0002_STRTG_BRT	Mcdnld-Is K2 Compressor Status -Strtg			0 mbma	CTBRTOP2
09/09/10 18:31:46.0	ON	ACK	BMD_YS0002_STRTG_BRT	Mcdnld-Is K2 Compressor Status -Strtg			0 mbma	CTBRTOP2
09/09/10 18:31:46.0	OFF	UNACK	BMD_YS0002_STRTG_BRT	Mcdnld-Is K2 Compressor Status -Strtg			0	
09/09/10 18:31:46.0	OFF	CLEAR	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	OFF		mbma	CTBRTOP2
09/09/10 18:31:51.7	LOW	UNACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	LOW			
09/09/10 18:32:15.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0	
09/09/10 18:32:15.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0	
09/09/10 18:32:21.0	ON	UNACK	CoCo_PP_Meter_Timeout	CoCo_PP_Meter RTU Failed			1	
09/09/10 18:32:42.0	LOW	ACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	LOW		MFV2	CTSF00P2
09/09/10 18:32:43.0	ON	ACK	CoCo_PP_Meter_Timeout	CoCo_PP_Meter RTU Failed			1 MFV2	CTSF00P2
09/09/10 18:32:51.5	OFF	ACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	LOW			
09/09/10 18:33:07.0	OFF	CLEAR	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	OFF		MFV2	CTSF00P2
09/09/10 18:34:39.0	OFF	CLEAR	CoCo_PP_Meter_Timeout	CoCo_PP_Meter RTU Failed			0	

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 18:34:39.0	OFF	ACK	CoCo_PP_Meter_Timeout	CoCo_PP_Meter RTU Failed		0		
09/09/10 18:35:01.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 18:36:30.0		Alarm	NSU_FI0001_BRT	High Setpoint		5	SMGb	CTBRTOP4
09/09/10 18:36:32.0	HIGH	UNACK	NSU_FI0001_BRT	Slvn-Ave M-1 Flow	HIGH			
09/09/10 18:37:03.0	OFF	ACK	BMD_FQI010_DP_BRT	Mcdnld Mstr Met In Vol Day Proj Calculated	LOW	217.87		
09/09/10 18:37:05.0	OFF	CLEAR	BMD_FQI010_DP_BRT	Mcdnld Mstr Met In Vol Day Proj Calculated	OFF	217.87	mbma	CTBRTOP2
09/09/10 18:37:27.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 18:38:25.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	axa1	CTBRTOP3
09/09/10 18:38:25.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	axa1	CTBRTOP3
09/09/10 18:38:25.0	HIGH	ACK	NSU_FI0001_BRT	Slvn-Ave M-1 Flow	HIGH		axa1	CTBRTOP3
09/09/10 18:38:59.6	OFF	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0		
09/09/10 18:39:00.6	OFF	ACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		0		
09/09/10 18:39:00.6	OFF	ACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW			
09/09/10 18:39:01.1	OFF	ACK	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		0		
09/09/10 18:39:01.1	OFF	ACK	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		0		
09/09/10 18:39:01.1	OFF	ACK	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		0		
09/09/10 18:39:01.1	OFF	ACK	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		0		
09/09/10 18:39:01.1	OFF	ACK	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		0		
09/09/10 18:39:01.1	OFF	ACK	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		0		
09/09/10 18:39:01.1	LL	UNACK	MMT_PT0083_BRT	Mlpts-Ter L132 Press	LOW LOW			
09/09/10 18:39:01.1	LL	UNACK	MMT_PT0084_BRT	Mlpts-Ter L101 Press	LOW LOW			
09/09/10 18:39:01.1	OFF	ACK	MMT_PT0040_OOR	Mlpts-Ter L109 Press Out of Range		0		
09/09/10 18:39:01.1	OFF	ACK	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		0		
09/09/10 18:39:01.1	LL	UNACK	MMT_PT0040_BRT	Mlpts-Ter L109 Press	LOW LOW			
09/09/10 18:39:01.1	OFF	ACK	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		0		
09/09/10 18:39:01.1	LL	UNACK	MMT_PT0029B_BRT	Mlpts-Ter Mixer D/S Press	LOW LOW			
09/09/10 18:39:01.1	OFF	ACK	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		0		
09/09/10 18:39:01.1	OFF	ACK	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		0		
09/09/10 18:39:01.1	OFF	ACK	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_PT0040_OOR	Mlpts-Ter L109 Press Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		0		
09/09/10 18:39:04.0	OFF	CLEAR	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		0		
09/09/10 18:39:10.0	LL	ACK	MMT_PT0029B_BRT	Mlpts-Ter Mixer D/S Press	LOW LOW		mbma	CTBRTOP2
09/09/10 18:39:11.0	OFF	CLEAR	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	OFF		mbma	CTBRTOP2
09/09/10 18:39:12.0	OFF	CLEAR	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0	mbma	CTBRTOP2
09/09/10 18:39:17.0	LL	ACK	MMT_PT0083_BRT	Mlpts-Ter L132 Press	LOW LOW			
09/09/10 18:39:17.0	LL	ACK	MMT_PT0040_BRT	Mlpts-Ter L109 Press	LOW LOW			
09/09/10 18:39:18.0	LL	ACK	MMT_PT0084_BRT	Mlpts-Ter L101 Press	LOW LOW			
09/09/10 18:39:44.5	ON	UNACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1		
09/09/10 18:39:45.6	ON	UNACK	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		1		
09/09/10 18:39:45.6	ON	UNACK	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		1		
09/09/10 18:39:45.6	ON	UNACK	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		1		
09/09/10 18:39:45.6	ON	UNACK	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		1		
09/09/10 18:39:45.6	ON	UNACK	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		1		
09/09/10 18:39:45.6	ON	UNACK	MMT_PT0040_OOR	Mlpts-Ter L109 Press Out of Range		1		
09/09/10 18:39:45.6	ON	UNACK	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		1		
09/09/10 18:39:45.6	ON	UNACK	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		1		
09/09/10 18:39:45.6	ON	UNACK	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		1		
09/09/10 18:39:45.6	ON	UNACK	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		1		
09/09/10 18:39:45.6	ON	UNACK	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		1		
09/09/10 18:39:45.6	ON	UNACK	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		1		
09/09/10 18:39:45.7	ON	UNACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		1		
09/09/10 18:39:45.7	LOW	UNACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW			
09/09/10 18:39:49.8	LOW	UNACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW			
09/09/10 18:40:05.0	LOW	UNACK	BMD_FQI010_DP_BRT	Mcdnld Mstr Met In Vol Day Proj Calculated	LOW	187.12		
09/09/10 18:41:26.1	ON	UNACK	BMD_Y0002_RUNNG_BRT	Mcdnld-Is K2 Compressor Status -Runng		1		
09/09/10 18:41:38.0	OFF	CLEAR	BMD_Y0002_RUNNG_BRT	Mcdnld-Is K2 Compressor Status -Runng		0	mbma	CTBRTOP2
09/09/10 18:41:38.0	ON	ACK	BMD_Y0002_RUNNG_BRT	Mcdnld-Is K2 Compressor Status -Runng		0	mbma	CTBRTOP2
09/09/10 18:41:38.0	OFF	UNACK	BMD_Y0002_RUNNG_BRT	Mcdnld-Is K2 Compressor Status -Runng		0		
09/09/10 18:41:49.0	LOW	UNACK	GIN_AI0600_LP_BRT	L101 Pck/Dft Calculated	LOW	-6.14		
09/09/10 18:42:32.0	LOW	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW		MFV2	CTSF00P2
09/09/10 18:42:32.0	LOW	ACK	BMD_FQI010_DP_BRT	Mcdnld Mstr Met In Vol Day Proj Calculated	LOW	187.12	MFV2	CTSF00P2
09/09/10 18:42:32.0	LOW	ACK	GIN_AI0600_LP_BRT	L101 Pck/Dft Calculated	LOW	-6.14	MFV2	CTSF00P2

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 18:42:33.0	ON	ACK	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		1	MFV2	CTSF00P2
09/09/10 18:42:33.0	ON	ACK	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		1	MFV2	CTSF00P2
09/09/10 18:42:33.0	ON	ACK	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		1	MFV2	CTSF00P2
09/09/10 18:42:34.0	ON	ACK	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		1	MFV2	CTSF00P2
09/09/10 18:42:34.0	ON	ACK	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		1	MFV2	CTSF00P2
09/09/10 18:42:35.0	ON	ACK	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		1	MFV2	CTSF00P2
09/09/10 18:42:35.0	ON	ACK	MMT_PT0040_OOR	Mlpts-Ter L109 Press Out of Range		1	MFV2	CTSF00P2
09/09/10 18:42:35.0	ON	ACK	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		1	MFV2	CTSF00P2
09/09/10 18:42:36.0	ON	ACK	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		1	MFV2	CTSF00P2
09/09/10 18:42:36.0	ON	ACK	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		1	MFV2	CTSF00P2
09/09/10 18:42:36.0	ON	ACK	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		1	MFV2	CTSF00P2
09/09/10 18:42:37.0	LOW	ACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW		MFV2	CTSF00P2
09/09/10 18:42:37.0	ON	ACK	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		1	MFV2	CTSF00P2
09/09/10 18:42:38.0	ON	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1	MFV2	CTSF00P2
09/09/10 18:42:38.0	ON	ACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		1	MFV2	CTSF00P2
09/09/10 18:44:09.0		Login	ODN\FHS2Admin	AutoLogin			System	CTSF0Admin4
09/09/10 18:44:10.0		System	Status	Citect USA - 2009/10/22 - C14 - 9/8/2010 09:00:00 AM			System	CTSF0Admin4
09/09/10 18:46:15.6	ON	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		1		
09/09/10 18:47:24.8	OFF	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		0		
09/09/10 18:48:57.0	OFF	CLEAR	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		0	mbma	CTBRTOP2
09/09/10 18:48:57.0	ON	ACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		0	mbma	CTBRTOP2
09/09/10 18:49:04.0	OFF	ACK	BMD_FQI010_DP_BRT	Mcdnld Mstr Met In Vol Day Proj Calculated	LOW	230.87		
09/09/10 18:49:49.0	OFF	CLEAR	BMD_FQI010_DP_BRT	Mcdnld Mstr Met In Vol Day Proj Calculated	OFF	230.87	MFV2	CTSF00P2
09/09/10 18:50:14.6	OFF	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0		
09/09/10 18:50:15.5	OFF	ACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW			
09/09/10 18:50:23.0	OFF	CLEAR	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0	MFV2	CTSF00P2
09/09/10 18:50:23.0	OFF	CLEAR	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	OFF		MFV2	CTSF00P2
09/09/10 18:50:59.7	ON	UNACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1		
09/09/10 18:51:00.3	LOW	UNACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW			
09/09/10 18:51:51.0	LOW	ACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW		J1Gw	CTSF00P4
09/09/10 18:51:52.0	ON	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1		
09/09/10 18:52:50.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 18:54:34.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	J1Gw	CTSF00P4
09/09/10 18:55:18.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 18:55:19.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 18:59:50.6	LL	UNACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW LOW			
09/09/10 19:00:52.0	LL	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW LOW		axa1	CTBRTOP3
09/09/10 19:01:05.0	OFF	ACK	GIN_AI0600_LP_BRT	L101 Pck/Dft Calculated	LOW	0		
09/09/10 19:01:29.2	OFF	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0		
09/09/10 19:01:29.9	HIGH	UNACK	MMT_ZT0029_BRT	Mlpts-Ter Mix Bypass V29 Pct Op	HIGH			
09/09/10 19:01:34.0		Alarm	NSU_FI0001_BRT	Low Setpoint		3.5	SMGb	CTBRTOP4
09/09/10 19:01:44.0	OFF	CLEAR	GIN_AI0600_LP_BRT	L101 Pck/Dft Calculated	OFF	0	MFV2	CTSF00P2
09/09/10 19:01:44.0	HIGH	ACK	MMT_ZT0029_BRT	Mlpts-Ter Mix Bypass V29 Pct Op	HIGH		MFV2	CTSF00P2
09/09/10 19:01:44.0	OFF	CLEAR	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0	MFV2	CTSF00P2
09/09/10 19:01:45.0	OFF	CLEAR	GIN_AI0600_LP_BRT	L101 Pck/Dft Calculated	OFF	0		
09/09/10 19:02:14.5	ON	UNACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1		
09/09/10 19:02:15.2	OFF	ACK	MMT_ZT0029_BRT	Mlpts-Ter Mix Bypass V29 Pct Op	HIGH			
09/09/10 19:02:24.0	OFF	CLEAR	MMT_ZT0029_BRT	Mlpts-Ter Mix Bypass V29 Pct Op	OFF		mbma	CTBRTOP2
09/09/10 19:02:59.3	OFF	UNACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0		
09/09/10 19:03:00.4	OFF	ACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		0		
09/09/10 19:03:00.4	OFF	ACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW			
09/09/10 19:03:00.9	OFF	ACK	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		0		
09/09/10 19:03:00.9	OFF	ACK	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		0		
09/09/10 19:03:00.9	OFF	ACK	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		0		
09/09/10 19:03:00.9	OFF	ACK	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		0		
09/09/10 19:03:00.9	OFF	ACK	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		0		
09/09/10 19:03:00.9	OFF	ACK	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		0		
09/09/10 19:03:00.9	OFF	ACK	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		0		
09/09/10 19:03:00.9	OFF	ACK	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		0		
09/09/10 19:03:00.9	OFF	ACK	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		0		
09/09/10 19:03:00.9	OFF	ACK	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		0		
09/09/10 19:03:00.9	OFF	ACK	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		0		
09/09/10 19:03:02.0	OFF	CLEAR	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		0		
09/09/10 19:03:04.0	OFF	CLEAR	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		0		
09/09/10 19:03:04.0	OFF	CLEAR	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		0		
09/09/10 19:03:04.0	OFF	CLEAR	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		0		
09/09/10 19:03:04.0	OFF	CLEAR	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		0		
09/09/10 19:03:04.0	OFF	CLEAR	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		0		
09/09/10 19:03:04.0	OFF	CLEAR	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		0		
09/09/10 19:03:04.0	OFF	CLEAR	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		0		
09/09/10 19:03:04.0	OFF	CLEAR	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		0		
09/09/10 19:03:04.0	OFF	CLEAR	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		0		
09/09/10 19:03:04.0	OFF	CLEAR	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		0		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 19:03:04.0	OFF	CLEAR	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		0		
09/09/10 19:03:25.0	OFF	CLEAR	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	OFF	0	axa1	CTBRTOP3
09/09/10 19:03:25.0	OFF	CLEAR	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0	axa1	CTBRTOP3
09/09/10 19:03:25.0	ON	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0		
09/09/10 19:03:44.6	ON	UNACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1		
09/09/10 19:03:45.3	ON	UNACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		1		
09/09/10 19:03:45.3	LOW	UNACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW	1		
09/09/10 19:03:45.8	ON	UNACK	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		1		
09/09/10 19:03:45.8	ON	UNACK	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		1		
09/09/10 19:03:45.8	ON	UNACK	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		1		
09/09/10 19:03:45.8	ON	UNACK	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		1		
09/09/10 19:03:45.8	ON	UNACK	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		1		
09/09/10 19:03:45.8	ON	UNACK	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		1		
09/09/10 19:03:45.8	ON	UNACK	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		1		
09/09/10 19:03:45.8	ON	UNACK	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		1		
09/09/10 19:03:45.8	ON	UNACK	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		1		
09/09/10 19:03:45.8	ON	UNACK	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		1		
09/09/10 19:03:45.8	ON	UNACK	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		1		
09/09/10 19:04:41.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 19:04:46.0	ON	ACK	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		1	axa1	CTBRTOP3
09/09/10 19:04:46.0	ON	ACK	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		1	axa1	CTBRTOP3
09/09/10 19:04:46.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	axa1	CTBRTOP3
09/09/10 19:04:47.0	ON	ACK	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		1	axa1	CTBRTOP3
09/09/10 19:04:47.0	ON	ACK	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		1	axa1	CTBRTOP3
09/09/10 19:04:48.0	ON	ACK	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		1	axa1	CTBRTOP3
09/09/10 19:04:48.0	ON	ACK	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		1	axa1	CTBRTOP3
09/09/10 19:04:48.0	ON	ACK	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		1	axa1	CTBRTOP3
09/09/10 19:04:49.0	ON	ACK	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		1	axa1	CTBRTOP3
09/09/10 19:04:49.0	ON	ACK	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		1	axa1	CTBRTOP3
09/09/10 19:04:49.0	ON	ACK	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		1	axa1	CTBRTOP3
09/09/10 19:04:49.0	ON	ACK	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		1	axa1	CTBRTOP3
09/09/10 19:04:50.0	ON	ACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		1		
09/09/10 19:04:50.0	LOW	ACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW	1	axa1	CTBRTOP3
09/09/10 19:04:51.0	ON	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1		
09/09/10 19:06:30.0		Alarm	NSU_PT0003_BRT	Low Setpoint		135	SMGb	CTBRTOP4
09/09/10 19:06:57.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 19:06:58.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 19:07:29.4	OFF	ACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		0		
09/09/10 19:07:32.0	OFF	CLEAR	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		0		
09/09/10 19:08:14.9	ON	UNACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		1		
09/09/10 19:08:34.6	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 19:08:34.6	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 19:08:39.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH		J1Gw	CTSF00P4
09/09/10 19:08:40.0	ON	ACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range		1	J1Gw	CTSF00P4
09/09/10 19:08:40.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH		J1Gw	CTSF00P4
09/09/10 19:08:52.6	OFF	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 19:08:52.6	OFF	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 19:09:00.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF		J1Gw	CTSF00P4
09/09/10 19:09:01.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF		J1Gw	CTSF00P4
09/09/10 19:11:13.4	OFF	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0		
09/09/10 19:11:40.0	OFF	CLEAR	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0	J1Gw	CTSF00P4
09/09/10 19:11:58.7	ON	UNACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1		
09/09/10 19:14:16.0	ON	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1	J1Gw	CTSF00P4
09/09/10 19:15:44.6	OFF	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0		
09/09/10 19:16:28.9	ON	UNACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1		
09/09/10 19:17:08.0	ON	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		1	J1Gw	CTSF00P4
09/09/10 19:19:04.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 19:19:16.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	axa1	CTBRTOP3
09/09/10 19:19:50.7	LOW	UNACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW			
09/09/10 19:21:03.0	LOW	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW			
09/09/10 19:21:24.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 19:21:25.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 19:21:48.9	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 19:21:48.9	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 19:22:06.9	OFF	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 19:22:06.9	OFF	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 19:22:51.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF			
09/09/10 19:22:51.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH		J1Gw	CTSF00P4
09/09/10 19:22:52.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF			
09/09/10 19:22:52.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 19:24:35.9	ON	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		1		
09/09/10 19:25:02.0	ON	ACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		1	J1Gw	CTSF00P4
09/09/10 19:25:20.4	OFF	ACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		0		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 19:25:40.8	ON	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		1		
09/09/10 19:26:00.7	OFF	UNACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		0		
09/09/10 19:26:19.0	OFF	CLEAR	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		0	J1Gw	CTSF00P4
09/09/10 19:26:19.0	ON	ACK	MMG_ES0008_BRT	Moss-Ld-M2 6+7 Metr1 Partial Fai		0	J1Gw	CTSF00P4
09/09/10 19:27:23.8	HIGH	UNACK	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	HIGH			
09/09/10 19:27:25.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 19:27:37.0	HIGH	ACK	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	HIGH		J1Gw	CTSF00P4
09/09/10 19:27:37.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	J1Gw	CTSF00P4
09/09/10 19:28:25.8	ON	UNACK	K15_FS0001A_BRT	Panoche L2 To L300A Backflow		1		
09/09/10 19:28:50.2	OFF	UNACK	K15_FS0001A_BRT	Panoche L2 To L300A Backflow		0		
09/09/10 19:29:03.0	OFF	CLEAR	K15_FS0001A_BRT	Panoche L2 To L300A Backflow		0	axa1	CTBRT0P3
09/09/10 19:29:03.0	ON	ACK	K15_FS0001A_BRT	Panoche L2 To L300A Backflow		0	axa1	CTBRT0P3
09/09/10 19:29:09.0		Setpoint	NMA_PIC010_CMD0	MRTIN-STA L132 D/S PRESS SP		0	BDMh	CTSF00P3
09/09/10 19:29:14.2	ON	UNACK	K15_FS0001A_BRT	Panoche L2 To L300A Backflow		1		
09/09/10 19:29:37.9	OFF	ACK	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	HIGH			
09/09/10 19:29:43.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 19:29:43.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 19:29:45.0		Setpoint	NMA_PIC013_CMD0	MRTIN-STA L132 BYP PRESS SP		0	BDMh	CTSF00P3
09/09/10 19:30:42.8	HIGH	UNACK	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	HIGH			
09/09/10 19:31:07.6	OFF	UNACK	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	HIGH			
09/09/10 19:31:26.0		System	Status	User Shutdown, Logoff			axa1	CTBRT0P3
09/09/10 19:31:31.0		System	Status	User Shutdown, Logoff			SMGb	CTBRT0P4
09/09/10 19:31:45.0	OFF	CLEAR	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	OFF		MFV2	CTSF00P2
09/09/10 19:31:45.0	HIGH	ACK	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	HIGH		MFV2	CTSF00P2
09/09/10 19:31:45.0	ON	ACK	K15_FS0001A_BRT	Panoche L2 To L300A Backflow		1	MFV2	CTSF00P2
09/09/10 19:34:30.4	ON	UNACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		1		
09/09/10 19:35:15.4	OFF	UNACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 19:36:03.0	OFF	CLEAR	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0	J1Gw	CTSF00P4
09/09/10 19:36:03.0	ON	ACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0	J1Gw	CTSF00P4
09/09/10 19:36:12.8	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 19:36:12.8	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 19:36:29.9	OFF	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 19:36:29.9	OFF	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 19:36:37.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF		J1Gw	CTSF00P4
09/09/10 19:36:37.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH		J1Gw	CTSF00P4
09/09/10 19:36:38.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF		J1Gw	CTSF00P4
09/09/10 19:36:38.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH		J1Gw	CTSF00P4
09/09/10 19:37:34.0	ON	UNACK	CoCo_PP_Meter_Timeout	CoCo_PP_Meter RTU Failed		1		
09/09/10 19:37:41.8	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 19:37:41.8	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 19:37:59.8	OFF	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 19:37:59.8	OFF	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 19:38:07.8	ON	UNACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		1		
09/09/10 19:38:11.0	ON	ACK	CoCo_PP_Meter_Timeout	CoCo_PP_Meter RTU Failed		1	J1Gw	CTSF00P4
09/09/10 19:38:11.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF		J1Gw	CTSF00P4
09/09/10 19:38:11.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH		J1Gw	CTSF00P4
09/09/10 19:38:12.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF		J1Gw	CTSF00P4
09/09/10 19:38:12.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH		J1Gw	CTSF00P4
09/09/10 19:38:13.0	ON	ACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		1	J1Gw	CTSF00P4
09/09/10 19:38:28.3	OFF	ACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0		
09/09/10 19:38:51.0	OFF	CLEAR	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0	MFV2	CTSF00P2
09/09/10 19:39:49.0	OFF	CLEAR	CoCo_PP_Meter_Timeout	CoCo_PP_Meter RTU Failed		0		
09/09/10 19:39:49.3	OFF	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW			
09/09/10 19:39:50.0	OFF	ACK	CoCo_PP_Meter_Timeout	CoCo_PP_Meter RTU Failed		0		
09/09/10 19:39:54.0	OFF	CLEAR	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	OFF		mbma	CTBRT0P2
09/09/10 19:40:11.0		System	Status	User Shutdown, Logoff			mbma	CTBRT0P2
09/09/10 19:42:45.2	ON	UNACK	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		1		
09/09/10 19:42:51.0	ON	ACK	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		1	J1Gw	CTSF00P4
09/09/10 19:44:15.3	ON	UNACK	MMT_FA0014R_BRT	Mil-Ter M14 Backflow Alarm		1		
09/09/10 19:44:16.9	HIGH	UNACK	MMT_FT0007_BRT	Mil-Ter M7 Diff Pressure	HIGH			
09/09/10 19:45:01.3	HIGH	UNACK	MMT_FI0032_BRT	Mlpts-Ter L101 M32 Flow	HIGH			
09/09/10 19:45:01.3	HIGH	UNACK	MMT_FI0030_BRT	Mlpts-Ter L100 M30 Flow	HIGH			
09/09/10 19:45:08.9	OFF	ACK	NMA_PS0005_BRT	Mrtin-Sta Gas Sup Rack1 Press Lo		0		
09/09/10 19:45:46.5	HIGH	UNACK	MMT_FT0008_BRT	Mil-Ter M8 Diff Pressure	HIGH			
09/09/10 19:46:14.1	ON	UNACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		1		
09/09/10 19:46:31.5	OFF	UNACK	MMT_FT0007_BRT	Mil-Ter M7 Diff Pressure	HIGH			
09/09/10 19:46:31.5	OFF	UNACK	MMT_FT0008_BRT	Mil-Ter M8 Diff Pressure	HIGH			
09/09/10 19:46:31.5	OFF	UNACK	MMT_FI0032_BRT	Mlpts-Ter L101 M32 Flow	HIGH			
09/09/10 19:46:31.5	OFF	UNACK	MMT_FI0030_BRT	Mlpts-Ter L100 M30 Flow	HIGH			
09/09/10 19:47:52.3	LOW	UNACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	LOW			
09/09/10 19:48:56.0	OFF	UNACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0		
09/09/10 19:49:06.0	ON	ACK	MMT_FA0014R_BRT	Mil-Ter M14 Backflow Alarm		1	MFV2	CTSF00P2
09/09/10 19:49:06.0	LOW	ACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	LOW		MFV2	CTSF00P2

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 19:49:07.0	OFF	CLEAR	MMT_FT0008_BRT	Mil-Ter M8 Diff Pressure	OFF		MFV2	CTSF00P2
09/09/10 19:49:07.0	HIGH	ACK	MMT_FT0008_BRT	Mil-Ter M8 Diff Pressure	HIGH		MFV2	CTSF00P2
09/09/10 19:49:07.0	OFF	CLEAR	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0	MFV2	CTSF00P2
09/09/10 19:49:07.0	ON	ACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0	MFV2	CTSF00P2
09/09/10 19:49:08.0	OFF	CLEAR	MMT_FI0032_BRT	MIpts-Ter L101 M32 Flow	OFF		MFV2	CTSF00P2
09/09/10 19:49:08.0	HIGH	ACK	MMT_FI0032_BRT	MIpts-Ter L101 M32 Flow	HIGH		MFV2	CTSF00P2
09/09/10 19:49:08.0	OFF	CLEAR	MMT_FI0030_BRT	MIpts-Ter L100 M30 Flow	OFF		MFV2	CTSF00P2
09/09/10 19:49:08.0	HIGH	ACK	MMT_FI0030_BRT	MIpts-Ter L100 M30 Flow	HIGH		MFV2	CTSF00P2
09/09/10 19:49:09.0	OFF	CLEAR	NMA_PS0005_BRT	Mrtin-Sta Gas Sup Rack1 Press Lo		0	MFV2	CTSF00P2
09/09/10 19:49:09.0	OFF	CLEAR	MMT_FT0007_BRT	Mil-Ter M7 Diff Pressure	OFF		MFV2	CTSF00P2
09/09/10 19:49:09.0	HIGH	ACK	MMT_FT0007_BRT	Mil-Ter M7 Diff Pressure	HIGH		MFV2	CTSF00P2
09/09/10 19:49:24.4	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 19:49:24.4	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 19:49:40.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			1	
09/09/10 19:49:40.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH		MFV2	CTSF00P2
09/09/10 19:49:41.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH		MFV2	CTSF00P2
09/09/10 19:49:41.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			1	MFV2
09/09/10 19:49:42.3	OFF	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 19:49:42.3	OFF	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 19:50:38.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF		J1Gw	CTSF00P4
09/09/10 19:50:39.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF		J1Gw	CTSF00P4
09/09/10 19:50:39.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF			
09/09/10 19:50:49.5	OFF	ACK	NSF_PT0106_BRT	Potrero-RTU Trans Hdr Press	LOW			
09/09/10 19:52:00.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0	
09/09/10 19:52:00.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed			0	
09/09/10 19:52:38.0	OFF	CLEAR	NSF_PT0106_BRT	Potrero-RTU Trans Hdr Press	OFF		J1Gw	CTSF00P4
09/09/10 19:52:59.4	ON	UNACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		1		
09/09/10 19:54:00.4	OFF	UNACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0		
09/09/10 19:54:38.2	LOW	UNACK	ABC_PT0001_BRT	Buck-Crk U/S Press	LOW			
09/09/10 19:55:23.0	OFF	CLEAR	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0	MFV2	CTSF00P2
09/09/10 19:55:23.0	ON	ACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0	MFV2	CTSF00P2
09/09/10 19:55:23.0	LOW	ACK	ABC_PT0001_BRT	Buck-Crk U/S Press	LOW		MFV2	CTSF00P2
09/09/10 19:55:59.7	OFF	ACK	NSU_FI0001_BRT	Slvn-Ave M-1 Flow	HIGH			
09/09/10 19:56:54.2	HIGH	UNACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 19:57:13.8	OFF	UNACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 19:57:34.2	HIGH	UNACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 19:57:54.4	OFF	ACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 19:57:57.0	HIGH	ACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH		J1Gw	CTSF00P4
09/09/10 19:58:01.0	OFF	CLEAR	NSU_FI0001_BRT	Slvn-Ave M-1 Flow	OFF		J1Gw	CTSF00P4
09/09/10 19:58:03.9	ON	UNACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		1		
09/09/10 19:58:08.0	OFF	CLEAR	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	OFF		J1Gw	CTSF00P4
09/09/10 19:58:08.0	ON	ACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		1	J1Gw	CTSF00P4
09/09/10 19:58:46.3	OFF	ACK	NMA_PS0006_BRT	Mrtin-Sta Gas Sup Rack2 Press Lo		0		
09/09/10 19:58:47.2	LOW	UNACK	NMA_PT0011_BRT	Mrtin-Sta L132 D/S Press	LOW			
09/09/10 19:59:44.3	LOW	UNACK	NSU_FI0001_BRT	Slvn-Ave M-1 Flow	LOW			
09/09/10 19:59:45.3	OFF	ACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0		
09/09/10 20:00:07.0	OFF	CLEAR	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0	J1Gw	CTSF00P4
09/09/10 20:00:08.0	LOW	ACK	NSU_FI0001_BRT	Slvn-Ave M-1 Flow	LOW		J1Gw	CTSF00P4
09/09/10 20:00:08.0	LOW	ACK	NMA_PT0011_BRT	Mrtin-Sta L132 D/S Press	LOW		J1Gw	CTSF00P4
09/09/10 20:00:09.0	OFF	CLEAR	NMA_PS0006_BRT	Mrtin-Sta Gas Sup Rack2 Press Lo		0	J1Gw	CTSF00P4
09/09/10 20:00:09.3	OFF	ACK	NMA_PT0011_BRT	Mrtin-Sta L132 D/S Press	LOW			
09/09/10 20:00:24.0	OFF	CLEAR	NMA_PT0011_BRT	Mrtin-Sta L132 D/S Press	OFF		J1Gw	CTSF00P4
09/09/10 20:01:03.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 20:01:12.7	LL	UNACK	KH2_AT1222_BRT	Hinkley L300B CUR Tot Odorant (TBM+THT)	LOW LOW			
09/09/10 20:02:34.8	HIGH	UNACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 20:03:08.6	ON	UNACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		1		
09/09/10 20:03:17.0	ON	ACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		1	BDMh	CTSF00P3
09/09/10 20:03:18.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 20:03:18.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	BDMh	CTSF00P3
09/09/10 20:03:18.0	HIGH	ACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH		BDMh	CTSF00P3
09/09/10 20:03:19.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 20:03:19.0	LL	ACK	KH2_AT1222_BRT	Hinkley L300B CUR Tot Odorant (TBM+THT)	LOW LOW		BDMh	CTSF00P3
09/09/10 20:03:35.4	OFF	ACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 20:04:31.0	ON	UNACK	LRCV_71B_Timeout	LRCV_71B RTU Failed		1		
09/09/10 20:04:31.1	ON	UNACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		1		
09/09/10 20:05:16.2	OFF	UNACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 20:06:10.5	OFF	ACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0		
09/09/10 20:06:26.0	OFF	CLEAR	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0	BDMh	CTSF00P3
09/09/10 20:06:26.0	ON	ACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0	BDMh	CTSF00P3
09/09/10 20:06:26.0	ON	ACK	LRCV_71B_Timeout	LRCV_71B RTU Failed		1	BDMh	CTSF00P3
09/09/10 20:06:27.0	OFF	CLEAR	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0	BDMh	CTSF00P3
09/09/10 20:06:28.0	OFF	CLEAR	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	OFF		BDMh	CTSF00P3
09/09/10 20:06:40.3	LOW	UNACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW			

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 20:06:49.0	OFF	CLEAR	LRCV_71B_Timeout	LRCV_71B RTU Failed		0		
09/09/10 20:06:49.0	OFF	ACK	LRCV_71B_Timeout	LRCV_71B RTU Failed		0		
09/09/10 20:09:32.4	ON	UNACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		1		
09/09/10 20:13:00.5	ON	UNACK	BBC_ET0009_00R	Bethany K2 Feeder Current Out of Range		1		
09/09/10 20:14:55.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 20:16:06.6	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 20:16:06.6	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 20:16:20.2	OFF	UNACK	BBC_ET0009_00R	Bethany K2 Feeder Current Out of Range		0		
09/09/10 20:16:24.6	OFF	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 20:16:24.6	OFF	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 20:17:17.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 20:18:45.0	ON	UNACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		1		
09/09/10 20:19:34.0	ON	ACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		1 BDMh		CTSF00P3
09/09/10 20:19:34.0	ON	ACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		1 BDMh		CTSF00P3
09/09/10 20:19:35.0	LOW	ACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW	BDMh		CTSF00P3
09/09/10 20:19:36.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF	BDMh		CTSF00P3
09/09/10 20:19:36.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH	BDMh		CTSF00P3
09/09/10 20:19:36.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF	BDMh		CTSF00P3
09/09/10 20:19:36.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH	BDMh		CTSF00P3
09/09/10 20:19:37.0	OFF	CLEAR	BBC_ET0009_00R	Bethany K2 Feeder Current Out of Range		0 BDMh		CTSF00P3
09/09/10 20:19:37.0	ON	ACK	BBC_ET0009_00R	Bethany K2 Feeder Current Out of Range		0 BDMh		CTSF00P3
09/09/10 20:19:37.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0 BDMh		CTSF00P3
09/09/10 20:19:37.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0 BDMh		CTSF00P3
09/09/10 20:19:42.7	LOW	UNACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW			
09/09/10 20:19:50.0	LOW	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW		J1Gw	CTSF00P4
09/09/10 20:21:18.0	OFF	CLEAR	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		0		
09/09/10 20:21:19.0	OFF	ACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		0		
09/09/10 20:22:13.0	ON	UNACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		1		
09/09/10 20:22:39.4	LOW	UNACK	SSD_PT0001_BRT	Smud-Int L400 Press	LOW			
09/09/10 20:22:58.0	ON	ACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		1		
09/09/10 20:22:59.0	LOW	ACK	SSD_PT0001_BRT	Smud-Int L400 Press	LOW		KLM7	CTSF00P5
09/09/10 20:23:17.0	ON	UNACK	LRCV_71A_Timeout	LRCV_71A RTU Failed		1		
09/09/10 20:23:57.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 20:24:47.0	ON	ACK	LRCV_71A_Timeout	LRCV_71A RTU Failed		1 BDMh		CTSF00P3
09/09/10 20:24:47.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1 BDMh		CTSF00P3
09/09/10 20:25:33.0	OFF	CLEAR	LRCV_71A_Timeout	LRCV_71A RTU Failed		0		
09/09/10 20:25:33.0	OFF	ACK	LRCV_71A_Timeout	LRCV_71A RTU Failed		0		
09/09/10 20:25:34.0		Setpoint	AAN_PIC152TD_CMD0	Antioch V152 D/S Pr Sp		660 BDMh		CTSF00P3
09/09/10 20:25:35.3	HIGH	UNACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 20:25:55.2	OFF	UNACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 20:26:07.0	OFF	CLEAR	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	OFF		J1Gw	CTSF00P4
09/09/10 20:26:07.0	HIGH	ACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH		J1Gw	CTSF00P4
09/09/10 20:26:15.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 20:26:15.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 20:26:19.0		Setpoint	ACD_PIC007_CMD0	Creed V7 D/S Press Sp		500 BDMh		CTSF00P3
09/09/10 20:26:45.7	LL	UNACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW LOW			
09/09/10 20:26:50.0		Setpoint	NMA_PIC010_CMD0	MRTIN-STA L132 D/S PRESS SP		145 KLM7		CTSF00P5
09/09/10 20:27:15.6	HIGH	UNACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 20:27:24.0	HIGH	ACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 20:27:24.0		Setpoint	AAN_PIC152TD_CMD0	Antioch V152 D/S Pr Sp		670 BDMh		CTSF00P3
09/09/10 20:27:25.0	LL	ACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW LOW			
09/09/10 20:27:44.0	OFF	CLEAR	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		0		
09/09/10 20:27:45.0	OFF	ACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		0		
09/09/10 20:27:56.0		Setpoint	AAN_PIC152TU_CMD0	Antioch V152 U/S Pr Sp		450 BDMh		CTSF00P3
09/09/10 20:28:08.0		Setpoint	NMA_PIC013_CMD0	MRTIN-STA L132 BYP PRESS SP		135 KLM7		CTSF00P5
09/09/10 20:28:39.5	LOW	UNACK	NMA_PT0011_BRT	Mrtin-Sta L132 D/S Press	LOW			
09/09/10 20:28:40.0		Setpoint	AAN_PIC154TD_CMD0	Antioch V154 D/S Pr Sp		670 BDMh		CTSF00P3
09/09/10 20:28:53.0	LOW	ACK	NMA_PT0011_BRT	Mrtin-Sta L132 D/S Press	LOW		J1Gw	CTSF00P4
09/09/10 20:30:06.3	LL	UNACK	ABC_PT0001_BRT	Buck-Crk U/S Press	LOW LOW			
09/09/10 20:30:22.0	LL	ACK	ABC_PT0001_BRT	Buck-Crk U/S Press	LOW LOW		J1Gw	CTSF00P4
09/09/10 20:31:30.0		Command	ALI_YS0002_CMD1	V101 Open			MFV2	CTSF00P2
09/09/10 20:31:30.5	HH	UNACK	AAN_FI0022B_BRT	Antioch T22 L303-400 Flow	HIGH HIGH			
09/09/10 20:31:39.0	OFF	ACK	ALI_YS0002_BRT	Lodi-Field Station Flow Shutin		0		
09/09/10 20:31:58.0	OFF	ACK	ALI_ZS0006_0_BRT	Lodi-Field V101 Not Open		0		
09/09/10 20:31:58.9	HH	UNACK	ACF_FI0001_BRT	Calpine-Ant Flow Rate	HIGH HIGH			
09/09/10 20:32:10.9	HIGH	UNACK	AAN_FI0022B_BRT	Antioch T22 L303-400 Flow	HIGH			
09/09/10 20:32:12.3	LOW	UNACK	ACD_PT0088_BRT	Creed L210W Press	LOW			
09/09/10 20:32:52.6	OFF	ACK	SSD_PT0001_BRT	Smud-Int L400 Press	LOW			
09/09/10 20:33:07.0	LOW	ACK	ACD_PT0088_BRT	Creed L210W Press	LOW		J1Gw	CTSF00P4
09/09/10 20:33:08.0	OFF	CLEAR	SSD_PT0001_BRT	Smud-Int L400 Press	OFF		J1Gw	CTSF00P4
09/09/10 20:33:08.0	HIGH	ACK	AAN_FI0022B_BRT	Antioch T22 L303-400 Flow	HIGH		J1Gw	CTSF00P4
09/09/10 20:33:09.0	OFF	CLEAR	ALI_YS0002_BRT	Lodi-Field Station Flow Shutin		0 J1Gw		CTSF00P4
09/09/10 20:33:09.0	OFF	CLEAR	ALI_ZS0006_0_BRT	Lodi-Field V101 Not Open		0 J1Gw		CTSF00P4

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 20:33:12.0	HH	ACK	ACF_FI0001_BRT	Calpine-Ant Flow Rate	HIGH HIGH		J1Gw	CTSF00P4
09/09/10 20:33:40.3	OFF	ACK	K15_FS0001A_BRT	Panoche L2 To L300A Backflow		0		
09/09/10 20:34:07.0		Setpoint	AAN_PIC154TD_CMD0	Antioch V154 D/S Pr Sp		710	BDMh	CTSF00P3
09/09/10 20:34:16.0	OFF	CLEAR	K15_FS0001A_BRT	Panoche L2 To L300A Backflow		0	J1Gw	CTSF00P4
09/09/10 20:34:28.7	ON	UNACK	K15_FS0001A_BRT	Panoche L2 To L300A Backflow		1		
09/09/10 20:34:45.0	ON	ACK	K15_FS0001A_BRT	Panoche L2 To L300A Backflow		1	J1Gw	CTSF00P4
09/09/10 20:34:54.2	OFF	ACK	ACF_FI0001_BRT	Calpine-Ant Flow Rate	HIGH HIGH			
09/09/10 20:35:02.0	OFF	CLEAR	ACF_FI0001_BRT	Calpine-Ant Flow Rate	OFF		J1Gw	CTSF00P4
09/09/10 20:35:02.3	OFF	ACK	AAN_FI0022B_BRT	Antioch T22 L303-400 Flow	HIGH			
09/09/10 20:35:12.0	OFF	CLEAR	AAN_FI0022B_BRT	Antioch T22 L303-400 Flow	OFF		J1Gw	CTSF00P4
09/09/10 20:35:13.0	OFF	CLEAR	AAN_FI0022B_BRT	Antioch T22 L303-400 Flow	OFF			
09/09/10 20:35:29.7	OFF	ACK	NMA_PT0011_BRT	Mrtin-Sta L132 D/S Press	LOW			
09/09/10 20:36:15.0	OFF	CLEAR	NMA_PT0011_BRT	Mrtin-Sta L132 D/S Press	OFF		J1Gw	CTSF00P4
09/09/10 20:36:55.3	OFF	ACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0		
09/09/10 20:37:06.5	OFF	ACK	K15_FS0001A_BRT	Panoche L2 To L300A Backflow		0		
09/09/10 20:37:51.8	LOW	UNACK	ABC_PT0001_BRT	Buck-Crk U/S Press	LOW			
09/09/10 20:38:25.0		Login	ODN\FHS2Admin	AutoLogin			System	CTSF0Admin3
09/09/10 20:38:26.0		System	Status	Citect USA - 2009/10/22 - C14 - 9/8/2010 09:00:00			System	CTSF0Admin3
09/09/10 20:38:27.0	OFF	CLEAR	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0	J1Gw	CTSF00P4
09/09/10 20:38:28.0	OFF	CLEAR	K15_FS0001A_BRT	Panoche L2 To L300A Backflow		0	J1Gw	CTSF00P4
09/09/10 20:38:52.0		Setpoint	NMA_PIC013_CMD0	MRTIN-Sta L132 BYP PRESS SP		140	KLM7	CTSF00P5
09/09/10 20:39:01.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 20:39:21.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	J1Gw	CTSF00P4
09/09/10 20:39:22.0	LOW	ACK	ABC_PT0001_BRT	Buck-Crk U/S Press	LOW			
09/09/10 20:39:37.6	ON	UNACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		1		
09/09/10 20:39:52.9	OFF	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW			
09/09/10 20:40:10.0		Alarm	ACD_PT0088_BRT	Low Setpoint		495	J1Gw	CTSF00P4
09/09/10 20:40:10.0	OFF	ACK	ACD_PT0088_BRT	Creed L210W Press	LOW			
09/09/10 20:40:15.0		Setpoint	NMA_PIC013_CMD0	MRTIN-Sta L132 BYP PRESS SP		145	KLM7	CTSF00P5
09/09/10 20:40:19.0	OFF	CLEAR	ACD_PT0088_BRT	Creed L210W Press	OFF		J1Gw	CTSF00P4
09/09/10 20:40:20.0	OFF	CLEAR	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	OFF		J1Gw	CTSF00P4
09/09/10 20:40:20.0	OFF	CLEAR	ACD_PT0088_BRT	Creed L210W Press	OFF			
09/09/10 20:40:21.0	ON	ACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		1	J1Gw	CTSF00P4
09/09/10 20:40:29.3	ON	UNACK	NMA_PS0006_BRT	Mrtin-Sta Gas Sup Rack2 Press Lo		1		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0071_ERROR_SF0	Mil-Ter Mon V71 Error		1		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0071_ERROR_BRT	Mil-Ter Mon V71 Error		1		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0070_ERROR_SF0	Mil-Ter Mon V70 Error		0		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0070_ERROR_BRT	Mil-Ter Mon V70 Error		0		
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0070_0_BRT	Mil-Ter Mon V70 Not Open		0		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0070_ERROR_SF0	Mil-Ter Mon V70 Error		1		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0070_ERROR_BRT	Mil-Ter Mon V70 Error		1		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0067_ERROR_SF0	Mil-Ter Mon V67 Error		0		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0067_ERROR_BRT	Mil-Ter Mon V67 Error		0		
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0067_0_BRT	Mil-Ter Mon V67 Not Open		0		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0067_ERROR_SF0	Mil-Ter Mon V67 Error		1		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0067_ERROR_BRT	Mil-Ter Mon V67 Error		1		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0066_ERROR_SF0	Mil-Ter Mon V66 Error		0		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0066_ERROR_BRT	Mil-Ter Mon V66 Error		0		
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0066_0_BRT	Mil-Ter Mon V66 Not Open		0		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0066_ERROR_SF0	Mil-Ter Mon V66 Error		1		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0066_ERROR_BRT	Mil-Ter Mon V66 Error		1		
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0063_0_BRT	Mil-Ter V63 Not Open		0		
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0039_0_BRT	Mil-Ter V39 Not Open		0		
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0037_0_BRT	Mil-Ter V37 Not Open		0		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0028_ERROR_SF0	Mil-Ter Mon V28 Error		0		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0028_ERROR_BRT	Mil-Ter Mon V28 Error		0		
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0028_0_BRT	Mil-Ter Byp Mon V28 Not Open		0		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0028_ERROR_SF0	Mil-Ter Mon V28 Error		1		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0028_ERROR_BRT	Mil-Ter Mon V28 Error		1		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0026_ERROR_SF0	Mil-Ter Mon V26 Error		0		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0026_ERROR_BRT	Mil-Ter Mon V26 Error		0		
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0026_0_BRT	Mil-Ter Mon V26 Not Open		0		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0026_ERROR_SF0	Mil-Ter Mon V26 Error		1		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0026_ERROR_BRT	Mil-Ter Mon V26 Error		1		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0020_ERROR_SF0	Mil-Ter Mon V20 Error		0		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0020_ERROR_BRT	Mil-Ter Mon V20 Error		0		
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0020_0_BRT	Mil-Ter Mon V20 Not Open		0		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0020_ERROR_SF0	Mil-Ter Mon V20 Error		1		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0020_ERROR_BRT	Mil-Ter Mon V20 Error		1		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0016_ERROR_SF0	Mil-Ter Mon V16 Error		0		
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0016_ERROR_BRT	Mil-Ter Mon V16 Error		0		
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0016_0_BRT	Mil-Ter Mon V16 Not Open		0		
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0016_ERROR_SF0	Mil-Ter Mon V16 Error		1		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0016_ERROR_BRT	Mil-Ter Mon V16 Error			1	
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0006_ERROR_SF0	Mil-Ter Mon V6 Error			0	
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0006_ERROR_BRT	Mil-Ter Mon V6 Error			0	
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0006_0_BRT	Mil-Ter Mon V6 Not Open			0	
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0006_ERROR_SF0	Mil-Ter Mon V6 Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0006_ERROR_BRT	Mil-Ter Mon V6 Error			1	
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0005_ERROR_SF0	Mil-Ter Mon V5 Error			0	
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0005_ERROR_BRT	Mil-Ter Mon V5 Error			0	
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0005_0_BRT	Mil-Ter Mon V5 Not Open			0	
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0005_ERROR_SF0	Mil-Ter Mon V5 Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0005_ERROR_BRT	Mil-Ter Mon V5 Error			1	
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0004_ERROR_SF0	Mil-Ter Mon V4 Error			0	
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0004_ERROR_BRT	Mil-Ter Mon V4 Error			0	
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0004_0_BRT	Mil-Ter Mon V4 Not Open			0	
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0004_ERROR_SF0	Mil-Ter Mon V4 Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0004_ERROR_BRT	Mil-Ter Mon V4 Error			1	
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0003_ERROR_SF0	Mil-Ter Mon V3 Error			0	
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0003_ERROR_BRT	Mil-Ter Mon V3 Error			0	
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0003_0_BRT	Mil-Ter Mon V3 Not Open			0	
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0003_ERROR_SF0	Mil-Ter Mon V3 Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ZS0003_ERROR_BRT	Mil-Ter Mon V3 Error			1	
09/09/10 20:40:29.7	OFF	ACK	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo			0	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0008_BRT	Mil-Ter V8 Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0010_BRT	Mil-Ter V10 Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0013_BRT	Mil-Ter V13 Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error			1	
09/09/10 20:40:29.7	ON	UNACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error			1	
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0071_ERROR_SF0	Mil-Ter Mon V71 Error			0	
09/09/10 20:40:29.7	OFF	UNACK	MMT_ZS0071_ERROR_BRT	Mil-Ter Mon V71 Error			0	
09/09/10 20:40:29.7	OFF	ACK	MMT_ZS0071_0_BRT	Mil-Ter Mon V71 Not Open			0	
09/09/10 20:40:30.4	OFF	ACK	MMT_PT0021D_OOR	Mil-Ter V21R D/S Pres Out of Range			0	
09/09/10 20:40:30.4	HIGH	UNACK	MMT_ZT0029_BRT	Mlpts-Ter Mix Bypass V29 Pct Op	HIGH			
09/09/10 20:40:30.4	OFF	ACK	MMT_PT0010BR_BRT	Mil-Ter Uic 10R U/S Pres	LOW			
09/09/10 20:40:30.4	OFF	ACK	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0008_OOR	Mlpts-Ter L300B Press Out of Range			0	
09/09/10 20:40:30.9	OFF	ACK	MMT_LT0001A_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range			0	
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0050_BRT	Mlpts-Ter Sjdfrm V50 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0049_BRT	Mlpts-Ter L132 V49 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0048_BRT	Mlpts-Ter L101 V48 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0045_BRT	Mlpts-Ter L109 V45 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0087_BRT	Mlpts-Ter L100 Press	LOW LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0087_OOR	Mlpts-Ter L100 Press Out of Range			0	
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0084_BRT	Mlpts-Ter L101 Press	LOW LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_LT0001B_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range			0	
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range			0	
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0083_BRT	Mlpts-Ter L132 Press	LOW LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range			0	
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0066_BRT	Mlpts-Ter L107 Mon V66 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range			0	
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0063_BRT	Mlpts-Ter Mon V63 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0071_BRT	Mlpts-Ter L131 Mon V71 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0040_OOR	Mlpts-Ter L109 Press Out of Range			0	
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0009_BRT	Mlpts-Ter Sjdfrm Press	LOW LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range			0	
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0040_BRT	Mlpts-Ter L109 Press	LOW LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range			0	

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0070_BRT	Mlpts-Ter L131 Mon V70 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0067_BRT	Mlpts-Ter L107 Mon V67 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		0		
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0029B_BRT	Mlpts-Ter Mixer D/S Press	LOW LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		0		
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		0		
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		0		
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0003_BRT	Mlpts-Ter M10 Mon V3 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0009_OOR	Mlpts-Ter Sjdfm Press Out of Range		0		
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0028_BRT	Mlpts-Ter Byp Mon V28 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0026_BRT	Mlpts-Ter Mixer Mon V26 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0016_BRT	Mlpts-Ter Mixer Mon V16 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0006_BRT	Mlpts-Ter M7 Mon V6 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0005_BRT	Mlpts-Ter M8 Mon V5 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0004_BRT	Mlpts-Ter M9 Mon V4 Pct Op	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0010_OOR	Mlpts-Ter L300A Press Out of Range		0		
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0012_OOR	Mlpts-Ter L131 Press Out of Range		0		
09/09/10 20:40:30.9	LOW	UNACK	MMT_PT0010_BRT	Mlpts-Ter L300A Press	LOW			
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0007_OOR	Mlpts-Ter L107 Press Out of Range		0		
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0017_OOR	Mlpts-Ter Mixer D/S Press Out of Range		0		
09/09/10 20:40:30.9	OFF	ACK	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		0		
09/09/10 20:40:30.9	OFF	ACK	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		0		
09/09/10 20:40:36.0	OFF	CLEAR	MMT_ZT0025_OOR	Mlpts-Ter L300B V25 Pct Op Out of Range		0		
09/09/10 20:40:36.0	OFF	CLEAR	MMT_PT0017_OOR	Mlpts-Ter Mixer D/S Press Out of Range		0		
09/09/10 20:40:36.0	OFF	CLEAR	MMT_PT0007_OOR	Mlpts-Ter L107 Press Out of Range		0		
09/09/10 20:40:36.0	OFF	CLEAR	MMT_PT0012_OOR	Mlpts-Ter L131 Press Out of Range		0		
09/09/10 20:40:36.0	OFF	CLEAR	MMT_PT0010_OOR	Mlpts-Ter L300A Press Out of Range		0		
09/09/10 20:40:36.0	OFF	CLEAR	MMT_PT0021D_OOR	Mil-Ter V21R D/S Press Out of Range		0		
09/09/10 20:40:36.0	OFF	CLEAR	MMT_ZT0004_OOR	Mlpts-Ter M9 Mon V4 Pct Op Out of Range		0		
09/09/10 20:40:36.0	OFF	CLEAR	MMT_ZT0003_OOR	Mlpts-Ter M10 Mon V3 Pct Op Out of Range		0		
09/09/10 20:40:36.0	OFF	CLEAR	MMT_LT0003_OOR	Mlpts-Ter Storage Tank Lvl Out of Range		0		
09/09/10 20:40:36.0	OFF	CLEAR	MMT_LT0002A_OOR	Mlpts-Ter L300B Sep 2 Liq Lvl Out of Range		0		
09/09/10 20:40:36.0	OFF	CLEAR	MMT_PT0029B_OOR	Mlpts-Ter Mixer D/S Press Out of Range		0		
09/09/10 20:40:37.0	OFF	CLEAR	MMT_ZT0067_OOR	Mlpts-Ter L107 Mon V67 Pct Op Out of Range		0		
09/09/10 20:40:37.0	OFF	CLEAR	MMT_PT0040_OOR	Mlpts-Ter L109 Press Out of Range		0		
09/09/10 20:40:37.0	OFF	CLEAR	MMT_PT0009_OOR	Mlpts-Ter Sjdfm Press Out of Range		0		
09/09/10 20:40:37.0	OFF	CLEAR	MMT_ZT0071_OOR	Mlpts-Ter L131 Mon V71 Pct Op Out of Range		0		
09/09/10 20:40:37.0	OFF	CLEAR	MMT_ZT0066_OOR	Mlpts-Ter L107 Mon V66 Pct Op Out of Range		0		
09/09/10 20:40:38.0	OFF	CLEAR	MMT_PT0083_OOR	Mlpts-Ter L132 Press Out of Range		0		
09/09/10 20:40:38.0	OFF	CLEAR	MMT_LT0001A_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range		0		
09/09/10 20:40:38.0	OFF	CLEAR	MMT_PT0084_OOR	Mlpts-Ter L101 Press Out of Range		0		
09/09/10 20:40:38.0	OFF	CLEAR	MMT_PT0087_OOR	Mlpts-Ter L100 Press Out of Range		0		
09/09/10 20:40:38.0	OFF	CLEAR	MMT_PT0008_OOR	Mlpts-Ter L300B Press Out of Range		0		
09/09/10 20:40:38.0	OFF	CLEAR	MMT_LT0001B_OOR	Mlpts-Ter L300A Sep Liq Lvl Out of Range		0		
09/09/10 20:40:40.0	LOW	ACK	MMT_PT0010_BRT	Mlpts-Ter L300A Press	LOW		J1Gw	CTSF00P4
09/09/10 20:40:41.0	ON	ACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:41.0	ON	ACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:41.0	ON	ACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:42.0	HIGH	ACK	MMT_ZT0029_BRT	Mlpts-Ter Mix Bypass V29 Pct Op	HIGH		J1Gw	CTSF00P4
09/09/10 20:40:42.0	ON	ACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:46.0	ON	ACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:46.0	ON	ACK	MMT_ES0013_BRT	Mil-Ter V13 Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:47.0	ON	ACK	MMT_ES0008_BRT	Mil-Ter V8 Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:47.0	ON	ACK	MMT_ES0010_BRT	Mil-Ter V10 Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:47.0	ON	ACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:55.0	ON	ACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:55.0	ON	ACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:56.0	ON	ACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:56.0	ON	ACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:56.0	ON	ACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:40:58.0	ON	ACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error		1	J1Gw	CTSF00P4
09/09/10 20:41:01.2	OFF	UNACK	NMA_PS0006_BRT	Mrtin-Sta Gas Sup Rack2 Press Lo		0		
09/09/10 20:41:01.2	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 20:41:01.2	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 20:41:14.7	OFF	UNACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		0		
09/09/10 20:41:14.7	OFF	UNACK	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error		0		
09/09/10 20:41:14.7	OFF	UNACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		0		
09/09/10 20:41:14.7	OFF	UNACK	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		0		
09/09/10 20:41:14.7	OFF	UNACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error		0		
09/09/10 20:41:14.7	OFF	UNACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		0		
09/09/10 20:41:14.7	OFF	UNACK	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		0		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0008_BRT	Mil-Ter V8 Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0010_BRT	Mil-Ter V10 Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0012_BRT	Mil-Ter V12 Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0013_BRT	Mil-Ter V13 Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0014_BRT	Mil-Ter V14 Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		0		
09/09/10 20:41:14.7	OFF	ACK	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		0		
09/09/10 20:41:14.7	ON	UNACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		1		
09/09/10 20:41:19.3	OFF	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 20:41:19.3	OFF	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 20:41:22.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 20:41:22.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 20:41:31.8	ON	UNACK	RHN_FT0002B_OOR	Herrmann L21-Vallejo Hi Orf Dp Out of Range		1		
09/09/10 20:41:59.0	ON	UNACK	Bethany_K_Timeout	Bethany_K RTU Failed		1		
09/09/10 20:41:59.4	OFF	ACK	MMT_FA0014R_BRT	Mil-Ter M14 Backflow Alarm		0		
09/09/10 20:41:59.4	OFF	UNACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 20:42:01.7	OFF	ACK	MMT_PT0062_OOR	Mlpts-Ter Sta Bypass Press Out of Range		0		
09/09/10 20:42:04.0	OFF	CLEAR	MMT_PT0062_OOR	Mlpts-Ter Sta Bypass Press Out of Range		0		
09/09/10 20:42:09.5	OFF	UNACK	RHN_FT0002B_OOR	Herrmann L21-Vallejo Hi Orf Dp Out of Range		0		
09/09/10 20:42:12.0	OFF	CLEAR	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0	MFV2	CTSF00P2
09/09/10 20:42:12.0	ON	ACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0	MFV2	CTSF00P2
09/09/10 20:42:12.0	OFF	CLEAR	RHN_FT0002B_OOR	Herrmann L21-Vallejo Hi Orf Dp Out of Range		0	MFV2	CTSF00P2
09/09/10 20:42:12.0	ON	ACK	RHN_FT0002B_OOR	Herrmann L21-Vallejo Hi Orf Dp Out of Range		0	MFV2	CTSF00P2
09/09/10 20:42:12.0	ON	ACK	Bethany_K_Timeout	Bethany_K RTU Failed		1	MFV2	CTSF00P2
09/09/10 20:42:13.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF	MFV2		CTSF00P2
09/09/10 20:42:13.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH	MFV2		CTSF00P2
09/09/10 20:42:17.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF	MFV2		CTSF00P2
09/09/10 20:42:17.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH	MFV2		CTSF00P2
09/09/10 20:42:18.0	OFF	CLEAR	MMT_ZS0004_ERROR_BRT	Mil-Ter Mon V4 Error		0	MFV2	CTSF00P2
09/09/10 20:42:18.0	ON	ACK	MMT_ZS0004_ERROR_BRT	Mil-Ter Mon V4 Error		0	MFV2	CTSF00P2
09/09/10 20:42:18.0	OFF	CLEAR	MMT_ZS0003_ERROR_SFO	Mil-Ter Mon V3 Error		0	MFV2	CTSF00P2
09/09/10 20:42:18.0	ON	ACK	MMT_ZS0003_ERROR_SFO	Mil-Ter Mon V3 Error		0	MFV2	CTSF00P2
09/09/10 20:42:18.0	OFF	CLEAR	MMT_ZS0003_ERROR_BRT	Mil-Ter Mon V3 Error		0	MFV2	CTSF00P2
09/09/10 20:42:18.0	ON	ACK	MMT_ZS0003_ERROR_BRT	Mil-Ter Mon V3 Error		0	MFV2	CTSF00P2
09/09/10 20:42:19.0	OFF	CLEAR	MMT_ZS0005_ERROR_BRT	Mil-Ter Mon V5 Error		0	MFV2	CTSF00P2
09/09/10 20:42:19.0	ON	ACK	MMT_ZS0005_ERROR_BRT	Mil-Ter Mon V5 Error		0	MFV2	CTSF00P2
09/09/10 20:42:19.0	OFF	CLEAR	MMT_ZS0004_ERROR_SFO	Mil-Ter Mon V4 Error		0	MFV2	CTSF00P2
09/09/10 20:42:19.0	ON	ACK	MMT_ZS0004_ERROR_SFO	Mil-Ter Mon V4 Error		0	MFV2	CTSF00P2
09/09/10 20:42:20.0	OFF	CLEAR	MMT_ZS0006_ERROR_BRT	Mil-Ter Mon V6 Error		0	MFV2	CTSF00P2
09/09/10 20:42:20.0	ON	ACK	MMT_ZS0006_ERROR_BRT	Mil-Ter Mon V6 Error		0	MFV2	CTSF00P2
09/09/10 20:42:20.0	OFF	CLEAR	MMT_ZS0005_ERROR_SFO	Mil-Ter Mon V5 Error		0	MFV2	CTSF00P2
09/09/10 20:42:20.0	ON	ACK	MMT_ZS0005_ERROR_SFO	Mil-Ter Mon V5 Error		0	MFV2	CTSF00P2
09/09/10 20:42:21.0	OFF	CLEAR	MMT_ZS0016_ERROR_BRT	Mil-Ter Mon V16 Error		0	MFV2	CTSF00P2
09/09/10 20:42:21.0	ON	ACK	MMT_ZS0016_ERROR_BRT	Mil-Ter Mon V16 Error		0	MFV2	CTSF00P2
09/09/10 20:42:21.0	OFF	CLEAR	MMT_ZS0006_ERROR_SFO	Mil-Ter Mon V6 Error		0	MFV2	CTSF00P2
09/09/10 20:42:21.0	ON	ACK	MMT_ZS0006_ERROR_SFO	Mil-Ter Mon V6 Error		0	MFV2	CTSF00P2
09/09/10 20:42:22.0	OFF	CLEAR	MMT_ZS0020_ERROR_BRT	Mil-Ter Mon V20 Error		0	MFV2	CTSF00P2
09/09/10 20:42:22.0	ON	ACK	MMT_ZS0020_ERROR_BRT	Mil-Ter Mon V20 Error		0	MFV2	CTSF00P2
09/09/10 20:42:22.0	OFF	CLEAR	MMT_ZS0016_ERROR_SFO	Mil-Ter Mon V16 Error		0	MFV2	CTSF00P2
09/09/10 20:42:22.0	ON	ACK	MMT_ZS0016_ERROR_SFO	Mil-Ter Mon V16 Error		0	MFV2	CTSF00P2
09/09/10 20:42:23.0	OFF	CLEAR	MMT_ZS0026_ERROR_BRT	Mil-Ter Mon V26 Error		0		
09/09/10 20:42:23.0	ON	ACK	MMT_ZS0026_ERROR_BRT	Mil-Ter Mon V26 Error		0		
09/09/10 20:42:23.0	OFF	CLEAR	MMT_ZS0020_ERROR_SFO	Mil-Ter Mon V20 Error		0		
09/09/10 20:42:23.0	ON	ACK	MMT_ZS0020_ERROR_SFO	Mil-Ter Mon V20 Error		0		
09/09/10 20:42:24.0	OFF	CLEAR	MMT_ZS0028_ERROR_SFO	Mil-Ter Mon V28 Error		0		
09/09/10 20:42:24.0	ON	ACK	MMT_ZS0028_ERROR_SFO	Mil-Ter Mon V28 Error		0		
09/09/10 20:42:24.0	OFF	CLEAR	MMT_ZS0028_ERROR_BRT	Mil-Ter Mon V28 Error		0		
09/09/10 20:42:24.0	ON	ACK	MMT_ZS0028_ERROR_BRT	Mil-Ter Mon V28 Error		0		
09/09/10 20:42:25.0	OFF	CLEAR	MMT_ZS0026_ERROR_SFO	Mil-Ter Mon V26 Error		0		
09/09/10 20:42:25.0	ON	ACK	MMT_ZS0026_ERROR_SFO	Mil-Ter Mon V26 Error		0		
09/09/10 20:42:25.0	OFF	CLEAR	MMT_ZS0066_ERROR_BRT	Mil-Ter Mon V66 Error		0		
09/09/10 20:42:25.0	ON	ACK	MMT_ZS0066_ERROR_BRT	Mil-Ter Mon V66 Error		0		
09/09/10 20:42:26.0	OFF	CLEAR	MMT_ZS0066_ERROR_SFO	Mil-Ter Mon V66 Error		0		
09/09/10 20:42:26.0	ON	ACK	MMT_ZS0066_ERROR_SFO	Mil-Ter Mon V66 Error		0		
09/09/10 20:42:27.0	OFF	CLEAR	MMT_ZS0067_ERROR_SFO	Mil-Ter Mon V67 Error		0		
09/09/10 20:42:27.0	ON	ACK	MMT_ZS0067_ERROR_SFO	Mil-Ter Mon V67 Error		0		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 20:42:29.0	OFF	CLEAR	MMT_ZS0071_ERROR_BRT	Mil-Ter Mon V71 Error		0	MFV2	CTSF00P2
09/09/10 20:42:29.0	ON	ACK	MMT_ZS0071_ERROR_BRT	Mil-Ter Mon V71 Error		0	MFV2	CTSF00P2
09/09/10 20:42:29.0	OFF	CLEAR	MMT_ZS0070_ERROR_BRT	Mil-Ter Mon V70 Error		0	MFV2	CTSF00P2
09/09/10 20:42:29.0	ON	ACK	MMT_ZS0070_ERROR_BRT	Mil-Ter Mon V70 Error		0	MFV2	CTSF00P2
09/09/10 20:42:29.0	OFF	CLEAR	MMT_ZS0067_ERROR_BRT	Mil-Ter Mon V67 Error		0	MFV2	CTSF00P2
09/09/10 20:42:29.0	ON	ACK	MMT_ZS0067_ERROR_BRT	Mil-Ter Mon V67 Error		0	MFV2	CTSF00P2
09/09/10 20:42:30.0	OFF	CLEAR	MMT_ZS0070_ERROR_SFO	Mil-Ter Mon V70 Error		0	MFV2	CTSF00P2
09/09/10 20:42:30.0	ON	ACK	MMT_ZS0070_ERROR_SFO	Mil-Ter Mon V70 Error		0	MFV2	CTSF00P2
09/09/10 20:42:30.0	OFF	CLEAR	MMT_ZS0071_ERROR_SFO	Mil-Ter Mon V71 Error		0	MFV2	CTSF00P2
09/09/10 20:42:30.0	ON	ACK	MMT_ZS0071_ERROR_SFO	Mil-Ter Mon V71 Error		0	MFV2	CTSF00P2
09/09/10 20:42:31.0	OFF	CLEAR	MMT_ES0027_BRT	Mil-Ter V27 Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:36.0	OFF	CLEAR	MMT_ES0017_BRT	Mil-Ter V17 Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:36.0	OFF	CLEAR	MMT_ES0021_BRT	Mil-Ter V21 Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:37.0	OFF	CLEAR	MMT_ES0013_BRT	Mil-Ter V13 Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:37.0	OFF	CLEAR	MMT_ES0014_BRT	Mil-Ter V14 Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:38.0	OFF	CLEAR	MMT_ES0011_BRT	Mil-Ter V11 Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:38.0	OFF	CLEAR	MMT_ES0012_BRT	Mil-Ter V12 Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:39.0	OFF	CLEAR	MMT_ES0009_BRT	Mil-Ter V9 Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:39.0	OFF	CLEAR	MMT_ES0010_BRT	Mil-Ter V10 Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:40.0	OFF	CLEAR	MMT_ES0062_BRT	Mil-Ter V62 Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:40.0	OFF	CLEAR	MMT_ES0008_BRT	Mil-Ter V8 Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:41.0	OFF	CLEAR	MMT_ES0017R_BRT	Mil-Ter V17R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:41.0	OFF	CLEAR	MMT_ES0027R_BRT	Mil-Ter V27R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:42.0	OFF	CLEAR	MMT_ES0014R_BRT	Mil-Ter V14R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:42.0	OFF	CLEAR	MMT_ES0029_BRT	Mil-Ter V29 Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:43.0	OFF	CLEAR	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:43.0	ON	ACK	MMT_ES0011R_BRT	Mil-Ter V11R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:43.0	OFF	CLEAR	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:43.0	ON	ACK	MMT_ES0012R_BRT	Mil-Ter V12R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:43.0	OFF	CLEAR	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:43.0	ON	ACK	MMT_ES0013R_BRT	Mil-Ter V13R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:44.9	OFF	ACK	MMT_ZT0029_BRT	Mlpts-Ter Mix Bypass V29 Pct Op	HIGH			
09/09/10 20:42:51.0	OFF	CLEAR	Bethany_K_Timeout	Bethany_K RTU Failed		0		
09/09/10 20:42:51.0	OFF	ACK	Bethany_K_Timeout	Bethany_K RTU Failed		0		
09/09/10 20:42:58.0	OFF	CLEAR	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:58.0	ON	ACK	MMT_ES0010R_BRT	Mil-Ter V10R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:58.0	OFF	CLEAR	MMT_ZT0029_BRT	Mlpts-Ter Mix Bypass V29 Pct Op	OFF			
09/09/10 20:42:59.0	OFF	CLEAR	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:59.0	ON	ACK	MMT_ES0008R_BRT	Mil-Ter V8R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:59.0	OFF	CLEAR	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:42:59.0	ON	ACK	MMT_ES0009R_BRT	Mil-Ter V9R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:43:00.0	OFF	CLEAR	NMA_PS0006_BRT	Mrtin-Sta Gas Sup Rack2 Press Lo		0	MFV2	CTSF00P2
09/09/10 20:43:00.0	ON	ACK	NMA_PS0006_BRT	Mrtin-Sta Gas Sup Rack2 Press Lo		0	MFV2	CTSF00P2
09/09/10 20:43:00.0	OFF	CLEAR	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:43:00.0	ON	ACK	MMT_ES0007R_BRT	Mil-Ter V7R Controller Error		0	MFV2	CTSF00P2
09/09/10 20:43:01.0	OFF	CLEAR	MMT_FA0013R_BRT	Mil-Ter M13 Backflow Alarm		0	MFV2	CTSF00P2
09/09/10 20:43:01.0	OFF	CLEAR	MMT_FA0014R_BRT	Mil-Ter M14 Backflow Alarm		0	MFV2	CTSF00P2
09/09/10 20:43:02.0	OFF	CLEAR	MMT_ZT0008R_BRT	Mlpts-Ter M8 V8R Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:02.0	OFF	CLEAR	MMT_LS0006_BRT	Mil-Ter Storage Tank Level Lo Lo		0	MFV2	CTSF00P2
09/09/10 20:43:03.0	OFF	CLEAR	MMT_PT0040_BRT	Mlpts-Ter L109 Press	OFF	MFV2		CTSF00P2
09/09/10 20:43:03.0	OFF	CLEAR	MMT_PT0029B_BRT	Mlpts-Ter Mixer D/S Press	OFF	MFV2		CTSF00P2
09/09/10 20:43:04.0	OFF	CLEAR	MMT_PT0084_BRT	Mlpts-Ter L101 Press	OFF	MFV2		CTSF00P2
09/09/10 20:43:04.0	OFF	CLEAR	MMT_PT0083_BRT	Mlpts-Ter L132 Press	OFF	MFV2		CTSF00P2
09/09/10 20:43:05.0	OFF	CLEAR	MMT_PT0087_BRT	Mlpts-Ter L100 Press	OFF	MFV2		CTSF00P2
09/09/10 20:43:05.0	OFF	ACK	MMT_FI0901_AA_BRT	Mlpts-Ter Stn Tot Flow In Calculated	LOW LOW	22.6		
09/09/10 20:43:05.0	OFF	CLEAR	MMT_PT0010BR_BRT	Mil-Ter Uic 10R U/S Pres	OFF	MFV2		CTSF00P2
09/09/10 20:43:06.0	OFF	CLEAR	MMT_ZT0003_BRT	Mlpts-Ter M10 Mon V3 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:06.0	OFF	CLEAR	MMT_PT0009_BRT	Mlpts-Ter Sjdfm Press	OFF	MFV2		CTSF00P2
09/09/10 20:43:07.0	OFF	CLEAR	MMT_ZT0005_BRT	Mlpts-Ter M8 Mon V5 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:07.0	OFF	CLEAR	MMT_ZT0004_BRT	Mlpts-Ter M9 Mon V4 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:08.0	OFF	CLEAR	MMT_ZT0016_BRT	Mlpts-Ter Mixer Mon V16 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:08.0	OFF	CLEAR	MMT_ZT0006_BRT	Mlpts-Ter M7 Mon V6 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:09.0	OFF	CLEAR	MMT_ZT0028_BRT	Mlpts-Ter Byp Mon V28 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:09.0	OFF	CLEAR	MMT_ZT0026_BRT	Mlpts-Ter Mixer Mon V26 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:10.0	OFF	CLEAR	MMT_ZT0067_BRT	Mlpts-Ter L107 Mon V67 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:10.0	OFF	CLEAR	MMT_ZT0066_BRT	Mlpts-Ter L107 Mon V66 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:11.0	OFF	CLEAR	MMT_ZT0071_BRT	Mlpts-Ter L131 Mon V71 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:11.0	OFF	CLEAR	MMT_ZT0070_BRT	Mlpts-Ter L131 Mon V70 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:12.0	OFF	CLEAR	MMT_ZT0045_BRT	Mlpts-Ter L109 V45 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:12.0	OFF	CLEAR	MMT_ZT0063_BRT	Mlpts-Ter Mon V63 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:13.0	OFF	CLEAR	MMT_ZT0049_BRT	Mlpts-Ter L132 V49 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:13.0	OFF	CLEAR	MMT_ZT0048_BRT	Mlpts-Ter L101 V48 Pct Op	OFF	MFV2		CTSF00P2
09/09/10 20:43:14.0	OFF	CLEAR	MMT_FI0901_AA_BRT	Mlpts-Ter Stn Tot Flow In Calculated	OFF	22.6 MFV2		CTSF00P2

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 20:43:14.0	OFF	CLEAR	MMT_ZT0050_BRT	Mlpts-Ter Sjdfm V50 Pct Op	OFF		MFV2	CTSF00P2
09/09/10 20:43:15.0	OFF	CLEAR	MMT_ZS0004_0_BRT	Mil-Ter Mon V4 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:15.0	OFF	CLEAR	MMT_ZS0003_0_BRT	Mil-Ter Mon V3 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:16.0	OFF	CLEAR	MMT_ZS0006_0_BRT	Mil-Ter Mon V6 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:16.0	OFF	CLEAR	MMT_ZS0005_0_BRT	Mil-Ter Mon V5 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:17.0	OFF	CLEAR	MMT_ZS0020_0_BRT	Mil-Ter Mon V20 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:17.0	OFF	CLEAR	MMT_ZS0016_0_BRT	Mil-Ter Mon V16 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:18.0	OFF	CLEAR	MMT_ZS0028_0_BRT	Mil-Ter Byp Mon V28 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:18.0	OFF	CLEAR	MMT_ZS0026_0_BRT	Mil-Ter Mon V26 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:19.0	OFF	CLEAR	MMT_ZS0039_0_BRT	Mil-Ter V39 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:19.0	OFF	CLEAR	MMT_ZS0037_0_BRT	Mil-Ter V37 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:20.0	OFF	CLEAR	MMT_ZS0066_0_BRT	Mil-Ter Mon V66 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:20.0	OFF	CLEAR	MMT_ZS0063_0_BRT	Mil-Ter V63 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:21.0	OFF	CLEAR	MMT_ZS0071_0_BRT	Mil-Ter Mon V71 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:21.0	OFF	CLEAR	MMT_ZS0070_0_BRT	Mil-Ter Mon V70 Not Open			0 MFV2	CTSF00P2
09/09/10 20:43:21.0	OFF	CLEAR	MMT_ZS0067_0_BRT	Mil-Ter Mon V67 Not Open			0 MFV2	CTSF00P2
09/09/10 20:44:03.0	LL	UNACK	MMT_FI0903_AA_BRT	Mlpts-Ter Penin Tot Flow Calculated	LOW LOW		0	
09/09/10 20:44:57.2	OFF	ACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 20:45:05.0	LL	UNACK	MMT_FI0904_AA_BRT	Mlpts-Ter Pen+Sjo Tot Flow Calculated	LOW LOW	0.9		
09/09/10 20:45:05.0	OFF	UNACK	MMT_FI0903_AA_BRT	Mlpts-Ter Penin Tot Flow Calculated	LOW LOW	3		
09/09/10 20:45:05.0	LL	UNACK	MMT_FI0901_AA_BRT	Mlpts-Ter Stn Tot Flow In Calculated	LOW LOW	0		
09/09/10 20:45:07.0	LL	ACK	MMT_FI0904_AA_BRT	Mlpts-Ter Pen+Sjo Tot Flow Calculated	LOW LOW	0.9 MFV2		CTSF00P2
09/09/10 20:45:07.0	LL	ACK	MMT_FI0901_AA_BRT	Mlpts-Ter Stn Tot Flow In Calculated	LOW LOW	0 MFV2		CTSF00P2
09/09/10 20:45:08.0	OFF	CLEAR	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	OFF		MFV2	CTSF00P2
09/09/10 20:45:08.0	OFF	CLEAR	MMT_FI0903_AA_BRT	Mlpts-Ter Penin Tot Flow Calculated	OFF		3 MFV2	CTSF00P2
09/09/10 20:45:08.0	LL	ACK	MMT_FI0903_AA_BRT	Mlpts-Ter Penin Tot Flow Calculated	LOW LOW		3 MFV2	CTSF00P2
09/09/10 20:45:17.4	HIGH	UNACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 20:45:32.0	HIGH	ACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH		J1Gw	CTSF00P4
09/09/10 20:45:37.5	OFF	ACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 20:45:45.0	OFF	CLEAR	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	OFF		J1Gw	CTSF00P4
09/09/10 20:46:00.4	OFF	ACK	ABC_PT0001_BRT	Buck-Crk U/S Press	LOW			
09/09/10 20:46:03.0	OFF	ACK	MMT_FI0904_AA_BRT	Mlpts-Ter Pen+Sjo Tot Flow Calculated	LOW LOW	4		
09/09/10 20:46:03.0	OFF	ACK	MMT_FI0901_AA_BRT	Mlpts-Ter Stn Tot Flow In Calculated	LOW LOW	3.6		
09/09/10 20:46:07.0	OFF	CLEAR	ABC_PT0001_BRT	Buck-Crk U/S Press	OFF		J1Gw	CTSF00P4
09/09/10 20:46:07.0	OFF	CLEAR	MMT_FI0901_AA_BRT	Mlpts-Ter Stn Tot Flow In Calculated	OFF		3.6 MFV2	CTSF00P2
09/09/10 20:46:08.0	OFF	CLEAR	MMT_FI0904_AA_BRT	Mlpts-Ter Pen+Sjo Tot Flow Calculated	OFF		4 MFV2	CTSF00P2
09/09/10 20:46:08.0	OFF	CLEAR	ABC_PT0001_BRT	Buck-Crk U/S Press	OFF			
09/09/10 20:46:51.6	LOW	UNACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW			
09/09/10 20:46:59.0	LOW	ACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW		MFV2	CTSF00P2
09/09/10 20:48:38.1	OFF	ACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	LOW			
09/09/10 20:49:04.0	OFF	CLEAR	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	OFF		J1Gw	CTSF00P4
09/09/10 20:49:05.0	OFF	CLEAR	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	OFF			
09/09/10 20:49:48.0		Setpoint	BRT_PIC026DT_CMD0	Brt-Plc V26 D/S Pr Sp		650 BDMh		CTSF00P3
09/09/10 20:49:55.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 20:51:43.0	ON	UNACK	Corning_N_Dome_Timeout	Corning_N_Dome RTU Failed		1		
09/09/10 20:52:13.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 20:53:23.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0 MFV2		CTSF00P2
09/09/10 20:53:23.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0 MFV2		CTSF00P2
09/09/10 20:53:23.0	ON	ACK	Corning_N_Dome_Timeout	Corning_N_Dome RTU Failed		1 MFV2		CTSF00P2
09/09/10 20:54:00.0	OFF	ACK	Corning_N_Dome_Timeout	Corning_N_Dome RTU Failed		0		
09/09/10 20:54:01.0	OFF	CLEAR	Corning_N_Dome_Timeout	Corning_N_Dome RTU Failed		0		
09/09/10 20:54:45.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 20:57:03.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 21:04:39.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0 MFV2		CTSF00P2
09/09/10 21:04:39.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0 MFV2		CTSF00P2
09/09/10 21:06:40.2	LL	UNACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW LOW			
09/09/10 21:06:48.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 21:08:57.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1 J1Gw		CTSF00P4
09/09/10 21:08:58.0	LL	ACK	ALM_AT0332_BRT	Los-Medanos Inj Odorant Tio	LOW LOW		J1Gw	CTSF00P4
09/09/10 21:09:08.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 21:09:08.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 21:11:49.0		System	Status	User Shutdown, Logoff			J1Gw	CTSF00P4
09/09/10 21:14:16.5	ON	UNACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		1		
09/09/10 21:14:48.0		Login	ODN\axa1	AutoLogin			System	CTSF00P4
09/09/10 21:14:49.0		System	Status	Citect USA - 2009/10/22 - C14 - 9/8/2010 09:00:00			System	CTSF00P4
09/09/10 21:15:01.4	OFF	UNACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 21:15:18.2	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 21:15:18.2	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 21:15:36.2	OFF	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 21:15:36.2	OFF	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF			
09/09/10 21:15:45.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF		axa1	CTSF00P4
09/09/10 21:15:45.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH		axa1	CTSF00P4
09/09/10 21:15:45.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF		axa1	CTSF00P4

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 21:15:45.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH		axa1	CTSF00P4
09/09/10 21:15:46.0	OFF	CLEAR	MMT_Y00006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 21:15:46.0	ON	ACK	MMT_Y00006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 21:18:32.0		Alarm	MMT_PT0010_BRT	Low Setpoint		375	BDMh	CTSF00P3
09/09/10 21:18:32.0	OFF	ACK	MMT_PT0010_BRT	MIpts-Ter L300A Press	LOW			
09/09/10 21:18:35.0	OFF	CLEAR	MMT_PT0010_BRT	MIpts-Ter L300A Press	OFF		BDMh	CTSF00P3
09/09/10 21:19:53.3	LL	UNACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW LOW			
09/09/10 21:20:42.2	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 21:20:42.2	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 21:20:49.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH		axa1	CTSF00P4
09/09/10 21:20:50.0	LL	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW LOW		axa1	CTSF00P4
09/09/10 21:20:50.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH		axa1	CTSF00P4
09/09/10 21:21:00.2	OFF	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 21:21:00.2	OFF	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 21:21:12.5	OFF	ACK	KH2_AT1222_BRT	Hinkley L300B CUR Tot Odorant (TBM+THT)	LOW LOW			
09/09/10 21:21:53.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF		BDMh	CTSF00P3
09/09/10 21:21:54.0	OFF	CLEAR	KH2_AT1222_BRT	Hinkley L300B CUR Tot Odorant (TBM+THT)	OFF		BDMh	CTSF00P3
09/09/10 21:21:54.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF		BDMh	CTSF00P3
09/09/10 21:24:49.0	ON	UNACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		1		
09/09/10 21:25:35.0	ON	ACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		1	axa1	CTSF00P4
09/09/10 21:26:06.0		Setpoint	MMT_ZIC021R_CMD0	Mil-Ter 21R Max Pct Op		80	BDMh	CTSF00P3
09/09/10 21:27:27.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 21:27:40.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	BDMh	CTSF00P3
09/09/10 21:28:03.1	ON	UNACK	MMT_Y00006_BRT	Mil-Plt Front Gate Status		1		
09/09/10 21:28:11.0	ON	ACK	MMT_Y00006_BRT	Mil-Plt Front Gate Status		1	BDMh	CTSF00P3
09/09/10 21:28:48.4	OFF	ACK	MMT_Y00006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 21:28:55.0	OFF	CLEAR	MMT_Y00006_BRT	Mil-Plt Front Gate Status		0	KLM7	CTSF00P5
09/09/10 21:29:15.0		Alarm	M7A_PT0003_BRT	Low Setpoint		370	BDMh	CTSF00P3
09/09/10 21:29:15.0	OFF	ACK	M7A_PT0003_BRT	PLS-7A D/S PRESS	LOW			
09/09/10 21:29:18.0	OFF	CLEAR	M7A_PT0003_BRT	PLS-7A D/S PRESS	OFF		BDMh	CTSF00P3
09/09/10 21:29:19.0	OFF	CLEAR	M7A_PT0003_BRT	PLS-7A D/S PRESS	OFF			
09/09/10 21:29:43.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 21:29:43.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 21:30:29.0		System	Status	User Shutdown			FHS2Admin	CTSF0Admin4
09/09/10 21:30:53.0		System	Status	User Shutdown			FHS2Admin	CTSF0Admin3
09/09/10 21:32:47.0	OFF	CLEAR	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		0		
09/09/10 21:32:47.0	OFF	ACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		0		
09/09/10 21:33:19.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 21:33:43.8	HIGH	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 21:34:03.2	OFF	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 21:35:31.4	OFF	ACK	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0		
09/09/10 21:35:41.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 21:35:50.0	OFF	CLEAR	KKT_ES1031_BRT	Ketmant K3 Emmission Control Trouble		0	BDMh	CTSF00P3
09/09/10 21:35:50.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	BDMh	CTSF00P3
09/09/10 21:35:50.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	BDMh	CTSF00P3
09/09/10 21:36:15.0		Setpoint	MMT_ZIC038R_CMD0	Mil-Ter 38R Max Pct Op		90	BDMh	CTSF00P3
09/09/10 21:36:27.0		Setpoint	MMT_ZIC040R_CMD0	Mil-Ter 40R Max Pct Op		90	BDMh	CTSF00P3
09/09/10 21:36:38.2	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 21:36:38.2	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 21:36:56.3	OFF	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 21:36:56.3	OFF	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 21:37:05.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF		BDMh	CTSF00P3
09/09/10 21:37:05.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH		BDMh	CTSF00P3
09/09/10 21:37:06.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF		BDMh	CTSF00P3
09/09/10 21:37:06.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH		BDMh	CTSF00P3
09/09/10 21:37:52.0		Setpoint	MMT_ZIC038R_CMD0	Mil-Ter 38R Max Pct Op		100	BDMh	CTSF00P3
09/09/10 21:38:00.0		Setpoint	MMT_ZIC040R_CMD0	Mil-Ter 40R Max Pct Op		100	BDMh	CTSF00P3
09/09/10 21:38:08.8	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 21:38:08.8	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 21:38:10.0		Setpoint	MMT_ZIC021R_CMD0	Mil-Ter 21R Max Pct Op		100	BDMh	CTSF00P3
09/09/10 21:38:26.7	OFF	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 21:38:26.7	OFF	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 21:38:36.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF		BDMh	CTSF00P3
09/09/10 21:38:36.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH		BDMh	CTSF00P3
09/09/10 21:38:36.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF		BDMh	CTSF00P3
09/09/10 21:38:36.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH		BDMh	CTSF00P3
09/09/10 21:39:51.7	LOW	UNACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW			
09/09/10 21:40:14.8	HIGH	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 21:40:14.8	HIGH	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 21:40:32.8	OFF	UNACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH			
09/09/10 21:40:32.8	OFF	UNACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH			
09/09/10 21:40:45.0	LOW	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW		axa1	CTSF00P4
09/09/10 21:40:45.0	OFF	CLEAR	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	OFF		axa1	CTSF00P4

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 21:40:45.0	HIGH	ACK	KKN_FI0002_BRT	Kern-Rvr Socal To Pge Flow Rate	HIGH		axa1	CTSF00P4
09/09/10 21:40:45.7	LL	UNACK	KH2_AT1122_BRT	Hinkley L300A CUR Tot Odorant (TBM+THT)	LOW LOW			
09/09/10 21:40:46.0	OFF	CLEAR	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	OFF		axa1	CTSF00P4
09/09/10 21:40:46.0	HIGH	ACK	KKN_FI0012_BRT	Kern-Rvr Socal To Pge M1 Flow	HIGH		axa1	CTSF00P4
09/09/10 21:41:04.0	LL	ACK	KH2_AT1122_BRT	Hinkley L300A CUR Tot Odorant (TBM+THT)	LOW LOW		axa1	CTSF00P4
09/09/10 21:41:49.4	HIGH	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 21:42:10.5	OFF	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 21:45:18.7	HIGH	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 21:45:40.0	OFF	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 21:49:06.0		Setpoint	NMA_PIC010_CMD0	MRTIN-STA L132 D/S PRESS SP		140 MFV2		CTSF00P2
09/09/10 21:49:42.0		Setpoint	NMA_PIC013_CMD0	MRTIN-STA L132 BYP PRESS SP		135 MFV2		CTSF00P2
09/09/10 21:50:06.0	ON	UNACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		1		
09/09/10 21:50:08.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 21:50:11.2	ON	UNACK	NMA_PS0006_BRT	Mrtin-Sta Gas Sup Rack2 Press Lo		1		
09/09/10 21:50:15.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1 axa1		CTSF00P4
09/09/10 21:50:15.0	ON	ACK	NMA_PS0006_BRT	Mrtin-Sta Gas Sup Rack2 Press Lo		1 axa1		CTSF00P4
09/09/10 21:50:16.0	ON	ACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		1 axa1		CTSF00P4
09/09/10 21:50:17.0		Setpoint	BRT_PIC118DT_CMD0	Brt-Plc V118 D/S Pr Sp		590 KLM7		CTSF00P5
09/09/10 21:50:37.0		Setpoint	BRT_PIC114DT_CMD0	Brt-Plc V114 D/S Pr Sp		600 KLM7		CTSF00P5
09/09/10 21:51:16.3	OFF	ACK	NMA_PS0006_BRT	Mrtin-Sta Gas Sup Rack2 Press Lo		0		
09/09/10 21:51:30.0	OFF	CLEAR	NMA_PS0006_BRT	Mrtin-Sta Gas Sup Rack2 Press Lo		0		
09/09/10 21:52:19.7	HIGH	UNACK	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	HIGH			
09/09/10 21:52:24.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 21:52:24.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 21:52:41.0	HIGH	ACK	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	HIGH		axa1	CTSF00P4
09/09/10 21:53:36.6	ON	UNACK	FCT_ES0003_BRT	Cffe-Clta G Street Comm Fail		1		
09/09/10 21:53:45.0		Setpoint	NMA_PIC013_CMD0	MRTIN-STA L132 BYP PRESS SP		130 MFV2		CTSF00P2
09/09/10 21:53:59.7	OFF	UNACK	FCT_ES0003_BRT	Cffe-Clta G Street Comm Fail		0		
09/09/10 21:54:19.0	OFF	CLEAR	FCT_ES0003_BRT	Cffe-Clta G Street Comm Fail		0 axa1		CTSF00P4
09/09/10 21:54:19.0	ON	ACK	FCT_ES0003_BRT	Cffe-Clta G Street Comm Fail		0 axa1		CTSF00P4
09/09/10 21:55:07.5	HIGH	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 21:55:19.0	OFF	CLEAR	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		0		
09/09/10 21:55:19.0	OFF	ACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		0		
09/09/10 21:55:27.8	OFF	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 21:59:41.2	OFF	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW			
09/09/10 22:00:40.0	OFF	CLEAR	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	OFF		BDMh	CTSF00P3
09/09/10 22:00:56.3	HIGH	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 22:01:01.6	LL	UNACK	KH2_AT1222_BRT	Hinkley L300B CUR Tot Odorant (TBM+THT)	LOW LOW			
09/09/10 22:01:07.8	LOW	UNACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	LOW			
09/09/10 22:01:16.8	OFF	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 22:01:20.0	LL	ACK	KH2_AT1222_BRT	Hinkley L300B CUR Tot Odorant (TBM+THT)	LOW LOW		BDMh	CTSF00P3
09/09/10 22:01:22.0	LOW	ACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	LOW			
09/09/10 22:04:39.0	ON	UNACK	Conway_Rnch_Timeout	Conway_Rnch RTU Failed		1		
09/09/10 22:05:27.0	ON	ACK	Conway_Rnch_Timeout	Conway_Rnch RTU Failed		1 axa1		CTSF00P4
09/09/10 22:06:06.2	LOW	UNACK	MM2_FI0001_BRT	Moss-Ld-M2 Units 1+2 Flow	LOW			
09/09/10 22:06:18.0	LOW	ACK	MM2_FI0001_BRT	Moss-Ld-M2 Units 1+2 Flow	LOW		axa1	CTSF00P4
09/09/10 22:06:23.2	HIGH	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 22:06:34.2	OFF	ACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	LOW			
09/09/10 22:06:34.2	OFF	UNACK	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	LOW			
09/09/10 22:06:44.5	OFF	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 22:07:10.0	OFF	CLEAR	Conway_Rnch_Timeout	Conway_Rnch RTU Failed		0		
09/09/10 22:07:10.0	OFF	ACK	Conway_Rnch_Timeout	Conway_Rnch RTU Failed		0		
09/09/10 22:09:10.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 22:09:16.0	OFF	CLEAR	NMA_PT0030_BRT	Mrtin-Sta L132 U/S Press	OFF		axa1	CTSF00P4
09/09/10 22:09:16.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1 axa1		CTSF00P4
09/09/10 22:10:09.9	HIGH	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 22:11:10.7	OFF	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 22:11:27.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 22:11:28.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 22:12:24.9	ON	UNACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		1		
09/09/10 22:12:33.0	ON	ACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		1 axa1		CTSF00P4
09/09/10 22:13:09.9	OFF	ACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 22:14:02.0		Setpoint	ABY_PIC003A_CMD0	Burney-K Target Suct Pr S		700 KLM7		CTSF00P5
09/09/10 22:14:22.0	OFF	CLEAR	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0 KLM7		CTSF00P5
09/09/10 22:15:34.4	OFF	ACK	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	LOW			
09/09/10 22:17:08.9	HH	UNACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	HIGH HIGH			
09/09/10 22:17:49.1	OFF	UNACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	HIGH HIGH			
09/09/10 22:18:41.0	ON	UNACK	LRCV_71A_Timeout	LRCV_71A RTU Failed		1		
09/09/10 22:19:09.2	LOW	UNACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	LOW			
09/09/10 22:19:09.2	HIGH	UNACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 22:19:28.9	OFF	UNACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	LOW			
09/09/10 22:19:28.9	OFF	UNACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH			
09/09/10 22:19:42.8	LOW	UNACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW			

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 22:20:05.2	OFF	ACK	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	HIGH			
09/09/10 22:20:17.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 22:20:25.4	HIGH	UNACK	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	HIGH			
09/09/10 22:20:58.0	OFF	UNACK	LRCV_71A_Timeout	LRCV_71A RTU Failed		0		
09/09/10 22:21:13.5	OFF	ACK	KH2_AT1122_BRT	Hinkley L300A CUR Tot Odorant (TBM+THT)	LOW LOW			
09/09/10 22:21:39.2	OFF	UNACK	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	HIGH			
09/09/10 22:22:37.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 22:22:56.0	OFF	CLEAR	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	OFF		KLM7	CTSF00P5
09/09/10 22:22:56.0	HIGH	ACK	MMG_FI0002_BRT	Moss-Ldg Units 6+7 Flow	HIGH		KLM7	CTSF00P5
09/09/10 22:22:57.0	OFF	CLEAR	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	OFF		KLM7	CTSF00P5
09/09/10 22:22:57.0	HIGH	ACK	BRT_FI0114N_BRT	Brt-Plt L114N North Flow	HIGH		KLM7	CTSF00P5
09/09/10 22:22:57.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	KLM7	CTSF00P5
09/09/10 22:22:57.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	KLM7	CTSF00P5
09/09/10 22:22:58.0	OFF	CLEAR	LRCV_71A_Timeout	LRCV_71A RTU Failed		0	KLM7	CTSF00P5
09/09/10 22:22:58.0	ON	ACK	LRCV_71A_Timeout	LRCV_71A RTU Failed		0	KLM7	CTSF00P5
09/09/10 22:22:58.0	OFF	CLEAR	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	OFF		KLM7	CTSF00P5
09/09/10 22:22:58.0	LOW	ACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	LOW		KLM7	CTSF00P5
09/09/10 22:22:59.0		Alarm	JSI_PT0001_BRT	High Setpoint		370 mgc4		CTSF00P1
09/09/10 22:22:59.0	OFF	CLEAR	KH2_AT1122_BRT	Hinkley L300A CUR Tot Odorant (TBM+THT)	OFF		KLM7	CTSF00P5
09/09/10 22:23:00.0	OFF	CLEAR	ABY_ST0002_BRT	Burney-K K2 React Turbine Speed	OFF		KLM7	CTSF00P5
09/09/10 22:25:29.0	LOW	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW		axa1	CTSF00P4
09/09/10 22:25:49.6	HH	UNACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	HIGH HIGH			
09/09/10 22:26:11.0	OFF	UNACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	HIGH HIGH			
09/09/10 22:26:43.0	OFF	CLEAR	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	OFF		KLM7	CTSF00P5
09/09/10 22:26:43.0	HH	ACK	BRT_FI0114S_BRT	Brt-Plt L114N South Flow	HIGH HIGH		KLM7	CTSF00P5
09/09/10 22:29:59.0	ON	UNACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		1		
09/09/10 22:30:15.0	ON	ACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		1	axa1	CTSF00P4
09/09/10 22:31:27.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 22:31:39.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	axa1	CTSF00P4
09/09/10 22:31:54.8	ON	UNACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		1		
09/09/10 22:32:27.0	OFF	CLEAR	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		0		
09/09/10 22:32:28.0	OFF	ACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		0		
09/09/10 22:32:39.1	OFF	UNACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0		
09/09/10 22:32:50.0	OFF	CLEAR	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0	axa1	CTSF00P4
09/09/10 22:32:50.0	ON	ACK	MMT_YS0006_BRT	Mil-Plt Front Gate Status		0	axa1	CTSF00P4
09/09/10 22:33:46.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 22:33:47.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 22:37:11.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 22:37:40.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	BDMh	CTSF00P3
09/09/10 22:39:27.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 22:39:27.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 22:39:54.1	OFF	ACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW			
09/09/10 22:41:04.7	OFF	ACK	KH2_AT1222_BRT	Hinkley L300B CUR Tot Odorant (TBM+THT)	LOW LOW			
09/09/10 22:42:25.4	HIGH	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 22:44:06.0	OFF	CLEAR	KH2_AT1222_BRT	Hinkley L300B CUR Tot Odorant (TBM+THT)	OFF		BDMh	CTSF00P3
09/09/10 22:44:06.0	OFF	CLEAR	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	OFF		BDMh	CTSF00P3
09/09/10 22:44:12.0		Alarm	MM2_FI0001_BRT	Low Setpoint Cleared			BDMh	CTSF00P3
09/09/10 22:44:12.0	OFF	ACK	MM2_FI0001_BRT	Moss-Ld-M2 Units 1+2 Flow	LOW			
09/09/10 22:44:15.0		Alarm	MM2_FI0001_BRT	High Setpoint		0.2	BDMh	CTSF00P3
09/09/10 22:44:16.0	OFF	CLEAR	MM2_FI0001_BRT	Moss-Ld-M2 Units 1+2 Flow	OFF		BDMh	CTSF00P3
09/09/10 22:44:24.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 22:45:07.5	ON	UNACK	RKS_ES0011_BRT	San-Ros-K Sebstopl Comm Failure		1		
09/09/10 22:45:29.5	OFF	UNACK	RKS_ES0011_BRT	San-Ros-K Sebstopl Comm Failure		0		
09/09/10 22:45:40.0		Alarm	ADE_PT0002B_BRT	High Setpoint		958	BDMh	CTSF00P3
09/09/10 22:45:45.0		Alarm	ADE_PT0002B_BRT	Low Setpoint		920	BDMh	CTSF00P3
09/09/10 22:45:45.0	OFF	ACK	ADE_PT0002B_BRT	Delevan-K L401 Disch Press	LOW			
09/09/10 22:46:27.0	OFF	CLEAR	ADE_PT0002B_BRT	Delevan-K L401 Disch Press	OFF			
09/09/10 22:46:27.0	OFF	CLEAR	RKS_ES0011_BRT	San-Ros-K Sebstopl Comm Failure			KLM7	CTSF00P5
09/09/10 22:46:27.0	ON	ACK	RKS_ES0011_BRT	San-Ros-K Sebstopl Comm Failure		0	KLM7	CTSF00P5
09/09/10 22:46:40.0	OFF	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	KLM7	CTSF00P5
09/09/10 22:47:13.0	OFF	UNACK	M6A_PT0003_BRT	PLS-6A D/S PRESS	HIGH			
09/09/10 22:48:03.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	KLM7	CTSF00P5
09/09/10 22:48:03.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0	KLM7	CTSF00P5
09/09/10 22:48:04.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 22:50:04.0	ON	UNACK	Rocklin_Timeout	Rocklin RTU Failed		1		
09/09/10 22:51:21.0	ON	ACK	Rocklin_Timeout	Rocklin RTU Failed		1	axa1	CTSF00P4
09/09/10 22:51:22.0	ON	UNACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		1		
09/09/10 22:51:29.0	ON	ACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		1		
09/09/10 22:51:44.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 22:51:50.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 22:52:22.0	OFF	CLEAR	Rocklin_Timeout	Rocklin RTU Failed		0		
09/09/10 22:52:22.0	OFF	ACK	Rocklin_Timeout	Rocklin RTU Failed		0		
09/09/10 22:54:02.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		

Alarm Log in Excel Format

Time	State	Type	Tag	Description	Description 2	Value	User	Location
09/09/10 22:54:02.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 22:56:30.0	ON	UNACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1		
09/09/10 22:56:38.0	OFF	CLEAR	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		0		
09/09/10 22:56:38.0	OFF	ACK	Todhunter_Lake_Timeout	Todhunter_Lake RTU Failed		0		
09/09/10 22:57:06.0	ON	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		1	axa1	CTSF00P4
09/09/10 22:58:48.0	OFF	CLEAR	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 22:58:50.0	OFF	ACK	Angwin_Reg_Timeout	Angwin_Reg RTU Failed		0		
09/09/10 22:59:42.7	LOW	UNACK	AWD_AT0042_BRT	Wg-Delevan Tot Odorant (Tbm+Tht)	LOW			