UPPER SKIN PANEL - WING CENTER TANK

CW-133 Z-2822 GREEN

This is a small portion of upper skin and skin flange of the double plus chord extending from the rear spar to S-2 and from the side of body to LBL 112. The upper external splice plate common to the rear spar terminal fitting still remains.

The panel remains generally flat and there is a fracture in the panel running inbd/outbd at S-1. A portion of the upper rear spar chord remains attached but the fasteners are distorted in multiple directions. Only a very small portion of the skin flange of S-1 remains attached. The fwd/inbd corner of the external splice plate has been separated from the skin panel. The fracture line on the skin flange of the double plus chord exhibits tearing in an aft direction.

Stephen F. Klupach In FAA 12.05-96 K. Guditte IAM 12-5-96 W. Sterant Bocion 12/5/94 Difflipto TWA 12-6-96 SD GREEN ALPA 12-6-96