


CW 167

UPPER PANEL VENT STRINGER  
SB + S9 LBL 98. WING CENTER  
SECTION.

CW 167 C332 GREEN

STRINGER IS 53 INCHES LONG  
AND FRACTURED AT BOTH ENDS  
FASTENERS FRACTURED IN SHEAR

STRINGER IS SOOTED



R. L. WHITTINGTON  
2/22/97

Leigh D. Johnson - ALPA  
3-20-97

Shwanderhise  
TWA 3/22/97

Denis Santiago ZAM  
3-26-97

Stephen F. Klapac H2  
FAA -04-02-97