

# LH SIDE-OF-BODY RIB PIECES

THE FOLLOWING ARE PIECES OF UPPER CHORD, WEB, AND STIFFENER ENDS, WITH MANY FASTENERS STILL IN PLACE AND

FRACTURES AROUND THE EDGES:

- D1  
V. Cozza  
ACFA 3/21/97
- CW-420** 12" LONG, FROM BS 1100 TO BS 1112  
Bhandishide  
TWA 3/23/97
- D2  
V. Cozza  
ACFA 3/21/97
- CW-421** 17" LONG, FROM BS 1112 TO BS 1129  
Z-2816  
GREEN
- D1  
V. Cozza  
3/21/97 ACFA
- CW-422** 7" LONG, FROM BS 1129 TO BS 1136
- D1  
V. Cozza  
ACFA 3/21/97
- CW-423** 15" LONG, FROM BS 1147 TO BS 1162
- D2
- CW-424** 33" LONG, FROM BS 1162 TO BS 1195  
C-2285

BOEING - D. ORTH 3/22/97

Bhandishide TWA 3/23/97

V. Cozza  
ACFA 3/21/97

Tom Teduce  
FAA 3-27-97

Dennis Santiago IAM  
3-28-97