

SPANWISE BEAM # 3

CW-610
Z-2764
GREEN

This panel extends from LBL 82 to 112 with stiffener and web fractures and tearing both top and bottom. No shear ties are attached.

There are three partial stiffeners attached to the web. The partial stiffeners are at LBL 83.24, 91.14, and 98.58. The web is bent ^{very} slightly forward at both the top and bottom, and aft 30 degrees from LBL 106 to 112.

SEE FIRE AND EXPLOSION FIELD NOTES. TCT.
~~No fire damage or sooting is observed.~~

Tom Kennedy 10/21/96
BOEING

TOM TADINO
FAA 10-29-96

SD GREEN 10-29-96

ALPA

C. J. Hill 11-26-96 TWA

C. J. Hill 11-27-96 I AM