

LOG # FBM-26

TARGET # \_\_\_\_\_

COORD: LAT \_\_\_\_\_


LONG \_\_\_\_\_

DEBRIS FIELD \_\_\_\_\_

26A NO TAG 9/24/96 - 2

26B NO TAG 8/10/96 - 9

26C NO TAG WITH 298



FLOOR BEAM ASSORTED PIECES STA 740

✓ 26A F/B RBL 11 TO RBL 55 (SEE F/B DWG)

RBL 3399 S/C ATTACHED, S/T SEGMENT  
FROM STA 700 TO STA 760

✓ 26B F/B UPPER CHORD & WEB LBL 96 TO LBL 110

WITH FLOOR BEAM SUPPORT POST

LOWER POST IS TORN, BENT AT BOTH END FRACTURES  
SEE F/B DWG.

✓ 26C F/B LOWER CHORD AND WEB LBL 80 TO LBL  
96 (SEE F/B DWG.)

*Barry Smith*  
10/23/96 BOEING  
Sen Jeddah IAA  
10:25:96

*Timothy*  
TWA 10-27-96

*Dennis Santiago IAM*  
11/23/96