


LOG # LF 135

TARGET # D2112

COORD: LAT _____
LONG _____

LF135 HAS THE FLOOR BEAMS,
FLOOR PANELS AND LAVATORY DRAIN
FROM AREA UNDER LAVATORY L AT DEBRIS FIELD
FROM AREA UNDER LAVATORY L AT DEBRIS FIELD
LBL 11.33 TO RBL 33.95 AND STA 1325 TO 1402.
FLOOR PANELS ARE STILL ATTACHED BUT ARE SOMEWHAT
BROKEN-UP. LAVATORY DRAIN, HOSE, FLOOR COVERING AND
LAVATORY PARTS ARE STILL ATTACHED. FLOOR BEAM AT LBL 11.33 IS
ATTACHED AT INTERCOSTAL AT STA 1350.



Ryanover slash
Boeing
Dennis Santiago IAA
3-6-97

NO FLOOR BEAM
- Stephen F Klapachon
FAA-03-14-97

Yeigh D Johnson - ALPA
3-17-97

Shandukh
TWA 3/21/97