


RTS 10/7/96



LOG # LF22

TARGET # _____


COORD: LAT 40-39-06

APPROX LONG 72-38-30

REFER FIRE AND EXPLOSION GROUP NOTES FOR FIRE DAMAGE

- EBRIS FIELD YELLOW

STA 520 TO STA 800, STR 37L TO 54R (36+PIECES OF SKIN AND STRINGERS. NO FIRE OR SMOKE APPARENT)



REV. A: POSITION OF LF22-27 CORRECTED B.H. (BOEING) 9/6/96
REV. B: ADDED LF22-37 B.H. (BOEING)

INTERNAL VIEW OF TYPICAL SKIN SEGMENT

SKIN CURLS OUTBD AT AREA NEAR FRAME CENTERLINE. NO FRAMES ARE ATTACHED (SOME SHEAR TIE FLANGES REMAIN).

R. Franchitti
IAM 10-25-96


Boeing
Neil Smith BOEING 10/24/96
TWA-10-6-96
John Zelikw FAA 10/24/96

1 SEC 42

LF 22-XX (NOTED IN SKETCH)

SEC 42 | SEC

SEE 65800004



Lee Zabus
 FAA
 10/22/96
 2