

LOG # RF37 ^{RF 10/1/96}

TARGET # _____

COORD: LAT _____

LONG _____

REFER METALLURGY GROUP NOTES

DEBRIS FIELD #1 green
(far)

REFER FIRE AND EXPLOSION GROUP NOTES FOR FIRE DAMAGE

Green Tag # C801

RHS skin panel from STA 930 to 1065, S-10R to S-27R.

The skin panel is quite sooted on both interior and exterior. In particular, the sooting is heaviest at the upper end of the panel at STA 1000 and the portion of the STA 1000 Bulkhead structure that extends below the panel.


The frames highlighted on the next sheet remain attached to the panel. Almost all stringer segments are attached and intact. This panel has distinctly more sooting than adjacent panels RF34 (green) RF20 and RF 21 (red).

Brandenburg TWA 10/1/96

*S. Dushahn
8/16/96*

*Tom Todaro
10-17-96
FRA*

*Dennis Santiago IAM
10/18/96*



↖ MID SPAR

3

FRONT