NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety Washington, D.C. 20594


March 09, 2015

Attachment 20

Fault Tree Titled "13.02 Uncommanded Feather Operation, Boost"

SYSTEM SAFETY

DCA15MA019



Page #: 1 6/21/2011