



Systems 9 - 747-SL-30-048 - Fig. 29. Wire bundles to the leading edge power drive units. These bundles are susceptible to failure since these bundles are exposed to the environment during takeoff and landing. Currently-produced airpla (text cut-off).