



Systems 9 - Exhibit No. 9A - Addendum 1 - (Fuel Probes) Photo 15. Fragment 80 Compensator internal upper LO-Z ring connector with blackened and deformed lower plastic features. Left photo faces head of screw.