

SPECIMEN 59 PC 1



Discolored Polyurethane Coating

Systems 9 - Exhibit No. 9B - Photo 17. Figure 17g. Discoloration caused by thermal damage to polyurethane coating (from N93119).