



Systems 9 - Exhibit No. 9B - Photo 3. Figure 3b. Radiograph of relay. Arrow indicates the coil that is tilted off its axis.