NTSB Investigation of Merrimack Valley, MA, Fires & Explosions NTSB Investigation PLD18MR003 Page 1 of 1 Name Argo, Dana Company & Department Columbia Gas, Operations Center Title Manager Date of Interview September 18, 2018

I have reviewed the transcript of my NTSB interview from the referenced investigation. I have answered questions to the best of my ability, but without the opportunity to review documents to refresh my recollection. Some of what I remember may be based on what others told me. My requested corrections and clarifications are as noted below.

Page	Line	Current	Request	Reason
6	10	10	16	Transcription Error
8	19	incident would be	incident (the response) would be	Clarification
13	4-6	I can tell you that there was, I mean, always discussing, you know, where sensing lines should be and things like that as far as risk.	I can tell you that there was discussion of, you know, where sensing lines should be and things like that as far as risk when I designed regulator stations.	Clarification
15	6	I was not aware of that.	I was not aware of that, but it does not surprise me.	Clarification
16	9	Yes, during the event, yes.	Yes, during the event (while the system was still overpressurized), yes.	Clarification
17	22	out to a worksite.	out to a worksite (to avoid a potential source of ignition).	Clarification
20	3	I do not do the training; it is a review	It is an emergency response plan rather than a training.	Clarification
23	13(+)		[The transcript abruptly ends. Much of the interview is missing.]	Clarification