NTSB Investigation of Merrimack Valley, MA, Fires & Explosions NTSB Investigation PLD18MR003

Page 1 of 4

Name	Mayes, Kevin Earl & Roorda, Adam
Company & Department	NiSource, Gas Control Department
Title	Senior Gas Controllers
Date of Interview	September 17, 2018

Page	Line	Current	Request	Reason
1	11 & 12	Friday, September 14	Monday, September 17	Transcription Error
2	13	Mr. Rhoads	Messrs. Mayes & Roorda	Transcription Error
7	2	Roorda	Wallace	Transcription Error
7	11	had	have	Transcription Error
8	12	we have to there a quarter till	we have to be there at a quarter till	Transcription Error
8	16	situation where	situation, where	Transcription Error
8	19	occurs system	occurs in the system	Transcription Error
10	13	We're recalled, we're required to respond within 10	We're required to respond within 10	Transcription Error
12	17	controls	controllers	Transcription Error
12	18	I believe we have 20.	23 Operationally Qualified	Correction &
			Controllers	Clarification
13	3	it is considered	is considered	Transcription Error
13	9	with M&R	with an M&R	Transcription Error
13	12	I can't answer that question, Sir.	No	Correction
13	23	changes alleviate	changes to alleviate	Transcription Error
14	11	change.	change that limit.	Transcription Error
14	12	So that		Transcription Error
14	13	That's that limit.		Transcription Error
14	20	If there's any	As to if there's any	Transcription Error
16	2	low alert to – you know, under – in very cold weather.	low alert due to large demand in very cold weather	Transcription Error / Clarification
17	19	MR. MAYES		Transcription Error
19	3	MAYES	ROORDA	Transcription Error
20	4	gas to make sure	Gas Systems Planning to make sure	Clarification
20	9	I cannot answer that. You know, that happens.	I can't say that it happens.	Transcription Error / Clarification
20	21	flow of alarms	flow alarms	Transcription Error

NTSB Investigation of Merrimack Valley, MA, Fires & Explosions NTSB Investigation PLD18MR003

Page 2 of 4

Name	Mayes, Kevin Earl & Roorda, Adam	
Company & Department	NiSource, Gas Control Department	
Title	Senior Gas Controllers	
Date of Interview	September 17, 2018	

Page	Line	Current	Request	Reason
20	23	float	flow	Transcription Error
21	7	of, you know, 2,400 Decatherms	of 2,400 Decatherms	Clarification
21	8	pound	mcf (thousands of cubic feet)	Transcription Error
21	15 & 17	MAYES	ROORDA	Transcription Error
22	5	tide	high	Transcription Error
22	13	So, they received a high- high, you	Received a High High,	Clarification
22	14	know, made the call to the field.	and made the call to the field.	Clarification
22	15	You know David was free to go after his turnover. He was	Mr. Rhoads was required to go drug test after his shift	Clarification
22	16	free to go drug test, so I was – and I'm fully aware or fully	I believe that our requirement is to try and get	Clarification
22	17	Sure that David would have stuck around. However, I needed him to	Employees tested within 2 hours	Clarification
22	18	leave to go drug testing per the, you know, requirements. You	I am sure that he would've stuck around although	Clarification
22	19	know, they would like us to get them there within two hours, I	there is no requirement so since we don't have control	Clarification
22	20	believe.	here.	Clarification
23	10	MAYES	ROORDA	Transcription Error
25	5	overseas	oversees	Transcription Error
25	17	Perdue	Purdue	Transcription Error
27	1	MR. MAYES: Sure, so these drops here – I said, pulled all	Mr. Roorda: Sure so these drops here like I said, I pulled	Transcription Error

NTSB Investigation of Merrimack Valley, MA, Fires & Explosions NTSB Investigation PLD18MR003

Page 3 of 4

Name	Mayes, Kevin Earl & Roorda, Adam	
Company & Department	NiSource, Gas Control Department	
Title	Senior Gas Controllers	
Date of Interview	September 17, 2018	

Page	Line	Current	Request	Reason
27	4	when it basically did not	when the system did not	Clarification
		get a good value, you know, to record	receive a good value to record.	
27	6	may be a communication	may be a communication	Clarification
		error or, you know, these sites are	error since most of	
27	7	cellular, you know. And so,	these sites utilize cellular or	Clarification
		it could be a, you know	satellite communications.	
27	9, 11, 13 & 19	MAYES	ROORDA	Transcription Error
28	10	MR. MAYES: I don't know.	Mr. Roorda: I don't know. I	Clarification
		I mean, I can't – I have	can't assume with the	
		provided,	information I have been provided.	
28	14	as I don't know the time	don't know the time of the	Clarification
			occurrence.	
28	16, 19 & 21	MAYES	ROORDA	Transcription Error
29	8	MAYES	ROORDA	Transcription Error
29	21	So, I do not know this	The SCADA system does not	Clarification
		system at all.	include that level of detail	
30	9, 14,	MAYES	ROORDA	Transcription Error
	19 & 23			
30	1	ROORDA	EVANS	Transcription Error
30	3 & 6	MAYES	LEMMERMAN	Transcription Error
31	2	MR. MAYES: I do – I do not.	Mr. Roorda: I do not. The	Transcription Error
		Intermittent controls	Instrument and Control	
			Department	
31	2, 5, 8,	MAYES	ROORDA	Transcription Error
	17, 18			
24	& 20	200224	514016	
31	4, 6	ROORDA	EVANS	Transcription Error
31	22	ROORDA	TOBIN	Transcription Error
31	25	MAYES	EVANS	Transcription Error

NTSB Investigation of Merrimack Valley, MA, Fires & Explosions NTSB Investigation PLD18MR003 Page 4 of 4 Name Mayes, Kevin Earl & Roorda, Adam Company & Department NiSource, Gas Control Department Title Senior Gas Controllers Date of Interview September 17, 2018

Page	Line	Current	Request	Reason
32	5, 8, 15 & 18	MAYES	ROORDA	Transcription Error
32	9 & 12	ROORDA	TOBIN	Transcription Error
33	10	September 14	September 17	Transcription Error