Tompkinsville- Danville, 30" Line 15 ILI History with Respect to Dents

- June 3, 1985 Standard resolution Tuboscope MFL (Unsure about caliper tool usage)
 - Twenty-five Dents were excavated and replaced. All anomaly and excavation data is contained in an
 excerpt from the RBASE database. (Dent Excerpt from RBASE STAN TOMP_15.xlsx)

June 22, 1992 – Standard resolution Tuboscope MFL (no caliper tool)

• No dent excavations from this ILI run. (see RBASE excerpt for anomaly data)

May 12, 2003 – Standard resolution Tuboscope MFL (no caliper tool)

- No dent excavations from this ILI run.
- ILI Report summary is contained in OSynopisRept647601.doc
- ILI data is contained in Tompkinsville 15 ILI Analysis.xls

June 24, 2010 – Hi-resolution GE MFL with Caliper & IMU

- Two dents were identified from this run for excavation (PAIR reports 6408 & 6946)
- ILI Report summary is contained in Tompkinsville 15 Final Report.pdf
- Excavation list is contained in ILI 2010 30IN Line 15 Tompkinsville Danville Emailed GRADED.xlsm

April 5, 2011 - Hi-resolution NDT MFL with Residual MFL (Hard Spot) (no caliper tool)

- No dent excavations from this ILI run.
- ILI summary report is contained in 70130.01_Spectra_Energy_Final_Report.pdf

May 1, 2018 - Hi-resolution BHGE MFL with Caliper & IMU

- Five Dents with Metal Loss identified for excavation
 - One previously excavated in 2010 (PAIR 6408)
 - o One excavated in 2018 (PAIR 1823304517)
 - Three pending excavations in 2019
- ILI summary report is contained in TOMP_15 (450455_30K) Inspection Report Issue 1 Rev 1.pdf
- Excavation list is contained in ILI 2018 30IN Line 15 TOMP-DANV with RunCom v0.9.9.10.xlsm

May 29, 2019 - Hi-resolution BHGE Caliper & IMU

- Final report pending (preliminary reports attached)
 - o TOMP_15 Area of Interest Report_(451191_N30).pdf
 - o Area of Interest Pipeline Listing 06 Aug 2019.xls

Files enclosed:

- Narrative (Tompkinsville_15 Dent Narrative.doc)
- 1985 & 1992
 - Dent Excerpt from RBASE STAN TOMP_15.xlsx
- 2003
 - o OSynopisRept647601.doc
 - Tompkinsville 15 ILI Analysis.xls
- 2010
 - PAIR reports 6408 & 6946
 - o Tompkinsville 15 Final Report.pdf
 - o ILI 2010 30IN Line 15 Tompkinsville Danville Emailed GRADED.xlsm
- 2011
 - 70130.01_Spectra_Energy_Final_Report.pdf
- 2018
 - PAIR 6408 & PAIR 1823304517
 - o TOMP_15 (450455_30K) Inspection Report Issue 1 Rev 1.pdf
 - ILI 2018 30IN Line 15 TOMP-DANV with RunCom v0.9.9.10.xlsm
- 2019
 - TOMP_15 Area of Interest Report_(451191_N30).pdf
 - Area of Interest Pipeline Listing 06 Aug 2019.xlsx