



Labor Date	Unit	Meter at the time	Work Order	Total Hours	Varranty YES/NO	Action: Description	Task: Description	Employee or <i>Vendor</i> Entered by	Labor Comments
4/12/22	01511	2602013	432-2022-2668	8.00	NO	30: INSPECTED	D-:DOORS	DILLON, KENNETH WILLIAM KEATING	WORK WITH ENGINEERING NTSB
4/12/22	01511	2602013	432-2022-2668	8.00	NO	30: INSPECTED	D-:DOORS	BROBERG, PAUL WILLIAM KEATING	WORK WITH ENGINEERING NTSB
4/11/22	01511	2602013	432-2022-2668	8.00	NO	30: INSPECTED	D-:DOORS	DILLON, KENNETH WILLIAM KEATING	WORK WITH ENGINEERING TO INSPECT TRAIN
4/5/22	01511	2601185	432-2022-2244	8.00	NO	55: REPAIRED	H-:HEAT - VENTILATOR AND AIR CONDITIONING SYSTEMS	SALOBEHAJ, ARMANDO DAVID WINFREY	R/R 6 HVAC MOTOR RESISTORS
4/4/22	01511	2601185	432-2022-2244	8.00	NO	90: MAJ COMP REPLCD/INSTLD	H-A2A:COMPRESSOR- AIR CONDITIONING	DILLON, KENNETH JOHN COYNE	R & R AC COMP MOTOR WITH GOOD USED SERIAL: 337267
4/4/22	01511	2601185	432-2022-2244	8.00	NO	90: MAJ COMP REPLCD/INSTLD	H-A2A:COMPRESSOR- AIR CONDITIONING	CALLAHAN, JAY JOHN COYNE	R & R AC COMP MOTOR WITH GOOD USED SERIAL: 337267
4/4/22	01511	2601185	432-2022-2244	8.00	NO	90: MAJ COMP REPLCD/INSTLD	H-A2A:COMPRESSOR- AIR CONDITIONING	NYAMUNDA, DOMINIC JOHN COYNE	R & R AC COMP MOTOR WITH GOOD USED SERIAL: 337267
4/2/22	01511	2601185	432-2022-2244	8.00	NO	31: TROUBLESHOOT	F-:ENGINE (PROPULSION)	PERKINS, KEVIN BRIAN WHIPPEN	SEE COMMENTS
3/30/22	01511	2601185	432-2022-2244	4.00	NO	74: SANDED/RESURFAC ED	T-A3:WHEELS	WHALEN, RYAN WILLIAM KEATING	CUT #4 AXLE
3/28/22	01511	2601185	432-2022-2244	8.00	NO	55: REPAIRED	E-S2A:INTERIOR LIGHTS	CUNNINGHAM, NATHAN THOMAS PEARSON	DEFERRED REPAIRS
3/28/22	01511	2601185	432-2022-2244	2.00	NO	31: TROUBLESHOOT	I A-:AIR SYSTEM	COSTELLO, CRAIG NATALINO SILVA	T/S LOW COMPRESSOR OF TIME, R&R`D A&R VALVE, OFF TIME 3:56

Additional notes and comments for Work Order 432-2022-2244:

T/S CASE. NOT COMPLETING 3RD POWER. FOUNS F3 AND F4 NOT PICKING. T/S TO F-2 NOT PICKING. T/S TO BAD B- AT TIME DELAY "B"/ R/R`D "B" CARD TEST CAS NOTCHED BOTH CARS. OK

REPLACED HVAC BUFFERING RESISTORS HAD TO REUSE OLD HARDWARE NO STOCK ON INSULATORS, JUMPERS, ETC.

3/27/22 01511	2600992	432-2022-2238	8.00	NO	30: INSPECTED	Y-M8:8-500-MILE INSPECTION	DESPEIGNES, HUGUES JOHN JOHNSTON	TRUCK INSP
3/27/22 01511	2600992	432-2022-2238	3.50	NO	30: INSPECTED	Y-M8:8-500-MILE INSPECTION	STEVENSON, TIMOTHY JOHN JOHNSTON	CAR BODY INSP
3/27/22 01511	2600992	432-2022-2238	4.00	NO	30: INSPECTED	Y-M8:8-500-MILE INSPECTION	CHACON, HENRY JOHN JOHNSTON	AIR AND ELECTRIC INSP
3/27/22 01511	2600992	432-2022-2238	4.00	NO	30: INSPECTED	Y-M8:8-500-MILE INSPECTION	CUNNINGHAM, NATHAN JOHN JOHNSTON	PROPULSION INSP





Labor Date	Unit	Meter at the time	Work Order	Total Hours	Proj # Warran YES/No		Task: Description	Employee or <i>Vendor</i> Entered by	Labor Comments
3/27/22	01511	2600992	432-2022-2238	0.10	NO	28:	A-A22:PURGE TANK	STEVENSON, TIMOTHY JOHN JOHNSTON	AIR PURGE
						DRAINED/EVACUAT	Ė	001111001111011011	
3/27/22	01511	2600992	432-2022-2238	0.40	NO	30: INSPECTED	Y-EAI:EQUAL ACCESS INSPECTION	STEVENSON, TIMOTHY JOHN JOHNSTON	EQUAL ACCESS INSP
3/11/22	01511	2597999	432-2021-7884	8.00	432D4AIR21 NO	08: SERVICED	A-AS:AIR COMPRESSOR SERVICE	SALOBEHAJ, ARMANDO STEPHEN WALKER	COMPLETE ANNUAL D4 AN AIR DRYER SERVICE

Additional notes and comments for Work Order 432-2021-7884:

OVERHAUL OF D4 OR D4-A COMPRESSORS WITH THE NEW GRAHAM WHITE AIR DRYERS OR VAPORLUX DRYER INSTALLED.

G:\PROCEDURES, PART LISTS, & BULLETINS\#2 CAR\D4-A COMPRESSOR

D4-A WITH NEW DRYER SERVICE PROC REV C.DOCX

CABOT D4-A NEW DRYER MAIN RECORD.DOCX

KIT-D4-RED KIT-D4-GW1								
3/7/22 0151	2597466	432-2022-1708	3.00	NO	30: INSPECTED	H-Y:HVAC INSPECTION	MILLER, IAN BILL MACDONALD	
3/7/22 0151	2597466	432-2022-1708	1.00	NO	30: INSPECTED	H-Y:HVAC INSPECTION	MCDONOUGH, JOHN BILL MACDONALD	
3/7/22 0151	2597466	432-2022-1708	1.00	NO	55: REPAIRED	Z-PA:PUBLIC ADDRESS AMPLIFIER	MILLER, IAN BILL MACDONALD	
3/7/22 0151	2597466	432-2022-1708	1.00	NO	55: REPAIRED	Z-PA:PUBLIC ADDRESS AMPLIFIER	MCDONOUGH, JOHN BILL MACDONALD	
3/1/22 0151	2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-Y1A:RATING- PROPULSION	CAFETEIRO, RYAN WESLEY DUDOVICZ	CHART AND ADJUST RATES
3/1/22 0151	2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-Y1A:RATING- PROPULSION	CAHILL, JEREMIAH WESLEY DUDOVICZ	CHART AND ADJUST RATES
2/28/22 0151	2595471	432-2020-11924	8.00	NO	31: TROUBLESHOO	T P-YA:PROPULSION SYSTEM INSPECTIONS	CAHILL, JEREMIAH WESLEY DUDOVICZ	SEE COMMENTS
2/28/22 0151	2595471	432-2020-11924	8.00	NO	31: TROUBLESHOOT	T P-YA:PROPULSION SYSTEM INSPECTIONS	CAFETEIRO, RYAN WESLEY DUDOVICZ	SEE COMMENTS
2/27/22 0151	2595471	432-2020-11924	3.00	NO	55: REPAIRED	T-Z1:TRUCK 1 - MAJ. COMP. CHGOUT.	KILLEEN, MICHAEL STEPHEN WALKER	R&R #1 TRUCK ASSEMBLY
2/27/22 0151	2595471	432-2020-11924	3.00	NO	55: REPAIRED	T-Z1:TRUCK 1 - MAJ. COMP. CHGOUT.	CUNNINGHAM, NATHAN STEPHEN WALKER	R&R #1 TRUCK ASSEMBLY
2/27/22 0151	2595471	432-2020-11924	3.00	NO	55: REPAIRED	T-Z1:TRUCK 1 - MAJ. COMP. CHGOUT.	CAHILL, JEREMIAH STEPHEN WALKER	R&R #1 TRUCK ASSEMBLY

KIT PART #`S





Labor Date	Unit	Meter at the time	Work Order	Total Hours	Proj #	Warranty YES/NO	Action: Description	Task: Description	Employee or <i>Vendor</i> Entered by	Labor Comments
2/27/22	01511	2595471	432-2020-11924	1.00		NO	55: REPAIRED	P-:ENGINE (PROPULSION)	DILLON, KENNETH BRIAN WHIPPEN	R/R`D GFI BOX
2/20/22	01511	2595471	432-2020-11924	8.00		NO	31: TROUBLESHOOT	F-:ENGINE (PROPULSION)	MACKINNON, BRUCE BRIAN WHIPPEN	T/S CASE
2/20/22	01511	2595471	432-2020-11924	8.00		NO	55: REPAIRED	P-:ENGINE (PROPULSION)	DILLON, KENNETH THOMAS PEARSON	SEE COMMENTS
1/14/22	01511	2595471	432-2020-11924	8.00		NO	55: REPAIRED	P-:ENGINE (PROPULSION)	O`CONNOR, EDDIE MICHAEL TRAYERS	CONTINUED PROPULSION CASE WORK
1/13/22	01511	2595471	432-2020-11924	8.00		NO	55: REPAIRED	P-:ENGINE (PROPULSION)	O`CONNOR, EDDIE MICHAEL TRAYERS	CONTINUED BURN JOB REPAIR SEE COMMENTS
1/9/22	01511	2595471	432-2020-11924	8.00		NO	31: TROUBLESHOOT	I P-:ENGINE (PROPULSION)	BENITEZ, ROBERTO BRIAN WHIPPEN	WORK ON GETTING CASE RUNNING
1/5/22	01511	2595471	432-2020-11924	6.00		NO	31: TROUBLESHOOT	I A-A12:FUSE- COMPRESSOR MOTOR	CUNNINGHAM, NATHAN KEVIN KELLER	SEE COMMENTS
1/2/22	01511	2595471	432-2020-11924	8.00		NO	55: REPAIRED	J-P2:UNCOUPLING AIR CYLINDER	FALLAVOLLITA, DANIE KEVIN KELLER	REPLACED CYLINDER
12/22/21	01511	2595471	432-2020-11924	3.00		NO	90: MAJ COMP REPLCD/INSTLD	P-TZ3:TRAC. MTR. 3-MAJ. COMP. CHGOUT	DESOUSA, MATHEW NOEL MONIZ	R/R`D TK-3323, #3 AND #4 TRACTION MOTORS LEFT UP FOR B/P
12/22/21	01511	2595471	432-2020-11924	3.00		NO	90: MAJ COMP REPLCD/INSTLD	P-TZ3:TRAC. MTR. 3-MAJ. COMP. CHGOUT	SCHLAGER, STEPHEN NOEL MONIZ	R/R`D TK-3323, #3 AND #4 TRACTION MOTORS LEFT UP FOR B/P
12/22/21	01511	2595471	432-2020-11924	3.00		NO	90: MAJ COMP REPLCD/INSTLD	P-TZ4:TRAC. MTR. 4-MAJ. COMP. CHGOUT	MAMMONE, JOHN NOEL MONIZ	R/R`D TK-3323, #3 AND #4 TRACTION MOTORS LEFT UP FOR B/P
12/22/21	01511	2595471	432-2020-11924	8.00		NO	90: MAJ COMP REPLCD/INSTLD	B-U:BRAKE PACKAGE	KILLEEN, MICHAEL BILL MACDONALD	
12/22/21	01511	2595471	432-2020-11924	8.00		NO	90: MAJ COMP REPLCD/INSTLD	B-U:BRAKE PACKAGE	DEVLIN, MICHAEL BILL MACDONALD	
12/21/21	01511	2595471	432-2020-11924	8.00		NO	90: MAJ COMP REPLCD/INSTLD	J-MZ1:DRAWBAR HEAD 1-MAJ.COMP.CHGOUT	KILLEEN, MICHAEL KEVIN KELLER	R/R`D #1 DRAWBAR HEAD
12/21/21	01511	2595471	432-2020-11924	8.00		NO	90: MAJ COMP REPLCD/INSTLD	J-MZ1:DRAWBAR HEAD 1-MAJ.COMP.CHGOUT	CUNNINGHAM, NATHAN KEVIN KELLER	R/R`D #1 DRAWBAR HEAD





Proj # Warranty **Action:** Labor Meter at Work Employee or Vendor **Total** Unit **Task: Description Labor Comments** YES/NO **Description** Date the time **Entered by** Order Hours

Additional notes and comments for Work Order 432-2020-11924:





Labor _{Unit} Meter at Work Total _{Proj} # Warranty Action: Task: Description Employee or *Vendor* Labor Comments Date the time Order Hours YES/NO Description

CONTINUED BURNT PROPULSION CASE REPAIRS, WILL NEED COIL AT END OF PROPULSION CASE. RECOMMEND MOVING TO WHEEL HOUSE FOR SAFE REPLACEMENT. NEED TO SOURCE A COIL

CONTINUED PROPULSION CASE REPAIR BEGAN TO INSTALL COIL AT END OF CASE AND PULL NEW WIRES.

COIL MOUNTED TO END OF CASE AND WIRES PULLED INTO THE CASE CAN BE MOVED TO A PIT. WIRING NEEDS COMPLETION AND PBC INSTALLED, AND CONTROLS TESTED.

REPLACED CABLING AND WIRING ON THE PBC AND FIELD SHUNTING COIL.

2/27/22 R/R`D GFI BOX

10/29/2021

CONTINUED PROPULSION REPAIR, RESISTOR WIRING STILL NEEDS TO BE LUGGED AND INSTALLED, AND CONTROLS CHECKED

1-5-22

AIR COMPRESSOR INOP FOUND BUFFER RESISTOR MELTED REPLACED ALSO FOUND WIRE MELTED HAD TO RUN NEW WIRE TO FRONT OF BOX. TESTED AND RAN OKAY.

STILL NEEDS CONTROLS CHECK AND TEST TRACK

1/13/2022

FINISHED CASE AND GRID WIRE REPAIR. CASE DOESN'T RUN UP BEGAN T/S. ADJUSTED SEVERAL LIGHT FINGERS CASE NOW RUNS UP TO SECOND BUT NO CALL INVERTOR CARD AND B CARD REPLACED STILL NO CAM NEEDS FURTHER T/S. (7PT AND AIR TO CASE C/O)

1/14/2022

CONTINUED T/S CASE ADJUSTED SEVERAL FINGERS AND CLEANED CONTACTS. REPLACED A FAULTY FIELD FORCING PANEL STILL NO CAM IN SECOND NEEDS FURTHER T/S

2/20/22 T/S CASE FURTHER. CASE RUNS THROUGH 2ND POWER BUT CAM WILL NOT ADVANCE PAST THAT POINT. SWAPPED LR, INV AND RATE CARD WITH MAT CAR. NO CHANGE. SWAPPED TIME DELAYS NO CHANGE. STILL NG

2/20/22 WIRING REPAIRED. CASE RUNS OKAY. 7 PT CUT IN CAR BECAUSE #1 MOTOR IS BURNT.

2-27-2022 2ND SHIFT #2 TM BURNT UP R&R TRUCK TO REPLACE #2 MOTOR MEGGED #1 MOTOR -> OK RE-INSTALL TRUCK





Labor Date	Unit	Meter at the time	Work Order	Total Hours	Proj # Wa	arranty ES/NO	Action: Description	Task: Description	Employee or <i>Vendor</i> Entered by	Labor Comments
**NO NO	OTCH -	CASE NEED	S FURTHER T/S	3						
12/18/21 (01511	2596017	432-2021-8242	0.01	432BLODN01	NO	28:	A-A22:PURGE TANK	WHIPPEN, BRIAN	DRAIN AIR TANKS
							DRAINED/EVACUATE	ГЕ	BRIAN WHIPPEN	

Additional notes and comments for Work Order 432-2021-8242:

DRAIN AIR TANKS, IF MULTI UNIT W/O HAS BEEN USED, ADD AN A-A22 TASK TO A WORK ORDER OPEN ON THE CAR YOU'RE WORKING ON AND ADD SOME LABOF THE TASK UNTIL NOV 2021

BOTH CARS MUST BE DRAINED EVEN IF THERE IS ONLY ONE COMPRESSOR CAR IN THE DUECE

10/29/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	O`CONNOR, EDDIE MICHAEL TRAYERS	CONTINUED PROPULSION REPAIRS
10/26/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	O`CONNOR, EDDIE NATALINO SILVA	CONTINUED PROPULSION REPAIR
10/15/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	O`CONNOR, EDDIE BRIAN WHIPPEN	REPLACED CABLING AND WIRING ON THE PBC AND FIELD SHUNTING CO
10/12/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	O`CONNOR, EDDIE MICHAEL TRAYERS	CONTINUED PROPULSION CASE REPAIRS
10/5/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	O`CONNOR, EDDIE MICHAEL TRAYERS	CONTINUED PROPULSION CASE REPAIRS
10/4/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	O`CONNOR, EDDIE MICHAEL TRAYERS	CONTINUED PROP CASE REPAIRS
9/28/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	E-:ELECTRICAL SYSTEM	O`CONNOR, EDDIE DAVID WINFREY	CONTINUE WIRING REPAIR
9/24/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	O`CONNOR, EDDIE WILLIAM KEATING	CONTINUE WIRING
9/23/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	O`CONNOR, EDDIE MICHAEL TRAYERS	CONTINUED PROPULSION REPAIRS
9/22/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	COSTELLO, CRAIG MICHAEL TRAYERS	CONTINUED PROPULSION REPAIRS
9/22/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	O`CONNOR, EDDIE MICHAEL TRAYERS	CONTINUED PROPULSION REPAIRS
9/21/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	COSTELLO, CRAIG MICHAEL TRAYERS	PROPULSION CASE REPAIF
9/21/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	O`CONNOR, EDDIE MICHAEL TRAYERS	PROPULSION CASE REPAIF
7/27/21 015	11 2595471	432-2020-11924	8.00	NO	55: REPAIRED	P-:ENGINE (PROPULSION)	VENTURA, JOVAN MICHAEL TRAYERS	CONTINUED BURNT CASE REPAIRS SEE COMMENTS
7/25/21 015	11 2595471	432-2020-11924	8.00	NO	31: TROUBLESHOO	T P-:ENGINE (PROPULSION)	VENTURA, JOVAN BRIAN WHIPPEN	FIELD SHUNTING COIL R/R NO STOCK ON NEW ONE





Labor Date	Unit	Meter at the time	Work Order	Total Hours	Proj # Warranty YES/NO	Action: Description	Task: Description	Employee or <i>Vendor</i> Entered by	Labor Comments
7/23/21	01511	2595471	432-2020-11924	8.00	NO	31: TROUBLESHOO	T P-:ENGINE (PROPULSION)	VENTURA, JOVAN DAVID MOONEY	T/S BURN JOB

Report Choice: DETAIL Report Type: SORTED BY DATE Units: 01511





Proj # Warranty **Action:** Labor Meter at Work **Employee or Vendor Total** Unit **Task: Description Labor Comments** YES/NO **Description** Date the time **Entered by** Order Hours

Additional notes and comments for Work Order 432-2020-11924:





Labor _{Unit} Meter at Work Total _{Proj} # Warranty Action: Task: Description Employee or *Vendor* Labor Comments Date the time Order Hours YES/NO Description

CONTINUED BURNT PROPULSION CASE REPAIRS, WILL NEED COIL AT END OF PROPULSION CASE. RECOMMEND MOVING TO WHEEL HOUSE FOR SAFE REPLACEMENT. NEED TO SOURCE A COIL

CONTINUED PROPULSION CASE REPAIR BEGAN TO INSTALL COIL AT END OF CASE AND PULL NEW WIRES.

COIL MOUNTED TO END OF CASE AND WIRES PULLED INTO THE CASE CAN BE MOVED TO A PIT. WIRING NEEDS COMPLETION AND PBC INSTALLED, AND CONTROLS TESTED.

REPLACED CABLING AND WIRING ON THE PBC AND FIELD SHUNTING COIL.

2/27/22 R/R`D GFI BOX

10/29/2021

CONTINUED PROPULSION REPAIR, RESISTOR WIRING STILL NEEDS TO BE LUGGED AND INSTALLED, AND CONTROLS CHECKED

1-5-22

AIR COMPRESSOR INOP FOUND BUFFER RESISTOR MELTED REPLACED ALSO FOUND WIRE MELTED HAD TO RUN NEW WIRE TO FRONT OF BOX. TESTED AND RAN OKAY.

STILL NEEDS CONTROLS CHECK AND TEST TRACK

1/13/2022

FINISHED CASE AND GRID WIRE REPAIR. CASE DOESN'T RUN UP BEGAN T/S. ADJUSTED SEVERAL LIGHT FINGERS CASE NOW RUNS UP TO SECOND BUT NO CALL INVERTOR CARD AND B CARD REPLACED STILL NO CAM NEEDS FURTHER T/S. (7PT AND AIR TO CASE C/O)

1/14/2022

CONTINUED T/S CASE ADJUSTED SEVERAL FINGERS AND CLEANED CONTACTS. REPLACED A FAULTY FIELD FORCING PANEL STILL NO CAM IN SECOND NEEDS FURTHER T/S

2/20/22 T/S CASE FURTHER. CASE RUNS THROUGH 2ND POWER BUT CAM WILL NOT ADVANCE PAST THAT POINT. SWAPPED LR, INV AND RATE CARD WITH MAT CAR. NO CHANGE. SWAPPED TIME DELAYS NO CHANGE. STILL NG

2/20/22 WIRING REPAIRED. CASE RUNS OKAY. 7 PT CUT IN CAR BECAUSE #1 MOTOR IS BURNT.

2-27-2022 2ND SHIFT #2 TM BURNT UP R&R TRUCK TO REPLACE #2 MOTOR MEGGED #1 MOTOR -> OK RE-INSTALL TRUCK





Labor Date	Unit	Meter at the time	Work Order	Total Hours	Proj #	Warranty YES/NO	Action: Description	Task: Description	Employee or <i>Vendor</i> Entered by	Labor Comments		
**NO N	NOTCH -	CASE NEE	DS FURTHER T/S	3								
7/19/21	01511	2595791	432-2021-3238	4.00	432UT2	21 NO	80: PERFORMED	T-AS:AXLE TEST - ULTRASONIC	FORESTA, STEPHEN WILLIAM KEATING	UT ALL AXLES NOTE UNIT AXLE AND TRUCK S/N AND ANY DEFECTS		
			ments for Work (ON OF AXLES.	Order 43	2-2021-3	238:						
USE C	LYMPUS	S EPOCH 60	00 UT UNIT IN BL	JE CASE	<u>.</u>							
UT INS	SPECTIC	N PROCED	URE, AXLE DRA	WINGS A	AND FOR	MS ARE LO	OCATED IN NETWO	ORK FOLDER:				
>RTLF	ORE\PR	OCEDURES	S, PART LISTS, &	BULLET	INS\UT A	XLE INSPE	ECTION PROCEDU	RE\				
7/3/21	01511	2595791	432-2021-3914	8.00	432HDST	P21 NO	50: REPLACED/CHANGI D	C-K4:STANCHION- PASSENGER E COMPART	STEVENSON, TIMOTHY DAVID MOONEY	REMOVE/ REPLACE EXISTING PASSENGER HANDSTRAPS WITH NEW		
HAND	Additional notes and comments for Work Order 432-2021-3914: HANDSTRAP REPLACEMENT PROGRAM FOLLOW GRAB STRAP INSTALLATION PROCEDURE # IN-STRAP-1. IF A COLLAR IS ALREADY INSTALLED SKIP STEP 1.											
5/18/21	01511	2595551	432-2021-2813	4.00	432ACPS	S21 NO	50: REPLACED/CHANGI D	H-A7A:PRESSURE CONTROL SWITCH- E A/C	SMITH, ALBERT NATALINO SILVA	REPLACE THE #1 & 2 CAR HP & MOD SWITCHES		
			ments for Work (R HP & MOD SWI		2-2021-2	813:						
MODU	JLATION	PRESSURE	E SWITCH, #1 CA E SWITCH, #2 CA H, #1 & 2 CARS,	R, MBTA	A P/N: 02	696003						
D	istinct :	# Units	Distinc	t # WO	Tot	Hrs Av	rg Hrs					

393.01

6.14

10