


HIGHWAY FACTORS ATTACHMENT

Typical Section for State Route 37

Louisville, NY

HWY23FH005

(2 pages)



Crash occurred near station 143+00