

**NATIONAL TRANSPORTATION SAFETY BOARD  
OFFICE OF AVIATION SAFETY  
WASHINGTON, D.C. 20594**

**ALASKA AIRLINE  
FLIGHT 1282, BOEING,  
737-9, N704AL  
PORTLAND, OREGON  
JANUARY 5, 2024**

**INVESTIGATIVE HEARING EXHIBIT LIST**

- 1A Order of Hearing
  - 1B Designation of Chairman Board of Inquiry
  - 1C Designation of Hearing Officer
  - 1D Designation of Parties to the Hearing
  - 1E Notice of Investigative Hearing
  - 1F Statement of Purpose
  - 1G Witness List
  - 1H Investigative Hearing Witness Professional Biographies
  - 1I Investigative Hearing Exhibit List
  - 1J Board of Inquiry and Technical Panel Professional Biographies
- 
- 2A Operational Factor – Group Chairman Factual Report
  - 2B Operational Factors – Attachment 1 – Crew Interview Transcripts and Statements

- 2C Operational Factors – Attachment 2 – Alaska Personnel Interview Transcripts
- 2D Operational Factors – Attachments 3 – Flight Crew Training Records
- 2E Operational Factors – Attachment 4 – Alaska Airlines Checklist
- 2F Operational Factors – Attachment 5 – Simulator Evaluation
- 2G Operational Factors – Attachment 6 – Sequence of Events
- 2H Operational Factors – Attachment 7 – Continuing Qualification Quarterly Training Rotation Schedule
- 2I Operational Factors – Attachment 8 – CBT Training Modules (Excerpts)
- 2J Operational Factors – Attachment 9 – Continuous Qualification 2025 LOFT Simulator Profile
- 2K Operational Factors – Attachment 10 – Weight and Balance
- 2L Operational Factors – Attachment 11 – Boeing Responses to Flight Deck Door Information Request
- 2M Operational Factors – Attachment 12 – NASA ASRS Database Query Results
- 2N Operational Factors – Attachment 13 – Flight Ops Training Bulletin (post-accident)
- 2O Operational Factors – Attachment 14 – Alaska Airlines Cabin Altitude Warning and Emergency Decent Training Video (postaccident)
  
- 6A Survival Factors Group Chair’s Factual Report
- 6B Survival Factors Attachment 1 Flight Attendants Interview Transcripts Redacted
- 6C Survival Factors – Attachment 2 Passenger Interview Summaries
  
- 7 Structures Group Chair’s Factual Report
  
- 9A Systems Group Chair’s Factual Report
- 9B Systems Factual Report Attachment 1
- 9C Systems Factual Report Attachment 2

- 9D Systems Factual Report Attachment 3
- 9E Boeing 737-7/8/8200/9/10 Aircraft Maintenance Manual Part I – System Description Section – Mid Cabin Exit Door Plug Temporary Revision 52 - 1001
  
- 10A Flight Data Recorder – Specialist’s Factual Report
- 10B Flight Data Recorder – Specialist’s Factual Report – Attachment 1 – FDR Tabular Data
- 10C Flight Data Recorder – Specialist’s Factual Report – Attachment 2 – QAR Tabular Data
- 10D Flight Data Recorder – Specialist’s Factual Report – Attachment 3 – FDR Tabular Data
- 10E Flight Data Recorder – Specialist’s Factual Report – Attachment 4 – QAR Tabular Data
- 10F Flight Data Recorder – Specialist’s Factual Report – Attachment 5 – FDR Tabular Data
- 10G Flight Data Recorder – Specialist’s Factual Report – Attachment 6 – QAR Tabular Data
  
- 11A Manufacturing Records and Human Performance Factual Report
- 11B Manufacturing Records and Human Performance Attachment 1 – NCR N1450292531 and NCO 145-8789-RSHK-1296-002NC
- 11C Manufacturing Records and Human Performance Attachment 2 – NCR N1450293199 and NCO 145-8789-RGEN-RSHK-001NC
- 11D Manufacturing Records and Human Performance Attachment 3 – Shiplside Action Tracker (SAT) 4650723
- 11E Manufacturing Records and Human Performance Attachment 4 – Previous MED plug Removals
- 11F Manufacturing Records and Human Performance Attachment 5 – Boeing Quality Alert 2023-0056-AR

- 11G Manufacturing Records and Human Performance Attachment 6 – BCA QMS Document Control Excerpt
- 11H Manufacturing Records and Human Performance Attachment 7 – BCA QMS Supplier Control Excerpt
- 11I Manufacturing Records and Human Performance Attachment 8 – BCA QMS Quality Escapes Excerpt
- 11J Manufacturing Records and Human Performance Attachment 9 – Boeing Safety Actions
- 11K Manufacturing Records and Human Performance Attachment 10 – Boeing Interview Transcripts Redacted
- 11L Manufacturing Records and Human Performance Attachment 11 – Spirit AeroSystems Interview Transcripts redacted
- 11M Manufacturing Records and Human Performances Attachment 12 – FAA Personnel Interview Transcripts
- 11N Manufacturing Records and Human Performances Attachment 13 – Boeing Executive Interviews Transcripts Redacted
- 11O Excerpts from Boeing Process Instruction 1581
- 11P Excerpts from Boeing Process Instruction – Apply Authority Media in the Common Manufacturing Execution System (CMES)
- 11Q Excerpts from Boeing Process Instruction – Perform Product Conformance
- 11R Excerpts from Boeing Process Instruction – Processing Product and Services Safety, Quality, or Compliance-Related Speak Up Reports
- 11S Boeing Installation Plan – INSTALLATION OF INSULATION BLANKETS SEC 46 – LEFT
- 11T Boeing Installation Plan – INSTALLATION OF INSULATION BLANKETS SEC 46 – RIGHT
- 11U Excerpts from Boeing Mid Exit Door Plug Rigging Drawing
- 11V Boing Process Instruction 1581 Document Change History Overview – 2013 – 2023 Excerpts

12 Cockpit Voice Recorder – Specialist’s Factual Report

15A Materials Group Chair’s Factual Report

15B Materials Group Chair’s Appendix A