

Incident # 8587539 Closed NON-PTC

Audit Trail Refresh Send To Call Response Summary Update

Opened 05-18-2018 02:32 [DWP](#) Department Engineering

Priority 1

[Escalation Policy](#)

Primary Asset Summary

Asset [6621 006 DOSWELL - 6OS SECTION](#) (NON-PTC)

Asset Type Track Segment Device CP TK CKT Track 3 TK Vendor Ticket#

Reg NO Div BA Sub RR 6621 MP CFP 21.7000 Street City/State VA

Other Asset Summary

[Add Asset](#)

Call List Section [7869](#)

Supervisor [Kaufman, Shawn](#) Available

[Rolodex](#) [Escalation Call List](#)

WS SMITH COVERS BETWEEN 5.2 & 57.5- J Horak AND L Scott BETWEEN 57.5 AND 110.19
PER DIV ENGR GREG WILHITE: CALL RDMSTR FIRST ON ANY DERAILMENT

Shift 1 00:00 - 24:00

Order	Name	Status	Until	Last Response	ETA	Last Accepted Call (12 hrs)
1	Smith, Stewart	Available		---		
2	Joyce, Wayne	Available		---		
3	Horak, Jesse	Available		---		
4	Scott, Larry M	Available		---		
5	Horak, Jesse	Available		---		
6	FORTUNE, JAMES	Available		---		
7	Kozlak, Adam	Available		---		

Notification Contacts

Attached Files

[Add Document](#)

No Documents Attached.

Related Incidents, Jumper and Shunt Logs Open

No related incidents, jumpers or shunts found for your department.

Incident History

[Update](#)

Description 05/18/2018 02:32:18	Status Unassigned	By David Price - Engineering	<input type="checkbox"/>
Inc Type Unknown	Asset Status Dtl	Priority 1	
Responsibility Control Center	Responsible Dept.	Message#	Jumpers N/A

Closed 05/18/2018 02:33:57	Status Closed	By David Price - Engineering	<input type="checkbox"/>
Inc Type Flash Flood Warning	Asset Status Dtl	Priority 1	
Responsibility Control Center	Responsible Dept.	Message#	Jumpers N/A

Incident Resolved: 05/18/2018 02:33:00

Equipment Type: N/A

Action Taken: Duplicate - refer to other incident number

FLASH FLOOD WARNING NUMBER 8422

EFFECTIVE 19:06EDT HOURS 2018-05-17 UNTIL 06:00EDT HOURS 2018-05-18

EXTENDED: Rain and storms have impacted this area throughout the day today with rates to 0.5"/hr to produce 2-3 inches of rainfall. A total of 3-5 inches have fallen throughout the last few days here. Watch for localized flash flooding through this morning.

BU/SL DIVISION SUBDIVISION STATIONS

BALTIMORE RF AND P MP CFP 6.9992 - LAUREL, VA to MP CFP 49.9992 - SUMMIT, VA

refer to Incident # 8587207

Operational Checks Performed

Dispatchers

[Update](#)

Shift 1st Desk [REDACTED]

Incident # 8587544 Closed NON-PTC

Audit Trail Refresh Send To Call Response Summary Update

Opened 05-18-2018 02:41 [TDH](#) Department Engineering

Priority 1

[Escalation Policy](#)

Primary Asset Summary

Asset [6619 009 CP ELMONT TO LAKESIDE #9 CKT](#) (NON-PTC)

Asset Type Track Segment Device TK CKT Track 2 Track Vendor Ticket#

Reg NO Div BA Sub RR 6619/6622 MP CFP 8.4000 Street City/State VA

Notes **First Ckt south of Elmont on 2 tk.**

Other Asset Summary

[Add Asset](#)

Call List Section [7869](#)

Supervisor [Kaufman, Shawn](#) Available

[Rolodex](#) [Escalation Call List](#)

**WS SMITH COVERS BETWEEN 5.2 & 57.5- J Horak AND L Scott BETWEEN 57.5 AND 110.19
PER DIV ENGR GREG WILHITE: CALL RDMSTR FIRST ON ANY DERAILMENT**

Shift 1 00:00 - 24:00

Order	Name	Status	Until	Last Response	ETA	Last Accepted Call (12 hrs)
1	Smith, Stewart	Available		--		
2	Joyce, Wayne	Available		--		
3	Horak, Jesse	Available		--		
4	Scott, Larry M	Available		--		
5	Horak, Jesse	Available		--		
6	FORTUNE, JAMES	Available		--		
7	Kozlak, Adam	Available		--		

Accepted Call

Name	Department	Accepted On	ETA
Kaufman, Shawn R	Engineering	05/18/2018 02:44	02:44

Notification Contacts

Attached Files

[Add Document](#)

No Documents Attached.

Related Incidents, Jumper and Shunt Logs Open

No related incidents, jumpers or shunts found for your department.

Incident History

[Update](#)

Description 05/18/2018 02:41:44 Status **Unassigned** By [Travis Hudson](#) - Engineering

Inc Type Unknown Asset Status Dtl Priority 1
Responsibility Control Center Responsible Dept. Message# Jumpers N/A

Updated 05/18/2018 02:43:25 Status **Unassigned** By [Travis Hudson](#) - Engineering

Inc Type Flash Flood Warning Asset Status Dtl Priority 1
Responsibility Control Center Responsible Dept. Message# Jumpers N/A

FLASH FLOOD WARNING NUMBER 8422
EFFECTIVE 19:06EDT HOURS 2018-05-17 UNTIL 06:00EDT HOURS 2018-05-18

EXTENDED: Rain and storms have impacted this area throughout the day today with rates to 0.5"/hr to produce 2-3 inches of rainfall. A total of 3-5 inches have fallen throughout the last few days here. Watch for localized flash flooding through this morning.

BU/SL DIVISION SUBDIVISION STATIONS
BALTIMORE RF AND P MP CFP 6.9992 - LAUREL, VA to MP CFP 49.9992
- SUMMIT, VA

Updated 05/18/2018 02:44:45 Status **Dispatched** By [Travis Hudson](#) - Engineering

Inc Type Flash Flood Warning Asset Status Dtl Priority 1
Responsibility Field Operations Responsible Dept. Message# Jumpers N/A

Status changed to Dispatched for Shawn Kaufman ETA of: N/A

Updated 05/18/2018 02:45:00

Status **Active**

By [TCIS AUTOMATION](#) - Engineering



Inc Type Flash Flood Warning

Asset Status Dtl

Priority

Responsibility

Responsible Dept.

Message#

Jumpers N/A

ETA time reached Status changed to Active

Closed 05/23/2018 06:29:11

Status **Closed**

By [Shawn Kaufman](#) - Engineering



Inc Type Flash Flood Warning

Asset Status Dtl

Priority 1

Responsibility Field Operations

Responsible Dept.

Message#

Jumpers N/A

Incident Resolved: 05/18/2018 07:00:00

Equipment Type: Track

Action Taken: FLASH FLOOD WARNING EXPIRED and INSPECTED

inspected no issues

Operational Checks Performed

Dispatchers

[Update](#)

Shift 1st Desk **BD** 1st Phone [REDACTED]

Incident # 8587592 Closed NON-PTC

Audit Trail Refresh Send To Call Response Summary Update

Opened 05-18-2018 04:39 [DWP](#) Department Engineering

Priority 1

[Escalation Policy](#)

Primary Asset Summary

Asset [6620 027 LAKESIDE to ELMONT - 27 CKT - TK 2](#) (NON-PTC)

Asset Type Track Segment Device TK CKT Track 2 Vendor Ticket#

Reg NO Div BA Sub RR 6620/6619 MP CFP 5.7000 Street City/State VA

Notes **Ckt between Elmont and Lakeside on 2 tk.**

Other Asset Summary

[Add Asset](#)

Call List Section [7869](#)

Supervisor [Kaufman, Shawn](#) Available

[Rolodex](#) [Escalation Call List](#)

**WS SMITH COVERS BETWEEN 5.2 & 57.5- J Horak AND L Scott BETWEEN 57.5 AND 110.19
PER DIV ENGR GREG WILHITE: CALL RDMSTR FIRST ON ANY DERAILMENT**

Shift 1 00:00 - 24:00

Order	Name	Status	Until	Last Response	ETA	Last Accepted Call (12 hrs)
1	Smith, Stewart	Available		--		
2	Joyce, Wayne	Available		--		
3	Horak, Jesse	Available		--		
4	Scott, Larry M	Available		--		
5	Horak, Jesse	Available		--		
6	FORTUNE, JAMES	Available		--		
7	Kozlak, Adam	Available		--		

Accepted Call

Name	Department	Accepted On	ETA
Kaufman, Shawn R	Engineering	05/18/2018 04:54	04:54

Notification Contacts

Attached Files[Add Document](#)

No Documents Attached.

Related Incidents, Jumper and Shunt Logs Open

No related incidents, jumpers or shunts found for your department.

Incident History[Update](#)

Description 05/18/2018 04:39:40	Status Unassigned	By David Price - Engineering	<input type="checkbox"/>
--	--------------------------	--	--------------------------

Inc Type Unknown	Asset Status Dtl	Priority 1	
Responsibility Control Center	Responsible Dept.	Message#	Jumpers N/A

Updated 05/18/2018 04:40:32	Status Unassigned	By David Price - Engineering	<input type="checkbox"/>
------------------------------------	--------------------------	--	--------------------------

Inc Type Flash Flood Warning	Asset Status Dtl	Priority 1	
Responsibility Control Center	Responsible Dept.	Message#	Jumpers N/A

FLASH FLOOD WARNING NUMBER 8431
 EFFECTIVE 04:29EDT HOURS 2018-05-18 UNTIL 09:00EDT HOURS 2018-05-18
 Rain with rates in excess of 0.5"/hr have produced 1-2 inches of rainfall over the last 3 hours. This rain is falling on saturated ground and will raise concerns for localized flash flooding.

BU/SL DIVISION SUBDIVISION STATIONS
 BALTIMORE RF AND P MP CFP 4.9992 - GREENDALE, VA to MP CFP 10.6092 - ELMONT, VA

Updated 05/18/2018 04:54:18	Status Dispatched	By David Price - Engineering	<input type="checkbox"/>
------------------------------------	--------------------------	--	--------------------------

Inc Type Flash Flood Warning	Asset Status Dtl	Priority 1	
Responsibility Field Operations	Responsible Dept.	Message#	Jumpers N/A

Status changed to Dispatched for Shawn Kaufman ETA of: N/A

Updated 05/18/2018 04:55:00	Status Active	By TCIS AUTOMATION - Engineering	<input type="checkbox"/>
------------------------------------	----------------------	--	--------------------------

Inc Type Flash Flood Warning Asset Status Dtl Priority
Responsibility Responsible Dept. Message# Jumpers N/A
ETA time reached Status changed to Active

Closed 05/23/2018 06:29:45 Status Closed By [Shawn Kaufman](#) - Engineering

Inc Type Flash Flood Warning Asset Status Dtl Priority 1
Responsibility Field Operations Responsible Dept. Message# Jumpers N/A

Incident Resolved: 05/18/2018 09:00:00
Equipment Type: Track
Action Taken: FLASH FLOOD WARNING EXPIRED and INSPECTED
inspected no issues
Operational Checks Performed

Dispatchers

[Update](#)

Shift 1st Desk **BD** 1st Phone [REDACTED]

Incident # 8588074 Closed NON-PTC

Audit Trail Refresh Send To Call Response Summary Update

Opened 05-18-2018 09:28 [TEH](#) Department Engineering

Priority 1

[Escalation Policy](#)

Primary Asset Summary

Asset [6603 001 ARKENDALE to POSSUM POINT - 1 CKT - TK 2](#) (NON-PTC)

Asset Type Track Segment Track 2 Vendor Ticket#

Reg NO Div BA Sub RR 6603/6610 MP CFP 72.6000 Street City/State QUANTICO VA

Notes When running on "approach" cabs, when reaching "mid-point blowdown" the cab signals will temporarily drop to "restricting" when a train is ahead. Both directions on both tracks, between Quantico and Dahlgren Jct.

Other Asset Summary

[Add Asset](#)

Call List Section [21269](#)

Supervisor [Kaufman, Shawn](#) Available

[Rolodex](#) [Escalation Call List](#)

Shift 1 00:00 - 24:00

Order	Name	Status	Until	Last Response	ETA	Last Accepted Call (12 hrs)
1	Horak, Jesse	Available		A/M_05-18-2018 09:38		
2	Scott, Larry M	Available		--		
3	Smith, Stewart	Available		--		
4	Joyce, Wayne	Available		--		
5	Faber, Jason	Available		--		
6	Kozlak, Adam	Available		--		

Notification Contacts

Attached Files

[Add Document](#)

No Documents Attached.

Related Incidents, Jumper and Shunt Logs Open

No related incidents, jumpers or shunts found for your department.

Incident History[Update](#)

Description 05/18/2018 09:28:09 Status **Unassigned** By [Thomas Haselden](#) - Engineering

Inc Type Unknown Asset Status Dtl Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

Updated 05/18/2018 09:28:37 Status **Unassigned** By [Thomas Haselden](#) - Engineering

Inc Type Flash Flood Warning Asset Status Dtl Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

FLASH FLOOD WARNING NUMBER 8433
EFFECTIVE 09:24EDT HOURS 2018-05-18 UNTIL 14:00EDT HOURS 2018-05-18
Rainfall rates exceeding 1.25"/hr will produce an additional 1.5 to 3 inches of rainfall across the area. Already saturated soil will yield flash flooding, with possible washouts and high water across the area.

BU/SL DIVISION SUBDIVISION STATIONS
BALTIMORE RF AND P MP CFP 65.0002 - DAFFAN, VA to MP CFP 84.9992 - NEABSCO, VA
BALTIMORE POPES CREEK MP QP 29.9992 - WINSTEAD, MD to MP QP 45.6792 - POPCREEK, MD
BALTIMORE HERBERT MP QJ 3.0002 - LONSIDING, MD to MP QJ 17.3592 - CHAPOINT, MD

Updated 05/18/2018 09:41:05 Status **Unassigned** By [Thomas Haselden](#) - Engineering

Inc Type Flash Flood Warning Asset Status Dtl Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

Left voice message with inspector Horak and voice message and email with RM.

Closed 05/23/2018 06:32:08 Status **Closed** By [Shawn Kaufman](#) - Engineering

Inc Type Flash Flood Warning Asset Status Dtl Priority 1

Responsibility Field Operations Responsible Dept. Message# Jumpers N/A

Incident Resolved: 05/19/2018 05:00:00
Equipment Type: Track

Action Taken: Track Restored to Service
slide at CFP 18.6. Repaired and back in service.
Operational Checks Performed

Dispatchers

[Update](#)

Shift 1st Desk **BD** 1st Phone 

Page Execution Time: 000.21 seconds