

Communication Summary

August 7, 2019

Information from: T. W. Cook, Recovery Company



Summary & Factual Information: Mr. Cook was asked how much fuel was recovered from the fuel tanks during the airplane recovery. He, in part, reported that both fuel tanks were breached and maybe about 5 gallons of fuel and ten gallons of water was present.

I can attest that the above summary is correct to the best of my knowledge:

Edward F. Malinowski
National Transportation Safety Board
Air Safety Investigator