



National Transportation Safety Board

Office of Aviation Safety

Central Region

Autopsy Report Summary

NTSB Accident No:	CEN20FA001
Accident Date/Time:	Thursday, 3 October 2019, at 0858 EDT
Accident Location:	Lansing, Michigan
Aircraft Make/Model:	Socata TBM 700 C2
Aircraft Registration:	N700AQ
Aircraft Serial No:	252

Pilot-in-Command

An autopsy of the pilot was performed by Sparrow Forensic Pathology, Lansing, Michigan. The autopsy report was reviewed by the NTSB Investigator-In-Charge and Chief Medical Officer. According to the autopsy report, the cause of death was blunt force injuries, and the manner of death was accident.

Pilot-Rated Passenger

An autopsy of the pilot-rated passenger was performed by Genesee County Medical Examiner, Flint, Michigan. The autopsy report was reviewed by the NTSB Investigator-In-Charge and Chief Medical Officer. According to the autopsy report, the cause of death was blunt force injuries, and the manner of death was accident.