





UZUSHIO

ALARM PRINTER

TYPE : UZAP

UZUSHIO ELECTRIC CO.,LTD.

SEL FEED



0705 CRSCODE TK
SEP.96 02:12.

MOON

L

MG-800 GOVERNOR SYSTEM ACTUATOR DRIVE UNIT

取り扱い上の注意点

1. コントロールユニットの電源を切る時は、アクチュエータドライブユニットの電源も切ってください。
2. アクチュエータドライブユニットの周囲温度は、45℃以上にならないように注意して下さい。
3. 異常発生時は以下の点検を実施して下さい。
 - 1) テンキー(030)~(034)のエラーコードを確認
 - 2) 燃料ラックがMAX. 側メカミットを確認
 - 3) 燃料ラックの操作力が重くないか確認
 - 4) 配線に異常が無い確認
 - 5) 保守・点検要領書に従ってトラブルシューティングを実施

Handling Precautions

1. When turning off the control unit, turn off the actuator drive unit at the same time.
2. Care must be taken so that the ambient temperature of the actuator drive unit does not exceed 45°C.
3. If any abnormal condition occurs, proceed as follows:
 - 1) Check error codes in ten-key addresses(030) to (034).
 - 2) Check if the FO rack touches the MAX. mechanical limiter.
 - 3) Check if the operating force of the FO rack is heavy.
 - 4) Check if there is any abnormal wiring.
 - 5) Troubleshoot according to the Maintenance Inspection Procedures.

⚠ 注意 CAUTION



感電注意

Voltage.
May cause
electric shock.

点検時には必ず電源を切ること
電圧やカバールームを開けず
と

DIESEL UNITED SULZER

Engine No.	DU-3563
Type	7RTA62
Rated Output	12800 KW.
Rated Output(B.H.P.)	17403 P.S.
Rated Speed	99 r.p.m.
Cylinder Bore	620 mm.
Piston Stroke	2150 mm.

Diesel United, Ltd.

AIOI JAPAN