



Federal Aviation Administration

Memorandum – Inspector Statement

Date: 01/May/2022

To: Atlanta FSDO Manager

From: Danny A. Cox, ASI, Atlanta FSDO, [REDACTED]

Subject: Accident N5704R, C172F, S/N; 17253357

On 30/Apr/2022, at approximately 1330 a student pilot and instructor were conducting training on runway 24 at Atlanta Speedway Airport (KHMP), in Hampton, Georgia. Wind conditions at time of touchdown reported at 200 @ 8 knots (5 know crosswind component). As the student touchdown and roll out attempted to correct for cross wind using Aileron and Rudder as she added rudder input her foot was also applying left brake pressure causing aircraft to veered off left side of runway 24. Pilot instructor attempted to correct condition but was unable to correct before hitting alpha 4 taxiway sign.

DANNY A COX Digitally signed by DANNY A COX
Date: 2022.05.01 15:45:16 -04'00'