NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASI	C INFORMA	TION											
Accide	nt/Incident Loc	ation					Accident/Incident Date/Time						
	City/Place: Kern				_ State: C	CA	Date	e: <u>09/</u>		Lo	cal Time: _	0844	
ZIP: <u>93</u>	3238 (Country: US/	4					mm/d	d/yyyy	Tir	me Zone: _	Pacific	
Latitude	:		Longitude:							11.	ine Zonei	acino	
	(Enter in decimal degrees or degrees:minutes:seconds)						Col	llision with	Other Air	eraft: C) Midair	OOn-groun	d O None
AIRC	RAFT INFO	RMATIO	N										
Registration Number: N9471H						□ IFR-Equi _] □ Commerc							
Manufacturer: Howard							□ Unmanne		gnt				
Model:	DGA-15P						Ma	aximum Gı	oss Weigh	t: <u>4500</u>		lbs	
Serial N	Number: <u>813</u>						W	eight at Tir	ne of Accid	ent/Inci	dent: <u>35</u> 0	00	_ lbs
Year of	Manufacture:	1943					Nu	ımber of Se	eats: 5		Flight Cre	w Seats: 1	
Amate			Kit/Plans Mak	ke:								Seats: 4	
	⊙ No	(Original Design				Nu	ımber of E	ngines:				
	ry of Aircraft		irworthiness Ce	rtificate		Landing Ge		* 1		_	e Type (Se		
AirplBallo		(Check all to				(Check all tha		<i>ply)</i> actable		O Reci	procating Shaft	OLıquı OSolid	d Rocket Rocket
OBlim	p/Dirigible	✓ Norma	al 🔲 Restric			☐ Tricycle			ailwheel	O Turb	o Prop	O Hybri	id Rocket
OGlide OGyro		☐ Aeroba☐ Balloo				☐ Amphibia	n	_	ligh Skid	O Turb O Turb		ONone OUnkn	
O Helic	opter	Comm	uter Special	Flight		Emergenc		oat 🔲 S	kid	O Elect		Ooman	O WIII
O Powe O Rock	ered Lift et	☐ Transp ☐ Utility		mental				ki ki/Wheel				,	
O Ultra	light	_ 0 time,		imental Light-Sport		1./	_		Fuel Sys		(Reciprocation (Recip		
O Unkn	iown		of Authorization	or Waiver (COA)			incn/			O Carb	uicioi	Oruei-	injected
		□None		Jnknown	 	☐ None	_	Date	Jnknown Rated Pow	or	Total	Time	Singa
			Engine			acturer's		of Mfg.	Horsep	ower or	Time	Inspection	Overhaul
Engine Eng. 1	Engine Manufa Pratt and Whitn		Model/Series R985 AN-14B		Serial N 207018	Number	-	mm/dd/yyyy UNK	O lbs of 7	Thrust	(hours) 5683	(hours)	(hours) 508
Eng. 2	T TALL AND WINLI	Су	11903 AIN-14B		207010		+	ONIX	450		3003	20	300
Eng. 3							1						
Eng. 4													
Last In	spection Type			Propelle	er 1	○Fixed P ⊙Control		Pitch	Prope	eller 2	_	Fixed Pitch Controllable I	Pitch
O 100 - H		inuous Airwo					Adjustable OGround Adjustable						
O AAIP O Annu	OCono al OUnki	ditional Inspec	etion	Manufac	turer:	<u> Iamilton Star</u>	ndard Manufacturer:						
	ast Inspection:		018	Model: _	2D30				Mode	:1:			
Date L	ast inspection:	mm/dd/yy		ELT In:	stalled:	⊙ Yes ○	No				ipment (Check all that	apply)
	ne Total Time:		hrs	If Yes:		Amanını izin			□ AD:	S-B rame Para	chute		
	rs measured at (S	/	: 1 - 4/T - : 1 - 4			er: <u>Ameri-Kir</u> .: <u>AK-450</u>	ig		Ang	le of Atta	ck Indicato	r	
TSO No.: OC91 (1) C91	la (121.5 MH	Aut	opilot a Recorde	r					
Type of Maintenance Program (Select one) OC126 (406 MHz)					(406 MHz)			□Elec	tronic Fli	ght Bag or	Handheld De	vice	
() (onditional (A mateur-built only)					unted in aircra			' = = -		ıltifunction mary Fligh			
O Manufacturer's Inspection Program Was						nected to anter		Ores ON	Han	dheld GP	S	P	
	r Approved Inspec inuous Airworthin	_	(AAIP)	If activa						ds Up Dis oard Wea			
O Other	r, specify:			Did ELT	Aid in L	ocating Aircra	ft: (Yes ONG			king Device	:	
	otion of Fire Ex	tinguishing	System	If not ac						l Warning			
NoneSpec				Indicate	Keason:	☐ Impact Dan ☐ Fire Damas		÷		eo Record er, Specify	ing Device y:		
C Spoo	y :					☐ Battery Ex		l/Damaged		- •			
						□Unknown							

OWNER/OPERATOR INFORMA	ATION					
Registered Aircraft Owner		City: Bakersfield				
Name: Todd Schultz		State: CA ZIP: 93308				
Fractional Ownership Aircraft: O Yes O	No	Country: USA				
Operator of Aircraft	gistered Owner	☐ Same Address as Registered Owner				
Name:		City:				
Doing Business As:		State: ZIP:				
Air Carrier/Operator Designator (4 Character	er Code):	Country:				
Operating Certificates Held (Check all that apply)	Regulation Flight Conducted Un	T				
□ None □ Flag Carrier Operating Certificate (FAR 121) □ Supplemental □ Air Cargo □ Foreign Air Carriers (FAR 129) □ Rotorcraft External Load (FAR 133) □ Commuter Air Carrier (FAR 135)	OFAR 91 OFAR 129 OFAR OFAR 103 OFAR 133 OFAR 135 OFAR 121 OFAR 135 OFAR 125 OFAR 137	431 O Non-Scheduled or Air Taxi O International				
□ On-Demand Air Taxi (FAR 135) □ Commercial Air Tour (FAR 136) □ Agricultural Aircraft (FAR 137) □ Pilot School (FAR 141) □ Certificate of Authorization or Waiver (COA) □ Commercial Space Transportation □ Experimental Permit □ Commercial Space Transportation License □ Other Operator of Large Aircraft	O Non-US, Non-commercial O Public Aircraft (Select one) O Armed Forces O Federal O State O Local O Unknown	Purpose of Flight for FAR 91, 103, 133, 137 (Select one) O Aerial Application OFirefighting OUnknown O Aerial Observation OFlight Test O Air Drop OGlider Tow O Air Race/Show OInstructional O Banner Tow OOther Work Use O Business OPersonal O Executive/Corporate OPositioning				
Revenue Sightseeing Flight	Air Medical Flight	O External Load O Skydiving Ferry				
O Yes O No	O Yes O No					
		proach, landing, takeoff, departure, or within 3 miles of an airport)				
	if accident/incident occurred on app	Distance From Airport Center: 0 sm Direction From Airport: degrees true Airport Elevation: 2614 ft. msl				
AIRPORT INFORMATION (Fill in Airport Name: Kern Valley Airport Identifier: L05	if accident/incident occurred on app	Distance From Airport Center: 0 sm Direction From Airport:				
Airport Name: Kern Valley Airport Identifier: L05 Proximity to Airport: O Off Airport/Airstri	if accident/incident occurred on application of the proof of the width: 500	Distance From Airport Center: 0 sm Direction From Airport: degrees true Airport Elevation: 2614 ft. msl				
AIRPORT INFORMATION (Fill in Airport Name: Kern Valley Airport Identifier: L05 Proximity to Airport: Off Airport/Airstri Runway Information Runway ID: 17 (L/R/C) Length: 35 Runway/Landing Surface (Check all that a Check Air Concrete Gravel Meta	if accident/incident occurred on apply p ② On Airport/Airstrip ② N/A 500 ft Width: 50 ft 1/Wood Water 1/Wood Unknown	Distance From Airport Center: 0				
AIRPORT INFORMATION (Fill in Airport Name: Kern Valley Airport Identifier: L05 Proximity to Airport: Off Airport/Airstri Runway Information Runway ID: 17 (L/R/C) Length: 35 Runway/Landing Surface (Check all that a language of the concrete Gravel Metall Dirt Ice Snow	if accident/incident occurred on application of the proof	Distance From Airport Center: 0				
AIRPORT INFORMATION (Fill in Airport Name: Kern Valley Airport Identifier: L05 Proximity to Airport: Off Airport/Airstri Runway Information Runway ID: 17 (L/R/C) Length: 35 Runway/Landing Surface (Check all that a gray) Asphalt Grass/Turf Maca Concrete Gravel Meta Snow Approach/Departure Segment (Select one OTaxi OVFR Departure OTFR Departure Processors)	if accident/incident occurred on application of the proof	Distance From Airport Center: 0				
AIRPORT INFORMATION (Fill in Airport Name: Kern Valley Airport Identifier: L05 Proximity to Airport: Off Airport/Airstri Runway Information Runway ID: 17 (L/R/C) Length: 35 Runway/Landing Surface (Check all that a Check a	if accident/incident occurred on application of the proof	Distance From Airport Center: 0				
AIRPORT INFORMATION (Fill in Airport Name: Kern Valley Airport Identifier: L05 Proximity to Airport: Off Airport/Airstri Runway Information Runway ID: 17 (L/R/C) Length: 35 Runway/Landing Surface (Check all that a gray) Asphalt Grass/Turf Maca Meta Gravel Meta Snow Louis Gravel Meta Snow Approach/Departure Segment (Select one OTaxi OVFR Departure OTaxi OVFR Departure OTakeoff OIFR Departure Proconditions (Check all that apply)	if accident/incident occurred on application of the proof	Distance From Airport Center: 0				

"FLIGHT CREWMEMBER 1" INFORMATION										
"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident ⊙ Pilot O Co-Pilot O Student Pilot O Flight Instructor O Check Pilot O Flight Engineer O Other Flight Crew										
"Flight Crewmember 1" was	pilot flying	□Yes □ N	No							
"Flight Crewmember 1" Ider	ntification									
First Name: Todd City of Residence: Bakersfield										
Middle Initial: H State: CA ZIP: 93308										
Last Name: Schultz Country: USA										
Age at time of Accident/Incident: 26 Date of Birth: mm/dd/yyyy										
Certificate Number:										
Degree of Injury Seat Occupied Restraint Type Inflatable Restraints										
⑤ None ⑤ Fatal ⑥ Minor ⑥ Unknown ⑥ Right ⑥ Rear ⑥ Serious ⑥ Center ⑥ Single Ø None Ø None Ø None										
Pilot Certificate(s) (Check all	1 -	<u> </u>			● Lap on O 3-point			У	☐ Installed	
None ☐ Flight In☐ Private ☐ Recreation☐ Student ☐ Sport	structor	Commercial Airline Transp Flight Enginee			O 4-point O 5-point O Unknow		O 4-point O 5-point O Unknow	vn	☐ Deploye	ed
Principal Occupation M	ledical Certific	ate		Med	lical Cert	ificate Va	lidity		Date of Las	t Medical
O Other	Class 1	Class 3 Driver's Lice Unknown	ense (Sport Pilot	tonly) OW		tations/wai ons/waivers ince		J nknown J/A	07/23/20° mm/dd/yy	
Medical Certificate Limitation	ons									
None										
Medical Certificate Special Is	ecuanca									
N/A	ssuance									
Date of Last Flight Review		Fligh	t Review Airo	eraft						
or Equivalent, Including	06/06/2019	Make	Cessna							
FAR 121/135 Checks:	06/06/2018 mm/dd/yyyy	— Model	ı: C25A							
Airplane Rating(s)	Other Aircraf			ent Rating(s)	1	Instructo	r Rating(s)			
(Check all that apply)	(Check all that a			l that apply)		(Check all				
☐ None☑ Single-Engine Land	☐ None		□ None			☐ None	C: 1 E		Instrument A	
✓ Single-Engine Land ✓ Single-Engine Sea	☐ Airship ☐ Balloon		☐ Airpla☐ Helico				e Single-Eng e Multi-Engi		Instrument l Helicopter	Helicopter
✓ Multiengine Land	☑ Glider		☐ Power			☐ Gyropla	ine		Glider	
☐ Multiengine Sea	☐ Gyroplane ☐ Helicopter					☐ Powered	d Lift		Sport	
	☐ Powered Lift									
Type Ratings						Student E	Endorsemei	nts (Include	dates)	
C525S										
Flight Time (Euton ammonwints			Airplane		Ι ΄	Inst	rument			
Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Single Engine	Airplane Multiengine	Night	Actual	Simulated	Rotorcraft	Glider	Lighter Than Air
Total Time	7,800	162	3,300	4,500	250	100	150		30	
Pilot in Command (PIC)	7,000	162	2,900	4,100	240	90	90		25	
Time as Instructor	1,800	0	1,700	100	35	5	20		0	
This Make/Model					5	<u> </u>	0			
Last 90 Days	75	15	15	60	10	2	0		0	
Last 30 Days	25	6	6	19	4	1	0		0	
Last 24 Hours	4	4	4	0	J 1	0	0	I	0	

"FLIGHT CREWMEMBER 2" INFORMATION										
"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident OPilot OCo-Pilot OStudent Pilot OFlight Instructor OCheck Pilot OFlight Engineer OOther Flight Crew										
"Flight Crewmember 2" v	vas pilot flying 🔲 Y	es □No)							
"Flight Crewmember 2" I	dentification									
First Name: City of Residence:										
Middle Initial: ZIP:										
Last Name:	Last Name: Country:									
	f Accident/Incident:									
			icate Number:							
Degree of Injury	Seat Occupied			Restra	int T	vpe		I	nflatable R	estraints
O None O Fatal	OLeft C	Front	OUnknown		ailabl	-	Used	-		
O Minor O Unknown O Serious		ORear OSingle			Mone		O None		☐ Not Inst	alled
	I	Single			Lap o		O Lap only	'	☐ Installed	
Pilot Certificate(s) (Check ☐ None ☐ Fligh	att Instructor	naraial	☐ US Military) 3-poi:) 4-poi:		O 3-point O 4-point		☐ Not Dep ☐ Deploye	-
☐ Private ☐ Recre		e Transport) 5-poi		O 5-point		☐ Unknow	n
☐ Student ☐ Spor	t ☐ Flight	t Engineer) Unkn	iown	O Unknow	n		
Principal Occupation	Medical Certificate			Medica	al Cei	rtificate Val	lidity]	Date of Las	t Medical
O Pilot	O None O Clas	ss 3				nitations/waiv	-	nknown		
O Other			(Sport Pilot only)			ations/waivers			mm/dd/yy	
O Unknown	O Class 2 O Unk	inown		O Spec	cial Iss	uance			mm/aa/yy	yy
Medical Certificate Limit	ations									
Medical Certificate Specia	al Issuance									
Date of Last Flight Review	v	Flight R	eview Aircraft							
or Equivalent, Including		_								
FAR 121/135 Checks:	mm/dd/yyyy	Model:								
Airplane Rating(s)	Other Aircraft Ra	_	Instrument R	ating(s)	T	Instructor	Rating(s)			
(Check all that apply)	(Check all that apply)		(Check all that a			(Check all th				
None	☐ None		None			☐ None		□	Instrument A	irplane
☐ Single-Engine Land☐ Single-Engine Sea	☐ Airship ☐ Balloon		☐ Airplane ☐ Helicopter			☐ Airplane ☐ Airplane			Instrument H Helicopter	elicopter
☐ Multiengine Land	☐ Glider		Powered Lift			Gyroplan			Glider	
☐ Multiengine Sea	☐ Gyroplane ☐ Helicopter					☐ Powered	Lift		Sport	
	☐ Powered Lift									
Type Ratings						Student En	idorsement	s (Include de	ates)	
FILL (T) = -			Airplane			Insti	rument			
Flight Time (Enter appropring number of hours in each box)	**** ****	s Make Model		plane iengine	Night		Simulated	Rotorcraft	Glider	Lighter Than Air
Total Time			Zingine 17441			1 setuai	Simulated		5	
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Addr	·ess						Seat Occupie	d	Injury
Middle Initial:	First Name:						O Left O Center O Right	O Front O Rear O Single O Unknown	O None O Minor O Serious O Fatal O Unknown
Pilot Certificate(s) (Check all that apply) None							Restraint Ty Available O None O Lap Only O 3-point O 4-point O 5-point O Unknown	Vsed O None O Lap Only O 3-point O 4-point O 5-point O Unknown	Inflatable Restraints Not Installed Installed Not Deployed Deployed Unknown
Crew Name and Address First Name: City of Residence: Middle Initial: State: ZIP: Last Name: Country:						OLeft OCenter ORight	O Front O Rear O Single O Unknown	O None O Minor O Serious O Fatal O Unknown	
Pilot Certificate(s) (Check all that apply) None Flight Instructor Commercial US Military Private Recreational Airline Transport Foreign Student Sport Flight Engineer Type Rating/Endorsement for Total Flight Time at the Time Accident/Incident Aircraft? Yes No of this Accident/Incident: hrs						Restraint Ty Available O None O Lap Only O 3-point O 4-point O 5-point O Unknown	Vsed None Lap Only 3-point 4-point 5-point Unknown	Inflatable Restraints Not Installed Installed Not Deployed Deployed Unknown	
PASSENGER(S) /	OTHER PERSO	NNEL (Ir	nclude c	abin crew; c	ontinue on se	eparate shee	t if necessary)		
Name and Address				Seat	Injury	Restraint T	`уре	Inflatable Restraints	Age
First Name: Kindra Middle Initial: M Last Name: Hill OCrew	State: <u>CA</u> Z	ZIP: <u>93308</u>		OLeft OCenter ORight OUnknown Row:	O None O Minor O Serious O Fatal O Unknown	Available O None O Lap Only O 3-point O 4-point O 5-point O Unknown	O 3-point O 4-point O 5-point	☑ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ○ Child Restraint ○ Lap-Held ○ Unknown
First Name: Middle Initial: Last Name: OCrew	State: 2	ZIP:		OLeft OCenter ORight OUnknown Row:	O None O Minor O Serious O Fatal O Unknown	Available O None O Lap Only O 3-point O 4-point O 5-point O Unknown	O 3-point O 4-point O 5-point	□ Not Installed □ Installed □ Not Deployed □ Deployed □ Unknown	☐ Under 5 years
First Name: Middle Initial: Last Name: OCrew	State: 2	ZIP:	<u> </u>	OLeft OCenter ORight OUnknown Row:	O None O Minor O Serious O Fatal O Unknown	Available O None O Lap Only O 3-point O 4-point O 5-point O Unknown	O 3-point O 4-point O 5-point	Not Installed Installed Not Deployed Deployed Unknown	☐Under 5 years
First Name: Middle Initial: Last Name: Crew	State: 2	ZIP:		OLeft OCenter ORight OUnknown Row:	O None O Minor O Serious O Fatal O Unknown	Available ONone OLap Only O3-point O4-point O5-point OUnknown	Used O None O Lap Only O 3-point O 4-point O 5-point	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years

FLIGHT ITINERARY	INFORMATIO	N						
Airport ID: L05 City: Kernville State: CA	Time	e of Departure :: 0844 :: Zone: Pacific	Airport ID: City: Bake State: CA	Destination Airport ID: L45 City: Bakersfield State: CA		Type Flight None Company Military VFR	y VFR VFR	O VFR/IFR O IFR O Unknown
Country: USA			Country: L	JSA		Activated?	OYes	ONo OUnknown
☐ VFR	☐ Special VFR ☐ IFR	□ Spe	ecial IFR R On Top		☐ VFR Flight Foll☐ Traffic Advisory		☐ Crui ☐ Unk	se nown / NA
☐ Class B ☐ Demo Area ☐ Air			itary Operations port Advisory A Training Area SA		□Special □Air Traffic Cont □Unknown	rol Area	Occui	de of In-Flight rrence: AGL ft msl
WEATHER INFORM	IATION AT THE	ACCIDENT	T/INCIDEN	T SITE				
Source of Pilot Weather In (Check all that apply) National Weather Service Flight Service Station TV/Radio Automated Report Commercial Weather Service On-Board Weather	☐ Com ☐ Mili ☐ Inter ☑ Non	tary net e		Facility ID: Observation Ti Time Zone: Distance from	servation Facility me: Accident Site: Accident Site:		nm	s true
Basic Conditions OVMC OIMC OUnknown		Light Conditi ODawn ODay	ODusk ONight	O Dark O Brig	k Night O Ur ht Night	nknown		
Sky/Lowest Cloud Condit	O Thin Broken O Thin Overcast O Unknown	Ceiling None (Clear) Sroken Overcast Ceiling Heigh	0	Obscured Indefinite Unknown ft agl	Temperature: Dew Point: Altimeter Sett	(C	C) orin.	(F)
Wind Direction ☐ Variable -or- Direction:degrees tru Intensity of Precipitation O Light O Moderate	Type of Precipit ☑ None □ Rain	kts ation (Check all t Drizzle Ice Pellets	☐ Freezin ☐ Snow S	kts g Rain	RVV Density Altitu Restriction to None Blowing Do	de: unk Visibility (C	feetmiles Check all to Fog Ground Fo	_ ft that apply)
O Heavy ⊙ N/A O Unknown	☐ Snow ☐ Hail ☐ Rain Showers	☐ Snow Pellet☐ Snow Grain☐ Ice Crystals	s 🛮 Freezin		☐ Blowing Sa ☐ Blowing Sn ☐ Blowing Sp ☐ Dust	ow 🔲 I oray 🔲 S	Haze ce Fog Smoke Jnknown	
Icing Forecast Amount None None N/A Type N/A Rime Clear Mixed Severe Unknown		Icing Actual Amount None Trace Light Moderate Severe Unknown	Type N/A Rime Clean Mixe Unkr	r ed	Turbulence Type (Check a ☑ None ☐ Clear Air ☐ Terrain-Indu ☐ Convective	uced		everity Light Moderate Severe Extreme
NOTAMs (D and FDC). None	AIRMETs, SIGN	AETs, PIREPs	s in effect at	the time of the	he accident/inci	dent:		

Aircraft Damage Name O Substantial O None: O Bustroyed O Unknown O Destroyed O Unknown O Unkno	DAMAGE	TO AIDODAFT AI	UD OTHER RD	DEDTY		
None O Substantial O Destroyed O Destroyed O In-Flight O Freat Unknown Time O Unknown Description of Damage to Aircraft and Other Property (Use additional sheet if necessary) Entire aircraft burned up NARRATIVE HISTORY OF FLIGHT (Please type or print in ink) Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.				DPERIY		
O Minor O Destroyed O Unknown O Din-Flight O Din-Ground O Unknown Time O Unknown O Description of Damage to Aircraft and Other Property (Use additional sheet if necessary) Entire aircraft burned up NARRATIVE HISTORY OF FLIGHT (Please type or print in ink) Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exitted immediately through the cabin door.		9		O Doth Capyerd and In Plant	-	O Doth Course Lond Live Fill La
Description of Damage to Aircraft and Other Property (Use additional sheet if necessary) Entire aircraft burned up NARRATIVE HISTORY OF FLIGHT (Please type or print in ink) Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.	_		-			
NARRATIVE HISTORY OF FLIGHT (Please type or print in ink) Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.	•			Ξ	- 0	_ •
NARRATIVE HISTORY OF FLIGHT (Please type or print in ink) Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.	Description	of Damage to Aircraft a	nd Other Property	(Use additional sheet if necessary)		
NARRATIVE HISTORY OF FLIGHT (Please type or print in ink) Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.	_	_	na Gener Property	ese dadinonal sheer (j necessary)		
Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.	Entire aircra	t burned up				
Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.						
Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.						
Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.						
Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.						
Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.						
wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.	NARRATIV	E HISTORY OF FLI	GHT (Please type o	r print in ink)		
destination. Provide as much detail as possible. Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.						
Started engine on the ramp and taxied to runway 17. Sat at idle 1000 RPM for engine oil to warm up at least 60C. Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.				ts if needed. State departure time and	and location, services	s obtained, and intended
Performed runup per operating manual, checked carb heat, magnetos, cycled prop, checked all engine gauges and everything was operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.	destination.	Provide as much detail as	possible.			
operating normally. Checked fuel to be on Main tank (Center) for takeoff as per manual. Gauge indicated 3/8 full. Front tank was 1/2. Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.						
Waited probably 10 minutes for traffic pattern to clear and made a standard short field takeoff. Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.						
Lifted off ground around 70 mph and accelerated to about 85 in a 10 degree nose up attitude. At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.						8 full. Front tank was 1/2.
At about 40-50 feet AGL the engine instantly lost power. At that speed, there was not enough time and altitude to lower the nose and flare for touchdown. Both landing gear collapsed and the aircraft slid on its belly 330 feet. My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.						
My passenger and I noticed fire and smoke as soon as we came to a stop and we exited immediately through the cabin door.	At about 40-	50 feet AGL the engine	instantly lost powe	r. At that speed, there was not e		de to lower the nose and flare
					limmodiataly through	h the eabin door
				s we came to a stop and we exited	immediately throug	n the cabin door.
	7 moran was	anon consumed by me				

RECOMMENDATION (How	could this	accident/incident ha	ave been pre	vented?)				
Operator/Owner Safety Recomm	endation							
There is no practical way to m pickup was near the middle of acceleration and the pump sur With fuel at a lower level, nose Occasional calibration of the finanual dip stick. Install electric boost pump to residue of the properties of the propert	the tank. Nocked a big and high pitch uel gauges	Vith the nose-high air bubble. after takeoff should should be recomm	attitude on t d recommer ended since	akeoff, I	suspect all the mited. no way to cont	fuel went to the ba	ck during the initial	
This is based on my theory of the cause. The engine driven fuel pump could have failed or any number of other things such as a loose hose or electrical grounding issue with the magnetos.								
MECHANICAL MALFUN	ICTION/F	FAILURE (If moi	re space is n	eeded, co	ntinue on sepa	rate sheet)		
Was there Mechanical Malfund (If yes, list the name of the part, man			scribe the failu	re.)			Total Time/Cycles On Part	
Not aware of mechanical mal	function at	this time					Hours	
							Cycles	
	Time Since This Part							
							Inspected/Overhauled	
							Hours	
FUEL & SERVICES INF	ORMATI	ON						
Fuel on Board at Last Takeoff		Fuel Type						
(Convert from pounds, as necessary)	Callons	○ 80/87 ○ 100 Low Lead	O 115/145 O Jet A		O Jet B O JP8	O Other, specify		
Other Services, if Any, Prior to	Gallons Denarture	O 100/130	O Jet A-1		O Automotive			
,	1							
EVACUATION OF AIRC	RAFT							
Was an emergency evacuation			☑ Yes	□ No				
Method of Exit – Describe how	the occupan	ts exited and how ma	any occupants	s evacuate	d each location			
Exit out cabin door. 2 people/								
OTHER AIRCRAFT - C	OLLISIO	(If air or ground	collision occ	urred. co	mplete this sect	tion for <i>other</i> aircraf	t)	
Aircraft Registration Number		ırer:				ъ	nage to Other Aircraft	
						□ D	estroyed	
Registered Owner of Other Air	craft			Pilot of	Other Aircraft			
Name:								
City: State: ZIP:				City: State:		ZIP:		
Country:				Country:				

ADDITIONAL INFORMATION (Please type or print in ink)							
Use this space if addi	tional space	e is needed for any answers.					
I HEREBY CERTIF	Y THAT TI	HE ABOVE INFORMATION IS COMPL	ETE AND ACCURATE TO THE I	BEST OF MY KNOWLEDGE			
Date of this Report	Name of	Pilot/Operator: Todd Schultz					
10/09/2018		e:					
mm/dd/yyyy	or	✓ Check here to electronically sign this	document				
			document				
	_	perator is Filing Report					
or □C	heck here t	o electronically sign this document					
		FOR NTSB	USE ONLY				
NTSB Accident/Incident/NTSB Accident/In	dent No.	Reviewed by NTSB Regional Office	Name of Investigator	Date Report Received			
WPK18LA2/8		WPR - Federal Way	S. Stein	October 9, 2018			