

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 1:13 AM	UNACK_ALM	30_ALM_SF_C_Diff_Press_HI	Filter C -- Diff Pressure Above 13		1	
10/1/21 1:13 AM	UNACK_ALM	30_ALM_SF_D_Diff_Press_HI	Filter D -- Diff Pressure Above 13		1	
10/1/21 1:13 AM	ACK_RTN	30_ALM_SF_D_Diff_Press_HI	Filter D -- Diff Pressure Above 13		1	NULL
10/1/21 1:13 AM	ACK	30_ALM_SF_D_Diff_Press_HI	Filter D -- Diff Pressure Above 13		1	NULL
10/1/21 2:01 AM	ACK_RTN	30_ALM_SF_C_Diff_Press_HI	Filter C -- Diff Pressure Above 13		1	NULL
10/1/21 2:01 AM	ACK	30_ALM_SF_C_Diff_Press_HI	Filter C -- Diff Pressure Above 13		1	NULL
10/1/21 4:08 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 4:16 AM	ACK_RTN	60_ALM_Chem_Biocide_LowFlow	Biocide Low Flow Alarm		1	NULL
10/1/21 4:16 AM	ACK	60_ALM_Chem_Biocide_LowFlow	Biocide Low Flow Alarm		1	NULL
10/1/21 4:16 AM	ACK_RTN	60_ALM_Chem_Biocide_HighFlow	Biocide High Flow Alarm		1	NULL
10/1/21 4:16 AM	ACK	60_ALM_Chem_Biocide_HighFlow	Biocide High Flow Alarm		1	NULL
10/1/21 4:16 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/1/21 4:16 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 4:16 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 4:23 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 4:23 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 4:27 AM	UNACK_ALM	30_ALM_SF_C_Diff_Press_HI	Filter C -- Diff Pressure Above 13		1	
10/1/21 4:27 AM	UNACK_ALM	30_ALM_SF_D_Diff_Press_HI	Filter D -- Diff Pressure Above 13		1	
10/1/21 4:27 AM	ACK_RTN	30_ALM_SF_D_Diff_Press_HI	Filter D -- Diff Pressure Above 13		1	NULL
10/1/21 4:27 AM	ACK	30_ALM_SF_D_Diff_Press_HI	Filter D -- Diff Pressure Above 13		1	NULL
10/1/21 4:27 AM	UNACK_ALM	30_ALM_SF_D_Diff_Press_HI	Filter D -- Diff Pressure Above 13		1	
10/1/21 4:29 AM	ACK_RTN	30_ALM_SF_C_Diff_Press_HI	Filter C -- Diff Pressure Above 13		1	NULL
10/1/21 4:29 AM	ACK	30_ALM_SF_C_Diff_Press_HI	Filter C -- Diff Pressure Above 13		1	NULL
10/1/21 4:29 AM	ACK_RTN	30_ALM_SF_D_Diff_Press_HI	Filter D -- Diff Pressure Above 13		1	NULL
10/1/21 4:29 AM	ACK	30_ALM_SF_D_Diff_Press_HI	Filter D -- Diff Pressure Above 13		1	NULL
10/1/21 4:59 AM	UNACK_ALM	20_ALM_Elly_Drive_Gain_High	LDS -- Elly Micro Motion Drive Gain High		1	
10/1/21 4:59 AM	ACK_RTN	20_ALM_Elly_Drive_Gain_High	LDS -- Elly Micro Motion Drive Gain High		1	NULL
10/1/21 4:59 AM	ACK	20_ALM_Elly_Drive_Gain_High	LDS -- Elly Micro Motion Drive Gain High		1	NULL
10/1/21 5:04 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 5:07 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 5:07 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 5:14 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 5:14 AM	ACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 5:14 AM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 5:14 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 5:24 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 5:27 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 5:27 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 5:27 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 5:27 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 5:29 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 5:30 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 5:46 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 5:46 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 5:46 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 5:46 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 5:46 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 5:49 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 5:51 AM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 5:51 AM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 5:51 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 5:51 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 5:51 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 5:51 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 5:51 AM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 5:51 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 5:51 AM	ACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 5:51 AM	ACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 5:55 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 5:56 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 5:56 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 5:57 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 5:57 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 5:57 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 5:58 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 6:17 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 6:19 AM	UNACK_ALM	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	
10/1/21 6:19 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 6:19 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 6:19 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 6:19 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 6:19 AM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 6:19 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 6:20 AM	ACK_RTN	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	NULL
10/1/21 6:20 AM	ACK	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	NULL
10/1/21 6:21 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 6:48 AM	UNACK_ALM	U35_ALM_051	ALM_051 : Z399-1A: Combustible Gas Detector (Enc) Monitor		2	
10/1/21 6:48 AM	UNACK_ALM	U35_SDFSLO_049	SDFSLO_049 : Z399-1B: Combustible Gas Detector (Enc) Monitor		1	
10/1/21 6:51 AM	ACK_RTN	U35_ALM_051	ALM_051 : Z399-1A: Combustible Gas Detector (Enc) Monitor		2	NULL
10/1/21 6:51 AM	ACK	U35_ALM_051	ALM_051 : Z399-1A: Combustible Gas Detector (Enc) Monitor		2	NULL
10/1/21 6:51 AM	ACK_RTN	U35_SDFSLO_049	SDFSLO_049 : Z399-1B: Combustible Gas Detector (Enc) Monitor		1	NULL
10/1/21 6:51 AM	ACK	U35_SDFSLO_049	SDFSLO_049 : Z399-1B: Combustible Gas Detector (Enc) Monitor		1	NULL
10/1/21 6:51 AM	UNACK_ALM	U36_ALM_014	ALM_014 : Fire/Gas System Lock-Out Active		2	
10/1/21 6:55 AM	UNACK_ALM	U36_ALM_051	ALM_051 : Z399-1A: Combustible Gas Detector (Enc) Monitor		2	
10/1/21 6:55 AM	UNACK_ALM	U36_ALM_025	ALM_025 : Z399-1B: Combustible Gas Detector (Enc) Monitor Alarm		2	
10/1/21 6:57 AM	ACK_ALM	U36_ALM_025	ALM_025 : Z399-1B: Combustible Gas Detector (Enc) Monitor Alarm		2	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 6:57 AM	ACK_ALM	U36_ALM_051	ALM_051 : Z399-1A: Combustible Gas Detector (Enc) Monitor		2	
10/1/21 6:57 AM	ACK_ALM	U36_ALM_014	ALM_014 : Fire/Gas System Lock-Out Active		2	
10/1/21 6:57 AM	ACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 6:57 AM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 6:57 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 6:57 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 6:57 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 7:00 AM	ACK_RTN	U36_ALM_025	ALM_025 : Z399-1B: Combustible Gas Detector (Enc) Monitor Alarm		2	
10/1/21 7:00 AM	ACK_RTN	U36_ALM_051	ALM_051 : Z399-1A: Combustible Gas Detector (Enc) Monitor		2	
10/1/21 7:00 AM	ACK_RTN	U36_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	
10/1/21 7:00 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 7:00 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 7:00 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 7:00 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 7:01 AM	UNACK_ALM	U36_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	
10/1/21 7:01 AM	ACK_RTN	U36_ALM_014	ALM_014 : Fire/Gas System Lock-Out Active		2	
10/1/21 7:13 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 7:13 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 7:13 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 7:13 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 7:20 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 7:27 AM	UNACK_ALM	85_TestTreatA_Test_Complete	V03A Well Test Complete		1	
10/1/21 7:27 AM	UNACK_ALM	85_TestTreatB_Test_Complete	V03B Well Test Complete		1	
10/1/21 7:27 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 7:27 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 7:32 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 7:41 AM	ACK_ALM	U36_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	
10/1/21 7:41 AM	ACK_ALM	85_TestTreatB_Test_Complete	V03B Well Test Complete		1	
10/1/21 7:41 AM	ACK_ALM	85_TestTreatA_Test_Complete	V03A Well Test Complete		1	
10/1/21 7:41 AM	ACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 7:41 AM	ACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 7:41 AM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 7:41 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 7:41 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 7:41 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 7:42 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 7:42 AM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	
10/1/21 7:42 AM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/1/21 7:42 AM	UNACK_ALM	14_ALM_Atmos_Comm_Fail_PS_PLC	Atmos Communications Failure to Beta PS PLC 5		500	
10/1/21 7:42 AM	UNACK_ALM	10_ALM_PLC_Comm_Fail_Atmos	Communications from PLC to Atmos Failed		1	
10/1/21 7:51 AM	ACK_RTN	10_ALM_PLC_Comm_Fail_Atmos	Communications from PLC to Atmos Failed		1	NULL
10/1/21 7:51 AM	ACK	10_ALM_PLC_Comm_Fail_Atmos	Communications from PLC to Atmos Failed		1	NULL
10/1/21 7:51 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 7:51 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 7:51 AM	ACK_RTN	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	NULL
10/1/21 7:51 AM	ACK	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	NULL
10/1/21 7:51 AM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/1/21 7:51 AM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/1/21 7:51 AM	ACK_RTN	14_ALM_Atmos_Comm_Fail_PS_PLC	Atmos Communications Failure to Beta PS PLC 5		500	NULL
10/1/21 7:51 AM	ACK	14_ALM_Atmos_Comm_Fail_PS_PLC	Atmos Communications Failure to Beta PS PLC 5		500	NULL
10/1/21 7:51 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 7:51 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 8:03 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 8:10 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 8:10 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 8:10 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 8:10 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 8:10 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 8:25 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 8:30 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 8:30 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 8:33 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 8:41 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 8:41 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 8:41 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 8:41 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 8:41 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:55 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 8:56 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 8:56 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 8:56 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 8:56 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 8:56 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 8:56 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 9:08 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 9:08 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 9:08 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 9:08 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 9:08 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:18 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 9:47 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/1/21 9:47 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 9:47 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 9:47 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 9:47 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 9:47 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 9:47 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 9:47 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 9:47 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 9:54 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 9:54 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 9:54 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 9:54 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 9:54 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 9:54 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 9:54 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 9:54 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 9:54 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 9:55 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 9:55 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 10:48 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 10:50 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 10:50 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 10:55 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	
10/1/21 10:55 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 10:55 AM	ACK	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 10:55 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	
10/1/21 10:56 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/1/21 10:56 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 10:56 AM	ACK	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 10:56 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 10:56 AM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 10:56 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/1/21 10:56 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	
10/1/21 10:59 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 11:00 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 11:01 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 11:01 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 11:01 AM	ACK	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 11:01 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 11:01 AM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 11:01 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 11:01 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 11:01 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:01 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:01 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	
10/1/21 11:01 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 11:01 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:01 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 11:01 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 11:01 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 11:01 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 11:01 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 11:01 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/1/21 11:01 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 11:01 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 11:01 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:01 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:01 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:01 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:01 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 11:02 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 11:02 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/1/21 11:02 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 11:02 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 11:02 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:02 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:02 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 11:06 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 11:08 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 11:08 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 11:08 AM	ACK	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 11:08 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/1/21 11:08 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/1/21 11:08 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 11:08 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 11:08 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 11:08 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 11:08 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 11:08 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 11:08 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/1/21 11:08 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 11:08 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:08 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:09 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 11:10 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:10 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:10 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 11:13 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/1/21 11:17 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/1/21 11:17 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/1/21 11:17 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 11:17 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 11:17 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 11:17 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 11:17 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 11:17 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 11:17 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 11:17 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 11:17 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 11:17 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/1/21 11:17 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/1/21 11:17 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/1/21 11:17 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 11:17 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 11:25 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/1/21 11:25 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 11:25 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 11:25 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 11:25 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 11:26 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/1/21 11:27 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 11:27 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 11:27 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 11:27 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 11:27 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/1/21 11:27 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 11:27 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 11:28 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/1/21 11:28 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 11:28 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 11:32 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	
10/1/21 11:32 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/1/21 11:32 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/1/21 11:32 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 11:32 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 11:32 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 11:32 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 11:32 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 11:33 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 11:36 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/1/21 11:36 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 11:36 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 11:36 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:36 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 11:36 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 11:36 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 11:37 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 11:37 AM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 11:37 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:37 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:37 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 11:37 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/1/21 11:37 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:37 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:37 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 11:41 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 11:41 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/1/21 11:41 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 11:41 AM	ACK	91_Alm_V01B_Water_Vlv_100_Pos	Warning--V01B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 11:41 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 11:41 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 11:41 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 11:41 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 11:41 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:41 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:42 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 11:43 AM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 11:43 AM	UNACK_ALM	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	
10/1/21 11:43 AM	UNACK_ALM	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	
10/1/21 11:43 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:43 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:44 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 11:47 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 11:48 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/1/21 11:48 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 11:48 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 11:48 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/1/21 11:48 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/1/21 11:48 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 11:48 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 11:48 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:48 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:48 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/1/21 11:48 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 11:48 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 11:48 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 11:49 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 11:51 AM	ACK_RTN	U36_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	
10/1/21 11:51 AM	ACK_RTN	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	NULL
10/1/21 11:51 AM	ACK	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	NULL
10/1/21 11:51 AM	ACK_RTN	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/1/21 11:51 AM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/1/21 11:51 AM	ACK_RTN	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	NULL
10/1/21 11:51 AM	ACK	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	NULL
10/1/21 11:56 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/1/21 11:56 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:56 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:56 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:56 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 11:56 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 11:56 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 12:03 PM	UNACK_ALM	50_ALM_Sat_NP07A_Dsl_Switch_Fail	NP07A Diesel Switch Failure		1	
10/1/21 12:03 PM	UNACK_ALM	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	
10/1/21 12:03 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 12:03 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 12:03 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 12:04 PM	UNACK_ALM	50_ALM_Cen_NJ01C_Dsl_Rep_Err	NJ01C Diesel Reported Without Usage Alarm		1	
10/1/21 12:04 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 12:04 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 12:04 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/1/21 12:04 PM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/1/21 12:04 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 12:04 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 12:04 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 12:04 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 12:04 PM	ACK_RTN	50_ALM_Sat_NP07A_Dsl_Switch_Fail	NP07A Diesel Switch Failure		1	NULL
10/1/21 12:04 PM	ACK	50_ALM_Sat_NP07A_Dsl_Switch_Fail	NP07A Diesel Switch Failure		1	NULL
10/1/21 12:04 PM	ACK_RTN	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/1/21 12:04 PM	ACK	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/1/21 12:04 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/1/21 12:04 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/1/21 12:04 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 12:04 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 12:04 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 12:04 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 12:04 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 12:12 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 12:12 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 12:12 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 12:12 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 12:12 PM	ACK_RTN	50_ALM_Cen_NJ01C_Dsl_Rep_Err	NJ01C Diesel Reported Without Usage Alarm		1	NULL
10/1/21 12:12 PM	ACK	50_ALM_Cen_NJ01C_Dsl_Rep_Err	NJ01C Diesel Reported Without Usage Alarm		1	NULL
10/1/21 12:13 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/1/21 12:13 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 12:13 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 12:13 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/1/21 12:13 PM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/1/21 12:13 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 12:13 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 12:13 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/1/21 12:13 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/1/21 12:13 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 12:14 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/1/21 12:15 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 12:15 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 12:15 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/1/21 12:15 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/1/21 12:15 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/1/21 12:15 PM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/1/21 12:15 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 12:15 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 12:15 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/1/21 12:15 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/1/21 12:15 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 12:23 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	
10/1/21 12:23 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/1/21 12:23 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 12:23 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/1/21 12:23 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/1/21 12:23 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/1/21 12:23 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 12:23 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 12:27 PM	UNACK_ALM	U37_ALARMS_2_6	U37-ALM-071: T5 Max TC - Min TC Spread High		2	
10/1/21 12:29 PM	ACK_RTN	U37_ALARMS_2_6	U37-ALM-071: T5 Max TC - Min TC Spread High		2	NULL
10/1/21 12:29 PM	ACK	U37_ALARMS_2_6	U37-ALM-071: T5 Max TC - Min TC Spread High		2	NULL
10/1/21 12:33 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 12:33 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 12:34 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/1/21 12:34 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 12:34 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 12:35 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/1/21 12:42 PM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 12:48 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 12:48 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 12:49 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 12:49 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 12:49 PM	ACK	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 12:49 PM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 12:49 PM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 12:55 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 12:55 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 12:55 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 12:55 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 12:55 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 12:55 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 12:59 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/1/21 12:59 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 12:59 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 1:04 PM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 1:08 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 1:08 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 1:08 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 1:08 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 1:08 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 1:08 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:08 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 1:08 PM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 1:08 PM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 1:08 PM	ACK_RTN	85_TestTreatA_Test_Complete	V03A Well Test Complete		1	
10/1/21 1:09 PM	ACK_RTN	85_TestTreatB_Test_Complete	V03B Well Test Complete		1	
10/1/21 1:09 PM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 1:10 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 1:10 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 1:12 PM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/1/21 1:12 PM	UNACK_ALM	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	
10/1/21 1:12 PM	UNACK_ALM	U36_ALM_054	ALM_054 : PT380: Lube Oil Header Press Low		2	
10/1/21 1:12 PM	UNACK_ALM	U36_SDFSLO_004	SDFSLO_004 : PT380: Lube Oil Header Press Low		1	
10/1/21 1:13 PM	ACK_RTN	U36_ALM_054	ALM_054 : PT380: Lube Oil Header Press Low		2	NULL
10/1/21 1:13 PM	ACK	U36_ALM_054	ALM_054 : PT380: Lube Oil Header Press Low		2	NULL
10/1/21 1:13 PM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/1/21 1:13 PM	ACK	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/1/21 1:13 PM	ACK_RTN	U36_SDFSLO_004	SDFSLO_004 : PT380: Lube Oil Header Press Low		1	NULL
10/1/21 1:13 PM	ACK	U36_SDFSLO_004	SDFSLO_004 : PT380: Lube Oil Header Press Low		1	NULL
10/1/21 1:16 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	
10/1/21 1:16 PM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/1/21 1:16 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Hi	Alarm--Train B Treater High Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 1:16 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Hi	Alarm--Train B Treater High Pressure		1	NULL
10/1/21 1:16 PM	ACK	91_Alm_TrainB_Treat_Press_Hi	Alarm--Train B Treater High Pressure		1	NULL
10/1/21 1:16 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 1:16 PM	ACK	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 1:16 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 1:16 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 1:16 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Hi	Alarm--Train B Treater High Pressure		1	
10/1/21 1:16 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:16 PM	ACK_RTN	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/1/21 1:16 PM	ACK	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/1/21 1:16 PM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 1:16 PM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 1:16 PM	UNACK_ALM	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	
10/1/21 1:16 PM	UNACK_ALM	U36_ALM_054	ALM_054 : PT380: Lube Oil Header Press Low		2	
10/1/21 1:18 PM	UNACK_ALM	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	
10/1/21 1:18 PM	UNACK_ALM	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	
10/1/21 1:18 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Hi	Alarm--Train B Treater High Pressure		1	NULL
10/1/21 1:18 PM	ACK	91_Alm_TrainB_Treat_Press_Hi	Alarm--Train B Treater High Pressure		1	NULL
10/1/21 1:19 PM	UNACK_ALM	U35_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	
10/1/21 1:20 PM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/1/21 1:20 PM	ACK	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/1/21 1:20 PM	ACK_RTN	U36_ALM_054	ALM_054 : PT380: Lube Oil Header Press Low		2	NULL
10/1/21 1:20 PM	ACK	U36_ALM_054	ALM_054 : PT380: Lube Oil Header Press Low		2	NULL
10/1/21 1:20 PM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/1/21 1:21 PM	ACK_RTN	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/1/21 1:21 PM	ACK	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/1/21 1:21 PM	ACK_RTN	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/1/21 1:21 PM	ACK	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/1/21 1:21 PM	ACK_RTN	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	NULL
10/1/21 1:21 PM	ACK	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	NULL
10/1/21 1:23 PM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 1:24 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 1:24 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 1:24 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 1:24 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 1:24 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 1:24 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:24 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 1:24 PM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 1:24 PM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 1:27 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 1:27 PM	ACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/1/21 1:27 PM	ACK_ALM	U35_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 1:27 PM	ACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 1:27 PM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:27 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 1:27 PM	ACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 1:27 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 1:27 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 1:33 PM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 1:34 PM	UNACK_ALM	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	
10/1/21 1:34 PM	UNACK_ALM	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	
10/1/21 1:35 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:35 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 1:35 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:35 PM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 1:35 PM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 1:35 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 1:42 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:42 PM	ACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 1:42 PM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:42 PM	ACK_ALM	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	
10/1/21 1:42 PM	ACK_ALM	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	
10/1/21 1:42 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 1:42 PM	ACK_RTN	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	
10/1/21 1:42 PM	ACK_RTN	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	
10/1/21 1:42 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:42 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:42 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 1:42 PM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:42 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:42 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 1:42 PM	UNACK_ALM	U36_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	
10/1/21 1:42 PM	UNACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/1/21 1:45 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 1:45 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 1:45 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 1:59 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 2:05 PM	ACK_RTN	U35_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	
10/1/21 2:10 PM	UNACK_ALM	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	
10/1/21 2:11 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 2:11 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 2:11 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 2:11 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 2:12 PM	ACK_RTN	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:12 PM	ACK	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 2:12 PM	UNACK_ALM	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	
10/1/21 2:12 PM	ACK_RTN	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:12 PM	ACK	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:13 PM	UNACK_ALM	40_Alm_WestBay_Shutdown_VSD_14	West Well Bay Shutdown Alarm -- VSD-14		1	
10/1/21 2:13 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:13 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:13 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 2:13 PM	UNACK_ALM	40_Alm_Well_VSD_14_Motor	Well VSD_14 Motor Alarm		600	
10/1/21 2:13 PM	UNACK_ALM	40_Alm_WestBay_Shutdown_VSD_10	West Well Bay Shutdown Alarm -- VSD-10		1	
10/1/21 2:14 PM	ACK_RTN	40_Alm_Well_VSD_14_Motor	Well VSD_14 Motor Alarm		600	NULL
10/1/21 2:14 PM	ACK	40_Alm_Well_VSD_14_Motor	Well VSD_14 Motor Alarm		600	NULL
10/1/21 2:14 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:14 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:14 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:14 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:14 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 2:14 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 2:14 PM	UNACK_ALM	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	
10/1/21 2:14 PM	ACK_RTN	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:14 PM	ACK	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:14 PM	UNACK_ALM	40_Alm_Well_VSD_10_Motor	Well VSD_10 Motor Alarm		600	
10/1/21 2:14 PM	UNACK_ALM	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	
10/1/21 2:14 PM	ACK_RTN	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:14 PM	ACK	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:14 PM	ACK_RTN	40_Alm_Well_VSD_10_Motor	Well VSD_10 Motor Alarm		600	NULL
10/1/21 2:14 PM	ACK	40_Alm_Well_VSD_10_Motor	Well VSD_10 Motor Alarm		600	NULL
10/1/21 2:14 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:14 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:14 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 2:15 PM	UNACK_ALM	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	
10/1/21 2:15 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:15 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:15 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:15 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:15 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 2:15 PM	UNACK_ALM	40_Alm_WestBay_Shutdown_VSD_16	West Well Bay Shutdown Alarm -- VSD-16		1	
10/1/21 2:15 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:15 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:15 PM	ACK_RTN	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:15 PM	ACK	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:15 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 2:15 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 2:15 PM	UNACK_ALM	40_Alm_Well_VSD_16_Motor	Well VSD_16 Motor Alarm		600	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 2:15 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:15 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:15 PM	UNACK_ALM	40_Alm_WestBay_Shutdown_VSD_02	West Well Bay Shutdown Alarm -- VSD-02		1	
10/1/21 2:15 PM	ACK_RTN	40_Alm_Well_VSD_16_Motor	Well VSD_16 Motor Alarm		600	NULL
10/1/21 2:15 PM	ACK	40_Alm_Well_VSD_16_Motor	Well VSD_16 Motor Alarm		600	NULL
10/1/21 2:15 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:15 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:15 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 2:15 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 2:15 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:15 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:15 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 2:16 PM	UNACK_ALM	40_Alm_Well_VSD_02_Motor	Well VSD_02 Motor Alarm		600	
10/1/21 2:16 PM	UNACK_ALM	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	
10/1/21 2:16 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:16 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:16 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 2:16 PM	ACK_RTN	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:16 PM	ACK	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:16 PM	ACK_RTN	40_Alm_Well_VSD_02_Motor	Well VSD_02 Motor Alarm		600	NULL
10/1/21 2:16 PM	ACK	40_Alm_Well_VSD_02_Motor	Well VSD_02 Motor Alarm		600	NULL
10/1/21 2:16 PM	UNACK_ALM	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	
10/1/21 2:16 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:16 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:16 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/1/21 2:17 PM	UNACK_ALM	60_Alm_Well_VSD_01_Motor	Well VSD_01 Motor Alarm		600	
10/1/21 2:17 PM	ACK_RTN	60_Alm_Well_VSD_01_Motor	Well VSD_01 Motor Alarm		600	NULL
10/1/21 2:17 PM	ACK	60_Alm_Well_VSD_01_Motor	Well VSD_01 Motor Alarm		600	NULL
10/1/21 2:21 PM	UNACK_ALM	40_Alm_WestBay_Shutdown_VSD_08	West Well Bay Shutdown Alarm -- VSD-08		1	
10/1/21 2:21 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:21 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/1/21 2:21 PM	ACK_RTN	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:21 PM	ACK	11_ALM_S02B_Tank_Level_High	Elly S02B Tank Level Exceeded 85%		1	NULL
10/1/21 2:21 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/1/21 2:21 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 2:21 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 2:21 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/1/21 2:21 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:21 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:21 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 2:24 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 2:26 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 2:26 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 2:39 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 2:40 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 2:40 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 2:40 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 2:40 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 2:40 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:40 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:40 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 2:40 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 2:40 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 2:40 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 2:42 PM	UNACK_ALM	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	
10/1/21 2:42 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:42 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:42 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 2:44 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/1/21 2:44 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 2:44 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 2:44 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:44 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:44 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 2:44 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:44 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:44 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/1/21 2:44 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 2:44 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 2:44 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 2:44 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 2:44 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 2:44 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/1/21 2:44 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 2:45 PM	ACK_RTN	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	NULL
10/1/21 2:45 PM	ACK	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	NULL
10/1/21 2:45 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:45 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:45 PM	UNACK_ALM	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	
10/1/21 2:45 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 2:45 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 2:45 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 2:45 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 2:45 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 2:45 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 2:45 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 2:45 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 2:45 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:45 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 2:45 PM	ACK_RTN	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	NULL
10/1/21 2:45 PM	ACK	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	NULL
10/1/21 2:45 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut	████████	1	████████
10/1/21 2:45 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning	████████	1	████████
10/1/21 2:45 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed	████████	1	████████
10/1/21 2:45 PM	UNACK_ALM	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm	████████	1	████████
10/1/21 2:45 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm	████████	40	████████
10/1/21 2:51 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 2:51 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:06 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure	████████	1	████████
10/1/21 3:06 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 3:06 PM	ACK	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 3:06 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 3:06 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/1/21 3:06 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure	████████	1	████████
10/1/21 3:06 PM	ACK_RTN	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	NULL
10/1/21 3:06 PM	ACK	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	NULL
10/1/21 3:09 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_03	East Well Bay Shutdown Alarm -- VSD-03	████████	1	████████
10/1/21 3:09 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 3:09 PM	ACK	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 3:09 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure	████████	1	████████
10/1/21 3:09 PM	UNACK_ALM	40_Alm_Well_VSD_03_Motor	Well VSD_03 Motor Alarm	████████	600	████████
10/1/21 3:09 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 3:09 PM	ACK	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 3:09 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure	████████	1	████████
10/1/21 3:09 PM	ACK_RTN	40_Alm_Well_VSD_03_Motor	Well VSD_03 Motor Alarm		600	NULL
10/1/21 3:09 PM	ACK	40_Alm_Well_VSD_03_Motor	Well VSD_03 Motor Alarm		600	NULL
10/1/21 3:09 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 3:09 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 3:09 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut	████████	1	████████
10/1/21 3:09 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_07	East Well Bay Shutdown Alarm -- VSD-07	████████	1	████████
10/1/21 3:09 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 3:09 PM	ACK	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 3:09 PM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL	████████	1	████████
10/1/21 3:09 PM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL	████████	1	████████
10/1/21 3:09 PM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/1/21 3:09 PM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/1/21 3:09 PM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 3:09 PM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 3:09 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_02	West Well Bay Shutdown Alarm -- VSD-02		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 3:09 PM	ACK	40_Alm_WestBay_Shutdown_VSD_02	West Well Bay Shutdown Alarm -- VSD-02		1	NULL
10/1/21 3:09 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_08	West Well Bay Shutdown Alarm -- VSD-08		1	NULL
10/1/21 3:09 PM	ACK	40_Alm_WestBay_Shutdown_VSD_08	West Well Bay Shutdown Alarm -- VSD-08		1	NULL
10/1/21 3:09 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_10	West Well Bay Shutdown Alarm -- VSD-10		1	NULL
10/1/21 3:09 PM	ACK	40_Alm_WestBay_Shutdown_VSD_10	West Well Bay Shutdown Alarm -- VSD-10		1	NULL
10/1/21 3:09 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_14	West Well Bay Shutdown Alarm -- VSD-14		1	NULL
10/1/21 3:09 PM	ACK	40_Alm_WestBay_Shutdown_VSD_14	West Well Bay Shutdown Alarm -- VSD-14		1	NULL
10/1/21 3:09 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_16	West Well Bay Shutdown Alarm -- VSD-16		1	NULL
10/1/21 3:09 PM	ACK	40_Alm_WestBay_Shutdown_VSD_16	West Well Bay Shutdown Alarm -- VSD-16		1	NULL
10/1/21 3:09 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_03	East Well Bay Shutdown Alarm -- VSD-03		1	NULL
10/1/21 3:09 PM	ACK	40_Alm_EastBay_Shutdown_VSD_03	East Well Bay Shutdown Alarm -- VSD-03		1	NULL
10/1/21 3:09 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_07	East Well Bay Shutdown Alarm -- VSD-07		1	NULL
10/1/21 3:09 PM	ACK	40_Alm_EastBay_Shutdown_VSD_07	East Well Bay Shutdown Alarm -- VSD-07		1	NULL
10/1/21 3:10 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 3:10 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 3:10 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 3:10 PM	UNACK_ALM	40_Alm_Well_VSD_07_Motor	Well VSD_07 Motor Alarm		600	
10/1/21 3:10 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_Input_15	East Well Bay Shutdown Alarm -- A-27		1	
10/1/21 3:10 PM	ACK_RTN	40_Alm_Well_VSD_07_Motor	Well VSD_07 Motor Alarm		600	NULL
10/1/21 3:10 PM	ACK	40_Alm_Well_VSD_07_Motor	Well VSD_07 Motor Alarm		600	NULL
10/1/21 3:10 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_Input_09	East Well Bay Shutdown Alarm -- A-21		1	
10/1/21 3:10 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_13	East Well Bay Shutdown Alarm -- VSD-13		1	
10/1/21 3:10 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:10 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:10 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:10 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_01	East Well Bay Shutdown Alarm -- VSD-01		1	
10/1/21 3:10 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_Input_13	East Well Bay Shutdown Alarm -- A-57		1	
10/1/21 3:10 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:10 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:10 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:10 PM	UNACK_ALM	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm		600	
10/1/21 3:11 PM	UNACK_ALM	40_Alm_Well_VSD_01_Motor	Well VSD_01 Motor Alarm		600	
10/1/21 3:11 PM	UNACK_ALM	40_Alm_WestBay_Shutdown_VSD_12	West Well Bay Shutdown Alarm -- VSD-12		1	
10/1/21 3:11 PM	UNACK_ALM	40_Alm_WestBay_Shutdown_VSD_04	West Well Bay Shutdown Alarm -- VSD-04		1	
10/1/21 3:11 PM	ACK_RTN	40_Alm_Well_VSD_01_Motor	Well VSD_01 Motor Alarm		600	NULL
10/1/21 3:11 PM	ACK	40_Alm_Well_VSD_01_Motor	Well VSD_01 Motor Alarm		600	NULL
10/1/21 3:11 PM	ACK_RTN	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm		600	NULL
10/1/21 3:11 PM	ACK	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm		600	NULL
10/1/21 3:11 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:11 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:11 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:11 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_Input_11	East Well Bay Shutdown Alarm -- A-55		1	
10/1/21 3:11 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 3:11 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:11 PM	UNACK_ALM	40_Alm_Well_VSD_04_Motor	Well VSD_04 Motor Alarm		600	
10/1/21 3:11 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:11 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_Input_14	East Well Bay Shutdown Alarm -- A-13		1	
10/1/21 3:11 PM	ACK_RTN	40_Alm_Well_VSD_04_Motor	Well VSD_04 Motor Alarm		600	NULL
10/1/21 3:11 PM	ACK	40_Alm_Well_VSD_04_Motor	Well VSD_04 Motor Alarm		600	NULL
10/1/21 3:11 PM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/1/21 3:11 PM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/1/21 3:11 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:11 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:11 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_04	West Well Bay Shutdown Alarm -- VSD-04		1	NULL
10/1/21 3:11 PM	ACK	40_Alm_WestBay_Shutdown_VSD_04	West Well Bay Shutdown Alarm -- VSD-04		1	NULL
10/1/21 3:11 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_12	West Well Bay Shutdown Alarm -- VSD-12		1	NULL
10/1/21 3:11 PM	ACK	40_Alm_WestBay_Shutdown_VSD_12	West Well Bay Shutdown Alarm -- VSD-12		1	NULL
10/1/21 3:11 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_01	East Well Bay Shutdown Alarm -- VSD-01		1	NULL
10/1/21 3:11 PM	ACK	40_Alm_EastBay_Shutdown_VSD_01	East Well Bay Shutdown Alarm -- VSD-01		1	NULL
10/1/21 3:11 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_13	East Well Bay Shutdown Alarm -- VSD-13		1	NULL
10/1/21 3:11 PM	ACK	40_Alm_EastBay_Shutdown_VSD_13	East Well Bay Shutdown Alarm -- VSD-13		1	NULL
10/1/21 3:11 PM	ACK_RTN	40_Alm_EastBay_Shutdown_Input_09	East Well Bay Shutdown Alarm -- A-21		1	NULL
10/1/21 3:11 PM	ACK	40_Alm_EastBay_Shutdown_Input_09	East Well Bay Shutdown Alarm -- A-21		1	NULL
10/1/21 3:11 PM	ACK_RTN	40_Alm_EastBay_Shutdown_Input_11	East Well Bay Shutdown Alarm -- A-55		1	NULL
10/1/21 3:11 PM	ACK	40_Alm_EastBay_Shutdown_Input_11	East Well Bay Shutdown Alarm -- A-55		1	NULL
10/1/21 3:11 PM	ACK_RTN	40_Alm_EastBay_Shutdown_Input_13	East Well Bay Shutdown Alarm -- A-57		1	NULL
10/1/21 3:11 PM	ACK	40_Alm_EastBay_Shutdown_Input_13	East Well Bay Shutdown Alarm -- A-57		1	NULL
10/1/21 3:11 PM	ACK_RTN	40_Alm_EastBay_Shutdown_Input_14	East Well Bay Shutdown Alarm -- A-13		1	NULL
10/1/21 3:11 PM	ACK	40_Alm_EastBay_Shutdown_Input_14	East Well Bay Shutdown Alarm -- A-13		1	NULL
10/1/21 3:11 PM	ACK_RTN	40_Alm_EastBay_Shutdown_Input_15	East Well Bay Shutdown Alarm -- A-27		1	NULL
10/1/21 3:11 PM	ACK	40_Alm_EastBay_Shutdown_Input_15	East Well Bay Shutdown Alarm -- A-27		1	NULL
10/1/21 3:11 PM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/1/21 3:11 PM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/1/21 3:11 PM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 3:11 PM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 3:11 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:11 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 3:11 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 3:11 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 3:11 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 3:12 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_09	East Well Bay Shutdown Alarm -- VSD-09		1	
10/1/21 3:12 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_11	East Well Bay Shutdown Alarm -- VSD-11		1	
10/1/21 3:13 PM	UNACK_ALM	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	
10/1/21 3:13 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:13 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:13 PM	ACK_RTN	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 3:13 PM	ACK	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	NULL
10/1/21 3:13 PM	UNACK_ALM	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	
10/1/21 3:13 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:13 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:13 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:13 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 3:13 PM	UNACK_ALM	40_Alm_Well_VSD_09_Motor	Well VSD_09 Motor Alarm		600	
10/1/21 3:13 PM	UNACK_ALM	40_Alm_Well_VSD_11_Motor	Well VSD_11 Motor Alarm		600	
10/1/21 3:13 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 3:13 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 3:13 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:13 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:13 PM	ACK_RTN	40_Alm_Well_VSD_09_Motor	Well VSD_09 Motor Alarm		600	NULL
10/1/21 3:13 PM	ACK	40_Alm_Well_VSD_09_Motor	Well VSD_09 Motor Alarm		600	NULL
10/1/21 3:13 PM	ACK_RTN	40_Alm_Well_VSD_11_Motor	Well VSD_11 Motor Alarm		600	NULL
10/1/21 3:13 PM	ACK	40_Alm_Well_VSD_11_Motor	Well VSD_11 Motor Alarm		600	NULL
10/1/21 3:13 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:13 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:13 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 3:13 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:13 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 3:14 PM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/1/21 3:14 PM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/1/21 3:14 PM	UNACK_ALM	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	
10/1/21 3:14 PM	UNACK_ALM	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	
10/1/21 3:14 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_09	East Well Bay Shutdown Alarm -- VSD-09		1	NULL
10/1/21 3:14 PM	ACK	40_Alm_EastBay_Shutdown_VSD_09	East Well Bay Shutdown Alarm -- VSD-09		1	NULL
10/1/21 3:14 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_11	East Well Bay Shutdown Alarm -- VSD-11		1	NULL
10/1/21 3:14 PM	ACK	40_Alm_EastBay_Shutdown_VSD_11	East Well Bay Shutdown Alarm -- VSD-11		1	NULL
10/1/21 3:14 PM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/1/21 3:14 PM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/1/21 3:14 PM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 3:14 PM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 3:15 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 3:15 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:15 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:15 PM	ACK_RTN	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	NULL
10/1/21 3:15 PM	ACK	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	NULL
10/1/21 3:15 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 3:15 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:15 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:15 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 3:15 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 3:15 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:15 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 3:15 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:15 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:15 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 3:15 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:15 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:15 PM	UNACK_ALM	40_Alm_WestBay_Shutdown_VSD_06	West Well Bay Shutdown Alarm -- VSD-06		1	
10/1/21 3:15 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:15 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:15 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 3:15 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:15 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:15 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:16 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 3:16 PM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/1/21 3:16 PM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/1/21 3:16 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_06	West Well Bay Shutdown Alarm -- VSD-06		1	NULL
10/1/21 3:16 PM	ACK	40_Alm_WestBay_Shutdown_VSD_06	West Well Bay Shutdown Alarm -- VSD-06		1	NULL
10/1/21 3:16 PM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/1/21 3:16 PM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/1/21 3:16 PM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/1/21 3:16 PM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 3:16 PM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 3:16 PM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/1/21 3:16 PM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/1/21 3:16 PM	UNACK_ALM	40_Alm_Well_VSD_06_Motor	Well VSD_06 Motor Alarm		600	
10/1/21 3:17 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:17 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:17 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 3:17 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:17 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:17 PM	ACK_RTN	40_Alm_Well_VSD_06_Motor	Well VSD_06 Motor Alarm		600	NULL
10/1/21 3:17 PM	ACK	40_Alm_Well_VSD_06_Motor	Well VSD_06 Motor Alarm		600	NULL
10/1/21 3:17 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 3:21 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:21 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:21 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 3:21 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:21 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:21 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 3:25 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 3:26 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 3:26 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:26 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 3:26 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 3:26 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 3:26 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:26 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:26 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 3:26 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 3:26 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:26 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:26 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 3:26 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 3:26 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 3:26 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 3:26 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 3:26 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:26 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:26 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:26 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 3:28 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:28 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:28 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:28 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:28 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:28 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:28 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 3:28 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:28 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:28 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:29 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 3:31 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	
10/1/21 3:31 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:31 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:31 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:31 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 3:31 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:32 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:32 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:32 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 3:32 PM	ACK	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 3:32 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:32 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	
10/1/21 3:33 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 3:33 PM	ACK	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 3:35 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 3:36 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 3:36 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 3:40 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 3:40 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:40 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:40 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 3:40 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 3:40 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:40 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 3:41 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:41 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:41 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 3:52 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/1/21 3:52 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:52 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 3:52 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 3:53 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 3:53 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 3:53 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 3:53 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 3:53 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 3:53 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:53 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:53 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/1/21 3:53 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 3:53 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 3:54 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/1/21 3:54 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 3:54 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 3:56 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/1/21 3:57 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 3:57 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 3:57 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 3:57 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 3:57 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 3:57 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 3:57 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:57 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 3:57 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/1/21 3:57 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/1/21 3:57 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 3:57 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 4:04 PM	UNACK_ALM	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	
10/1/21 4:04 PM	UNACK_ALM	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	
10/1/21 4:04 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 4:04 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 4:04 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 4:04 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 4:04 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:04 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:04 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 4:04 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 4:04 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/1/21 4:04 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/1/21 4:04 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 4:04 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 4:04 PM	UNACK_ALM	U35_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/1/21 4:05 PM	UNACK_ALM	U35_SDFSLO_001	SDFSLO_001 : Fail to Ignite		1	
10/1/21 4:05 PM	UNACK_ALM	U35_ALMH_020	ALMH_020 : GFMV Gas Fuel Flow Fault		3	
10/1/21 4:05 PM	UNACK_ALM	U35_ALMH_019	ALMH_019 : Gas Fuel Metering Valve Position Feedback Fault		3	
10/1/21 4:05 PM	UNACK_ALM	U35_ALM_036	ALM_036 : Bently Nevada High Vibration Summary Alarm		2	
10/1/21 4:05 PM	ACK_RTN	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/1/21 4:05 PM	ACK	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/1/21 4:05 PM	ACK_RTN	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	NULL
10/1/21 4:05 PM	ACK	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	NULL
10/1/21 4:05 PM	ACK_RTN	U35_ALMH_020	ALMH_020 : GFMV Gas Fuel Flow Fault		3	NULL
10/1/21 4:05 PM	ACK	U35_ALMH_020	ALMH_020 : GFMV Gas Fuel Flow Fault		3	NULL
10/1/21 4:05 PM	ACK_RTN	U35_ALMH_019	ALMH_019 : Gas Fuel Metering Valve Position Feedback Fault		3	NULL
10/1/21 4:05 PM	ACK	U35_ALMH_019	ALMH_019 : Gas Fuel Metering Valve Position Feedback Fault		3	NULL
10/1/21 4:05 PM	ACK_RTN	U35_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/1/21 4:05 PM	ACK	U35_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/1/21 4:06 PM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/1/21 4:06 PM	ACK_RTN	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	NULL
10/1/21 4:06 PM	ACK	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	NULL
10/1/21 4:06 PM	ACK_RTN	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	NULL
10/1/21 4:06 PM	ACK	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	NULL
10/1/21 4:06 PM	ACK_RTN	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	NULL
10/1/21 4:06 PM	ACK	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	NULL
10/1/21 4:06 PM	ACK_RTN	U36_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	NULL
10/1/21 4:06 PM	ACK	U36_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	NULL
10/1/21 4:07 PM	ACK_RTN	U35_SDFSLO_001	SDFSLO_001 : Fail to Ignite		1	NULL
10/1/21 4:07 PM	ACK	U35_SDFSLO_001	SDFSLO_001 : Fail to Ignite		1	NULL
10/1/21 4:07 PM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/1/21 4:08 PM	UNACK_ALM	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 4:08 PM	UNACK_ALM	U36_ALM_054	ALM_054 : PT380: Lube Oil Header Press Low		2	
10/1/21 4:08 PM	UNACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/1/21 4:08 PM	UNACK_ALM	50_ALM_CEMS_Priority_1	CEMS Priority #1 Alarm		1	
10/1/21 4:08 PM	UNACK_ALM	50_ALM_Sat_NP10B_Dsl_Meter_Fail	NP10B Diesel Meter Failure		1	
10/1/21 4:09 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 4:09 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 4:09 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 4:09 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 4:09 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:09 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:09 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 4:09 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 4:09 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/1/21 4:09 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/1/21 4:09 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 4:09 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 4:09 PM	ACK_RTN	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	NULL
10/1/21 4:09 PM	ACK	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	NULL
10/1/21 4:09 PM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/1/21 4:09 PM	ACK	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/1/21 4:09 PM	ACK_RTN	U36_ALM_054	ALM_054 : PT380: Lube Oil Header Press Low		2	NULL
10/1/21 4:09 PM	ACK	U36_ALM_054	ALM_054 : PT380: Lube Oil Header Press Low		2	NULL
10/1/21 4:10 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 4:10 PM	UNACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 4:11 PM	UNACK_ALM	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	
10/1/21 4:11 PM	UNACK_ALM	50_ALM_Sat_NP10B_Dsl_Switch_Fail	NP10B Diesel Switch Failure		1	
10/1/21 4:11 PM	ACK_RTN	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/1/21 4:11 PM	ACK	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/1/21 4:11 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:11 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:11 PM	ACK_RTN	50_ALM_CEMS_Priority_1	CEMS Priority #1 Alarm		1	NULL
10/1/21 4:11 PM	ACK	50_ALM_CEMS_Priority_1	CEMS Priority #1 Alarm		1	NULL
10/1/21 4:11 PM	ACK_RTN	50_ALM_Sat_NP10B_Dsl_Meter_Fail	NP10B Diesel Meter Failure		1	NULL
10/1/21 4:11 PM	ACK	50_ALM_Sat_NP10B_Dsl_Meter_Fail	NP10B Diesel Meter Failure		1	NULL
10/1/21 4:11 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 4:13 PM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/1/21 4:13 PM	UNACK_ALM	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	
10/1/21 4:17 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 4:22 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:22 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:22 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 4:22 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 4:22 PM	ACK_RTN	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 4:22 PM	ACK	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/1/21 4:22 PM	ACK_RTN	50_ALM_Sat_NP10B_Dsl_Switch_Fail	NP10B Diesel Switch Failure		1	NULL
10/1/21 4:22 PM	ACK	50_ALM_Sat_NP10B_Dsl_Switch_Fail	NP10B Diesel Switch Failure		1	NULL
10/1/21 4:22 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 4:22 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 4:22 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 4:22 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 4:22 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 4:22 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 4:28 PM	UNACK_ALM	30_S04_Tank_High_Level_Alm	S04 Tank High Level Alarm		1	
10/1/21 4:28 PM	UNACK_ALM	30_ALM_TankLvl_High_Warn_S04	Alarm -- S04 Tank Level High > 90%		1	
10/1/21 4:28 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 4:28 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 4:28 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 4:28 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 4:28 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:28 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:28 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 4:28 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 4:28 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/1/21 4:28 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/1/21 4:28 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 4:28 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 4:28 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:28 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:28 PM	ACK_RTN	30_S04_Tank_High_Level_Alm	S04 Tank High Level Alarm		1	NULL
10/1/21 4:28 PM	ACK	30_S04_Tank_High_Level_Alm	S04 Tank High Level Alarm		1	NULL
10/1/21 4:28 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 4:28 PM	UNACK_ALM	30_S04_Tank_High_Level_Alm	S04 Tank High Level Alarm		1	
10/1/21 4:30 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 4:30 PM	UNACK_ALM	85_TestTreatA_Purge_Complete	V03A Purge Complete. Ready To Start Test.		1	
10/1/21 4:31 PM	UNACK_ALM	85_TestTreatB_Purge_Complete	V03B Purge Complete. Ready To Start Test.		1	
10/1/21 4:32 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 4:34 PM	UNACK_ALM	30_ALM_TankLvl_High_S04	Alarm -- S04 Tank Level High > 95%		1	
10/1/21 4:34 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:34 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:34 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 4:34 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 4:34 PM	ACK_RTN	30_S04_Tank_High_Level_Alm	S04 Tank High Level Alarm		1	NULL
10/1/21 4:34 PM	ACK	30_S04_Tank_High_Level_Alm	S04 Tank High Level Alarm		1	NULL
10/1/21 4:34 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 4:34 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 4:34 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 4:34 PM	UNACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/1/21 4:34 PM	UNACK_ALM	30_S04_Tank_High_Level_Alm	S04 Tank High Level Alarm		1	
10/1/21 4:36 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/1/21 4:36 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 4:36 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 4:39 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 4:39 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 4:39 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 4:39 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 4:39 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:39 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:39 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 4:39 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 4:39 PM	ACK_RTN	30_S04_Tank_High_Level_Alm	S04 Tank High Level Alarm		1	NULL
10/1/21 4:39 PM	ACK	30_S04_Tank_High_Level_Alm	S04 Tank High Level Alarm		1	NULL
10/1/21 4:39 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/1/21 4:39 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/1/21 4:39 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 4:39 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 4:39 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:39 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:39 PM	ACK_RTN	30_ALM_TankLvL_High_S04	Alarm -- S04 Tank Level High > 95%		1	NULL
10/1/21 4:39 PM	ACK	30_ALM_TankLvL_High_S04	Alarm -- S04 Tank Level High > 95%		1	NULL
10/1/21 4:39 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 4:39 PM	UNACK_ALM	30_S04_Tank_High_Level_Alm	S04 Tank High Level Alarm		1	
10/1/21 4:45 PM	UNACK_ALM	40_Alm_Well_VSD_03_Motor	Well VSD_03 Motor Alarm		600	
10/1/21 4:45 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 4:47 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 4:47 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 4:47 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 4:47 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 4:47 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:47 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:47 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 4:47 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 4:47 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:47 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:47 PM	ACK_RTN	40_Alm_Well_VSD_03_Motor	Well VSD_03 Motor Alarm		600	NULL
10/1/21 4:47 PM	ACK	40_Alm_Well_VSD_03_Motor	Well VSD_03 Motor Alarm		600	NULL
10/1/21 4:47 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 4:47 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 4:47 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 4:47 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 4:47 PM	ACK_RTN	30_S04_Tank_High_Level_Alm	S04 Tank High Level Alarm		1	NULL
10/1/21 4:47 PM	ACK	30_S04_Tank_High_Level_Alm	S04 Tank High Level Alarm		1	NULL
10/1/21 4:47 PM	ACK_RTN	30_ALM_TankLvl_High_Warn_S04	Alarm -- S04 Tank Level High > 90%		1	NULL
10/1/21 4:47 PM	ACK	30_ALM_TankLvl_High_Warn_S04	Alarm -- S04 Tank Level High > 90%		1	NULL
10/1/21 4:47 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/1/21 4:47 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/1/21 4:47 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 4:47 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 4:47 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 4:47 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 4:47 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 4:51 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:51 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:56 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 4:56 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 4:56 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 4:56 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 4:56 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 4:56 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:56 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 4:56 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 4:56 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 4:56 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 4:56 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 4:56 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/1/21 4:56 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/1/21 4:56 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 4:56 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 4:56 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 4:56 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 4:56 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:56 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 4:56 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 4:56 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 5:04 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	
10/1/21 5:04 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 5:04 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 5:04 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 5:04 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 5:04 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 5:04 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 5:04 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 5:04 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 5:04 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	NULL
10/1/21 5:04 PM	ACK	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	NULL
10/1/21 5:04 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/1/21 5:04 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/1/21 5:04 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/1/21 5:04 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 5:04 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	
10/1/21 5:04 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:04 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:04 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 5:04 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 5:04 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 5:04 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 5:04 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:04 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:04 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 5:04 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 5:05 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	NULL
10/1/21 5:05 PM	ACK	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	NULL
10/1/21 5:09 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	
10/1/21 5:09 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:09 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:09 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 5:09 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:09 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:09 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 5:12 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 5:20 PM	UNACK_ALM	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	
10/1/21 5:21 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 5:21 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 5:21 PM	ACK	91_Alm_TrainB_Treat_Press_Hi_Wrn	Warning--Train B Treater High Pressure		1	NULL
10/1/21 5:21 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:21 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:21 PM	ACK_RTN	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	NULL
10/1/21 5:21 PM	ACK	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	NULL
10/1/21 5:21 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 5:21 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 5:21 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 5:21 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 5:21 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 5:21 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 5:21 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 5:23 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 5:23 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/1/21 5:24 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	
10/1/21 5:24 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	NULL
10/1/21 5:24 PM	ACK	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	NULL
10/1/21 5:24 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 5:24 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 5:24 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:24 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:24 PM	ACK_RTN	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:24 PM	ACK	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:24 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 5:24 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 5:24 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 5:24 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 5:29 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/1/21 5:31 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/1/21 5:37 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 5:37 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/1/21 5:37 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 5:37 PM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/1/21 5:37 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 5:37 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/1/21 5:37 PM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/1/21 5:37 PM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/1/21 5:37 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 5:37 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 5:41 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/1/21 5:41 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 5:43 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 5:50 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	
10/1/21 5:50 PM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/1/21 5:50 PM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/1/21 5:50 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 5:50 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 5:50 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 5:50 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 5:50 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 5:50 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 5:50 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/1/21 5:50 PM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/1/21 5:50 PM	ACK	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/1/21 5:51 PM	UNACK_ALM	U36_ALM_001	ALM_001 : Fuel Transfer Lockout Disabled		2	
10/1/21 5:51 PM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 5:52 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 5:52 PM	UNACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 5:53 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	NULL
10/1/21 5:53 PM	ACK	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	NULL
10/1/21 5:53 PM	UNACK_ALM	U36_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	
10/1/21 5:56 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 5:56 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 5:56 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:56 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:56 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 5:56 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/1/21 5:56 PM	ACK_RTN	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/1/21 5:56 PM	ACK	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/1/21 5:56 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 5:56 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 5:56 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:56 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:56 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 5:58 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	
10/1/21 5:58 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:58 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 5:58 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 5:58 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	NULL
10/1/21 5:58 PM	ACK	91_Alm_V02B_Water_Vlv_Pos	Warning--V02B Water Out Valve Closed		1	NULL
10/1/21 6:48 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 6:48 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 6:48 PM	ACK_RTN	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	NULL
10/1/21 6:48 PM	ACK	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	NULL
10/1/21 6:58 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 6:58 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 6:58 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 6:58 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 6:58 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 6:58 PM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 6:58 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 6:58 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 6:58 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 6:58 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 7:04 PM	UNACK_ALM	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	
10/1/21 7:06 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:06 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:06 PM	ACK_RTN	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL
10/1/21 7:06 PM	ACK	11_ALM_Mainline_PAM_A_High_Cut	Pipeline PAM A Cut Probe -- High Cut		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 7:06 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 7:06 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 7:06 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 7:06 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 7:06 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 7:06 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 7:06 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 7:06 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 7:06 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 7:06 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 7:10 PM	UNACK_ALM	40_Alm_Well_VSD_12_Motor	Well VSD_12 Motor Alarm		600	
10/1/21 7:14 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 7:14 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 7:14 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 7:14 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 7:14 PM	ACK_RTN	40_Alm_Well_VSD_12_Motor	Well VSD_12 Motor Alarm		600	NULL
10/1/21 7:14 PM	ACK	40_Alm_Well_VSD_12_Motor	Well VSD_12 Motor Alarm		600	NULL
10/1/21 7:14 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 7:14 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 7:15 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:15 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:15 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 7:15 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 7:15 PM	UNACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 7:15 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:15 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:15 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:15 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:15 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 7:15 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 7:15 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:15 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:15 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 7:15 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:15 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:15 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 7:28 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:28 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:28 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 7:28 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:28 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:28 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 7:29 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 7:29 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:29 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:29 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:29 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 7:29 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 7:29 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED	████████	1	████████
10/1/21 7:29 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed	████████	1	████████
10/1/21 7:29 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:29 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:29 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:29 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:29 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED	████████	1	████████
10/1/21 7:29 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm	████████	40	████████
10/1/21 7:29 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed	████████	1	████████
10/1/21 7:29 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:29 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:29 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:29 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 7:29 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed	████████	1	████████
10/1/21 7:29 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED	████████	1	████████
10/1/21 7:39 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:39 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:39 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 7:39 PM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 7:39 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 7:39 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 7:39 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED	████████	1	████████
10/1/21 7:39 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:39 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 7:39 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED	████████	1	████████
10/1/21 7:39 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%	████████	1	████████
10/1/21 7:39 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%	████████	1	████████
10/1/21 8:25 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 8:25 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 8:25 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:25 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:25 PM	ACK_RTN	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:25 PM	ACK	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:25 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 8:25 PM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 8:25 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed	████████	1	████████
10/1/21 8:25 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 8:25 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 8:25 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 8:25 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:29 PM	ACK_ALM	U36_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	
10/1/21 8:29 PM	ACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/1/21 8:29 PM	ACK_ALM	U36_ALM_001	ALM_001 : Fuel Transfer Lockout Disabled		2	
10/1/21 8:29 PM	ACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/1/21 8:29 PM	ACK_ALM	U35_ALM_036	ALM_036 : Bently Nevada High Vibration Summary Alarm		2	
10/1/21 8:29 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:29 PM	ACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 8:29 PM	ACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 8:29 PM	ACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 8:29 PM	ACK_ALM	85_TestTreatB_Purge_Complete	V03B Purge Complete. Ready To Start Test.		1	
10/1/21 8:29 PM	ACK_ALM	85_TestTreatA_Purge_Complete	V03A Purge Complete. Ready To Start Test.		1	
10/1/21 8:29 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:29 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:29 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 8:39 PM	UNACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 8:39 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 8:39 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 8:39 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 8:39 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 8:39 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 8:39 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 8:39 PM	UNACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 8:39 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:39 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:39 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 8:39 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 8:39 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 8:39 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 8:39 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:39 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:39 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:39 PM	ACK_RTN	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	NULL
10/1/21 8:39 PM	ACK	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	NULL
10/1/21 8:39 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 8:39 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 8:39 PM	UNACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 8:40 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:40 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:40 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 8:40 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 8:40 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 8:40 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 8:40 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:40 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 8:40 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 8:41 PM	ACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 8:41 PM	ACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 8:41 PM	ACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 8:41 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:41 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:41 PM	ACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 8:41 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:41 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:41 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:41 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:42 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:42 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:42 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:42 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:42 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:42 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:43 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:43 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:43 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:43 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:43 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:43 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:45 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:45 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:45 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:45 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:45 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:45 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:48 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:48 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:48 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:52 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:52 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:52 PM	ACK_RTN	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 8:52 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:52 PM	UNACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 8:54 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_Input_15	East Well Bay Shutdown Alarm -- A-27		1	
10/1/21 8:54 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:54 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 8:54 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 8:54 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 8:54 PM	ACK_RTN	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	NULL
10/1/21 8:54 PM	ACK	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	NULL
10/1/21 8:54 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:54 PM	UNACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 8:54 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 8:56 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:56 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:56 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 8:58 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:58 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 8:58 PM	ACK_RTN	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 9:00 PM	ACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:00 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:00 PM	ACK_ALM	40_Alm_EastBay_Shutdown_Input_15	East Well Bay Shutdown Alarm -- A-27		1	
10/1/21 9:00 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/1/21 9:00 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 9:00 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 9:06 PM	UNACK_ALM	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	
10/1/21 9:06 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:06 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:06 PM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/1/21 9:06 PM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/1/21 9:06 PM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 9:06 PM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 9:06 PM	ACK_RTN	40_Alm_EastBay_Shutdown_Input_15	East Well Bay Shutdown Alarm -- A-27		1	
10/1/21 9:06 PM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/1/21 9:06 PM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 9:06 PM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 9:06 PM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/1/21 9:06 PM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/1/21 9:07 PM	UNACK_ALM	11_ALM_Mainline_PAM_B_High_Cut	Pipeline PAM B Cut Probe -- High Cut		1	
10/1/21 9:14 PM	ACK_ALM	11_ALM_Mainline_PAM_B_High_Cut	Pipeline PAM B Cut Probe -- High Cut		1	
10/1/21 9:14 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:14 PM	ACK_ALM	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	
10/1/21 9:14 PM	ACK_RTN	11_ALM_Mainline_PAM_B_High_Cut	Pipeline PAM B Cut Probe -- High Cut		1	
10/1/21 9:14 PM	ACK_RTN	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:14 PM	ACK_RTN	85_ALM_TestTreatB_Heat_High_Temp	TIC V03B High Temperature Alarm		1	
10/1/21 9:14 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:14 PM	UNACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:14 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:16 PM	UNACK_ALM	85_ALM_TestTreatA_Heat_High_Temp	TIC V03A High Temperature Alarm		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 9:16 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 9:16 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 9:16 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 9:16 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 9:17 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 9:17 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 9:17 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:17 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:17 PM	ACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 9:17 PM	ACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 9:17 PM	ACK_ALM	85_ALM_TestTreatA_Heat_High_Temp	TIC V03A High Temperature Alarm		1	
10/1/21 9:17 PM	ACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:17 PM	ACK_RTN	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:17 PM	ACK_RTN	85_ALM_TestTreatA_Heat_High_Temp	TIC V03A High Temperature Alarm		1	
10/1/21 9:17 PM	UNACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:17 PM	UNACK_ALM	85_ALM_TestTreatA_Heat_High_Temp	TIC V03A High Temperature Alarm		1	
10/1/21 9:17 PM	ACK_ALM	85_ALM_TestTreatA_Heat_High_Temp	TIC V03A High Temperature Alarm		1	
10/1/21 9:17 PM	ACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:17 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:17 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:18 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 9:18 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 9:18 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 9:18 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 9:19 PM	ACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 9:19 PM	ACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 9:19 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:19 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:19 PM	ACK_RTN	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:19 PM	ACK_RTN	85_ALM_TestTreatA_Heat_High_Temp	TIC V03A High Temperature Alarm		1	
10/1/21 9:19 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:19 PM	UNACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:22 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 9:22 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 9:22 PM	ACK_RTN	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	NULL
10/1/21 9:22 PM	ACK	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	NULL
10/1/21 9:22 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:22 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 9:22 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 9:22 PM	UNACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:22 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 9:22 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 9:22 PM	ACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 9:22 PM	ACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 9:22 PM	ACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 9:22 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:22 PM	ACK_RTN	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:22 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:22 PM	UNACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:22 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:23 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 9:23 PM	UNACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 9:24 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 9:24 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 9:24 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 9:24 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 9:24 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 9:24 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 9:24 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 9:24 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 9:24 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:24 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:24 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 9:24 PM	ACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 9:24 PM	ACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:24 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 9:24 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 9:24 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 9:24 PM	ACK_RTN	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:24 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:24 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 9:24 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 9:24 PM	UNACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:24 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:24 PM	ACK_ALM	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 9:24 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 9:24 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 9:24 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 9:24 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 9:35 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/1/21 9:35 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 9:35 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/1/21 9:53 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 9:53 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 9:53 PM	ACK_RTN	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 9:53 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 10:01 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:01 PM	UNACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 10:01 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:01 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:01 PM	ACK_RTN	85_ALM_TestTreatB_Gas_Low_Press	PIC V03B Low Pressure Alarm		1	
10/1/21 10:01 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:01 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:01 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:01 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:05 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:05 PM	ACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 10:05 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:05 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:05 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:05 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:05 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:05 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:05 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:06 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:11 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/1/21 10:11 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 10:11 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 10:11 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/1/21 10:11 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:11 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:11 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:16 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/1/21 10:16 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:16 PM	ACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/1/21 10:16 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:16 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:16 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:16 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:16 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:16 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:16 PM	ACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:16 PM	ACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:16 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:16 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:16 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:16 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:16 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:16 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 10:16 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:16 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:16 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:16 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:16 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:16 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:16 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:21 PM	ACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:21 PM	ACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:21 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:21 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:21 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:23 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:23 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:23 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:23 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:23 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:23 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:23 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:24 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:24 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:24 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:29 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 10:29 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:29 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:29 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:29 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:29 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:29 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:33 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:33 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:33 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:33 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:33 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:33 PM	ACK_RTN	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 10:33 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:33 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 10:33 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 10:33 PM	UNACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 10:33 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 10:33 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:33 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:33 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 10:34 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:34 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:34 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:34 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:34 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:34 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 10:34 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 10:34 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:34 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 10:35 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 10:35 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:35 PM	ACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 10:35 PM	ACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:35 PM	ACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:35 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:35 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:35 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:35 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:35 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:35 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:37 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:37 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 10:37 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:39 PM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 10:49 PM	ACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 10:49 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:49 PM	ACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:49 PM	ACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:49 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 10:49 PM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 10:49 PM	ACK_RTN	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/1/21 10:49 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 10:49 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 10:49 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/1/21 10:49 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 10:49 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/1/21 10:49 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 10:49 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 10:50 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 10:54 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 10:54 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 10:54 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 10:54 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 10:54 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 10:54 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:54 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:54 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 10:54 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 10:54 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 11:00 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:00 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:00 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 11:02 PM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 11:14 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 11:14 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 11:14 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 11:14 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 11:14 PM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 11:14 PM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 11:14 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 11:14 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 11:15 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:15 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:15 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 11:15 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 11:15 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 11:15 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 11:15 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 11:15 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 11:15 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 11:15 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_13	East Well Bay Shutdown Alarm -- VSD-13		1	
10/1/21 11:16 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 11:16 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 11:16 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 11:16 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 11:16 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 11:16 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 11:16 PM	UNACK_ALM	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm		600	
10/1/21 11:16 PM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/1/21 11:16 PM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/1/21 11:16 PM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 11:16 PM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/1/21 11:16 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_13	East Well Bay Shutdown Alarm -- VSD-13		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 11:16 PM	ACK	40_Alm_EastBay_Shutdown_VSD_13	East Well Bay Shutdown Alarm -- VSD-13			1 NULL
10/1/21 11:16 PM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL			1 [REDACTED]
10/1/21 11:16 PM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL			1 NULL
10/1/21 11:16 PM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL			1 NULL
10/1/21 11:16 PM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL			1 NULL
10/1/21 11:16 PM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL			1 NULL
10/1/21 11:16 PM	ACK_RTN	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm			600 NULL
10/1/21 11:16 PM	ACK	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm			600 NULL
10/1/21 11:30 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED	ra [REDACTED] g		1 [REDACTED]
10/1/21 11:30 PM	UNACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED			1 [REDACTED]
10/1/21 11:31 PM	ACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED			1 [REDACTED]
10/1/21 11:31 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 [REDACTED]
10/1/21 11:31 PM	ACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 [REDACTED]
10/1/21 11:31 PM	ACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 [REDACTED]
10/1/21 11:31 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 [REDACTED]
10/1/21 11:31 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 [REDACTED]
10/1/21 11:31 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 [REDACTED]
10/1/21 11:31 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 [REDACTED]
10/1/21 11:31 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 [REDACTED]
10/1/21 11:31 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 [REDACTED]
10/1/21 11:31 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 [REDACTED]
10/1/21 11:31 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 [REDACTED]
10/1/21 11:31 PM	ACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 [REDACTED]
10/1/21 11:31 PM	ACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 [REDACTED]
10/1/21 11:31 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 [REDACTED]
10/1/21 11:31 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 [REDACTED]
10/1/21 11:32 PM	UNACK_ALM	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm			600 [REDACTED]
10/1/21 11:32 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 NULL
10/1/21 11:32 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 NULL
10/1/21 11:32 PM	ACK_RTN	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm			600 NULL
10/1/21 11:32 PM	ACK	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm			600 NULL
10/1/21 11:32 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 [REDACTED]
10/1/21 11:32 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 [REDACTED]
10/1/21 11:32 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 NULL
10/1/21 11:32 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 NULL
10/1/21 11:32 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 [REDACTED]
10/1/21 11:32 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 [REDACTED]
10/1/21 11:33 PM	UNACK_ALM	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm			600 [REDACTED]
10/1/21 11:34 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/1/21 11:34 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/1/21 11:34 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 NULL
10/1/21 11:34 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 NULL
10/1/21 11:34 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED			1 [REDACTED]

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 11:34 PM	ACK_RTN	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm		600	NULL
10/1/21 11:34 PM	ACK	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm		600	NULL
10/1/21 11:34 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 11:35 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 11:35 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 11:35 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 11:35 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 11:35 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 11:35 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/1/21 11:35 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 11:35 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 11:35 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 11:35 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:35 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/1/21 11:35 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 11:35 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 11:39 PM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 11:44 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 11:44 PM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/1/21 11:44 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 11:44 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 11:44 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 11:44 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 11:44 PM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 11:44 PM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 11:44 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 11:44 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 11:44 PM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/1/21 11:45 PM	UNACK_ALM	50_ALM_Cen_NJ01A_Cam_Accum_10	NJ01A Cameron and Daily AccumTotals Not Within 10%		1	
10/1/21 11:45 PM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 11:45 PM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/1/21 11:45 PM	ACK_RTN	50_ALM_Cen_NJ01A_Cam_Accum_10	NJ01A Cameron and Daily AccumTotals Not Within 10%		1	NULL
10/1/21 11:45 PM	ACK	50_ALM_Cen_NJ01A_Cam_Accum_10	NJ01A Cameron and Daily AccumTotals Not Within 10%		1	NULL
10/1/21 11:45 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 11:45 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 11:45 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 11:45 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 11:45 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/1/21 11:45 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 11:45 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 11:45 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 11:45 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 11:56 PM	ACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/1/21 11:56 PM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 11:56 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 11:56 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 11:56 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 11:56 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/1/21 11:59 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 11:59 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 11:59 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 11:59 PM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 11:59 PM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/1/21 11:59 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/1/21 11:59 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 11:59 PM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/1/21 11:59 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/1/21 11:59 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 11:59 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/1/21 11:59 PM	UNACK_ALM	50_ALM_Cen_NJ01A_Cam_HSC_10	NJ01A Cameron and HSC Totals Not Within 10%		1	
10/2/21 12:00 AM	UNACK_ALM	50_ALM_CEMS_Cur_Proc_Rpt_NL	Process Report For Current Month Was Not Loaded		1	
10/2/21 12:00 AM	ACK_ALM	50_ALM_CEMS_Cur_Proc_Rpt_NL	Process Report For Current Month Was Not Loaded		1	
10/2/21 12:00 AM	ACK_ALM	50_ALM_Cen_NJ01A_Cam_HSC_10	NJ01A Cameron and HSC Totals Not Within 10%		1	
10/2/21 12:00 AM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:00 AM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:00 AM	ACK_RTN	50_ALM_Cen_NJ01A_Cam_HSC_10	NJ01A Cameron and HSC Totals Not Within 10%		1	
10/2/21 12:00 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:00 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:05 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 12:06 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:06 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:06 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:06 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:06 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:06 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:06 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:06 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:06 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:06 AM	UNACK_ALM	30_ALM_TankLvl_Low_S05A	Alarm -- S05A Tank Level Low < 5%		1	
10/2/21 12:06 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:06 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:06 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:06 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:06 AM	ACK_RTN	30_ALM_TankLvl_Low_S05A	Alarm -- S05A Tank Level Low < 5%		1	NULL
10/2/21 12:06 AM	ACK	30_ALM_TankLvl_Low_S05A	Alarm -- S05A Tank Level Low < 5%		1	NULL
10/2/21 12:06 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 12:06 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:06 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:06 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:06 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:06 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:06 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:10 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:10 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:16 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:16 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:16 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:16 AM	UNACK_ALM	30_ALM_TankLvl_High_S06	Alarm -- S06 Tank Level High > 80%		1	
10/2/21 12:16 AM	ACK_RTN	30_ALM_TankLvl_High_S06	Alarm -- S06 Tank Level High > 80%		1	NULL
10/2/21 12:16 AM	ACK	30_ALM_TankLvl_High_S06	Alarm -- S06 Tank Level High > 80%		1	NULL
10/2/21 12:16 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:16 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:16 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:16 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:16 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:16 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:16 AM	ACK_RTN	85_TestTreatA_Purge_Complete	V03A Purge Complete. Ready To Start Test.		1	
10/2/21 12:16 AM	ACK_RTN	85_TestTreatB_Purge_Complete	V03B Purge Complete. Ready To Start Test.		1	
10/2/21 12:16 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:16 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:16 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:16 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:16 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:16 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:19 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 12:19 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:19 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:19 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:19 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:19 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:19 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:20 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:20 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:27 AM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:27 AM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:27 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:27 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:27 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:27 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 12:27 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:27 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:27 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:27 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:27 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:27 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:33 AM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:33 AM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:33 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:33 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:33 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:33 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:40 AM	UNACK_ALM	40_Alm_WestBay_Shutdown_VSD_06	West Well Bay Shutdown Alarm -- VSD-06		1	
10/2/21 12:40 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:40 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:40 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:40 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:40 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:40 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:40 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:40 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 12:40 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:41 AM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/2/21 12:41 AM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/2/21 12:41 AM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/2/21 12:41 AM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/2/21 12:41 AM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/2/21 12:41 AM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/2/21 12:41 AM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_06	West Well Bay Shutdown Alarm -- VSD-06		1	NULL
10/2/21 12:41 AM	ACK	40_Alm_WestBay_Shutdown_VSD_06	West Well Bay Shutdown Alarm -- VSD-06		1	NULL
10/2/21 12:41 AM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/2/21 12:41 AM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/2/21 12:41 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:41 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 12:41 AM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/2/21 12:41 AM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/2/21 12:41 AM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/2/21 12:41 AM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/2/21 12:41 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 1:03 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 1:03 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 1:03 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 1:11 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 1:11 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 1:11 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 1:30 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	██████████	1	██████████
10/2/21 1:30 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 1:30 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 1:33 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%	██████████	1	██████████
10/2/21 1:34 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 1:34 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 1:34 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED	██████████	1	██████████
10/2/21 1:34 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 1:34 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 1:34 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 1:34 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 1:34 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED	██████████	1	██████████
10/2/21 1:34 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 1:34 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 1:34 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED	██████████	1	██████████
10/2/21 1:34 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm	██████████	40	██████████
10/2/21 1:34 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 1:34 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 1:34 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 1:34 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 1:34 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED	██████████	1	██████████
10/2/21 1:34 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%	██████████	1	██████████
10/2/21 1:42 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	██████████	1	██████████
10/2/21 1:42 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 1:42 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 1:45 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	██████████	1	██████████
10/2/21 1:45 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 1:45 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 1:47 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	██████████	1	██████████
10/2/21 1:48 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 1:48 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 2:08 AM	UNACK_ALM	30_ALM_TankLvl_Low_S05A	Alarm -- S05A Tank Level Low < 5%	██████████	1	██████████
10/2/21 2:08 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 2:08 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 2:08 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 2:08 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 2:08 AM	ACK_RTN	30_ALM_TankLvl_Low_S05A	Alarm -- S05A Tank Level Low < 5%		1	NULL
10/2/21 2:08 AM	ACK	30_ALM_TankLvl_Low_S05A	Alarm -- S05A Tank Level Low < 5%		1	NULL
10/2/21 2:08 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 2:08 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 2:08 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED	██████████	1	██████████

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 2:08 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 2:49 AM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 2:49 AM	ACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 2:49 AM	ACK_RTN	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/2/21 2:49 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 2:57 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 3:00 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 3:00 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 3:00 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 3:00 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 3:01 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 3:01 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 3:01 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 3:01 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 3:01 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 3:01 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 3:01 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 3:06 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/2/21 3:14 AM	UNACK_ALM	30_ALM_TankLvL_Low_S05A	Alarm -- S05A Tank Level Low < 5%		1	
10/2/21 3:14 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 3:14 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 3:14 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 3:14 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 3:14 AM	ACK_RTN	30_ALM_TankLvL_Low_S05A	Alarm -- S05A Tank Level Low < 5%		1	NULL
10/2/21 3:14 AM	ACK	30_ALM_TankLvL_Low_S05A	Alarm -- S05A Tank Level Low < 5%		1	NULL
10/2/21 3:14 AM	ACK_RTN	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/2/21 3:14 AM	ACK	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	NULL
10/2/21 3:14 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 4:05 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 4:05 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 4:05 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 4:05 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 4:05 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 4:05 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 4:05 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 4:05 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 4:05 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 4:05 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 4:10 AM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_13	East Well Bay Shutdown Alarm -- VSD-13		1	
10/2/21 4:10 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 4:10 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 4:10 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 4:10 AM	UNACK_ALM	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm		600	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 4:39 AM	ACK_RTN	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm		600	NULL
10/2/21 4:39 AM	ACK	40_Alm_Well_VSD_13_Motor	Well VSD_13 Motor Alarm		600	NULL
10/2/21 4:39 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 4:39 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 4:42 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 4:42 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 4:42 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 4:42 AM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/2/21 4:42 AM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/2/21 4:42 AM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/2/21 4:42 AM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/2/21 4:42 AM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/2/21 4:42 AM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/2/21 4:42 AM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_13	East Well Bay Shutdown Alarm -- VSD-13		1	NULL
10/2/21 4:42 AM	ACK	40_Alm_EastBay_Shutdown_VSD_13	East Well Bay Shutdown Alarm -- VSD-13		1	NULL
10/2/21 5:01 AM	UNACK_ALM	30_ALM_TankLvl_Low_S05A	Alarm -- S05A Tank Level Low < 5%		1	
10/2/21 5:01 AM	ACK_RTN	30_ALM_TankLvl_Low_S05A	Alarm -- S05A Tank Level Low < 5%		1	NULL
10/2/21 5:01 AM	ACK	30_ALM_TankLvl_Low_S05A	Alarm -- S05A Tank Level Low < 5%		1	NULL
10/2/21 5:01 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:01 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:01 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 5:02 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 5:03 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:03 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:03 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 5:04 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:04 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:10 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 5:10 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:10 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:10 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 5:11 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:11 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:15 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 5:16 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:16 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:28 AM	UNACK_ALM	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	
10/2/21 5:28 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 5:37 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 5:37 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 5:37 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 5:37 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 5:39 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 5:39 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 5:39 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 5:40 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 5:40 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 5:40 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:40 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:40 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 5:40 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 5:40 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 5:40 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 5:40 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 5:40 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 5:40 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 5:40 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 5:43 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 5:43 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 5:43 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 5:49 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 5:55 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 5:56 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:56 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:57 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 5:57 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:57 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:59 AM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 5:59 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 5:59 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 5:59 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:59 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:59 AM	UNACK_ALM	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	
10/2/21 5:59 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:59 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:59 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 5:59 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 5:59 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 5:59 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 5:59 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 6:01 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 6:01 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 6:01 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 6:07 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 6:07 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 6:07 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 7:01 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 7:01 AM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 7:01 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 7:01 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 7:01 AM	ACK_RTN	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	NULL
10/2/21 7:01 AM	ACK	14_ALM_Atmos_Leak_Detected	Atmos -- LEAK DETECTED		1	NULL
10/2/21 7:01 AM	ACK_RTN	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 7:01 AM	ACK	10_ALM_Leak_Detect_From_Atmos	Signal from Atmos -- LEAK DETECTED		1	NULL
10/2/21 7:01 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 7:01 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 7:01 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 7:01 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 7:15 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 7:16 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 7:16 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 7:16 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 7:16 AM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 7:34 AM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/2/21 7:46 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 7:46 AM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/2/21 7:46 AM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/2/21 7:46 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 7:46 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 7:46 AM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/2/21 7:51 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:51 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:51 AM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/2/21 7:51 AM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/2/21 7:51 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 7:51 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 7:51 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 7:51 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:51 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:55 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 7:55 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 7:55 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 7:57 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:10 AM	UNACK_ALM	40_Alm_Well_Scatter	Well Red-Eye Scatter Alarm		600	
10/2/21 8:16 AM	UNACK_ALM	85_TestTreatA_Test_Complete	V03A Well Test Complete		1	
10/2/21 8:16 AM	UNACK_ALM	85_TestTreatB_Test_Complete	V03B Well Test Complete		1	
10/2/21 8:24 AM	UNACK_ALM	60_Alm_Well_VSD_06_Motor	Well VSD_06 Motor Alarm		600	
10/2/21 8:27 AM	ACK_RTN	60_Alm_Well_VSD_06_Motor	Well VSD_06 Motor Alarm		600	NULL
10/2/21 8:27 AM	ACK	60_Alm_Well_VSD_06_Motor	Well VSD_06 Motor Alarm		600	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:31 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:32 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:32 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:32 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:32 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:32 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:32 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:32 AM	UNACK_ALM	20_ALM_Eureka_Disch_PSI_Low	Eureka Pipeline Discharge PSI Fell Below 170 PSI		1	
10/2/21 8:32 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:32 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:32 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:32 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:32 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:32 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:32 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:32 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:32 AM	ACK_RTN	20_ALM_Eureka_Disch_PSI_Low	Eureka Pipeline Discharge PSI Fell Below 170 PSI		1	NULL
10/2/21 8:32 AM	ACK	20_ALM_Eureka_Disch_PSI_Low	Eureka Pipeline Discharge PSI Fell Below 170 PSI		1	NULL
10/2/21 8:32 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:33 AM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_01	East Well Bay Shutdown Alarm -- VSD-01		1	
10/2/21 8:33 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:33 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:33 AM	ACK_RTN	50_ALM_Cen_NJ01A_Modbus_Fail	NJ01A Modbus Fail		1	
10/2/21 8:33 AM	UNACK_ALM	50_ALM_Cen_NJ01A_Modbus_Fail	NJ01A Modbus Fail		1	
10/2/21 8:33 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:33 AM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_07	East Well Bay Shutdown Alarm -- VSD-07		1	
10/2/21 8:33 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:33 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:33 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:33 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:33 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:33 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:33 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:33 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:33 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:33 AM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_09	East Well Bay Shutdown Alarm -- VSD-09		1	
10/2/21 8:33 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:33 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:33 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:33 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:33 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:34 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:34 AM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_11	East Well Bay Shutdown Alarm -- VSD-11		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:36 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:36 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:36 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:36 AM	UNACK_ALM	40_Alm_WestBay_Shutdown_VSD_14	West Well Bay Shutdown Alarm -- VSD-14		1	
10/2/21 8:36 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:36 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:36 AM	UNACK_ALM	40_Alm_WestBay_Shutdown_VSD_16	West Well Bay Shutdown Alarm -- VSD-16		1	
10/2/21 8:36 AM	UNACK_ALM	40_Alm_WestBay_Shutdown_VSD_08	West Well Bay Shutdown Alarm -- VSD-08		1	
10/2/21 8:36 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:36 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:36 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:36 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:36 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:36 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:37 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:37 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:37 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:37 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:37 AM	UNACK_ALM	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		40	
10/2/21 8:37 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		1	
10/2/21 8:37 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:37 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:37 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:37 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:37 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:38 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:38 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:38 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:38 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:38 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:38 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:38 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:38 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:38 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:38 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:38 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:38 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:38 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:38 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:38 AM	UNACK_ALM	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low		500	
10/2/21 8:38 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:38 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:38 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:38 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:38 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:38 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:38 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:38 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:38 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:38 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:38 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:38 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:38 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:38 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:38 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:38 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:38 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:39 AM	UNACK_ALM	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:40 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:40 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:40 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:40 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:40 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:40 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:40 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:40 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:40 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:40 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:40 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:40 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:40 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:40 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:40 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:40 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:41 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:41 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:41 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:41 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:41 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:41 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:41 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:41 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:41 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:41 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:41 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:41 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:41 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:41 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:41 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:41 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:41 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:41 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:41 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:41 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:41 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:41 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:41 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:41 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:41 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:41 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:41 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:42 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:42 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:42 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:42 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:42 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:42 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:42 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:42 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:42 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:42 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:42 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:42 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:42 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:42 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 8:44 AM	UNACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	
10/2/21 8:49 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:49 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:49 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 8:49 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:49 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:49 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:49 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:49 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:49 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:49 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:49 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:49 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:49 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:49 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:49 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:49 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:49 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:49 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:49 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:49 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:49 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:49 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:49 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:49 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:49 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:49 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:49 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:49 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:49 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:49 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:49 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:49 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:49 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:52 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:52 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:52 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:52 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:52 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:52 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:52 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:52 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:52 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:52 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:52 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:52 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:52 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:52 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:52 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:53 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 8:53 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:53 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:53 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:53 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:53 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:53 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:53 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:53 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:53 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:53 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:53 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:53 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:53 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:53 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:53 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:53 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:53 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:53 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 8:53 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 8:53 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:53 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:53 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:53 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:53 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:53 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:53 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 8:53 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 8:53 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:53 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:53 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:53 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:53 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:53 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:53 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:53 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:53 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:53 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 8:53 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:53 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:53 AM	ACK_RTN	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low		500	NULL
10/2/21 8:53 AM	ACK	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low		500	NULL
10/2/21 8:53 AM	ACK_RTN	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	NULL
10/2/21 8:53 AM	ACK	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	NULL
10/2/21 8:53 AM	UNACK_ALM	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low		500	
10/2/21 8:53 AM	UNACK_ALM	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	
10/2/21 8:54 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 8:54 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:54 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:54 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:54 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:54 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:54 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:54 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 8:54 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 8:54 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:54 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:54 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:54 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:54 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:54 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:54 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:54 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:54 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:54 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:54 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 8:54 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:54 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:54 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:54 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:54 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:54 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:54 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:54 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:54 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:54 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:54 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:54 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 8:55 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:55 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 8:55 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:55 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:55 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:55 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:55 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 8:55 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:55 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 8:55 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:55 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 8:57 AM	UNACK_ALM	50_ALM_Cen_NJ01B_Dsl_Rep_Err	NJ01B Diesel Reported Without Usage Alarm		1	
10/2/21 8:59 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 8:59 AM	ACK_RTN	50_ALM_Cen_NJ01B_Dsl_Rep_Err	NJ01B Diesel Reported Without Usage Alarm		1	NULL
10/2/21 8:59 AM	ACK	50_ALM_Cen_NJ01B_Dsl_Rep_Err	NJ01B Diesel Reported Without Usage Alarm		1	NULL
10/2/21 8:59 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:59 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:59 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 8:59 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 8:59 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:59 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:00 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:00 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:00 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:00 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:00 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:00 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:00 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:00 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:00 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:00 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:00 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:00 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:00 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:00 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:00 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:00 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:00 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:00 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:00 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:00 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:00 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:02 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:02 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:02 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:02 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:02 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:02 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:02 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:02 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:02 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:02 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:02 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:02 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:02 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:02 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:02 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:02 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:02 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:02 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:02 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:02 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:02 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:02 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:02 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:02 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 9:02 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:03 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:03 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:03 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:03 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:03 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:03 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:03 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:03 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:03 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:03 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:03 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:03 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:03 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:03 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:03 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:03 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:03 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:03 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:03 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:03 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:03 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:03 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:03 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:03 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:03 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:04 AM	UNACK_ALM	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	
10/2/21 9:04 AM	UNACK_ALM	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	
10/2/21 9:04 AM	UNACK_ALM	U36_ALM_036	ALM_036 : Bently Nevada High Vibration Summary Alarm		2	
10/2/21 9:06 AM	UNACK_ALM	50_ALM_Sat_NP07A_Dsl_Switch_Fail	NP07A Diesel Switch Failure		1	
10/2/21 9:06 AM	UNACK_ALM	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	
10/2/21 9:06 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:06 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:06 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:06 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:06 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:06 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:06 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:06 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:06 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:06 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:06 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:06 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:06 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:06 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:06 AM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_03	East Well Bay Shutdown Alarm -- VSD-03		1	
10/2/21 9:06 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:06 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:06 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:06 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:06 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:06 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:06 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:06 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:06 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:06 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:06 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:06 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 9:06 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:09 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 9:09 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 9:09 AM	ACK_RTN	50_ALM_Sat_NP07A_Dsl_Switch_Fail	NP07A Diesel Switch Failure		1	NULL
10/2/21 9:09 AM	ACK	50_ALM_Sat_NP07A_Dsl_Switch_Fail	NP07A Diesel Switch Failure		1	NULL
10/2/21 9:09 AM	ACK_RTN	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/2/21 9:09 AM	ACK	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/2/21 9:09 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:09 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:09 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 9:09 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:09 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:09 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:09 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:09 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:09 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:09 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:09 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:09 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:09 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:09 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:09 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:09 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:09 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:09 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:09 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:09 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:09 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:09 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:09 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:09 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:09 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:10 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:10 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:10 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:10 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:10 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:10 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:10 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:10 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:10 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:10 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:10 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:10 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:10 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:10 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:10 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:10 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:10 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:10 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:10 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:10 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:11 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:11 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:11 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:11 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:11 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:11 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 9:11 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:11 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:11 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:11 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:11 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:11 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:11 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:11 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:11 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:11 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:11 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:11 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:11 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:11 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:11 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:11 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:11 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 9:11 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 9:11 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:11 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:11 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 9:11 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:12 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:12 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:12 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:12 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:12 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:12 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:12 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:12 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:12 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:12 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:12 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:12 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:12 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:12 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:12 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:12 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:12 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:12 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:12 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:12 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:12 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:12 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:12 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:12 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:12 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:12 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:12 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:12 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 9:12 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 9:12 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:12 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:12 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 9:13 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:13 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/2/21 9:13 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:13 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:13 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:13 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:13 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:13 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:13 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:13 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:13 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:13 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:13 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:13 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:13 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:13 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:13 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:13 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:13 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 9:13 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 9:13 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:13 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:13 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:13 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:13 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:13 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:13 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:13 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:13 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/2/21 9:13 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:13 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:13 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:21 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 9:21 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:21 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:21 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:21 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:21 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:21 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:21 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:21 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:21 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:21 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:21 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:21 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:21 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:21 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:21 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:21 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:21 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 9:21 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 9:21 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:21 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:21 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:21 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:21 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:21 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:21 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:21 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:21 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:21 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:21 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:29 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:29 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:29 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:29 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:29 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 9:29 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:29 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:29 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:29 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:29 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:29 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:29 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:30 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:30 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:30 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:30 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:30 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:30 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:30 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:30 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 9:30 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:30 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:30 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:30 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 9:30 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 9:30 AM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 9:30 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 9:30 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:30 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:30 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:30 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:30 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:30 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:30 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:30 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:30 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:30 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:30 AM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 9:30 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 9:30 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 9:30 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:33 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:33 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:33 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:33 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:33 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:33 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:33 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:33 AM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 9:33 AM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 9:33 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 9:33 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 9:33 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:33 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:33 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:33 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:33 AM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 9:33 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 9:33 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 9:33 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 9:45 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName	
10/2/21 9:45 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL	
10/2/21 9:56 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1		
10/2/21 9:56 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL	
10/2/21 9:56 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL	
10/2/21 9:56 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL	
10/2/21 9:56 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL	
10/2/21 9:56 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL	
10/2/21 9:56 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL	
10/2/21 9:56 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL	
10/2/21 9:56 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL	
10/2/21 9:56 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL	
10/2/21 9:56 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL	
10/2/21 9:56 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL	
10/2/21 9:56 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL	
10/2/21 9:56 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL	
10/2/21 9:56 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL	
10/2/21 9:56 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL	
10/2/21 9:56 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL	
10/2/21 9:56 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1		
10/2/21 9:56 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1		
10/2/21 9:56 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1		
10/2/21 9:56 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1		
10/2/21 9:56 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1		
10/2/21 9:56 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1		
10/2/21 9:56 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1		
10/2/21 9:56 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1		
10/2/21 9:56 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL	
10/2/21 9:56 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL	
10/2/21 9:56 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1		
10/2/21 9:57 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL	
10/2/21 9:57 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL	
10/2/21 10:07 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1	
10/2/21 10:07 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1	
10/2/21 10:07 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL	
10/2/21 10:07 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL	
10/2/21 10:07 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL	
10/2/21 10:07 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL	
10/2/21 10:07 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL	
10/2/21 10:07 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL	
10/2/21 10:07 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL	
10/2/21 10:07 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL	
10/2/21 10:07 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL	
10/2/21 10:07 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:07 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 10:07 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 10:07 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 10:07 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 10:07 AM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/2/21 10:07 AM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/2/21 10:07 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 10:07 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 10:07 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 10:07 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1
10/2/21 10:07 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning			1
10/2/21 10:07 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1
10/2/21 10:07 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature			1
10/2/21 10:07 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 10:07 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 10:07 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 10:07 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 10:07 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 10:07 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 10:07 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 10:07 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 10:07 AM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/2/21 10:07 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/2/21 10:07 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 10:09 AM	UNACK_ALM	U36_ALM_027	ALM_027 : PT341: Fuel Gas Header Pressure High			2
10/2/21 10:09 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS			1
10/2/21 10:10 AM	UNACK_ALM	U35_ALM_027	ALM_027 : PT341: Fuel Gas Header Pressure High			2
10/2/21 10:11 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure			1
10/2/21 10:11 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 10:11 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 10:11 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1 NULL
10/2/21 10:11 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1 NULL
10/2/21 10:11 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure			1 NULL
10/2/21 10:11 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure			1 NULL
10/2/21 10:11 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning			1 NULL
10/2/21 10:11 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning			1 NULL
10/2/21 10:11 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1 NULL
10/2/21 10:11 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1 NULL
10/2/21 10:11 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 10:11 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 10:11 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature			1 NULL
10/2/21 10:11 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature			1 NULL
10/2/21 10:11 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:11 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:11 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:11 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:11 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 10:11 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 10:11 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 10:11 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 10:11 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:11 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 10:11 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 10:11 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 10:11 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 10:11 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:11 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:11 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:11 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 10:17 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 10:17 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 10:17 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 10:17 AM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 10:17 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 10:17 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 10:17 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 10:17 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 10:17 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 10:17 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 10:17 AM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 10:17 AM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 10:17 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:17 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:17 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 10:26 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:26 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:26 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:26 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 10:27 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 10:27 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 10:27 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:27 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:27 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	1	NULL
10/2/21 10:27 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	1	NULL
10/2/21 10:27 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	1	NULL
10/2/21 10:27 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	1	NULL
10/2/21 10:27 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	1	NULL
10/2/21 10:27 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 10:27 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:27 AM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 10:27 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 10:27 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:27 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 10:27 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 10:27 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:27 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:27 AM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 10:27 AM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 10:27 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 10:27 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 10:27 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:27 AM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 10:27 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 10:27 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:27 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:27 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:27 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:28 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:28 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 10:28 AM	ACK_RTN	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low		500	NULL
10/2/21 10:28 AM	ACK	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low		500	NULL
10/2/21 10:28 AM	ACK_RTN	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	NULL
10/2/21 10:28 AM	ACK	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	NULL
10/2/21 10:28 AM	UNACK_ALM	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low		500	
10/2/21 10:28 AM	UNACK_ALM	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	
10/2/21 10:28 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 10:28 AM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 10:28 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 10:28 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 10:28 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:28 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm	[REDACTED]	1	NULL
10/2/21 10:28 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed	[REDACTED]	1	NULL
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm	[REDACTED]	1	[REDACTED]
10/2/21 10:28 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning	[REDACTED]	1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning	[REDACTED]	1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:28 AM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 10:28 AM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 10:28 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 10:28 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 10:29 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 10:29 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 10:29 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 10:29 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 10:29 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 10:29 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	
10/2/21 10:29 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:29 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 10:29 AM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 10:29 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 10:29 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 10:29 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:30 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:30 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:31 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:31 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:31 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:32 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:32 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:32 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:32 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:32 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:32 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:33 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:33 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:33 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:33 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:33 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 10:33 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName	
10/2/21 10:33 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL	
10/2/21 10:33 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL	
10/2/21 10:33 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL	
10/2/21 10:33 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL	
10/2/21 10:33 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL	
10/2/21 10:33 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL	
10/2/21 10:33 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL	
10/2/21 10:33 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL	
10/2/21 10:33 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL	
10/2/21 10:33 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL	
10/2/21 10:33 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL	
10/2/21 10:33 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL	
10/2/21 10:33 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL	
10/2/21 10:33 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL	
10/2/21 10:33 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL	
10/2/21 10:33 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL	
10/2/21 10:33 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1		
10/2/21 10:33 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1		
10/2/21 10:33 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1		
10/2/21 10:33 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1		
10/2/21 10:33 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1		
10/2/21 10:33 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1		
10/2/21 10:33 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1		
10/2/21 10:33 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1		
10/2/21 10:33 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1		
10/2/21 10:33 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL	
10/2/21 10:33 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL	
10/2/21 10:33 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1		
10/2/21 10:35 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1		
10/2/21 10:36 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL	
10/2/21 10:36 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL	
10/2/21 10:36 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1		
10/2/21 10:37 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL	
10/2/21 10:37 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL	
10/2/21 10:37 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1	
10/2/21 10:37 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1	
10/2/21 10:37 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1	
10/2/21 10:37 AM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1	
10/2/21 10:37 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1	NULL
10/2/21 10:37 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1	NULL
10/2/21 10:37 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1	NULL
10/2/21 10:37 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1	NULL
10/2/21 10:37 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:37 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 10:37 AM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 10:37 AM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 10:37 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:37 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:37 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 10:37 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:37 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:37 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:38 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:38 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:38 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:39 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:39 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:39 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:41 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:41 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:41 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:43 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:43 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:43 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:44 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:44 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:46 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:46 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:46 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:47 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 10:47 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 10:47 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 10:47 AM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 10:47 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:47 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi	Alarm--Train B Emul Heater X04B Hi Temperature		1	NULL
10/2/21 10:47 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 10:47 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 10:47 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 10:47 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 10:47 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 10:47 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 10:47 AM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 10:47 AM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 10:47 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:47 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:47 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:49 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	[REDACTED]	1	[REDACTED]
10/2/21 10:49 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:49 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:49 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	[REDACTED]	1	[REDACTED]
10/2/21 10:49 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:49 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:51 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	[REDACTED]	1	[REDACTED]
10/2/21 10:51 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:51 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:51 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	[REDACTED]	1	[REDACTED]
10/2/21 10:51 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:51 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:52 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	[REDACTED]	1	[REDACTED]
10/2/21 10:52 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:52 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:53 AM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	[REDACTED]	1	[REDACTED]
10/2/21 10:53 AM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:53 AM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:55 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed	[REDACTED]	1	[REDACTED]
10/2/21 10:55 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:55 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:56 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm	[REDACTED]	1	[REDACTED]
10/2/21 10:57 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	[REDACTED]	1 [REDACTED]
10/2/21 10:57 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	[REDACTED]	1 [REDACTED]
10/2/21 10:57 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/2/21 10:57 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 10:57 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 10:57 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 10:57 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 10:57 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 10:57 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 10:57 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:57 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 10:57 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm	[REDACTED]	1	[REDACTED]
10/2/21 11:01 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:01 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:07 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	[REDACTED]	1 [REDACTED]
10/2/21 11:07 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	[REDACTED]	1 [REDACTED]
10/2/21 11:07 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/2/21 11:07 AM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/2/21 11:07 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:07 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:07 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 11:07 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 11:07 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 11:07 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 11:07 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 11:07 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 11:07 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 11:07 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 11:07 AM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 11:07 AM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 11:07 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:07 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 11:07 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 11:07 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 11:07 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 11:16 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/2/21 11:17 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 11:17 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 11:17 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 11:17 AM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 11:17 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 11:17 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 11:17 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:17 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:17 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 11:17 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 11:17 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:17 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:17 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 11:17 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 11:17 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 11:17 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 11:17 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 11:17 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 11:17 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 11:17 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 11:17 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 11:17 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 11:17 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 11:17 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 11:17 AM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 11:17 AM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 11:17 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 11:17 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 11:17 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 11:17 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:17 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 11:17 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 11:17 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	
10/2/21 11:17 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 11:17 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 11:17 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 11:21 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:21 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 11:21 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 11:21 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:21 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:21 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 11:21 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 11:21 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:21 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:21 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 11:21 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 11:21 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 11:21 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 11:21 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:21 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:21 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 11:21 AM	ACK	91_Alm_TrainB_X04B_Temp_Hi_Warn	Warning--Train B Emul Heater X04B Hi Temp Warning		1	NULL
10/2/21 11:21 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 11:21 AM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 11:21 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 11:21 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 11:21 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 11:21 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 11:21 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 11:21 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:21 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 11:21 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:21 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 11:21 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 11:21 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:21 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 11:21 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 11:21 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 11:21 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 11:21 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 11:27 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 11:27 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 11:27 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 11:27 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 11:27 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 11:27 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 11:27 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 11:27 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 11:27 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 11:27 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 11:27 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 11:27 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 11:37 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 11:37 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 11:37 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 11:37 AM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 11:37 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 11:37 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 11:37 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 11:37 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 11:37 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 11:37 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 11:37 AM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 11:37 AM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 11:37 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 11:37 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 11:37 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 11:47 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 11:47 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 11:47 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 11:47 AM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 11:47 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 11:47 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 11:47 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1 NULL
10/2/21 11:47 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1 NULL
10/2/21 11:47 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 11:47 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 11:47 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 11:47 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 11:47 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 11:47 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 11:47 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 11:47 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 11:47 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 11:47 AM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 11:47 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:47 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:47 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour
10/2/21 11:47 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour
10/2/21 11:47 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			Eu_Elly Leak Detect 10 Minute
10/2/21 11:47 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			Eu_Elly Leak Detect 10 Minute
10/2/21 11:47 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly			10 Inch Pipeline 1 Hour Leak Detect Alarm
10/2/21 11:47 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly			10 Inch Pipeline 1 Hour Leak Detect Alarm
10/2/21 11:47 AM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly			10 Inch Pipeline 10 Minute Leak Detect Alarm
10/2/21 11:47 AM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly			10 Inch Pipeline 10 Minute Leak Detect Alarm
10/2/21 11:47 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 11:47 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:47 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 11:47 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:47 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 11:47 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:47 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 11:47 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 11:49 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:49 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:57 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour
10/2/21 11:57 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			Eu_Elly Leak Detect 10 Minute
10/2/21 11:57 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly			10 Inch Pipeline 1 Hour Leak Detect Alarm
10/2/21 11:57 AM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly			10 Inch Pipeline 10 Minute Leak Detect Alarm
10/2/21 11:57 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour
10/2/21 11:57 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour
10/2/21 11:57 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			Eu_Elly Leak Detect 10 Minute
10/2/21 11:57 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			Eu_Elly Leak Detect 10 Minute
10/2/21 11:57 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly			10 Inch Pipeline 1 Hour Leak Detect Alarm
10/2/21 11:57 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly			10 Inch Pipeline 1 Hour Leak Detect Alarm
10/2/21 11:57 AM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly			10 Inch Pipeline 10 Minute Leak Detect Alarm
10/2/21 11:57 AM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly			10 Inch Pipeline 10 Minute Leak Detect Alarm
10/2/21 11:57 AM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 11:57 AM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 11:57 AM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 12:07 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour
10/2/21 12:07 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			Eu_Elly Leak Detect 10 Minute
10/2/21 12:07 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly			10 Inch Pipeline 1 Hour Leak Detect Alarm
10/2/21 12:07 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour
10/2/21 12:07 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour
10/2/21 12:07 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			Eu_Elly Leak Detect 10 Minute

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 12:07 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 12:07 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:07 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:07 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:07 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:07 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:09 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:09 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 12:09 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 12:09 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:09 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:10 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:14 PM	UNACK_ALM	60_Alm_Well_Test_LA_PSI_Low_Warn	Well Test LA 1802 Pressure Low Warning		1	NULL
10/2/21 12:17 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 12:17 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 12:17 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:17 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 12:17 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 12:17 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 12:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 12:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 12:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 12:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 12:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 12:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 12:17 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 12:17 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 12:17 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 12:17 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 12:17 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:17 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:17 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 12:17 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 12:17 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 12:17 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 12:17 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:17 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:17 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 12:17 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 12:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 12:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 12:17 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 12:17 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:17 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:17 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 12:25 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:25 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:25 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:25 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:25 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:25 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:25 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 12:25 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 12:25 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 12:25 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 12:25 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 12:25 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 12:25 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 12:25 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 12:25 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 12:25 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 12:25 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 12:25 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 12:25 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:25 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:25 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 12:25 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 12:25 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 12:25 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 12:25 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 12:25 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 12:25 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 12:25 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 12:27 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 12:27 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 12:27 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 12:27 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 12:27 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 12:27 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 12:27 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 12:27 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 12:27 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 12:27 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:27 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 12:27 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 12:27 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:27 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:27 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:37 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 12:37 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:37 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 12:37 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 12:37 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 12:37 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 12:37 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 12:37 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 12:37 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 12:37 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 12:37 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 12:37 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 12:37 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 12:37 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 12:37 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 12:37 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 12:37 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:37 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:37 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 12:37 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 12:37 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 12:37 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 12:37 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:37 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:37 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 12:37 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 12:37 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:37 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:37 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 12:37 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 12:37 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 12:37 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 12:37 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 12:37 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 12:37 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:37 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:42 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 12:42 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 12:47 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 12:47 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 12:47 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 12:47 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 12:47 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 12:47 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 12:47 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 12:47 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 12:47 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 12:47 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 12:47 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 12:47 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 12:47 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 12:47 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 12:47 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 12:47 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 12:47 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 12:47 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 12:47 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 12:47 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:47 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:47 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:47 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 12:47 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:47 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 12:47 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 12:47 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 12:47 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 12:47 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 12:47 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 12:47 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 12:47 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 12:47 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 12:47 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 12:47 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 12:48 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 12:48 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 12:48 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 12:48 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 12:48 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 12:48 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 12:48 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 12:48 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 12:48 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 12:48 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 12:48 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 12:48 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1 NULL
10/2/21 12:48 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1 NULL
10/2/21 12:48 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 12:48 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 12:48 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1
10/2/21 12:48 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 12:48 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 12:48 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 12:48 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/2/21 12:48 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1
10/2/21 12:48 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1
10/2/21 12:48 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 12:48 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 12:48 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 12:49 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 12:49 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 12:57 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 12:57 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 12:57 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 12:57 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 12:57 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 12:57 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 12:57 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 12:57 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 12:57 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:57 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 12:57 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 12:57 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 12:57 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 12:57 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 12:57 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 1:07 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 1:07 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 1:07 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 1:07 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 1:07 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 1:07 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 1:07 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 1:07 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 1:07 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 1:07 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 1:07 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 1:07 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 1:07 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 1:07 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 1:07 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 1:17 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 1:17 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 1:17 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 1:17 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 1:17 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1 NULL	
10/2/21 1:17 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1 NULL	
10/2/21 1:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1 NULL	
10/2/21 1:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1 NULL	
10/2/21 1:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1 NULL	
10/2/21 1:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1 NULL	
10/2/21 1:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1 NULL	
10/2/21 1:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1 NULL	
10/2/21 1:17 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1 NULL	
10/2/21 1:17 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1 NULL	
10/2/21 1:17 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1 NULL	
10/2/21 1:17 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1 NULL	
10/2/21 1:17 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 1:17 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 1:17 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 1:17 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 1:17 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 1:17 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 1:17 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 1:17 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 1:17 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	
10/2/21 1:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 1:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 1:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 1:17 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 1:17 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 1:17 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 1:17 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 1:17 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 1:27 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 1:27 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 1:27 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 1:27 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1 NULL
10/2/21 1:27 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1 NULL
10/2/21 1:27 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 1:27 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 1:27 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 1:27 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 1:27 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 1:27 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 1:27 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 1:27 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 1:27 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1 NULL
10/2/21 1:27 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1 NULL
10/2/21 1:27 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 1:27 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 1:27 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 1:27 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 1:27 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 1:27 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 1:27 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1
10/2/21 1:27 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 1:27 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 1:27 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 1:27 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/2/21 1:27 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1
10/2/21 1:27 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 1:27 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 1:27 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 1:37 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 1:37 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 1:37 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 1:37 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 1:37 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 1:37 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 1:37 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 1:37 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 1:37 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 1:37 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 1:37 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 1:37 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 1:37 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 1:37 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 1:37 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 1:43 PM	UNACK_ALM	U39_ALARMS_1_29	U39-ALM-062: T5 TC6 Deviation from AVG Hi			2

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 1:43 PM	UNACK_ALM	U39_ALARMS_1_25	U39-ALM-058: T5 TC2 Deviation from AVG Hi	[REDACTED]	2	[REDACTED]
10/2/21 1:44 PM	ACK_RTN	U39_ALARMS_1_29	U39-ALM-062: T5 TC6 Deviation from AVG Hi		2	NULL
10/2/21 1:44 PM	ACK	U39_ALARMS_1_29	U39-ALM-062: T5 TC6 Deviation from AVG Hi		2	NULL
10/2/21 1:44 PM	ACK_RTN	U39_ALARMS_1_25	U39-ALM-058: T5 TC2 Deviation from AVG Hi		2	NULL
10/2/21 1:44 PM	ACK	U39_ALARMS_1_25	U39-ALM-058: T5 TC2 Deviation from AVG Hi		2	NULL
10/2/21 1:47 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	[REDACTED]	1 [REDACTED]
10/2/21 1:47 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	[REDACTED]	1 [REDACTED]
10/2/21 1:47 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/2/21 1:47 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/2/21 1:47 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 1:47 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 1:47 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 1:47 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 1:47 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 1:47 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 1:47 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 1:47 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 1:47 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 1:47 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 1:47 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 1:47 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 1:47 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	[REDACTED]	1 NULL
10/2/21 1:47 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	[REDACTED]	1 NULL
10/2/21 1:47 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	[REDACTED]	1 NULL
10/2/21 1:47 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	[REDACTED]	1 NULL
10/2/21 1:47 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	[REDACTED]	1 NULL
10/2/21 1:47 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	[REDACTED]	1 NULL
10/2/21 1:47 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm	[REDACTED]	1 NULL
10/2/21 1:47 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm	[REDACTED]	1 NULL
10/2/21 1:47 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature	[REDACTED]	1	[REDACTED]
10/2/21 1:47 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]	1	[REDACTED]
10/2/21 1:47 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed	[REDACTED]	1	[REDACTED]
10/2/21 1:47 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]	1	[REDACTED]
10/2/21 1:47 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]	1	[REDACTED]
10/2/21 1:47 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning	[REDACTED]	1	[REDACTED]
10/2/21 1:47 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 1:47 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 1:47 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm	[REDACTED]	1	[REDACTED]
10/2/21 1:57 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	[REDACTED]	1 [REDACTED]
10/2/21 1:57 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	[REDACTED]	1 [REDACTED]
10/2/21 1:57 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/2/21 1:57 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/2/21 1:57 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 1:57 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1 NULL
10/2/21 1:57 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 1:57 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 1:57 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 1:57 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 1:57 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 1:57 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 1:57 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 1:57 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 1:57 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1 NULL
10/2/21 1:57 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1 NULL
10/2/21 1:57 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 1:57 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 1:57 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 1:57 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 1:57 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 1:57 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 1:57 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 1:57 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 1:57 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 1:57 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 1:57 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1
10/2/21 1:57 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 1:57 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 1:57 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 1:57 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/2/21 1:57 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1
10/2/21 1:57 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 2:07 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 2:07 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 2:07 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 2:07 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 2:07 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 2:07 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 2:07 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 2:07 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 2:07 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 2:07 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 2:07 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 2:07 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 2:07 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 2:07 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 2:07 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 2:07 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 2:07 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 2:07 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 2:17 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 2:17 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 2:17 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 2:17 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 2:17 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 2:17 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 2:17 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 2:17 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 2:17 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 2:17 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 2:17 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 2:17 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 2:17 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 2:17 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 2:17 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 2:27 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 2:27 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 2:27 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 2:27 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 2:27 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 2:27 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 2:27 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 2:27 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 2:27 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 2:27 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 2:27 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 2:27 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 2:27 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 2:27 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 2:27 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 2:37 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 2:37 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 2:37 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 2:37 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 2:37 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 2:37 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 2:37 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 2:37 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 2:37 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 2:37 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 2:37 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 2:37 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 2:37 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 2:37 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 2:37 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1 NULL
10/2/21 2:37 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1 NULL
10/2/21 2:37 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 2:37 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 2:37 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 2:37 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 2:37 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 2:37 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 2:37 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 2:37 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 2:37 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1
10/2/21 2:37 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 2:37 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 2:37 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 2:37 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/2/21 2:37 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1
10/2/21 2:37 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 2:37 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 2:37 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 2:43 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/2/21 2:43 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1 NULL
10/2/21 2:43 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1 NULL
10/2/21 2:43 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 2:43 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 2:43 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 2:43 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 2:43 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 2:43 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 2:43 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 2:43 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 2:43 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1 NULL
10/2/21 2:43 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1 NULL
10/2/21 2:43 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature			1
10/2/21 2:43 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 2:43 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 2:43 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 2:43 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/2/21 2:43 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning			1
10/2/21 2:43 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 2:43 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 2:43 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 2:47 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 2:47 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 2:47 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 2:47 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 2:47 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 2:47 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 2:47 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 2:47 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 2:47 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 2:47 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 2:47 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 2:47 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 2:47 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 2:47 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 2:47 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 2:57 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 2:57 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 2:57 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 2:57 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 2:57 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 2:57 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 2:57 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 2:57 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 2:57 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 2:57 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 2:57 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi	Alarm--Train B Crude Heater X02B Hi Temperature		1	NULL
10/2/21 2:57 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 2:57 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 2:57 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 2:58 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 2:58 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 2:58 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 2:58 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 2:58 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 2:58 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 2:58 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 2:58 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 2:58 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 2:58 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 2:58 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 2:58 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 2:58 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 2:58 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 2:58 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 2:58 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	
10/2/21 2:58 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 2:58 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 2:59 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 3:01 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/2/21 3:07 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 3:07 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 3:07 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 3:07 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 3:07 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 3:07 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 3:07 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 3:07 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 3:07 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 3:07 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 3:07 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 3:07 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 3:07 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 3:07 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 3:07 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 3:07 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 3:07 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 3:07 PM	ACK	91_Alm_TrainB_X02B_Temp_Hi_Warn	Warning--Train B Crude Heater X02B Hi Temp Warning		1	NULL
10/2/21 3:07 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 3:11 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/2/21 3:17 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 3:17 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 3:17 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 3:17 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 3:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 3:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 3:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 3:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 3:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 3:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 3:17 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 3:17 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 3:17 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 3:17 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 3:17 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 3:17 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 3:17 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 3:17 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 3:17 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 3:17 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 3:17 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1 NULL	
10/2/21 3:17 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1 NULL	
10/2/21 3:17 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 3:17 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 3:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 3:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 3:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 3:17 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 3:17 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 3:27 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 3:27 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 3:27 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 3:27 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 3:27 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1 NULL	
10/2/21 3:27 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1 NULL	
10/2/21 3:27 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1 NULL	
10/2/21 3:27 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1 NULL	
10/2/21 3:27 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1 NULL	
10/2/21 3:27 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1 NULL	
10/2/21 3:27 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1 NULL	
10/2/21 3:27 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1 NULL	
10/2/21 3:27 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 3:27 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 3:27 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 3:27 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 3:27 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 3:27 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 3:27 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 3:27 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 3:27 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 3:27 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 3:27 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 3:27 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 3:27 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 3:27 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 3:27 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 3:37 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 3:37 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 3:37 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly			1 [REDACTED]
10/2/21 3:37 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			1 NULL
10/2/21 3:37 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			1 NULL
10/2/21 3:37 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			1 NULL
10/2/21 3:37 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			1 NULL
10/2/21 3:37 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly			1 NULL
10/2/21 3:37 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly			1 NULL
10/2/21 3:37 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 3:37 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 3:37 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm	[REDACTED]		1 [REDACTED]
10/2/21 3:45 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed	[REDACTED]		1 [REDACTED]
10/2/21 3:45 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 3:45 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 3:45 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 3:45 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 3:45 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 3:45 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 3:45 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 3:45 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 3:45 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 3:45 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 3:45 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 3:45 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 3:45 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]		1 [REDACTED]
10/2/21 3:45 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed	[REDACTED]		1 [REDACTED]
10/2/21 3:45 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]		1 [REDACTED]
10/2/21 3:45 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]		1 [REDACTED]
10/2/21 3:45 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed	[REDACTED]		1 [REDACTED]
10/2/21 3:45 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm	[REDACTED]		40 [REDACTED]
10/2/21 3:45 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 3:45 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 3:45 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm	[REDACTED]		1 [REDACTED]
10/2/21 3:47 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly			1 [REDACTED]
10/2/21 3:47 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly			1 [REDACTED]
10/2/21 3:47 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			1 [REDACTED]
10/2/21 3:47 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			1 [REDACTED]
10/2/21 3:47 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			1 NULL
10/2/21 3:47 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			1 NULL
10/2/21 3:47 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			1 NULL
10/2/21 3:47 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			1 NULL
10/2/21 3:47 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly			1 NULL
10/2/21 3:47 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly			1 NULL
10/2/21 3:47 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 3:47 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 3:47 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 3:47 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 3:47 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40 NULL	
10/2/21 3:47 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40 NULL	
10/2/21 3:47 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 3:47 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 3:57 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 3:57 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 3:57 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 3:57 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 3:57 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1 NULL	
10/2/21 3:57 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1 NULL	
10/2/21 3:57 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1 NULL	
10/2/21 3:57 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1 NULL	
10/2/21 3:57 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1 NULL	
10/2/21 3:57 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1 NULL	
10/2/21 3:57 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1 NULL	
10/2/21 3:57 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1 NULL	
10/2/21 3:57 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1 NULL	
10/2/21 3:57 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1 NULL	
10/2/21 3:57 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 3:57 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 3:57 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 3:57 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 3:57 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 3:57 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 3:57 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 3:57 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 3:57 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 3:57 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 3:57 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 3:57 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 3:57 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 3:57 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 3:57 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 3:57 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 4:07 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 4:07 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 4:07 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 4:07 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 4:07 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 4:07 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 4:07 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 4:07 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 4:07 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 4:07 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 4:07 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 4:07 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 4:07 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 4:07 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 4:07 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 4:09 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/2/21 4:10 PM	ACK_RTN	91_Alm_VO2B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1 NULL	
10/2/21 4:10 PM	ACK	91_Alm_VO2B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1 NULL	
10/2/21 4:17 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 4:17 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 4:17 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 4:17 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1 NULL	
10/2/21 4:17 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1 NULL	
10/2/21 4:17 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1 NULL	
10/2/21 4:17 PM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1 NULL	
10/2/21 4:17 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1 NULL	
10/2/21 4:17 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1 NULL	
10/2/21 4:17 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 4:17 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 4:17 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 4:17 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 4:17 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 4:17 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 4:17 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 4:17 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 4:17 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 4:17 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 4:17 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 4:22 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 4:27 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 4:27 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 4:27 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 4:27 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 4:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/2/21 4:27 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/2/21 4:27 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1 NULL	
10/2/21 4:27 PM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1 NULL	
10/2/21 4:27 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1 NULL	
10/2/21 4:27 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1 NULL	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 4:27 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 4:27 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 4:27 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 4:27 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 4:27 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 4:27 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 4:27 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 4:27 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 4:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 4:27 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 4:27 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 4:27 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 4:27 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 4:27 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 4:37 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 4:37 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 4:37 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 4:37 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 4:37 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 4:37 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 4:37 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 4:37 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 4:37 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 4:37 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 4:37 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 4:37 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 4:37 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 4:37 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 4:37 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 4:37 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 4:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 4:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 4:37 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 4:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 4:37 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 4:44 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/2/21 4:46 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/2/21 4:47 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 4:47 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 4:47 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 4:47 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 4:47 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 4:47 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 4:47 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 4:47 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 4:47 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 4:47 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 4:47 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 4:47 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 4:47 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/2/21 4:47 PM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/2/21 4:47 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 4:47 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 4:47 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 4:47 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 4:47 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 4:47 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 4:47 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 4:47 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 4:47 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 4:47 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 4:47 PM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1 NULL
10/2/21 4:47 PM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1 NULL
10/2/21 4:47 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 4:47 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 4:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 4:47 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 4:47 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/2/21 4:47 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/2/21 4:47 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 4:47 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 4:47 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 4:47 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/2/21 4:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 4:47 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS			1
10/2/21 4:47 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/2/21 4:47 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/2/21 4:47 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/2/21 4:57 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 4:57 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 4:57 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 4:57 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 4:57 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 4:57 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 4:57 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 4:57 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 4:57 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 4:57 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 4:57 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 4:57 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 4:57 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 4:57 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 4:57 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 4:57 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 4:57 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 4:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 4:57 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 4:57 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/2/21 4:57 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/2/21 4:57 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 4:57 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 4:57 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 4:57 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/2/21 4:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 5:07 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 5:07 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 5:07 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 5:07 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 5:07 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 5:07 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 5:07 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 5:07 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 5:07 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 5:07 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 5:07 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 5:07 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 5:07 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 5:07 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 5:07 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 5:07 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 5:07 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 5:07 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 5:07 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 5:07 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 5:07 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 5:07 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 5:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 5:07 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 5:07 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 5:07 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 5:07 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 5:07 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 5:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 5:07 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 5:17 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 5:17 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 5:17 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 5:17 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 5:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 5:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 5:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 5:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 5:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 5:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 5:17 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 5:17 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 5:17 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 5:17 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 5:17 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 5:17 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 5:17 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 5:17 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 5:17 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 5:17 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 5:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 5:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 5:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 5:17 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 5:17 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:17 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 5:17 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:17 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:17 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 5:20 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 5:20 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:20 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:20 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:20 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:20 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 5:20 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 5:20 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 5:20 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 5:20 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 5:20 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 5:20 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 5:20 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 5:20 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 5:20 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 5:20 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 5:20 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 5:20 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 5:20 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 5:20 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 5:20 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/2/21 5:20 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 5:27 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 5:27 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 5:27 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 5:27 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 5:27 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 5:27 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 5:27 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 5:27 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 5:27 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 5:27 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 5:27 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 5:27 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 5:27 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 5:27 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 5:27 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/2/21 5:27 PM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/2/21 5:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 5:27 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 5:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 5:27 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 5:27 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 5:27 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/2/21 5:27 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/2/21 5:27 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 5:37 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 5:37 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 5:37 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 5:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:37 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:37 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:37 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 5:37 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 5:37 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 5:37 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 5:37 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 5:37 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 5:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:37 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:37 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:37 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:37 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:42 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 5:47 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 5:47 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 5:47 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 5:47 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 5:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:47 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:47 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 5:47 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 5:47 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 5:47 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 5:47 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 5:47 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 5:47 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 5:47 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 5:47 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 5:47 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 5:47 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 5:47 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 5:47 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 5:47 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 5:47 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 5:47 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 5:47 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 5:47 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 5:47 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 5:47 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 5:47 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 5:47 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 5:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 5:47 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 5:47 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 5:47 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 5:47 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 5:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:47 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:47 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:47 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 5:47 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 5:47 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 5:47 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 5:57 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 5:57 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 5:57 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 5:57 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 5:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:57 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:57 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 5:57 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 5:57 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 5:57 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 5:57 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 5:57 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 5:57 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 5:57 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 5:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 5:57 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:57 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:57 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 5:59 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 5:59 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:59 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:59 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:59 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 5:59 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:59 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 5:59 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 5:59 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 5:59 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 5:59 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 5:59 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 5:59 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 5:59 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 5:59 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 5:59 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 5:59 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 5:59 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 5:59 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 5:59 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 5:59 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 5:59 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 5:59 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:59 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 5:59 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 5:59 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 5:59 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 5:59 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 6:00 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 6:00 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 6:00 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 6:00 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 6:00 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 6:00 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 6:00 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 6:00 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 6:00 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 6:00 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 6:00 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 6:00 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 6:00 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 6:00 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 6:00 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 6:00 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 6:00 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 6:00 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 6:00 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 6:00 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 6:00 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 6:00 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 6:00 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 6:00 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 6:00 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 6:00 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 6:00 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 6:00 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 6:00 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 6:00 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 6:00 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 6:00 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 6:00 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 6:00 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 6:00 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 6:00 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 6:00 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 6:00 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 6:00 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 6:00 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 6:00 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 6:00 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 6:00 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 6:00 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 6:00 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 6:00 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 6:00 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 6:00 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 6:00 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 6:00 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 6:00 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 6:00 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 6:00 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 6:00 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 6:00 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 6:00 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 6:00 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 6:00 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 6:00 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 6:00 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 6:00 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 6:00 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 6:00 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 6:06 PM	ACK_RTN	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/2/21 6:06 PM	ACK	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/2/21 6:06 PM	UNACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	
10/2/21 6:07 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 6:07 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 6:07 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 6:07 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 6:07 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 6:07 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 6:07 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/2/21 6:07 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/2/21 6:07 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 6:07 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 6:07 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 6:07 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 6:07 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 6:07 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 6:07 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 6:07 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 6:07 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 6:07 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 6:07 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 6:07 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 6:07 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/2/21 6:07 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/2/21 6:07 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/2/21 6:07 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 6:17 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 6:17 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 6:17 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 6:17 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 6:17 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 6:17 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 6:17 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 6:17 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 6:17 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 6:17 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/2/21 6:17 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/2/21 6:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 6:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 6:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 6:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 6:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 6:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 6:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 6:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 6:17 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 6:17 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 6:17 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 6:17 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 6:17 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 6:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 6:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 6:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 6:17 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 6:17 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 6:17 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 6:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 6:17 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 6:17 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 6:17 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 6:17 PM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 6:17 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 6:17 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 6:17 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 6:17 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 6:27 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 6:27 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 6:27 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 6:27 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 6:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 6:27 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 6:27 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 6:27 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 6:27 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 6:27 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 6:27 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 6:27 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 6:27 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 6:27 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 6:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 6:27 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 6:27 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 6:27 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 6:37 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 6:37 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 6:37 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 6:37 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 6:37 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 6:37 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 6:37 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 6:37 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 6:37 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 6:37 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 6:37 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 6:37 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 6:37 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 6:37 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 6:37 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 6:37 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 6:37 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 6:37 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 6:37 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 6:37 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 6:37 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 6:37 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 6:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 6:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 6:37 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 6:37 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 6:37 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 6:37 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 6:37 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 6:37 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 6:37 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 6:37 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 6:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 6:37 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 6:37 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 6:37 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 6:47 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 6:47 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 6:47 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 6:47 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 6:47 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 6:47 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 6:47 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 6:47 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 6:47 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 6:47 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 6:47 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 6:47 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 6:47 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 6:47 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 6:47 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 6:47 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 6:47 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 6:47 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 6:47 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 6:47 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/2/21 6:47 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1 NULL	
10/2/21 6:47 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1 NULL	
10/2/21 6:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/2/21 6:47 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/2/21 6:47 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40 NULL	
10/2/21 6:47 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40 NULL	
10/2/21 6:47 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 6:47 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 6:47 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 6:47 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 6:47 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 6:47 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1 NULL	
10/2/21 6:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 6:47 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 6:47 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 6:47 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 6:57 PM	UNACK_ALM	20_ALM_Elly_Omni_Flow_Error	Alarm -- Elly Omni / PLC Flow Variance High		1	
10/2/21 6:57 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 6:57 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 6:57 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 6:57 PM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/2/21 6:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/2/21 6:57 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/2/21 6:57 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40 NULL	
10/2/21 6:57 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40 NULL	
10/2/21 6:57 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1 NULL	
10/2/21 6:57 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1 NULL	
10/2/21 6:57 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1 NULL	
10/2/21 6:57 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1 NULL	
10/2/21 6:57 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1 NULL	
10/2/21 6:57 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1 NULL	
10/2/21 6:57 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1 NULL	
10/2/21 6:57 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1 NULL	
10/2/21 6:57 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 6:57 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 6:57 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 6:57 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 6:57 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 6:57 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly			1 NULL
10/2/21 6:57 PM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly			1 NULL
10/2/21 6:57 PM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly			1 NULL
10/2/21 6:57 PM	ACK_RTN	20_ALM_Elly_Omni_Flow_Error	Alarm -- Elly Omni / PLC Flow Variance High			1 NULL
10/2/21 6:57 PM	ACK	20_ALM_Elly_Omni_Flow_Error	Alarm -- Elly Omni / PLC Flow Variance High			1 NULL
10/2/21 6:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 6:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 6:57 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 6:57 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 6:57 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 6:57 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/2/21 6:57 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/2/21 6:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 6:57 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/2/21 6:57 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/2/21 6:57 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 6:57 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 6:57 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 6:57 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1
10/2/21 6:57 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1
10/2/21 7:07 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 7:07 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 7:07 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 7:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 7:07 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 7:07 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 7:07 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 7:07 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 7:07 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 7:07 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 7:07 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 7:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 7:07 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 7:07 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm			1 NULL
10/2/21 7:07 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/2/21 7:07 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/2/21 7:07 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 7:07 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 7:07 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 7:07 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 7:07 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 7:07 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 7:07 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 7:07 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:07 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:07 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 7:07 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 7:07 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 7:07 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 7:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:07 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 7:07 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 7:10 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 7:10 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:10 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:10 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 7:10 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 7:10 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:10 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:10 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:10 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:10 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:10 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:10 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:10 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:10 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:10 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:10 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:10 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:10 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:10 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 7:10 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 7:10 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 7:10 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 7:10 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 7:10 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 7:10 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 7:10 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 7:10 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 7:10 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:10 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:10 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:10 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:10 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:10 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 7:10 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:10 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:10 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:10 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:10 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:10 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:10 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:10 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 7:10 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 7:10 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 7:10 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 7:10 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 7:10 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 7:10 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 7:10 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:10 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 7:12 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:12 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:17 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 7:17 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 7:17 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 7:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:17 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 7:17 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 7:17 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 7:17 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 7:17 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 7:17 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 7:17 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 7:17 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 7:17 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 7:17 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 7:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:17 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:17 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 7:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 7:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 7:17 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 7:17 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 7:17 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 7:20 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/2/21 7:20 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/2/21 7:20 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/2/21 7:20 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:20 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:20 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:20 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:20 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:20 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:20 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:20 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:20 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:20 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:20 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 7:20 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 7:20 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 7:20 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 7:20 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:20 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/2/21 7:20 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 7:20 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 7:20 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 7:20 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 7:20 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 7:20 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 7:27 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 7:27 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 7:27 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/2/21 7:27 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/2/21 7:27 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:27 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:27 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:27 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:27 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:27 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:27 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:27 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:27 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 7:27 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 7:27 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 7:27 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 7:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:27 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:27 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 7:27 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 7:27 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/2/21 7:27 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 7:27 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 7:27 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 7:27 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 7:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:27 PM	UNACK_ALM	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	
10/2/21 7:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:37 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/2/21 7:37 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/2/21 7:37 PM	ACK_RTN	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 7:37 PM	ACK	30_S03_Tank_Low_Level_Alm	S03 Tank Low Level Alarm		1	NULL
10/2/21 7:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:37 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 7:37 PM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 7:37 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 7:37 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 7:37 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:37 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:37 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:37 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:37 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:37 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:37 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:37 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:37 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 7:37 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 7:37 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 7:37 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 7:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:37 PM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 7:37 PM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 7:37 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 7:37 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	1	[REDACTED]
10/2/21 7:37 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	1	[REDACTED]
10/2/21 7:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:37 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	1	NULL
10/2/21 7:37 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	1	NULL
10/2/21 7:37 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	1	NULL
10/2/21 7:37 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	1	NULL
10/2/21 7:37 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	1	NULL
10/2/21 7:37 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	1	NULL
10/2/21 7:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/2/21 7:37 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:37 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:37 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:37 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:37 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:37 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:37 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:37 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:37 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 7:37 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 7:37 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]	1	[REDACTED]
10/2/21 7:37 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed	[REDACTED]	1	[REDACTED]
10/2/21 7:37 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]	1	[REDACTED]
10/2/21 7:37 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]	1	[REDACTED]
10/2/21 7:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/2/21 7:37 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm	[REDACTED]	1	[REDACTED]
10/2/21 7:44 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed	[REDACTED]	1	[REDACTED]
10/2/21 7:44 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:44 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:44 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/2/21 7:44 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:44 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:44 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:44 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:44 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:44 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:44 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:44 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:44 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:44 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 7:44 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 7:44 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 7:44 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:44 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:44 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 7:44 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 7:45 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:45 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 7:45 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 7:45 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 7:45 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 7:45 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 7:45 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 7:45 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 7:47 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 7:47 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 7:47 PM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/2/21 7:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:47 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:47 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:47 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:47 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:47 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:47 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:47 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:47 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:47 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:47 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:47 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:47 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 7:47 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 7:47 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 7:47 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 7:47 PM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 7:47 PM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/2/21 7:47 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 7:47 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 7:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:47 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 7:47 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 7:47 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 7:47 PM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 7:47 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 7:47 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 7:47 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 7:47 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 7:47 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 7:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:47 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:47 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:47 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:47 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:47 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 7:47 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:47 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 7:47 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:47 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:47 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:47 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:47 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 7:47 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 7:47 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 7:47 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 7:47 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 7:47 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 7:47 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 7:47 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 7:47 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 7:47 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 7:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:47 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 7:48 PM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/2/21 7:48 PM	ACK_RTN	U36_ALM_001	ALM_001 : Fuel Transfer Lockout Disabled		2	
10/2/21 7:48 PM	ACK_RTN	U36_ALM_027	ALM_027 : PT341: Fuel Gas Header Pressure High		2	NULL
10/2/21 7:48 PM	ACK	U36_ALM_027	ALM_027 : PT341: Fuel Gas Header Pressure High		2	NULL
10/2/21 7:48 PM	ACK_RTN	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/2/21 7:48 PM	ACK_RTN	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	NULL
10/2/21 7:48 PM	ACK	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	NULL
10/2/21 7:48 PM	ACK_RTN	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	NULL
10/2/21 7:48 PM	ACK	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	NULL
10/2/21 7:48 PM	ACK_RTN	U36_ALM_040	ALM_040 : S387: Liquid Fuel Pressure LowLow		2	
10/2/21 7:54 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 7:54 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:54 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 7:54 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 7:54 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 7:54 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 7:54 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 7:54 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 7:54 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 7:54 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 7:54 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/2/21 7:54 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 7:54 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 7:54 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 NULL
10/2/21 7:54 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 NULL
10/2/21 7:54 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 7:54 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 7:54 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 7:54 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 7:54 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 7:54 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/2/21 7:54 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/2/21 7:54 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 7:54 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 7:54 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 7:54 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 7:54 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 7:54 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/2/21 7:54 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1
10/2/21 7:54 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1
10/2/21 7:54 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 7:54 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/2/21 7:54 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/2/21 7:54 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/2/21 7:57 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 7:57 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 7:57 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 7:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 7:57 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 7:57 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 7:57 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 7:57 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 7:57 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 7:57 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 7:57 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 7:57 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 7:57 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 7:57 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 7:57 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 7:57 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:57 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 7:57 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 7:57 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 7:57 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 7:57 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 7:57 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 7:57 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 7:57 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 7:57 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 7:57 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 7:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 7:59 PM	UNACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/2/21 8:00 PM	ACK_RTN	U36_ALM_036	ALM_036 : Bently Nevada High Vibration Summary Alarm		2	NULL
10/2/21 8:00 PM	ACK	U36_ALM_036	ALM_036 : Bently Nevada High Vibration Summary Alarm		2	NULL
10/2/21 8:01 PM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/2/21 8:01 PM	UNACK_ALM	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	
10/2/21 8:04 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 8:04 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 8:04 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:04 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:04 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:04 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:04 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:04 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:04 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 8:04 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 8:04 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:04 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:04 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:04 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:04 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:04 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:04 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:04 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 8:04 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:04 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 8:04 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 8:04 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:04 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 8:07 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	1	
10/2/21 8:07 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:07 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:07 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:07 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:07 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:07 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:07 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:07 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:07 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:07 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:07 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:07 PM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 8:07 PM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 8:07 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 8:07 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 8:07 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:07 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:07 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:07 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:07 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:07 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:07 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 8:07 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:07 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 8:07 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 8:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:07 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:07 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:07 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:07 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:07 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:07 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:07 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:07 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:07 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:07 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:07 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:07 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:07 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:07 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:07 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 8:07 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:07 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 8:07 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 8:07 PM	ACK_RTN	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/2/21 8:07 PM	ACK	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/2/21 8:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:07 PM	UNACK_ALM	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	
10/2/21 8:07 PM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/2/21 8:07 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 8:07 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:12 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:12 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:12 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:12 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 8:12 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 8:12 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 8:12 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:12 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:12 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:12 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:12 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:12 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:12 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:12 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:12 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:12 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:12 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:12 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:12 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:12 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 8:12 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:12 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 8:12 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 8:12 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:12 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:12 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:12 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:17 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 8:17 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 8:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:17 PM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 8:17 PM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/2/21 8:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 8:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 8:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 8:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 8:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 8:17 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 8:17 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 8:17 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 NULL
10/2/21 8:17 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 NULL
10/2/21 8:17 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:17 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:17 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:17 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:17 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:17 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 8:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:17 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 8:17 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 8:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:17 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:27 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 8:27 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 8:27 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 8:27 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 8:27 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 8:27 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 8:27 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 8:27 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 8:27 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 8:27 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 8:27 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 NULL
10/2/21 8:27 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 NULL
10/2/21 8:27 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:27 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:27 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:27 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 8:27 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:27 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 8:27 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 8:27 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 8:27 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1
10/2/21 8:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 8:37 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 8:37 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 8:37 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 8:37 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 8:37 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 8:37 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 8:37 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 8:37 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 8:37 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 8:37 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 8:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 8:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 8:37 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 8:37 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 8:37 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 8:37 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 8:37 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 8:37 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1
10/2/21 8:37 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:37 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:37 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:37 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 8:37 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 8:37 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 8:37 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 8:37 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 8:37 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 8:37 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 8:37 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 8:37 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 8:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 8:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 8:37 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 8:37 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 8:37 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 8:37 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1
10/2/21 8:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:37 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:37 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:37 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:37 PM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/2/21 8:37 PM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/2/21 8:37 PM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_02	West Well Bay Shutdown Alarm -- VSD-02		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_WestBay_Shutdown_VSD_02	West Well Bay Shutdown Alarm -- VSD-02		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_04	West Well Bay Shutdown Alarm -- VSD-04		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_WestBay_Shutdown_VSD_04	West Well Bay Shutdown Alarm -- VSD-04		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_06	West Well Bay Shutdown Alarm -- VSD-06		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_WestBay_Shutdown_VSD_06	West Well Bay Shutdown Alarm -- VSD-06		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_08	West Well Bay Shutdown Alarm -- VSD-08		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_WestBay_Shutdown_VSD_08	West Well Bay Shutdown Alarm -- VSD-08		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_10	West Well Bay Shutdown Alarm -- VSD-10		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_WestBay_Shutdown_VSD_10	West Well Bay Shutdown Alarm -- VSD-10		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_12	West Well Bay Shutdown Alarm -- VSD-12		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_WestBay_Shutdown_VSD_12	West Well Bay Shutdown Alarm -- VSD-12		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_14	West Well Bay Shutdown Alarm -- VSD-14		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_WestBay_Shutdown_VSD_14	West Well Bay Shutdown Alarm -- VSD-14		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_WestBay_Shutdown_VSD_16	West Well Bay Shutdown Alarm -- VSD-16		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_WestBay_Shutdown_VSD_16	West Well Bay Shutdown Alarm -- VSD-16		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_01	East Well Bay Shutdown Alarm -- VSD-01		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_EastBay_Shutdown_VSD_01	East Well Bay Shutdown Alarm -- VSD-01		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_03	East Well Bay Shutdown Alarm -- VSD-03		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_EastBay_Shutdown_VSD_03	East Well Bay Shutdown Alarm -- VSD-03		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_07	East Well Bay Shutdown Alarm -- VSD-07		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_EastBay_Shutdown_VSD_07	East Well Bay Shutdown Alarm -- VSD-07		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_09	East Well Bay Shutdown Alarm -- VSD-09		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_EastBay_Shutdown_VSD_09	East Well Bay Shutdown Alarm -- VSD-09		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_11	East Well Bay Shutdown Alarm -- VSD-11		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_EastBay_Shutdown_VSD_11	East Well Bay Shutdown Alarm -- VSD-11		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_EastBay_Shutdown_Input_14	East Well Bay Shutdown Alarm -- A-13		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_EastBay_Shutdown_Input_14	East Well Bay Shutdown Alarm -- A-13		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_EastBay_Shutdown_Input_15	East Well Bay Shutdown Alarm -- A-27		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_EastBay_Shutdown_Input_15	East Well Bay Shutdown Alarm -- A-27		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:37 PM	ACK_RTN	40_Alm_EastBay_Shutdown_Input_13	East Well Bay Shutdown Alarm -- A-57		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_EastBay_Shutdown_Input_13	East Well Bay Shutdown Alarm -- A-57		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_EastBay_Shutdown_Input_09	East Well Bay Shutdown Alarm -- A-21		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_EastBay_Shutdown_Input_09	East Well Bay Shutdown Alarm -- A-21		1	NULL
10/2/21 8:37 PM	ACK_RTN	40_Alm_EastBay_Shutdown_Input_11	East Well Bay Shutdown Alarm -- A-55		1	NULL
10/2/21 8:37 PM	ACK	40_Alm_EastBay_Shutdown_Input_11	East Well Bay Shutdown Alarm -- A-55		1	NULL
10/2/21 8:38 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:38 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:38 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:38 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:38 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:38 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:47 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 8:47 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 8:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:47 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:47 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:47 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:47 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:47 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:47 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:47 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:47 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:47 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:47 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:47 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:47 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:47 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:47 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:47 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:47 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:47 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:47 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 8:47 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 8:47 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:47 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 8:47 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 8:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:47 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 8:47 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:55 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:55 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 8:55 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 8:55 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 8:55 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/2/21 8:55 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 NULL
10/2/21 8:55 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 NULL
10/2/21 8:55 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 8:55 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 8:55 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 8:55 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 8:55 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 8:55 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 8:55 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 8:55 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 8:55 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 8:55 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 8:55 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 8:55 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/2/21 8:55 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 8:55 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 8:55 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/2/21 8:55 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1
10/2/21 8:55 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/2/21 8:57 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 8:57 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 8:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 8:57 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 8:57 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 8:57 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 8:57 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 8:57 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 8:57 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 8:57 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 8:57 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 8:57 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 8:57 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:57 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:57 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:57 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/2/21 8:57 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/2/21 8:57 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/2/21 8:57 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:57 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 8:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:57 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:57 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:57 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:57 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:57 PM	ACK_RTN	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low		500	NULL
10/2/21 8:57 PM	ACK	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low		500	NULL
10/2/21 8:57 PM	ACK_RTN	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	NULL
10/2/21 8:57 PM	ACK	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	NULL
10/2/21 8:57 PM	ACK_RTN	60_Alm_Well_Test_LA_PSI_Low_Warn	Well Test LA 1802 Pressure Low Warning		1	NULL
10/2/21 8:57 PM	ACK	60_Alm_Well_Test_LA_PSI_Low_Warn	Well Test LA 1802 Pressure Low Warning		1	NULL
10/2/21 8:57 PM	UNACK_ALM	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low		500	
10/2/21 8:57 PM	UNACK_ALM	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 8:59 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:59 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:59 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 8:59 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:59 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:59 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 8:59 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 8:59 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:59 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:59 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 8:59 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/2/21 8:59 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:59 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 8:59 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 8:59 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:59 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/2/21 8:59 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 8:59 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:59 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 8:59 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:59 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 8:59 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 8:59 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 8:59 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 8:59 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 9:07 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 9:07 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 9:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:07 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:07 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:07 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:07 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:07 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 9:07 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 9:07 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 9:07 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 9:07 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 9:07 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 NULL
10/2/21 9:07 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 NULL
10/2/21 9:07 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour 1 NULL
10/2/21 9:07 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour 1 NULL
10/2/21 9:07 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			Eu_Elly Leak Detect 10 Minute 1 NULL
10/2/21 9:07 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			Eu_Elly Leak Detect 10 Minute 1 NULL
10/2/21 9:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 [REDACTED]
10/2/21 9:07 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 [REDACTED]
10/2/21 9:07 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 [REDACTED]
10/2/21 9:07 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 [REDACTED]
10/2/21 9:07 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 [REDACTED]
10/2/21 9:07 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 [REDACTED]
10/2/21 9:17 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour 1 [REDACTED]
10/2/21 9:17 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			Eu_Elly Leak Detect 10 Minute 1 [REDACTED]
10/2/21 9:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 9:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/2/21 9:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 9:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/2/21 9:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 9:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/2/21 9:17 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 9:17 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/2/21 9:17 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 NULL
10/2/21 9:17 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning			1 NULL
10/2/21 9:17 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour 1 NULL
10/2/21 9:17 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni			Eu_Elly Leak Detect 1 Hour 1 NULL
10/2/21 9:17 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			Eu_Elly Leak Detect 10 Minute 1 NULL
10/2/21 9:17 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni			Eu_Elly Leak Detect 10 Minute 1 NULL
10/2/21 9:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 9:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/2/21 9:17 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/2/21 9:17 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/2/21 9:17 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 9:17 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/2/21 9:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 [REDACTED]
10/2/21 9:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 [REDACTED]
10/2/21 9:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 [REDACTED]
10/2/21 9:17 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 [REDACTED]

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:17 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 9:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:17 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 9:18 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:18 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:18 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:18 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:18 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:18 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:18 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:18 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:18 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:18 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:18 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:18 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:18 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:18 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:18 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:18 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:18 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 9:18 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:23 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 9:23 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:27 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 9:27 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:27 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:27 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:27 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:27 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:27 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:27 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:27 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:27 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:27 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:27 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:27 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:27 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 9:27 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 9:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:27 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 9:27 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 9:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:27 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:27 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:27 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:27 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:27 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:27 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:27 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:27 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 9:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:27 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 9:27 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:27 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:27 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:27 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:27 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:27 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:27 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:27 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:27 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:27 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:27 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 9:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:27 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:27 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:27 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:27 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:27 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:27 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:27 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 9:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:28 PM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_03	East Well Bay Shutdown Alarm -- VSD-03		1	
10/2/21 9:28 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:28 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:28 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:28 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:28 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:28 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:28 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:28 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:28 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:28 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:28 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:28 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:28 PM	UNACK_ALM	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	
10/2/21 9:28 PM	UNACK_ALM	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHI		2	
10/2/21 9:30 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:30 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:30 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:30 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:30 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:30 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:30 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:30 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:30 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:30 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:30 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:30 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:30 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:30 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:30 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 9:30 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 9:30 PM	ACK_RTN	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/2/21 9:30 PM	ACK	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/2/21 9:30 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:30 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:30 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:30 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:30 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 9:30 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:30 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:30 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:30 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:30 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:30 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:30 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:30 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:30 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:30 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:30 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:30 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:30 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:30 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:30 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:30 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:30 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:30 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:30 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 9:30 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 9:30 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 9:30 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:30 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:30 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:30 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:30 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:30 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:32 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 9:34 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/2/21 9:35 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/2/21 9:35 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/2/21 9:35 PM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/2/21 9:35 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:35 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:35 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/2/21 9:35 PM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/2/21 9:35 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:35 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:35 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:35 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:35 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:35 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:35 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:35 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:35 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:35 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:35 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 9:35 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 9:35 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:35 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:35 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 9:35 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:35 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:35 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/2/21 9:35 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:35 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:35 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:35 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:35 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 9:35 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:35 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 9:35 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:35 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:37 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/2/21 9:37 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1
10/2/21 9:38 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:38 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:38 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 9:38 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 9:38 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:38 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:38 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:38 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:38 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/2/21 9:38 PM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/2/21 9:38 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:38 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:38 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:38 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:38 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:38 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:38 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:38 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:38 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:38 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:38 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:38 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:38 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:38 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:38 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 9:38 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:38 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:38 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/2/21 9:38 PM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/2/21 9:38 PM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/2/21 9:38 PM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/2/21 9:38 PM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/2/21 9:38 PM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/2/21 9:38 PM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/2/21 9:38 PM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_03	East Well Bay Shutdown Alarm -- VSD-03		1	NULL
10/2/21 9:38 PM	ACK	40_Alm_EastBay_Shutdown_VSD_03	East Well Bay Shutdown Alarm -- VSD-03		1	NULL
10/2/21 9:38 PM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/2/21 9:38 PM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/2/21 9:38 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:38 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:38 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:38 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:38 PM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/2/21 9:38 PM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/2/21 9:38 PM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/2/21 9:38 PM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/2/21 9:38 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:38 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:38 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:38 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:38 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:38 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:38 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:38 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:38 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:38 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:38 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/2/21 9:38 PM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/2/21 9:38 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:38 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:38 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:38 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:38 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:38 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:38 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:38 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:38 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:38 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:38 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/2/21 9:38 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 9:38 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:38 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:40 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 9:46 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 9:46 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:46 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:46 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:46 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:46 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:46 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:46 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:46 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:46 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/2/21 9:46 PM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/2/21 9:46 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:46 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:46 PM	ACK_RTN	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	NULL
10/2/21 9:46 PM	ACK	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	NULL
10/2/21 9:46 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:46 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 9:46 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 9:46 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 9:46 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:46 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 9:46 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 9:46 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:46 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:46 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:46 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 9:46 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:46 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 9:46 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:46 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 9:46 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:46 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 9:46 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:46 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 9:46 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:46 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 9:46 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 9:46 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 9:46 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 9:46 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 9:46 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 9:46 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 9:46 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 9:51 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 10:01 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:01 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:01 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:01 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:01 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 10:01 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:01 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:01 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:01 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:01 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:01 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:01 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 10:01 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 10:01 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:01 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:01 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 10:01 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 10:01 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:01 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:01 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 10:01 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 10:01 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:01 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:01 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/2/21 10:01 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:01 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:01 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:01 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:01 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:01 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 10:01 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 10:02 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:02 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/2/21 10:03 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:03 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:03 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:03 PM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	
10/2/21 10:03 PM	UNACK_ALM	60_Alm_ShipPump_B_Disch_PSI_Low	Eureka Shipping Pump 1302B Low Discharge Pressure		500	
10/2/21 10:03 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/2/21 10:04 PM	ACK_RTN	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/2/21 10:04 PM	ACK	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/2/21 10:04 PM	ACK_RTN	60_Alm_ShipPump_B_Disch_PSI_Low	Eureka Shipping Pump 1302B Low Discharge Pressure		500	NULL
10/2/21 10:04 PM	ACK	60_Alm_ShipPump_B_Disch_PSI_Low	Eureka Shipping Pump 1302B Low Discharge Pressure		500	NULL
10/2/21 10:04 PM	ACK_RTN	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low		500	NULL
10/2/21 10:04 PM	ACK	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low		500	NULL
10/2/21 10:04 PM	UNACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	
10/2/21 10:04 PM	UNACK_ALM	60_Alm_ShipPump_B_Disch_PSI_Low	Eureka Shipping Pump 1302B Low Discharge Pressure		500	
10/2/21 10:04 PM	ACK_RTN	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/2/21 10:04 PM	ACK	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/2/21 10:04 PM	ACK_RTN	60_Alm_ShipPump_B_Disch_PSI_Low	Eureka Shipping Pump 1302B Low Discharge Pressure		500	NULL
10/2/21 10:04 PM	ACK	60_Alm_ShipPump_B_Disch_PSI_Low	Eureka Shipping Pump 1302B Low Discharge Pressure		500	NULL
10/2/21 10:04 PM	UNACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	
10/2/21 10:04 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:04 PM	ACK_RTN	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/2/21 10:04 PM	ACK	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/2/21 10:04 PM	UNACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	
10/2/21 10:05 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:05 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:05 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:05 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:05 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:05 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:05 PM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/2/21 10:05 PM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/2/21 10:05 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 10:05 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/2/21 10:05 PM	ACK_RTN	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	NULL
10/2/21 10:05 PM	ACK	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	NULL
10/2/21 10:05 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:05 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:05 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:05 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:05 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 10:05 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 10:05 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:05 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:05 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:05 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:05 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:05 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:05 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 10:05 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 10:05 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 10:05 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:05 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:05 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:05 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:05 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 10:05 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 10:05 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:05 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:05 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:05 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	
10/2/21 10:05 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:05 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:05 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:06 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:06 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:06 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:06 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:06 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 10:06 PM	ACK	91_Alm_TrainB_X04B_Temp_Low_Warn	Warning--Train B Emul Heater X04B Low Temp Warning		1	NULL
10/2/21 10:06 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:06 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:06 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:06 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:06 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:06 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:06 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:06 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:06 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:06 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:06 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:06 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:06 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:06 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:06 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:06 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:06 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:06 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:06 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:06 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:06 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 10:06 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 10:06 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:06 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:06 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:06 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:06 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:06 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:06 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:06 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:06 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:06 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 10:06 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 10:06 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:06 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:06 PM	UNACK_ALM	20_ALM_Elly_Drive_Gain_High	LDS -- Elly Micro Motion Drive Gain High		1	
10/2/21 10:06 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 10:06 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:06 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:06 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:06 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:06 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:06 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:06 PM	ACK_RTN	20_ALM_Elly_Drive_Gain_High	LDS -- Elly Micro Motion Drive Gain High		1	NULL
10/2/21 10:06 PM	ACK	20_ALM_Elly_Drive_Gain_High	LDS -- Elly Micro Motion Drive Gain High		1	NULL
10/2/21 10:06 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:06 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:06 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:06 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:06 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 10:06 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 10:06 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:06 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:06 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:06 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:06 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:06 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:06 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:06 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 10:07 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:07 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:07 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:09 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:09 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:09 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:11 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 10:12 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 10:12 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 10:12 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:12 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:12 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:12 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:12 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:12 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:12 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:12 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:12 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:12 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:12 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 10:12 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:12 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:12 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:13 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:13 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:13 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:13 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:13 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:13 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:13 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:13 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:13 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:13 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:13 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:13 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:13 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:13 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:13 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:13 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:15 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:15 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:15 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:16 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:17 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:17 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:17 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:17 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:17 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 10:17 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 10:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:17 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 10:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:17 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:17 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:17 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:17 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:17 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 10:17 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:17 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:18 PM	ACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 10:18 PM	ACK_ALM	U35_ALM_027	ALM_027 : PT341: Fuel Gas Header Pressure High		2	
10/2/21 10:18 PM	ACK_ALM	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	
10/2/21 10:18 PM	ACK_ALM	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	
10/2/21 10:18 PM	ACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:18 PM	ACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/2/21 10:18 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 10:18 PM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:18 PM	ACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:18 PM	ACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:18 PM	ACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:18 PM	ACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:18 PM	ACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:18 PM	ACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	
10/2/21 10:18 PM	ACK_ALM	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	
10/2/21 10:18 PM	ACK_ALM	85_TestTreatB_Test_Complete	V03B Well Test Complete		1	
10/2/21 10:18 PM	ACK_ALM	85_TestTreatA_Test_Complete	V03A Well Test Complete		1	
10/2/21 10:18 PM	ACK_ALM	50_ALM_Cen_NJ01A_Modbus_Fail	NJ01A Modbus Fail		1	
10/2/21 10:18 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:18 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:18 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:18 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:18 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 10:18 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:18 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:18 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:18 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:18 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:18 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:18 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:18 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 10:19 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:19 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:19 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:20 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:21 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:21 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:21 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:21 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:21 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:21 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:21 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:21 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:21 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:21 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:21 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:21 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:21 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:21 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:21 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 10:21 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:21 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:21 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:21 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:21 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:21 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:21 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 10:21 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 10:21 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 10:22 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:22 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:22 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 10:26 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:26 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:26 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:26 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:26 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:26 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:26 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:26 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:26 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:26 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:26 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 10:26 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 10:26 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:26 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:26 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:26 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:26 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:26 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:26 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:26 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:26 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:26 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:26 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:26 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:26 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:26 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:26 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:26 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:26 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:26 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	[REDACTED]	1	[REDACTED]
10/2/21 10:26 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:26 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:28 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	[REDACTED]	1	[REDACTED]
10/2/21 10:28 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:28 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:29 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected	[REDACTED]	1	[REDACTED]
10/2/21 10:29 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:29 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 10:31 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/2/21 10:46 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:46 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:52 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 10:52 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 10:52 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:52 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:52 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:52 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:52 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/2/21 10:52 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/2/21 10:53 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed	[REDACTED]	1	[REDACTED]
10/2/21 10:54 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:54 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:54 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:54 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:54 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:54 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:54 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:54 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:54 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:54 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:54 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:54 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:54 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:54 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:54 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]	1	[REDACTED]
10/2/21 10:54 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure	[REDACTED]	1	[REDACTED]
10/2/21 10:54 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed	[REDACTED]	1	[REDACTED]
10/2/21 10:54 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature	[REDACTED]	1	[REDACTED]
10/2/21 10:54 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:54 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:54 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:54 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 10:54 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:54 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:54 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:54 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:54 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 10:54 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 10:54 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:54 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:54 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 10:54 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:54 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:54 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:54 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:54 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 10:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 10:58 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:59 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:59 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 10:59 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:59 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 10:59 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:59 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 10:59 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:59 PM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 10:59 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:59 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 10:59 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:59 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 10:59 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 10:59 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 10:59 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:59 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 10:59 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:59 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 10:59 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 10:59 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 10:59 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 10:59 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 10:59 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 10:59 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 10:59 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 10:59 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 11:04 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 11:10 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:11 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:11 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:11 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:11 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:11 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 11:11 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 11:11 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:11 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:11 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:11 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:11 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:11 PM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:11 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 11:11 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 11:11 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:11 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:11 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:11 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 11:11 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:11 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 11:11 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:11 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 11:11 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/2/21 11:11 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 11:11 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 11:11 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:11 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:11 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:11 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:11 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:11 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:11 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 11:11 PM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/2/21 11:11 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:11 PM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:11 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:11 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:11 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:11 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:11 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:11 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 11:11 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 11:11 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:11 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:11 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:11 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:11 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:11 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/2/21 11:11 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 11:11 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 11:11 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 11:11 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 11:13 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 11:13 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 11:13 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 11:15 PM	UNACK_ALM	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	
10/2/21 11:15 PM	ACK_RTN	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 11:15 PM	ACK	30_Flare_Status_Vent_Pole_Alm	Elly Vent Pole Flow Detected		1	NULL
10/2/21 11:16 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 11:16 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:16 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:24 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:24 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:24 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:24 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:24 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 11:24 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:24 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:24 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/2/21 11:24 PM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/2/21 11:24 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:24 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:24 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:24 PM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:24 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:24 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:24 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 11:24 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 11:24 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:24 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:24 PM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/2/21 11:24 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 11:24 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 11:24 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:24 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:24 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 11:24 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/2/21 11:24 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:24 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:24 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:25 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:25 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:25 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:25 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:25 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:25 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:25 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:25 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:25 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:25 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 11:25 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/2/21 11:25 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 11:25 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:25 PM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/2/21 11:25 PM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/2/21 11:25 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:25 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:25 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:25 PM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:25 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:25 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:25 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:25 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:25 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:25 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:25 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:25 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:25 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:25 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 11:25 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 11:25 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 11:25 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 11:25 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:25 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:25 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:25 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:25 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:25 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:25 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:25 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:25 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:25 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:25 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:25 PM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:25 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 11:25 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 11:25 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:25 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:25 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:25 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:25 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:25 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:25 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:25 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 11:25 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 11:25 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:25 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:25 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 11:25 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 11:28 PM	UNACK_ALM	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	
10/2/21 11:28 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 11:28 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 11:28 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:28 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:28 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:28 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:28 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:28 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:28 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:28 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:28 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:28 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:28 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:28 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:28 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:28 PM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:28 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 11:28 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/2/21 11:28 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:28 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:28 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:28 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:28 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:28 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:28 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:28 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:28 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:28 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 11:28 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	
10/2/21 11:28 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:28 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:28 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 11:28 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 11:29 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 11:34 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 11:34 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 11:34 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:34 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:34 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:34 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:34 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 11:34 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 11:34 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:34 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:34 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:34 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:34 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:34 PM	ACK	91_Alm_TrainB_Treat_Press_Lo_Wrn	Warning--Train B Treater Low Pressure		1	NULL
10/2/21 11:34 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:34 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:34 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:34 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:34 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 11:34 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:34 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 11:34 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:34 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/2/21 11:34 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:34 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/2/21 11:34 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 11:34 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/2/21 11:34 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:34 PM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/2/21 11:34 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:34 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/2/21 11:34 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 11:34 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 11:34 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:34 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:34 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:34 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:34 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 11:34 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:34 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 11:34 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:34 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:34 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:34 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 11:37 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/2/21 11:37 PM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	
10/2/21 11:37 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/2/21 11:39 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 11:45 PM	UNACK_ALM	50_ALM_Cen_NJ01C_Cam_Accum_10	NJ01C Cameron and Daily AccumTotals Not Within 10%		1	
10/2/21 11:45 PM	UNACK_ALM	50_ALM_Cen_NJ01A_Cam_Accum_10	NJ01A Cameron and Daily AccumTotals Not Within 10%		1	
10/2/21 11:50 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:50 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 11:50 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 11:50 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:50 PM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:50 PM	ACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 11:50 PM	ACK_ALM	50_ALM_Cen_NJ01A_Cam_Accum_10	NJ01A Cameron and Daily AccumTotals Not Within 10%		1	
10/2/21 11:50 PM	ACK_ALM	50_ALM_Cen_NJ01C_Cam_Accum_10	NJ01C Cameron and Daily AccumTotals Not Within 10%		1	
10/2/21 11:50 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 11:50 PM	ACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/2/21 11:50 PM	ACK_ALM	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	
10/2/21 11:50 PM	ACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/2/21 11:50 PM	ACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 11:50 PM	ACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:50 PM	ACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:50 PM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 11:50 PM	ACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:50 PM	ACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 11:50 PM	ACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:50 PM	ACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:50 PM	ACK_ALM	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	
10/2/21 11:50 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:50 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 11:50 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:50 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/2/21 11:50 PM	ACK_RTN	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	
10/2/21 11:50 PM	ACK_RTN	50_ALM_Cen_NJ01C_Cam_Accum_10	NJ01C Cameron and Daily AccumTotals Not Within 10%		1	
10/2/21 11:50 PM	ACK_RTN	50_ALM_Cen_NJ01A_Cam_Accum_10	NJ01A Cameron and Daily AccumTotals Not Within 10%		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 11:50 PM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/2/21 11:50 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:50 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 11:50 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 11:50 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:50 PM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:50 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:50 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:50 PM	ACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:50 PM	ACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:50 PM	ACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/2/21 11:50 PM	ACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/2/21 11:50 PM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/2/21 11:50 PM	ACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/2/21 11:50 PM	ACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/2/21 11:50 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:50 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:50 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 11:50 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 11:50 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:50 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:50 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 11:50 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/2/21 11:55 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/2/21 11:59 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:59 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/2/21 11:59 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 11:59 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/2/21 11:59 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:59 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/2/21 11:59 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 11:59 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/2/21 11:59 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/2/21 11:59 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/2/21 11:59 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/2/21 11:59 PM	UNACK_ALM	50_ALM_Cen_NJ01A_Cam_HSC_10	NJ01A Cameron and HSC Totals Not Within 10%		1	
10/3/21 12:04 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 12:05 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:05 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:05 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:05 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:05 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:05 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 12:05 AM	ACK_RTN	50_ALM_CEMS_Cur_Proc_Rpt_NL	Process Report For Current Month Was Not Loaded		1	
10/3/21 12:05 AM	ACK_RTN	50_ALM_Cen_NJ01A_Cam_HSC_10	NJ01A Cameron and HSC Totals Not Within 10%		1	NULL
10/3/21 12:05 AM	ACK	50_ALM_Cen_NJ01A_Cam_HSC_10	NJ01A Cameron and HSC Totals Not Within 10%		1	NULL
10/3/21 12:05 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:05 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:05 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:05 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:05 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 12:05 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 12:05 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 12:05 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:05 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:05 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 12:05 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:05 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:05 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:05 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:05 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 12:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:07 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:07 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:07 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:07 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:07 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:07 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:07 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:07 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:07 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:07 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:07 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 12:07 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 12:07 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 12:07 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 12:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:07 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:07 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:07 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:07 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:07 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 12:07 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:07 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 12:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:07 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 12:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:07 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:07 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:10 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 12:12 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:12 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:12 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:12 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:12 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:12 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:12 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 12:12 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 12:12 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 12:12 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 12:12 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:12 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:12 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:12 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:12 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:12 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:12 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:12 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:12 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 12:12 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 12:12 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:12 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:12 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 12:12 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:12 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:12 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:12 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:12 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 12:12 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 12:12 AM	ACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 12:12 AM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 12:12 AM	ACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 12:12 AM	ACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:12 AM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:12 AM	ACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:12 AM	ACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:12 AM	ACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:12 AM	ACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:12 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:12 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:12 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:12 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:12 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:12 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:12 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 12:12 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:12 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:12 AM	ACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:12 AM	ACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:12 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:12 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:12 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:12 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:12 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 12:12 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 12:12 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:12 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:12 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 12:12 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:12 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:12 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 12:12 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 12:17 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/3/21 12:17 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:17 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:17 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:17 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:17 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 12:17 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 12:17 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:17 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:17 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:17 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:17 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 12:17 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/3/21 12:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:17 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:17 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:17 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:17 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:17 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:17 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 12:17 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 12:52 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 12:52 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:52 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:52 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:52 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:52 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:52 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:52 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:52 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:52 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:52 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:52 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:52 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:52 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:52 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:52 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:52 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:52 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 12:52 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 12:52 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 12:52 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 12:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:52 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:52 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:52 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 12:52 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 12:52 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:52 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:52 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 12:52 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:52 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:52 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:52 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 12:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 1:24 AM	UNACK_ALM	U35_ALM_043	ALM_043 : PT341: Fuel Gas Hdr Press Low - Xfer to Liq		2	
10/3/21 1:25 AM	UNACK_ALM	U36_ALM_043	ALM_043 : PT341: Fuel Gas Hdr Press Low - Xfer to Liq		2	
10/3/21 1:43 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 1:43 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 1:59 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/3/21 1:59 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:59 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:59 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 1:59 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 1:59 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:59 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:59 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 1:59 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 2:04 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 2:04 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 2:04 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 2:04 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 2:04 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 2:04 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 2:04 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 2:04 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 2:04 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 2:04 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 2:04 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 2:04 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 2:04 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 2:04 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 2:04 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 2:05 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 2:20 AM	ACK_ALM	U35_ALM_043	ALM_043 : PT341: Fuel Gas Hdr Press Low - Xfer to Liq		2	
10/3/21 2:20 AM	ACK_ALM	U36_ALM_043	ALM_043 : PT341: Fuel Gas Hdr Press Low - Xfer to Liq		2	
10/3/21 2:20 AM	ACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 2:20 AM	ACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 2:20 AM	ACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 2:20 AM	ACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 2:20 AM	ACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 2:20 AM	ACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 2:20 AM	ACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 2:20 AM	ACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 2:20 AM	ACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 2:20 AM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 2:20 AM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 2:20 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 2:20 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 2:20 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 2:20 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 2:20 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 2:20 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 2:20 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 2:20 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 2:20 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 2:20 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 2:20 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 2:20 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 2:20 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 2:20 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 2:20 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 2:20 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 2:20 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 2:20 AM	ACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 2:20 AM	ACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 2:20 AM	ACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 2:20 AM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 2:20 AM	ACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 2:20 AM	ACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 2:20 AM	ACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 2:20 AM	ACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 2:20 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 2:20 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 2:20 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 2:20 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 2:25 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 2:26 AM	ACK_RTN	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	
10/3/21 2:26 AM	UNACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	
10/3/21 2:37 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 2:50 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 2:50 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 2:50 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 2:50 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 2:50 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 2:50 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 2:50 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 2:50 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 2:50 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 2:50 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 2:50 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 2:50 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 2:50 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 2:50 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 2:50 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 2:50 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 2:50 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 2:50 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 2:50 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 2:50 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 2:50 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 2:50 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 2:50 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 2:50 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 2:55 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 3:00 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 3:00 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:00 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:00 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:00 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:00 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:00 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:00 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:00 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:00 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:00 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:00 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:00 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:00 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:00 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:00 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:00 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:00 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:00 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:00 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 3:00 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:00 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:00 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:00 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:00 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:00 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:00 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:00 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:00 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 3:00 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 3:00 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 3:00 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 3:00 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 3:00 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 3:00 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 3:00 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:00 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:00 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:00 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:00 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:00 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:00 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:00 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:00 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:00 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:00 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:00 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:00 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:00 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:00 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:00 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:00 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 3:00 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 3:00 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 3:00 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 3:00 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 3:00 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 3:00 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 3:00 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 3:06 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 3:08 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/3/21 3:08 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:08 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:08 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:08 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:08 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:08 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:08 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:08 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:08 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:08 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:08 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 3:08 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 3:08 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:08 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:08 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:08 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:08 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:08 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:08 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:08 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:08 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 3:08 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 3:08 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/3/21 3:08 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 3:08 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 3:08 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 3:08 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 3:08 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:08 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:08 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:08 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:08 AM	UNACK_ALM	U37_ALARMS_2_9	U37-ALM-074: Spare Alarm 074		2	
10/3/21 3:08 AM	UNACK_ALM	U37_ALARMS_0_9	U37-ALM-010: PT-386: Fuel Gas Supply Pressure Low Alarm - XFER		2	
10/3/21 3:10 AM	UNACK_ALM	U39_ALARMS_2_9	U39-ALM-074: Spare Alarm 074		2	
10/3/21 3:10 AM	UNACK_ALM	U39_ALARMS_0_9	U39-ALM-010: PT-386: Fuel Gas Supply Pressure Low Alarm - XFER		2	
10/3/21 3:12 AM	UNACK_ALM	U38_ALARMS_2_9	U38-ALM-074: Spare Alarm 074		2	
10/3/21 3:12 AM	UNACK_ALM	U38_ALARMS_0_9	U38-ALM-010: PT-386: Fuel Gas Supply Pressure Low Alarm - XFER		2	
10/3/21 3:12 AM	ACK_RTN	U38_ALARMS_1_25	U38-ALM-058: T5 TC2 Deviation from AVG Hi		2	
10/3/21 3:13 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 3:15 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 3:15 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:15 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:15 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:15 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:15 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 3:15 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 3:15 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName	
10/3/21 3:15 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL	
10/3/21 3:15 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL	
10/3/21 3:15 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL	
10/3/21 3:15 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL	
10/3/21 3:15 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL	
10/3/21 3:15 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL	
10/3/21 3:15 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL	
10/3/21 3:15 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL	
10/3/21 3:15 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL	
10/3/21 3:15 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL	
10/3/21 3:15 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL	
10/3/21 3:15 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL	
10/3/21 3:15 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL	
10/3/21 3:15 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL	
10/3/21 3:15 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL	
10/3/21 3:15 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL	
10/3/21 3:15 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL	
10/3/21 3:15 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1		
10/3/21 3:15 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1		
10/3/21 3:15 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1		
10/3/21 3:15 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1		
10/3/21 3:15 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1		
10/3/21 3:15 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1		
10/3/21 3:15 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1		
10/3/21 3:15 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1		
10/3/21 3:15 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40		
10/3/21 3:15 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1		
10/3/21 3:18 AM	UNACK_ALM	60_Alm_ShipPump_B_Disch_PSI_Low	Eureka Shipping Pump 1302B Low Discharge Pressure		500		
10/3/21 3:18 AM	ACK_RTN	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL	
10/3/21 3:18 AM	ACK	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL	
10/3/21 3:18 AM	UNACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1		
10/3/21 3:18 AM	ACK_RTN	60_Alm_ShipPump_B_Disch_PSI_Low	Eureka Shipping Pump 1302B Low Discharge Pressure		500	NULL	
10/3/21 3:18 AM	ACK	60_Alm_ShipPump_B_Disch_PSI_Low	Eureka Shipping Pump 1302B Low Discharge Pressure		500	NULL	
10/3/21 3:18 AM	UNACK_ALM	60_Alm_ShipPump_B_Disch_PSI_Low	Eureka Shipping Pump 1302B Low Discharge Pressure		500		
10/3/21 3:18 AM	UNACK_ALM	60_Alm_ShipPump_C_Disch_PSI_Low	Eureka Shipping Pump 1302C Low Discharge Pressure		500		
10/3/21 3:19 AM	ACK_RTN	60_Alm_ShipPump_C_Disch_PSI_Low	Eureka Shipping Pump 1302C Low Discharge Pressure		500	NULL	
10/3/21 3:19 AM	ACK	60_Alm_ShipPump_C_Disch_PSI_Low	Eureka Shipping Pump 1302C Low Discharge Pressure		500	NULL	
10/3/21 3:20 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1		
10/3/21 3:27 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1	
10/3/21 3:27 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1	
10/3/21 3:27 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1	
10/3/21 3:27 AM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1	
10/3/21 3:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:27 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:27 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:27 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:27 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:27 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	1	NULL
10/3/21 3:27 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour	1	NULL
10/3/21 3:27 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	1	NULL
10/3/21 3:27 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute	1	NULL
10/3/21 3:27 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	1	NULL
10/3/21 3:27 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm	1	NULL
10/3/21 3:27 AM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm	1	NULL
10/3/21 3:27 AM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm	1	NULL
10/3/21 3:27 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:27 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	ACK_RTN	60_Alm_ShipPump_B_Disch_PSI_Low	Eureka Shipping Pump 1302B Low Discharge Pressure		500	NULL
10/3/21 3:27 AM	ACK	60_Alm_ShipPump_B_Disch_PSI_Low	Eureka Shipping Pump 1302B Low Discharge Pressure		500	NULL
10/3/21 3:27 AM	ACK_RTN	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	
10/3/21 3:27 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 3:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 3:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 3:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 3:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 3:27 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 3:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:27 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 3:27 AM	UNACK_ALM	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	
10/3/21 3:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:29 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/3/21 3:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 3:32 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:32 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:32 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:32 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:32 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:32 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:32 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:32 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:32 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:32 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:32 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:32 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:32 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 3:32 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 3:32 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:32 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:32 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:32 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:32 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:32 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:32 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 3:32 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 3:32 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 3:32 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 3:32 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 3:32 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 3:32 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:32 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:32 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:32 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:32 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:32 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:32 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:32 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:32 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:32 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:32 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:32 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:32 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:32 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:32 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 3:32 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 3:32 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 3:32 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 3:32 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 3:32 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 3:32 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 3:32 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 3:33 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/3/21 3:33 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 3:34 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:34 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:34 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:34 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:34 AM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/3/21 3:34 AM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/3/21 3:34 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:34 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:34 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 3:34 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 3:34 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:34 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:34 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:34 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:34 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:34 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:34 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:34 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:34 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:34 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:34 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 3:34 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 3:34 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature			1 NULL
10/3/21 3:34 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature			1 NULL
10/3/21 3:34 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 3:34 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 3:34 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/3/21 3:34 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 3:34 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 3:34 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 3:34 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 3:34 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 3:34 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 3:34 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 3:34 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 3:34 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature			1
10/3/21 3:34 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 3:34 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 3:34 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 3:34 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 3:34 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 3:37 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1
10/3/21 3:37 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 3:37 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 3:37 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 3:37 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 3:37 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/3/21 3:37 AM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/3/21 3:37 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature			1 NULL
10/3/21 3:37 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature			1 NULL
10/3/21 3:37 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/3/21 3:37 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/3/21 3:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 3:37 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 3:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 3:37 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 3:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 3:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 3:37 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/3/21 3:37 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 3:37 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/3/21 3:37 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning			1
10/3/21 3:37 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:37 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 3:37 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:37 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:37 AM	ACK_RTN	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/3/21 3:37 AM	ACK	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/3/21 3:37 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:37 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:37 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:37 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:37 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:37 AM	UNACK_ALM	30_ALM_TankLvL_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/3/21 3:37 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 3:37 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 3:38 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:38 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:38 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:38 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:38 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 3:38 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 3:38 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:38 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:38 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:38 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:38 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 3:38 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 3:39 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:39 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:39 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:39 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:39 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:39 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:39 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 3:39 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 3:39 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:39 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:39 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:39 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:39 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:39 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:39 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:39 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:39 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:39 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:39 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 3:39 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/3/21 3:39 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 3:39 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 3:39 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 3:39 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 3:42 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 3:42 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:42 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:42 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:42 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:42 AM	ACK_RTN	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	
10/3/21 3:42 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:42 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:42 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:42 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:42 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:42 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:42 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 3:42 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 3:42 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:42 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:42 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:42 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:42 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 3:43 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 3:43 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 3:43 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:43 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:45 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 3:45 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:45 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:45 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:45 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:45 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:45 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:45 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:45 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:45 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 3:45 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 3:45 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:45 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:45 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 3:45 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 3:45 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:45 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:45 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:45 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:45 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:45 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:45 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:45 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:45 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 3:45 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 3:45 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 3:45 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 3:45 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 3:45 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 3:48 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 3:48 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:48 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:48 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:48 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:48 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:48 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:48 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 3:48 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 3:48 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:48 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:48 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:48 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:48 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:48 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:48 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:48 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:48 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:48 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:48 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:48 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:48 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:48 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 3:48 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 3:48 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 3:48 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 3:48 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 3:48 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 3:48 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 3:48 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 3:48 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:48 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:48 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 3:48 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/3/21 3:49 AM	UNACK_ALM	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	
10/3/21 3:50 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 3:53 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:53 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:53 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:53 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:53 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:53 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:53 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/3/21 3:53 AM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/3/21 3:53 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:53 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:53 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:53 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 3:53 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:53 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:53 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 3:53 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 3:53 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 3:54 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:54 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:54 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:54 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:54 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 3:54 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 3:54 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:54 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:54 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 3:54 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 3:54 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:54 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:54 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:54 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:54 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:54 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:54 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:54 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:54 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:54 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:54 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 3:54 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 3:54 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 3:54 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 3:54 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 3:54 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 3:54 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 3:54 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:54 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:54 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:54 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:58 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 3:58 AM	ACK_RTN	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 3:58 AM	ACK	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:01 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 4:01 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:01 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:01 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:01 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:01 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:01 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:01 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:01 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:01 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 4:01 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 4:01 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:01 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:01 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:01 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:01 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 4:01 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 4:01 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 4:01 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:01 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 4:01 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:01 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:01 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:01 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:01 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:01 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:01 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:01 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:01 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:01 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:01 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:01 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:01 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:01 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:01 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:01 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 4:01 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:01 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 4:01 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 4:01 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 4:01 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 4:01 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:01 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:04 AM	UNACK_ALM	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	
10/3/21 4:04 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:04 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:04 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:04 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:04 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:04 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:04 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:04 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:04 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:04 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:04 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:04 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:04 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:04 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:04 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:04 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:04 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:04 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:04 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:04 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:04 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 4:04 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 4:04 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 4:04 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:04 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 4:04 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:04 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 4:04 AM	UNACK_ALM	60_Alm_ShipPump_C_Disch_PSI_Low	Eureka Shipping Pump 1302C Low Discharge Pressure		500	
10/3/21 4:06 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 4:12 AM	UNACK_ALM	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	
10/3/21 4:12 AM	ACK_RTN	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:12 AM	ACK	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:12 AM	ACK_RTN	60_Alm_ShipPump_C_Disch_PSI_Low	Eureka Shipping Pump 1302C Low Discharge Pressure		500	NULL
10/3/21 4:12 AM	ACK	60_Alm_ShipPump_C_Disch_PSI_Low	Eureka Shipping Pump 1302C Low Discharge Pressure		500	NULL
10/3/21 4:12 AM	UNACK_ALM	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	
10/3/21 4:12 AM	ACK_RTN	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:12 AM	ACK	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:13 AM	UNACK_ALM	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	
10/3/21 4:13 AM	ACK_RTN	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/3/21 4:13 AM	ACK	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/3/21 4:13 AM	ACK_RTN	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:13 AM	ACK	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:13 AM	UNACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	
10/3/21 4:13 AM	UNACK_ALM	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	
10/3/21 4:16 AM	ACK_RTN	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:16 AM	ACK	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:16 AM	UNACK_ALM	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	
10/3/21 4:17 AM	ACK_RTN	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/3/21 4:17 AM	ACK	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/3/21 4:17 AM	ACK_RTN	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:17 AM	ACK	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:17 AM	UNACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost			1
10/3/21 4:17 AM	UNACK_ALM	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm			1
10/3/21 4:17 AM	ACK_RTN	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm			1 NULL
10/3/21 4:17 AM	ACK	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm			1 NULL
10/3/21 4:17 AM	ACK_RTN	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low			500 NULL
10/3/21 4:17 AM	ACK	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low			500 NULL
10/3/21 4:17 AM	UNACK_ALM	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low			500
10/3/21 4:17 AM	UNACK_ALM	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm			1
10/3/21 4:23 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1
10/3/21 4:23 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 4:23 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 4:23 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 4:23 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 4:23 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature			1 NULL
10/3/21 4:23 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature			1 NULL
10/3/21 4:23 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 4:23 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 4:23 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 4:23 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 4:23 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 4:23 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 4:23 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/3/21 4:23 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/3/21 4:23 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 4:23 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 4:23 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 4:23 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 4:23 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 4:23 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 4:23 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 4:23 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 4:23 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 4:23 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 4:23 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 4:23 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 4:23 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 4:23 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1
10/3/21 4:23 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 4:23 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 4:23 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/3/21 4:23 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning			1
10/3/21 4:23 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 4:23 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:23 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 4:23 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 4:23 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:23 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:23 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:23 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:23 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:23 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:23 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:23 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:23 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:23 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:23 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:23 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:23 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:23 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:23 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 4:23 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/3/21 4:23 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 4:23 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:23 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 4:23 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:23 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 4:23 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:23 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:25 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:25 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:25 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:25 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:25 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:25 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:25 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:25 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:25 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 4:27 AM	UNACK_ALM	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1
10/3/21 4:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 4:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 4:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:27 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:27 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:27 AM	ACK_RTN	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/3/21 4:27 AM	ACK	20_ALM_LDS_10_MIN	Eureka to Elly	10 Inch Pipeline 10 Minute Leak Detect Alarm		1 NULL
10/3/21 4:27 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 4:27 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 4:27 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:27 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:27 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:27 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 4:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/3/21 4:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 4:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 4:27 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 4:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:27 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 4:27 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 4:27 AM	ACK_RTN	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/3/21 4:27 AM	ACK	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL
10/3/21 4:27 AM	ACK_RTN	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:27 AM	ACK	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:27 AM	UNACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	
10/3/21 4:27 AM	UNACK_ALM	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	
10/3/21 4:28 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 4:34 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 4:35 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:35 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:35 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 4:35 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 4:35 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:35 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:35 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:35 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:35 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 4:35 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 4:35 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:35 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:35 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:35 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:35 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:35 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:35 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:35 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:35 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:35 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:35 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:35 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:35 AM	ACK_RTN	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	NULL
10/3/21 4:35 AM	ACK	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	NULL
10/3/21 4:35 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:35 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:35 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:35 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:35 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 4:35 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 4:35 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 4:35 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:35 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 4:35 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:35 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 4:35 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:35 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:35 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:35 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:35 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:35 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:35 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 4:37 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:37 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:37 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:37 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:37 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:37 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:37 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:37 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:37 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:37 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:37 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 4:37 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 4:37 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 4:37 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:37 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 4:37 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:37 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 4:37 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 4:37 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 4:37 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:37 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:37 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:37 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:37 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:37 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:37 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:37 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:37 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:37 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:37 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 4:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:37 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:37 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:37 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 4:37 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:37 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 4:37 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:37 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 4:37 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:37 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 4:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:37 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 4:38 AM	ACK_RTN	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:38 AM	ACK	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	NULL
10/3/21 4:38 AM	ACK_RTN	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	NULL
10/3/21 4:38 AM	ACK	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	NULL
10/3/21 4:38 AM	UNACK_ALM	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	
10/3/21 4:38 AM	UNACK_ALM	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	
10/3/21 4:39 AM	ACK_RTN	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	
10/3/21 4:39 AM	ACK_RTN	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	
10/3/21 4:39 AM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/3/21 4:39 AM	ACK_RTN	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/3/21 4:39 AM	UNACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/3/21 4:39 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:39 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:39 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:39 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:39 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:39 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:40 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 4:41 AM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/3/21 4:41 AM	UNACK_ALM	U36_SDFSLO_020	SDFSLO_020 : T5 Overtemp		1	
10/3/21 4:41 AM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/3/21 4:41 AM	ACK	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/3/21 4:41 AM	ACK_RTN	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	NULL
10/3/21 4:41 AM	ACK	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	NULL
10/3/21 4:41 AM	ACK_RTN	U36_SDFSLO_020	SDFSLO_020 : T5 Overtemp		1	NULL
10/3/21 4:41 AM	ACK	U36_SDFSLO_020	SDFSLO_020 : T5 Overtemp		1	NULL
10/3/21 4:42 AM	UNACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/3/21 4:43 AM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/3/21 4:43 AM	UNACK_ALM	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	
10/3/21 4:44 AM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/3/21 4:44 AM	ACK	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/3/21 4:45 AM	UNACK_ALM	U36_SDFSLO_017	SDFSLO_017 : Power Turbine Underspeed		1	
10/3/21 4:45 AM	UNACK_ALM	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	
10/3/21 4:45 AM	UNACK_ALM	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	
10/3/21 4:46 AM	ACK_RTN	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:46 AM	ACK	60_Low_Pressure_Alm	Feeder Pump Pressure Lost			1 NULL
10/3/21 4:46 AM	UNACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost			1 [REDACTED]
10/3/21 4:46 AM	ACK_RTN	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi			2 NULL
10/3/21 4:46 AM	ACK	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi			2 NULL
10/3/21 4:46 AM	ACK_RTN	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out			2 NULL
10/3/21 4:46 AM	ACK	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out			2 NULL
10/3/21 4:46 AM	ACK_RTN	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi			2 NULL
10/3/21 4:46 AM	ACK	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi			2 NULL
10/3/21 4:46 AM	ACK_RTN	U36_SDFSLO_017	SDFSLO_017 : Power Turbine Underspeed			1 NULL
10/3/21 4:46 AM	ACK	U36_SDFSLO_017	SDFSLO_017 : Power Turbine Underspeed			1 NULL
10/3/21 4:47 AM	UNACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out			2 [REDACTED]
10/3/21 4:47 AM	UNACK_ALM	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm			1 [REDACTED]
10/3/21 4:47 AM	UNACK_ALM	50_ALM_Sat_NP10B_Dsl_Switch_Fail	NP10B Diesel Switch Failure			1 [REDACTED]
10/3/21 4:47 AM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas			2 [REDACTED]
10/3/21 4:48 AM	UNACK_ALM	U36_SDFSLO_020	SDFSLO_020 : T5 Overtemp			1 [REDACTED]
10/3/21 4:48 AM	ACK_RTN	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out			2 NULL
10/3/21 4:48 AM	ACK	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out			2 NULL
10/3/21 4:48 AM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas			2 NULL
10/3/21 4:48 AM	ACK	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas			2 NULL
10/3/21 4:48 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 4:48 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 4:48 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 4:48 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 4:48 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 4:48 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 4:48 AM	ACK_RTN	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail			1 NULL
10/3/21 4:48 AM	ACK	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail			1 NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 4:48 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 4:48 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature			1 NULL
10/3/21 4:48 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature			1 NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 4:48 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 4:48 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 4:48 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/3/21 4:48 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/3/21 4:48 AM	ACK_RTN	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm			1 NULL
10/3/21 4:48 AM	ACK	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:48 AM	ACK_RTN	50_ALM_Sat_NP10B_Dsl_Switch_Fail	NP10B Diesel Switch Failure		1	NULL
10/3/21 4:48 AM	ACK	50_ALM_Sat_NP10B_Dsl_Switch_Fail	NP10B Diesel Switch Failure		1	NULL
10/3/21 4:48 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:48 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 4:48 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:48 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 4:48 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 4:48 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:48 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:48 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:48 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:48 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 4:48 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:48 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:48 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 4:48 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:48 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:48 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:48 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:48 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:48 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:48 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:48 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:48 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:48 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 4:48 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:48 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 4:48 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:48 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:48 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 4:48 AM	ACK_RTN	U36_SDFSLO_020	SDFSLO_020 : T5 Overtemp		1	NULL
10/3/21 4:48 AM	ACK	U36_SDFSLO_020	SDFSLO_020 : T5 Overtemp		1	NULL
10/3/21 4:49 AM	UNACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/3/21 4:50 AM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/3/21 4:50 AM	UNACK_ALM	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	
10/3/21 4:53 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 4:57 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:57 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:58 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 4:58 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:58 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:58 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 4:58 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 4:58 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:58 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:58 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:58 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:58 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:58 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:58 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:58 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 4:58 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:58 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:58 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:58 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:58 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:58 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 4:58 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:58 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:58 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 4:58 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 4:58 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:58 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:58 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:03 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/3/21 5:03 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 5:04 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:04 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:04 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:04 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:04 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:04 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:04 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 5:04 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 5:04 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/3/21 5:04 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/3/21 5:04 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:04 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:04 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:04 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:04 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:04 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:04 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:04 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:04 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:04 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:04 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:04 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:04 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/3/21 5:04 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:04 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:04 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:04 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:04 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:04 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 5:04 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:05 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/3/21 5:05 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/3/21 5:05 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:05 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:05 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:05 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:05 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:05 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:05 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:05 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:05 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:05 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:05 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:05 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:05 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 5:05 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 5:05 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:05 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:05 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:05 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:05 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 5:05 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 5:05 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:05 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:05 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:05 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:05 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:05 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:05 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 5:05 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 5:05 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:05 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:05 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 5:05 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 5:06 AM	UNACK_ALM	20_ALM_Eureka_Disch_PSI_Low	Eureka Pipeline Discharge PSI Fell Below 170 PSI		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:06 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:06 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:06 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:06 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:06 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:06 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:06 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:06 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:06 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:06 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:06 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:06 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:06 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:06 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:06 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:06 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:06 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:06 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:06 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:06 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:06 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:06 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:06 AM	ACK_RTN	20_ALM_Eureka_Disch_PSI_Low	Eureka Pipeline Discharge PSI Fell Below 170 PSI		1	NULL
10/3/21 5:06 AM	ACK	20_ALM_Eureka_Disch_PSI_Low	Eureka Pipeline Discharge PSI Fell Below 170 PSI		1	NULL
10/3/21 5:06 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:06 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:06 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:06 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:06 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:06 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:06 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:06 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:06 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:06 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:06 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:06 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:06 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:06 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:06 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:06 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:06 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:06 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:06 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:06 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:06 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:06 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:06 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:06 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:06 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:06 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:06 AM	ACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 5:06 AM	ACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/3/21 5:06 AM	ACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/3/21 5:06 AM	ACK_ALM	U38_ALARMS_0_9	U38-ALM-010: PT-386: Fuel Gas Supply Pressure Low Alarm - XFER		2	
10/3/21 5:06 AM	ACK_ALM	U38_ALARMS_2_9	U38-ALM-074: Spare Alarm 074		2	
10/3/21 5:06 AM	ACK_ALM	U39_ALARMS_0_9	U39-ALM-010: PT-386: Fuel Gas Supply Pressure Low Alarm - XFER		2	
10/3/21 5:06 AM	ACK_ALM	U39_ALARMS_2_9	U39-ALM-074: Spare Alarm 074		2	
10/3/21 5:06 AM	ACK_ALM	U37_ALARMS_0_9	U37-ALM-010: PT-386: Fuel Gas Supply Pressure Low Alarm - XFER		2	
10/3/21 5:06 AM	ACK_ALM	U37_ALARMS_2_9	U37-ALM-074: Spare Alarm 074		2	
10/3/21 5:06 AM	ACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:06 AM	ACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:06 AM	ACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:06 AM	ACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:06 AM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:06 AM	ACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:06 AM	ACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:06 AM	ACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:06 AM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 5:06 AM	ACK_ALM	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	
10/3/21 5:06 AM	ACK_ALM	60_Low_Pressure_Alm	Feeder Pump Pressure Lost		1	
10/3/21 5:06 AM	ACK_ALM	60_Alm_Solids_Pmp_Mud_Pmp_Vlv	Solids Pump to Mud Pump Valve Alarm		1	
10/3/21 5:06 AM	ACK_ALM	60_Alm_Gas_Pipeline_PSI_Low	Eureka Shipping Gas Pipeline Pressure Low		500	
10/3/21 5:06 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:06 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:06 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:06 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:08 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 5:08 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/3/21 5:08 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/3/21 5:08 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1 NULL	
10/3/21 5:08 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1 NULL	
10/3/21 5:08 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:08 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:09 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 5:11 AM	UNACK_ALM	U36_ALM_041	ALM_041 : SPARE		2	
10/3/21 5:12 AM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:12 AM	UNACK_ALM	U36_ALM_036	ALM_036 : Bently Nevada High Vibration Summary Alarm		2	
10/3/21 5:12 AM	UNACK_ALM	U36_SDFSLO_026	SDFSLO_026 : Bently Nevada High Bearing Temperature Summary SD		1	
10/3/21 5:13 AM	UNACK_ALM	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	
10/3/21 5:13 AM	UNACK_ALM	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	
10/3/21 5:14 AM	ACK_RTN	U36_ALM_041	ALM_041 : SPARE		2	NULL
10/3/21 5:14 AM	ACK	U36_ALM_041	ALM_041 : SPARE		2	NULL
10/3/21 5:14 AM	ACK_RTN	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	NULL
10/3/21 5:14 AM	ACK	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	NULL
10/3/21 5:14 AM	ACK_RTN	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/3/21 5:14 AM	ACK_RTN	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	NULL
10/3/21 5:14 AM	ACK	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	NULL
10/3/21 5:14 AM	ACK_RTN	U36_SDFSLO_026	SDFSLO_026 : Bently Nevada High Bearing Temperature Summary SD		1	NULL
10/3/21 5:14 AM	ACK	U36_SDFSLO_026	SDFSLO_026 : Bently Nevada High Bearing Temperature Summary SD		1	NULL
10/3/21 5:15 AM	UNACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/3/21 5:16 AM	UNACK_ALM	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	
10/3/21 5:16 AM	UNACK_ALM	50_ALM_Sat_NP10B_Dsl_Switch_Fail	NP10B Diesel Switch Failure		1	
10/3/21 5:16 AM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/3/21 5:16 AM	UNACK_ALM	U36_SDFSLO_020	SDFSLO_020 : T5 Overtemp		1	
10/3/21 5:17 AM	ACK_RTN	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	NULL
10/3/21 5:17 AM	ACK	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	NULL
10/3/21 5:17 AM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/3/21 5:17 AM	ACK	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/3/21 5:17 AM	ACK_RTN	U36_SDFSLO_020	SDFSLO_020 : T5 Overtemp		1	NULL
10/3/21 5:17 AM	ACK	U36_SDFSLO_020	SDFSLO_020 : T5 Overtemp		1	NULL
10/3/21 5:18 AM	UNACK_ALM	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/3/21 5:18 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK_RTN	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	
10/3/21 5:18 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:18 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:18 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:18 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:18 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:18 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:18 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:18 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:18 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 5:18 AM	ACK_RTN	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/3/21 5:18 AM	ACK	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:18 AM	ACK_RTN	50_ALM_Sat_NP10B_Dsl_Switch_Fail	NP10B Diesel Switch Failure		1	NULL
10/3/21 5:18 AM	ACK	50_ALM_Sat_NP10B_Dsl_Switch_Fail	NP10B Diesel Switch Failure		1	NULL
10/3/21 5:18 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:18 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:18 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:18 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:18 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:18 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:18 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:18 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:18 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:18 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:18 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:18 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:18 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:18 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:18 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:18 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:18 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:18 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:18 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:18 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:18 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 5:18 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:18 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:18 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 5:18 AM	UNACK_ALM	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/3/21 5:18 AM	ACK_RTN	U36_ALM_036	ALM_036 : Bently Nevada High Vibration Summary Alarm		2	NULL
10/3/21 5:18 AM	ACK	U36_ALM_036	ALM_036 : Bently Nevada High Vibration Summary Alarm		2	NULL
10/3/21 5:19 AM	UNACK_ALM	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	
10/3/21 5:19 AM	UNACK_ALM	U36_ALM_054	ALM_054 : PT380: Lube Oil Header Press Low		2	
10/3/21 5:19 AM	ACK_RTN	U36_ALM_054	ALM_054 : PT380: Lube Oil Header Press Low		2	NULL
10/3/21 5:19 AM	ACK	U36_ALM_054	ALM_054 : PT380: Lube Oil Header Press Low		2	NULL
10/3/21 5:19 AM	ACK_RTN	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/3/21 5:19 AM	ACK	U36_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	NULL
10/3/21 5:20 AM	UNACK_ALM	U36_SDFSLO_017	SDFSLO_017 : Power Turbine Underspeed		1	
10/3/21 5:20 AM	UNACK_ALM	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHI		2	
10/3/21 5:20 AM	UNACK_ALM	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	
10/3/21 5:21 AM	ACK_RTN	U35_ALM_036	ALM_036 : Bently Nevada High Vibration Summary Alarm		2	
10/3/21 5:21 AM	ACK_RTN	U35_ALM_027	ALM_027 : PT341: Fuel Gas Header Pressure High		2	
10/3/21 5:21 AM	UNACK_ALM	U35_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/3/21 5:22 AM	UNACK_ALM	U35_ALMH_020	ALMH_020 : GFMV Gas Fuel Flow Fault		3	
10/3/21 5:22 AM	UNACK_ALM	U35_ALMH_019	ALMH_019 : Gas Fuel Metering Valve Position Feedback Fault		3	
10/3/21 5:22 AM	ACK_RTN	U35_ALMH_019	ALMH_019 : Gas Fuel Metering Valve Position Feedback Fault		3	NULL
10/3/21 5:22 AM	ACK	U35_ALMH_019	ALMH_019 : Gas Fuel Metering Valve Position Feedback Fault		3	NULL
10/3/21 5:22 AM	ACK_RTN	U35_ALMH_020	ALMH_020 : GFMV Gas Fuel Flow Fault		3	NULL
10/3/21 5:22 AM	ACK	U35_ALMH_020	ALMH_020 : GFMV Gas Fuel Flow Fault		3	NULL
10/3/21 5:22 AM	UNACK_ALM	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	
10/3/21 5:22 AM	UNACK_ALM	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	
10/3/21 5:23 AM	UNACK_ALM	U35_ALMH_020	ALMH_020 : GFMV Gas Fuel Flow Fault		3	
10/3/21 5:23 AM	UNACK_ALM	U35_ALMH_019	ALMH_019 : Gas Fuel Metering Valve Position Feedback Fault		3	
10/3/21 5:23 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 5:23 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:23 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:23 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:23 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:23 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:23 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:23 AM	ACK_RTN	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/3/21 5:23 AM	ACK	50_ALM_Sat_NP10B_VHSC_Fail	NP10B VHSC Fail		1	NULL
10/3/21 5:23 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:23 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:23 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:23 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:23 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:23 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:23 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:23 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:23 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:23 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:23 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:23 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:23 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:23 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:23 AM	ACK_RTN	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/3/21 5:23 AM	ACK	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/3/21 5:23 AM	ACK_RTN	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	NULL
10/3/21 5:23 AM	ACK	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	NULL
10/3/21 5:23 AM	UNACK_ALM	U35_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/3/21 5:23 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 5:23 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:23 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:23 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:23 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:23 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 5:23 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:23 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:23 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:23 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:23 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 5:24 AM	UNACK_ALM	U35_ALM_029	ALM_029 : T7 Overtemp		2	
10/3/21 5:25 AM	UNACK_ALM	40_Alm_EastBay_Shutdown_VSD_03	East Well Bay Shutdown Alarm -- VSD-03		1	
10/3/21 5:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:26 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:26 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 5:26 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 5:26 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 5:26 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:26 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:26 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 5:26 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 5:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:26 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:26 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:26 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:26 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:26 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:26 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:26 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:26 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:27 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:27 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:27 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:27 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:27 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:27 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:27 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 5:27 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:28 AM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/3/21 5:28 AM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/3/21 5:28 AM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/3/21 5:28 AM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/3/21 5:28 AM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/3/21 5:28 AM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/3/21 5:28 AM	ACK_RTN	40_Alm_EastBay_Shutdown_VSD_03	East Well Bay Shutdown Alarm -- VSD-03		1	NULL
10/3/21 5:28 AM	ACK	40_Alm_EastBay_Shutdown_VSD_03	East Well Bay Shutdown Alarm -- VSD-03		1	NULL
10/3/21 5:28 AM	UNACK_ALM	40_Alm_Inhibit_VSD_Shutdown	NULL		1	
10/3/21 5:28 AM	UNACK_ALM	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	
10/3/21 5:28 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:28 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:28 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:28 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:28 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:28 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:28 AM	ACK_RTN	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/3/21 5:28 AM	ACK	40_Alm_Inhibit_VSD_Shutdown	NULL		1	NULL
10/3/21 5:28 AM	ACK_RTN	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/3/21 5:28 AM	ACK	40_Alm_Inhibit_WellBay_Shutdown	NULL		1	NULL
10/3/21 5:28 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 5:32 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:32 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:32 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:32 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:32 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:32 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:32 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:32 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:32 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:32 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:32 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:32 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:32 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:32 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:32 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:32 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:32 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:32 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:32 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:32 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:32 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:32 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:32 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:32 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:32 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:32 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:32 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	
10/3/21 5:32 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:32 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 5:32 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:32 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:33 AM	ACK_RTN	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	NULL
10/3/21 5:33 AM	ACK	U36_ALM_061	ALM_061 : Z347-1: Pump Non-Drive End Vibration \$NHi		2	NULL
10/3/21 5:33 AM	ACK_RTN	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	NULL
10/3/21 5:33 AM	ACK	U36_ALM_060	ALM_060 : Z346-1: Pump Drive End Vibration Hi		2	NULL
10/3/21 5:33 AM	ACK_RTN	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	NULL
10/3/21 5:33 AM	ACK	U36_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	NULL
10/3/21 5:33 AM	ACK_RTN	U36_SDFSLO_017	SDFSLO_017 : Power Turbine Underspeed		1	NULL
10/3/21 5:33 AM	ACK	U36_SDFSLO_017	SDFSLO_017 : Power Turbine Underspeed		1	NULL
10/3/21 5:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 5:47 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:47 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:51 AM	UNACK_ALM	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	
10/3/21 5:51 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:51 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:51 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:51 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:51 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:51 AM	ACK	91_Alm_TrainB_X02B_Temp_Low	Alarm--Train B Crude Heater X02B Low Temperature		1	NULL
10/3/21 5:51 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:51 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:51 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:51 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:51 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:51 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:51 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:51 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:51 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:51 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:51 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:51 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:51 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:51 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:51 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:51 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:51 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:51 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:51 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/3/21 5:51 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/3/21 5:52 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/3/21 5:52 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/3/21 5:52 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 5:52 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 5:52 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:52 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:52 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:52 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:52 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:52 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:52 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:52 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:52 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:52 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:52 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:52 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:52 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/3/21 5:52 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/3/21 5:52 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:52 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:52 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:52 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:54 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 5:55 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/3/21 5:55 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/3/21 5:55 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 5:55 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 5:55 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:55 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:55 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:55 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:55 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:55 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:55 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:55 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:55 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:55 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 5:55 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:55 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:55 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:55 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:55 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/3/21 5:55 AM	UNACK_ALM	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	
10/3/21 5:55 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:55 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:55 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 5:55 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 5:55 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 5:55 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:55 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:56 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 5:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:57 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:57 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:57 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 6:02 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 6:17 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 6:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:17 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 6:17 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 6:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:17 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:17 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/3/21 6:17 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/3/21 6:17 AM	ACK_RTN	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 6:17 AM	ACK	91_Alm_TrainB_X02B_Temp_Low_Warn	Warning--Train B Crude Heater X02B Low Temp Warning		1	NULL
10/3/21 6:17 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:17 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:17 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:17 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:17 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:17 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:17 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:17 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:17 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 6:17 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 6:17 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 6:17 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 6:17 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 6:17 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 6:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 6:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 6:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:17 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:17 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:17 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	
10/3/21 6:17 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 6:17 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 6:17 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 6:17 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 6:17 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 6:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 6:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 6:17 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 6:22 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 6:26 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 6:26 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo_Warn	Warning--Train B FWKO Low Pressure		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:26 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 6:26 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 6:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:26 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:26 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 6:26 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 6:26 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 6:26 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 6:26 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 6:26 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 6:26 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 6:26 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 6:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:26 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:26 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:26 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 6:26 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 6:26 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 6:26 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 6:26 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 6:26 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 6:26 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 6:26 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 6:27 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 6:27 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 6:27 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 6:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 6:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 6:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 6:27 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 6:27 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 6:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:27 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:27 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 6:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 6:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 6:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 6:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 6:27 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	
10/3/21 6:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 6:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 6:30 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:30 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:30 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:30 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:30 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 6:30 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 6:31 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 6:35 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 6:36 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 6:36 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 6:36 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:36 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:36 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:36 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:36 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:36 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:36 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:36 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:36 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 6:36 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed		1	NULL
10/3/21 6:36 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:36 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:36 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 6:36 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 6:36 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:36 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:36 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 6:36 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 6:36 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 6:36 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 6:36 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 6:36 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1
10/3/21 6:36 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 6:36 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 6:37 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 6:37 AM	UNACK_ALM	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1
10/3/21 6:37 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 6:37 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 6:37 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 6:37 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 6:37 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 6:37 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 6:37 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 6:37 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 6:37 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 6:37 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 6:37 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/3/21 6:37 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/3/21 6:37 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 6:37 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 6:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 6:37 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 6:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 6:37 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 6:37 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 6:37 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 6:37 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 6:37 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 6:37 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 6:37 AM	UNACK_ALM	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1
10/3/21 6:37 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 6:37 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 6:37 AM	ACK_RTN	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/3/21 6:37 AM	ACK	20_ALM_LDS_1_HR	Eureka to Elly	10 Inch Pipeline 1 Hour Leak Detect Alarm		1 NULL
10/3/21 6:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 6:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 6:37 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/3/21 6:38 AM	UNACK_ALM	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low			500
10/3/21 6:41 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 6:44 AM	ACK_RTN	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 6:44 AM	ACK	91_Alm_V02B_Oil_Vlv_Pos	Warning--V02B Oil Out Valve Closed			1 NULL
10/3/21 6:47 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 [REDACTED]
10/3/21 6:47 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 6:47 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 6:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 6:47 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 6:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 6:47 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 6:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 6:47 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 6:47 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]		1 [REDACTED]
10/3/21 6:47 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]		1 [REDACTED]
10/3/21 6:50 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%	[REDACTED]		1 [REDACTED]
10/3/21 6:50 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 6:50 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 6:50 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 6:50 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 6:50 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]		1 [REDACTED]
10/3/21 6:50 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]		1 [REDACTED]
10/3/21 6:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]		1 [REDACTED]
10/3/21 6:52 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 6:52 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 6:52 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 6:52 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 6:52 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 6:52 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 6:52 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 6:52 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 6:52 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 6:52 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 6:52 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 6:52 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 6:52 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 6:52 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 6:52 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 6:52 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 6:52 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]		1 [REDACTED]
10/3/21 6:52 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]		1 [REDACTED]
10/3/21 6:52 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature	[REDACTED]		1 [REDACTED]
10/3/21 6:52 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]		1 [REDACTED]
10/3/21 6:52 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed	[REDACTED]		1 [REDACTED]
10/3/21 6:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]		1 [REDACTED]
10/3/21 6:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]		1 [REDACTED]

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 6:56 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 6:56 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:56 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:56 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:56 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:56 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 6:56 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 6:57 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 6:57 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 6:57 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 6:57 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 6:57 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 6:57 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:57 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 6:57 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:57 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 6:57 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:57 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 6:57 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:57 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 6:57 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 6:57 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 6:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:57 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 6:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:57 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 6:57 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 6:57 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 6:57 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 6:57 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 6:57 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 6:57 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 6:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 6:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 6:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 7:03 AM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/3/21 7:03 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLG	Communications Failure from Beta PS to Elly_LDS		1	
10/3/21 7:07 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 7:07 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 7:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:07 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 7:07 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 7:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 7:07 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 7:07 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/3/21 7:07 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/3/21 7:07 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 7:07 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 7:07 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 7:07 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 7:07 AM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1 NULL
10/3/21 7:07 AM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1 NULL
10/3/21 7:07 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 7:07 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 7:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 7:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 7:07 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/3/21 7:10 AM	ACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1
10/3/21 7:10 AM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/3/21 7:10 AM	ACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 7:10 AM	ACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 7:10 AM	ACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 7:10 AM	ACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 7:10 AM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 7:10 AM	ACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 7:10 AM	ACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 7:10 AM	ACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 7:10 AM	ACK_ALM	60_Alm_Oil_Pipeline_PSI_Low	Eureka Shipping Oil Pipeline Pressure Low			500
10/3/21 7:10 AM	ACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/3/21 7:10 AM	ACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 7:10 AM	ACK_ALM	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm			1
10/3/21 7:10 AM	ACK_ALM	U35_ALM_029	ALM_029 : T7 Overtemp			2
10/3/21 7:10 AM	ACK_ALM	U35_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas			2
10/3/21 7:10 AM	ACK_ALM	U35_ALMH_019	ALMH_019 : Gas Fuel Metering Valve Position Feedback Fault			3
10/3/21 7:10 AM	ACK_ALM	U35_ALMH_020	ALMH_020 : GFMV Gas Fuel Flow Fault			3
10/3/21 7:10 AM	ACK_ALM	U35_ALM_011	ALM_011 : Fuel Transfer Locked Out			2
10/3/21 7:10 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 7:10 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 7:10 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/3/21 7:10 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 7:10 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 7:10 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 7:10 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/3/21 7:10 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 7:12 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 7:12 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 7:12 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 7:12 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 7:12 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 7:12 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 7:12 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 7:12 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/3/21 7:12 AM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/3/21 7:12 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 7:12 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 7:12 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 7:12 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 7:12 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/3/21 7:12 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 7:17 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 7:17 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 7:17 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 7:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 7:17 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 7:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 7:17 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 7:17 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1
10/3/21 7:17 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 7:17 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 7:17 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 7:17 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 7:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 7:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 7:17 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1
10/3/21 7:17 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 7:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 7:18 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 7:18 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 7:18 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 7:18 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 7:18 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 7:18 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 7:18 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 7:18 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 7:18 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 7:18 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 7:18 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 7:18 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 7:18 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 7:18 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 7:18 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 7:18 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 7:18 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 7:18 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 7:18 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 7:18 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 7:23 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 7:27 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 7:27 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 7:27 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 7:27 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 7:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 7:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 7:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 7:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 7:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 7:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 7:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 7:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 7:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 7:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 7:27 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/3/21 7:27 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/3/21 7:27 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 7:27 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 7:27 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 7:27 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 7:27 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 7:27 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 7:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 7:27 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 7:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 7:27 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 7:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 7:27 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 7:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 7:27 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 7:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 7:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 7:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 7:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 7:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 7:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 7:27 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 7:27 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 7:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 7:32 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 7:32 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 7:32 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 7:32 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 7:32 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 7:32 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 7:32 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 7:32 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 7:32 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 7:32 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 7:32 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 7:32 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 7:32 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:32 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:32 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 7:32 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 7:32 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 7:32 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 7:32 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 7:32 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 7:32 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 7:32 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 7:32 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 7:32 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 7:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 7:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 7:32 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 7:32 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 7:37 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 7:37 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 7:37 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 7:37 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 7:37 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 7:37 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 7:37 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 7:37 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 7:37 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 7:37 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 7:37 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 7:37 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 7:37 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 7:37 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 7:37 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	1	NULL
10/3/21 7:37 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	1	NULL
10/3/21 7:37 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	1	NULL
10/3/21 7:37 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	1	NULL
10/3/21 7:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:37 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 7:37 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 7:37 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 7:37 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 7:37 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 7:37 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 7:37 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 7:37 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 7:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 7:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 7:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 7:39 AM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/3/21 7:46 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 7:46 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 7:46 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 7:46 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 7:46 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 7:46 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 7:46 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 7:46 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 7:46 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 7:46 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 7:46 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 7:46 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 7:46 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 7:46 AM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 7:46 AM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 7:46 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:46 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:46 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 7:46 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 7:46 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 7:46 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 7:46 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 7:46 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 7:46 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 7:46 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 7:46 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 7:46 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 7:46 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 7:46 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 7:46 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:46 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:46 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 7:46 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 7:46 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 7:46 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 7:47 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 7:47 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 7:47 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 7:47 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 7:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:47 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 7:47 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 7:47 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 7:47 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 7:47 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 7:47 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 7:47 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 7:47 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 7:47 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 7:51 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 7:57 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 7:57 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 7:57 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 7:57 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 7:57 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 7:57 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 7:57 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 7:57 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 7:57 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 7:57 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 7:57 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 7:57 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 7:57 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 7:57 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 7:57 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 7:57 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 7:57 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 7:57 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 7:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:57 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 7:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 7:57 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 7:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 7:57 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 7:57 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 7:57 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 7:57 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 7:57 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 7:57 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 7:57 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 7:57 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 7:57 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 7:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 7:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 7:57 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 8:02 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 8:04 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 8:04 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 8:04 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 8:04 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 8:04 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 8:04 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 8:04 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 8:04 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 8:04 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 8:04 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 8:04 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 8:07 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 8:07 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 8:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 8:07 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 8:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 8:07 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 8:07 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 8:07 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 8:07 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 8:07 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 8:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 8:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 8:09 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 8:09 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 8:09 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 8:09 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 8:09 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 8:09 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 8:09 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 8:09 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 8:09 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 8:09 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 8:09 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 8:09 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 8:09 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 8:09 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 8:09 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/3/21 8:09 AM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/3/21 8:09 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 8:09 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 8:09 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 8:09 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 8:09 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 8:09 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 8:09 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 8:09 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 8:09 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 8:09 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 8:09 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 8:09 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 8:09 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 8:09 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 8:09 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/3/21 8:09 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 8:09 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 8:09 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 8:17 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 8:17 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 8:17 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 8:17 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 8:17 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 8:17 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 8:17 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 8:17 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 8:17 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 8:17 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 8:17 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 8:17 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 8:17 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 8:17 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 8:17 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 8:17 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 8:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 8:17 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 8:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 8:17 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 8:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 8:17 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 8:17 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 8:17 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 8:17 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 8:17 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 8:17 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 8:17 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 8:17 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 8:17 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 8:17 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 8:17 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 8:17 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 8:17 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 8:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 8:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 8:17 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 8:17 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 8:22 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 8:27 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 8:27 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 8:27 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 8:27 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 8:27 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 8:27 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 8:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 8:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 8:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 8:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 8:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 8:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 8:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 8:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 8:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 8:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 8:27 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 8:27 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 8:27 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 8:27 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 8:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 8:27 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 8:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 8:27 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 8:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 8:27 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 8:27 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 8:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 8:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 8:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 8:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 8:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 8:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 8:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 8:27 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/3/21 8:29 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS			1
10/3/21 8:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 8:37 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 8:37 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 8:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 8:37 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 8:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 8:37 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 8:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 8:37 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 8:37 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/3/21 8:37 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/3/21 8:37 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 8:37 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 8:37 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 8:37 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 8:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 8:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 8:42 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 8:47 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 [REDACTED]
10/3/21 8:47 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/3/21 8:47 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 8:47 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 8:47 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 8:47 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 8:47 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 8:47 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 8:47 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 8:47 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 8:47 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 8:47 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 8:47 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 8:47 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 8:47 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 8:47 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 8:47 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 8:47 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 8:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 8:47 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 8:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 8:47 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 8:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 8:47 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 8:47 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.	[REDACTED]	1	[REDACTED]
10/3/21 8:47 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]	1	[REDACTED]
10/3/21 8:47 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]	1	[REDACTED]
10/3/21 8:47 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature	[REDACTED]	1	[REDACTED]
10/3/21 8:47 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]	1	[REDACTED]
10/3/21 8:47 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed	[REDACTED]	1	[REDACTED]
10/3/21 8:47 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 8:47 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 8:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 8:57 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 [REDACTED]
10/3/21 8:57 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/3/21 8:57 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 8:57 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 8:57 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 8:57 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 8:57 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 8:57 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 8:57 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 8:57 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 8:57 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 8:57 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 8:57 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 8:57 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 8:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 8:57 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 8:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 8:57 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 8:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 8:57 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 8:57 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 8:57 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 8:57 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 8:57 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 8:57 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 8:57 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 8:57 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 8:57 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 8:57 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 8:57 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 8:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 8:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 9:01 AM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	
10/3/21 9:01 AM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/3/21 9:01 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/3/21 9:02 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 9:03 AM	ACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 9:03 AM	ACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/3/21 9:03 AM	ACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/3/21 9:03 AM	ACK_ALM	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	
10/3/21 9:03 AM	ACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 9:03 AM	ACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 9:03 AM	ACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 9:03 AM	ACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 9:03 AM	ACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 9:03 AM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 9:03 AM	ACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 9:03 AM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 9:03 AM	ACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 9:03 AM	ACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	
10/3/21 9:03 AM	ACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 9:03 AM	ACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 9:03 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 9:03 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 9:03 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 9:03 AM	ACK_RTN	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly			1
10/3/21 9:03 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS			1
10/3/21 9:03 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 9:03 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 9:03 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 9:03 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 9:03 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 9:03 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 9:03 AM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1
10/3/21 9:03 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1
10/3/21 9:03 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 9:03 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 9:03 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 9:03 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 9:03 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 9:03 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 9:03 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/3/21 9:03 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 9:03 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 9:03 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 9:03 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/3/21 9:03 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1
10/3/21 9:03 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/3/21 9:03 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 9:03 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/3/21 9:07 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 9:07 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 9:07 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 9:07 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 9:07 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 9:07 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 9:07 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 9:07 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 9:07 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 9:07 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 9:07 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 9:07 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 9:07 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 9:07 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 9:07 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 9:07 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 9:07 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 9:07 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 9:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 9:07 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 9:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 9:07 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 9:07 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 9:07 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 9:07 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 9:07 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 9:07 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 9:07 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 9:07 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 9:07 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 9:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 9:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 9:07 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 9:08 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 9:17 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 9:17 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 9:17 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 9:17 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 9:17 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 9:17 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 9:17 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 9:17 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 9:17 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 9:17 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 9:17 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 9:17 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 9:17 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 9:17 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 9:17 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 9:17 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 9:17 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 9:17 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 9:17 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 9:17 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 9:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 9:17 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 9:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 9:17 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 9:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 9:17 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 9:17 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 9:17 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 9:17 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 9:17 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 9:17 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 9:17 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 9:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 9:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 9:17 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/3/21 9:22 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 9:27 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 9:27 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 9:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 9:27 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 9:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 9:27 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 9:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 9:27 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 9:27 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 9:27 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 9:27 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 9:27 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 9:27 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/3/21 9:27 AM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1 NULL
10/3/21 9:27 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 9:27 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 9:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 9:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 9:27 AM	UNACK_ALM	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%			1
10/3/21 9:27 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 9:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 9:37 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 9:37 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 9:37 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 9:37 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 9:37 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 9:37 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 9:37 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 9:37 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 9:37 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 9:37 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 9:37 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 9:37 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 9:37 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 9:37 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 9:37 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 9:37 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 9:37 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 9:37 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 9:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 9:37 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 9:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 9:37 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 9:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 9:37 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 9:37 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 9:37 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 9:37 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 9:37 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 9:37 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 9:37 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 9:37 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 9:37 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 9:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 9:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 9:42 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 9:47 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 9:47 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 9:47 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 9:47 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 9:47 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 9:47 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 9:47 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 9:47 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 9:47 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 9:47 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 9:47 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 9:47 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 9:47 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 9:47 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 9:47 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 9:47 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 9:47 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 9:47 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 9:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 9:47 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 9:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 9:47 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 9:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 9:47 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 9:47 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 9:47 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 9:47 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 9:47 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 9:47 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 9:47 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 9:47 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 9:47 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 9:47 AM	ACK_RTN	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/3/21 9:47 AM	ACK	30_ALM_TankLvl_Low_Low_S06	Alarm -- S06 Tank Level Low Low < 20%		1	NULL
10/3/21 9:50 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 9:50 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 9:50 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 9:50 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 9:50 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 9:50 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 9:50 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 9:50 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 9:50 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 9:50 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 9:50 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 9:50 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 9:50 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 9:50 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 9:50 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 9:50 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 9:50 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 9:50 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 9:50 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 9:50 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 9:50 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 9:50 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 9:50 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 9:50 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 9:50 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 9:50 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 9:50 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 9:50 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 9:50 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 9:50 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 9:50 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 9:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 9:57 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 9:57 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 9:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 9:57 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 9:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 9:57 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 9:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 9:57 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 9:57 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 9:57 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 9:57 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 9:57 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 9:57 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 9:57 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 9:57 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 9:57 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 9:57 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 9:57 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 9:57 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 9:57 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 9:57 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 9:57 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 9:57 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 9:57 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 9:57 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 9:57 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 9:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 9:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 9:57 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 9:57 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 9:57 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 9:57 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 9:57 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 9:57 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 9:57 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 10:02 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 10:05 AM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	
10/3/21 10:05 AM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 10:05 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS	[REDACTED]	1	[REDACTED]
10/3/21 10:07 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 [REDACTED]
10/3/21 10:07 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/3/21 10:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 10:07 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 10:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 10:07 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 10:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 10:07 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 10:07 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/3/21 10:07 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/3/21 10:07 AM	ACK_RTN	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	NULL
10/3/21 10:07 AM	ACK	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	NULL
10/3/21 10:07 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 10:07 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 10:07 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 10:07 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 10:07 AM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 10:07 AM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 10:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 10:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 10:10 AM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm	[REDACTED]	1	[REDACTED]
10/3/21 10:10 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS	[REDACTED]	1	[REDACTED]
10/3/21 10:10 AM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly	[REDACTED]	1	[REDACTED]
10/3/21 10:12 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 10:17 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 [REDACTED]
10/3/21 10:17 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/3/21 10:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 10:17 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 10:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 10:17 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 10:17 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 10:17 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 10:17 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/3/21 10:17 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/3/21 10:17 AM	ACK_RTN	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	NULL
10/3/21 10:17 AM	ACK	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	NULL
10/3/21 10:17 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 10:17 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 10:17 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 10:17 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 10:17 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 10:17 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 10:17 AM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 10:17 AM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 10:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 10:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 10:17 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 10:22 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 10:27 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 10:27 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 10:27 AM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	
10/3/21 10:27 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 10:27 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 10:27 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 10:27 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 10:27 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 10:27 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 10:27 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 10:27 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 10:27 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 10:27 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 10:27 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 10:27 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 10:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 10:27 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 10:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 10:27 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 10:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 10:27 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 10:27 AM	ACK_RTN	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	NULL
10/3/21 10:27 AM	ACK	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	NULL
10/3/21 10:27 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 10:27 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 10:27 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 10:27 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 10:27 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 10:27 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 10:27 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 10:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 10:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 10:28 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/3/21 10:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 10:37 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	1	[REDACTED]
10/3/21 10:37 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	1	[REDACTED]
10/3/21 10:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 10:37 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 10:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 10:37 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 10:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 10:37 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 10:37 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/3/21 10:37 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/3/21 10:37 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	1	NULL
10/3/21 10:37 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	1	NULL
10/3/21 10:37 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	1	NULL
10/3/21 10:37 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	1	NULL
10/3/21 10:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 10:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 10:42 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 10:47 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	1	[REDACTED]
10/3/21 10:47 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	1	[REDACTED]
10/3/21 10:47 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 10:47 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 10:47 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 10:47 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 10:47 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 10:47 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 10:47 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 10:47 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 10:47 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 10:47 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 10:47 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 10:47 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 10:47 AM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 10:47 AM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 10:47 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	1	NULL
10/3/21 10:47 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	1	NULL
10/3/21 10:47 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	1	NULL
10/3/21 10:47 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	1	NULL
10/3/21 10:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 10:47 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 10:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 10:47 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 10:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 10:47 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 10:47 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 10:47 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 10:47 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 10:47 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 10:47 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 10:47 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 10:47 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 10:47 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 10:47 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 10:48 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 10:48 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 10:48 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 10:48 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 10:48 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 10:48 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 10:48 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 10:48 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 10:48 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 10:48 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 10:48 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 10:48 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 10:48 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 10:48 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 10:48 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 10:48 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 10:48 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 10:48 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 10:48 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 10:48 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 10:48 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 10:48 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 10:48 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 10:48 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 10:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 10:57 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 10:57 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 10:57 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 10:57 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 10:57 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 10:57 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 10:57 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 10:57 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 10:57 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 10:57 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 10:57 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 10:57 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 10:57 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 10:57 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 10:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 10:57 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 10:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 10:57 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 10:57 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 10:57 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 10:57 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 10:57 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 10:57 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 10:57 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 10:57 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 10:57 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 10:57 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 10:57 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 10:57 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 10:57 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 10:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 10:57 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 11:02 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 11:03 AM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS			1
10/3/21 11:03 AM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly			1
10/3/21 11:03 AM	UNACK_ALM	10_ALM_PS_Omni_Comm	OMNI Pump Station Communication Failure			1
10/3/21 11:03 AM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1
10/3/21 11:07 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 11:07 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 11:07 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/3/21 11:07 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/3/21 11:07 AM	ACK_RTN	10_ALM_PS_Omni_Comm	OMNI Pump Station Communication Failure			1 NULL
10/3/21 11:07 AM	ACK	10_ALM_PS_Omni_Comm	OMNI Pump Station Communication Failure			1 NULL
10/3/21 11:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 11:07 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 11:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 11:07 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 11:07 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 11:07 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 11:07 AM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/3/21 11:07 AM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/3/21 11:07 AM	ACK_RTN	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 11:07 AM	ACK	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly			1 NULL
10/3/21 11:07 AM	ACK_RT	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 11:07 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 11:07 AM	ACK_RT	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 11:07 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 11:07 AM	ACK_RT	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 11:07 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 11:07 AM	ACK_RT	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1 NULL
10/3/21 11:07 AM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1 NULL
10/3/21 11:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 11:07 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 11:07 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1
10/3/21 11:07 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/3/21 11:12 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 11:17 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 11:17 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 11:17 AM	ACK_RT	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 11:17 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 11:17 AM	ACK_RT	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 11:17 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 11:17 AM	ACK_RT	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 11:17 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 11:17 AM	ACK_RT	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 11:17 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 11:17 AM	ACK_RT	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 11:17 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 11:17 AM	ACK_RT	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 11:17 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 11:17 AM	ACK_RT	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 11:17 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 11:17 AM	ACK_RT	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 11:17 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 11:17 AM	ACK_RT	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 11:17 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 11:17 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 11:17 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 11:17 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 11:17 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 11:17 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 11:17 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 11:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 11:17 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 11:18 AM	ACK_RT	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 11:18 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 11:18 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 11:18 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 11:22 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 11:27 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 [REDACTED]
10/3/21 11:27 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/3/21 11:27 AM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 11:27 AM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 11:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 11:27 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 11:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 11:27 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 11:27 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 11:27 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 11:27 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 11:27 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 11:27 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 11:27 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 11:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 11:27 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 11:27 AM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm	[REDACTED]	1	[REDACTED]
10/3/21 11:32 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 11:37 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 [REDACTED]
10/3/21 11:37 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/3/21 11:37 AM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 11:37 AM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 11:37 AM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 11:37 AM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 11:37 AM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 11:37 AM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 11:37 AM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 11:37 AM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 11:37 AM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 11:37 AM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 11:37 AM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 11:37 AM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 11:37 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 11:37 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 11:37 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 11:37 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 11:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 11:37 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 11:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 11:37 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 11:37 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 11:37 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 11:37 AM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 11:37 AM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 11:37 AM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 11:37 AM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 11:37 AM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 11:37 AM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 11:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 11:37 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 11:42 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 11:47 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 11:47 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 11:47 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 11:47 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 11:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 11:47 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 11:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 11:47 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 11:47 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 11:47 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 11:47 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 11:47 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 11:47 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 11:47 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 11:47 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 11:47 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 11:47 AM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 11:52 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 11:57 AM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 11:57 AM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 11:59 AM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 11:59 AM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 11:59 AM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 11:59 AM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 11:59 AM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 11:59 AM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 11:59 AM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 11:59 AM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 11:59 AM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 11:59 AM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40 NULL
10/3/21 11:59 AM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 11:59 AM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 11:59 AM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 11:59 AM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 11:59 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 11:59 AM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 11:59 AM	UNACK_ALM	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 11:59 AM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 12:04 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 12:07 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 12:07 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 12:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:07 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:07 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:07 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:07 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:07 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:07 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:07 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:07 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:07 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:07 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:07 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:07 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:07 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:07 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:07 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:07 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 12:07 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 12:07 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 12:07 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 12:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:07 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 12:07 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:07 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 12:07 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:07 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:07 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:12 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 12:17 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 12:17 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:17 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 12:17 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 12:17 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 12:17 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 12:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:17 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 12:17 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:17 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 12:17 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:17 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 12:17 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:17 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:17 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:17 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 12:17 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 12:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:17 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 12:17 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:17 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:17 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 12:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 12:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 12:17 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/3/21 12:17 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 12:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 12:17 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 12:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 12:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 12:17 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1
10/3/21 12:22 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 12:27 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 12:27 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 12:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 12:27 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 12:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 12:27 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 12:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 12:27 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 12:27 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 12:27 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 12:27 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 12:27 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 12:27 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 12:27 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 12:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 12:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 12:27 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 12:32 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 12:37 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 12:37 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 12:37 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 12:37 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 12:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 12:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 12:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 12:37 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 12:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 12:37 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:37 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 12:37 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 12:37 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 12:37 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 12:37 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 12:37 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 12:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:37 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 12:37 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 12:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:37 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:37 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:37 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:37 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:37 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:37 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:37 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:37 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:37 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:37 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:37 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:37 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:37 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:37 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 12:37 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 12:37 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 12:37 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:37 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:37 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:42 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 12:47 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 12:47 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 12:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:47 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:47 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 12:47 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:47 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 12:47 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 12:47 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 12:47 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 12:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 12:47 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 12:47 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 12:52 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 12:57 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 12:57 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 12:57 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:57 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 12:57 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:57 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 12:57 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:57 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 12:57 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:57 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 12:57 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:57 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 12:57 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:57 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 12:57 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 12:57 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 12:57 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 12:57 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 12:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:57 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 12:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:57 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 12:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:57 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 12:57 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 12:57 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	rar
10/3/21 12:57 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 12:57 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 12:57 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 12:57 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 12:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 12:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 1:00 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 1:00 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 1:00 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 1:00 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 1:00 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 1:00 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 1:00 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 1:00 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 1:00 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 1:00 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 1:00 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 1:00 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 1:00 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:00 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:00 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:00 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:00 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 1:00 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 1:00 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 1:00 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 1:00 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 1:00 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 1:00 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 1:00 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 1:02 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 1:07 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 1:07 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 1:07 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 1:07 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 1:07 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 1:07 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 1:07 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 1:07 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 1:07 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 1:07 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 1:07 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 1:07 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 1:07 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 1:07 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 1:07 PM	ACK_RTN	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 1:07 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 1:07 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 1:07 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 1:07 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 1:07 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 1:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:07 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 1:07 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 1:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:07 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:07 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 1:07 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 1:07 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 1:07 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 1:07 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 1:07 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 1:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 1:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 1:07 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 1:12 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 1:13 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 1:14 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:14 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:14 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 1:14 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 1:14 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:14 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:14 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 1:14 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 1:14 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 1:14 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 1:14 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 1:14 PM	ACK	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	NULL
10/3/21 1:14 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 1:14 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:14 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:14 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:14 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:14 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 1:14 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 1:17 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 1:17 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 1:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 1:17 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 1:17 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 1:17 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 1:17 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 1:17 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 1:17 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 1:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 1:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 1:17 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 1:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 1:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 1:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 1:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 1:19 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 1:20 PM	ACK_RTN	U35_ALM_004	ALM_004 : S387-1: Liq Fuel Press Low - Xfer to Gas		2	
10/3/21 1:20 PM	ACK_RTN	U35_ALMH_020	ALMH_020 : GFMV Gas Fuel Flow Fault		3	
10/3/21 1:20 PM	ACK_RTN	U35_ALMH_019	ALMH_019 : Gas Fuel Metering Valve Position Feedback Fault		3	
10/3/21 1:20 PM	ACK_RTN	U35_ALM_029	ALM_029 : T7 Overtemp		2	
10/3/21 1:20 PM	ACK_RTN	U35_ALM_011	ALM_011 : Fuel Transfer Locked Out		2	
10/3/21 1:20 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:20 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 1:20 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 1:20 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 1:20 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:20 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 1:20 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 1:20 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 1:20 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 1:20 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 1:20 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 1:20 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 1:20 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 1:20 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 1:20 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 1:20 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 1:20 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 1:20 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 1:20 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 1:20 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 1:20 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 1:20 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 1:20 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 1:20 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 1:20 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 1:20 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 1:25 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 1:27 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 1:27 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 1:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 1:27 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 1:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 1:27 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 1:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 1:27 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 1:27 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 1:27 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 1:27 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 1:27 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 1:27 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 1:27 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 1:27 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 1:27 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 1:27 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 1:27 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 1:27 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 1:27 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 1:27 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 1:27 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 1:27 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 1:27 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 1:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 1:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 1:27 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 1:27 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 1:27 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 1:27 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 1:27 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 1:27 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 1:32 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 1:37 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 [REDACTED]
10/3/21 1:37 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/3/21 1:37 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 NULL
10/3/21 1:37 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 NULL
10/3/21 1:37 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 NULL
10/3/21 1:37 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 NULL
10/3/21 1:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/3/21 1:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/3/21 1:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1 NULL	
10/3/21 1:37 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1 NULL	
10/3/21 1:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1 NULL	
10/3/21 1:37 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1 NULL	
10/3/21 1:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 1:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 1:42 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 1:43 PM	UNACK_ALM	14_ALM_Atmos_Comm_Fail_PS_PLC	Atmos Communications Failure to Beta PS PLC 5	[REDACTED]	500	[REDACTED]
10/3/21 1:47 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 [REDACTED]
10/3/21 1:47 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/3/21 1:47 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 NULL
10/3/21 1:47 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 NULL
10/3/21 1:47 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 NULL
10/3/21 1:47 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 NULL
10/3/21 1:47 PM	ACK_RTN	14_ALM_Atmos_Comm_Fail_PS_PLC	Atmos Communications Failure to Beta PS PLC 5		500 NULL	
10/3/21 1:47 PM	ACK	14_ALM_Atmos_Comm_Fail_PS_PLC	Atmos Communications Failure to Beta PS PLC 5		500 NULL	
10/3/21 1:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/3/21 1:47 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/3/21 1:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1 NULL	
10/3/21 1:47 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1 NULL	
10/3/21 1:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1 NULL	
10/3/21 1:47 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1 NULL	
10/3/21 1:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 1:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 1:52 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 1:57 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm	[REDACTED]	1 [REDACTED]
10/3/21 1:57 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 [REDACTED]
10/3/21 1:58 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1 NULL	
10/3/21 1:58 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1 NULL	
10/3/21 1:58 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/3/21 1:58 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/3/21 1:58 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1 NULL	
10/3/21 1:58 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1 NULL	
10/3/21 1:58 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1 NULL	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 1:58 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 1:58 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 1:58 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 1:58 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 1:58 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 1:58 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 1:58 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 1:58 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 1:58 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 1:58 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 1:58 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 1:58 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 1:58 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 1:58 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 1:58 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 1:58 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 1:58 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 1:58 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 1:58 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 1:58 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 1:58 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 1:58 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 1:58 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 1:58 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 1:58 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 1:58 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1
10/3/21 2:03 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 2:07 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1
10/3/21 2:07 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 2:07 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1
10/3/21 2:07 PM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1 NULL
10/3/21 2:07 PM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1 NULL
10/3/21 2:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 2:07 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 2:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 2:07 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 2:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 2:07 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 2:07 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 2:07 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 2:07 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 2:07 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	10 Inch Pipeline 24 Hour Leak Detect Alarm		1 NULL
10/3/21 2:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 2:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 2:07 PM	UNACK_ALM	U36_ALM_039	ALM_039 : PT341: Fuel Gas Header Pressure LowLow	[REDACTED]	2	[REDACTED]
10/3/21 2:12 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 2:17 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	[REDACTED]	1	[REDACTED]
10/3/21 2:17 PM	UNACK_ALM	20_ALM_LDS_24_HR	Eureka to Elly	[REDACTED]	1	[REDACTED]
10/3/21 2:17 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	[REDACTED]	1	NULL
10/3/21 2:17 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	[REDACTED]	1	NULL
10/3/21 2:17 PM	ACK_RTN	20_ALM_LDS_24_HR	Eureka to Elly	[REDACTED]	1	NULL
10/3/21 2:17 PM	ACK	20_ALM_LDS_24_HR	Eureka to Elly	[REDACTED]	1	NULL
10/3/21 2:17 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm	[REDACTED]	1	NULL
10/3/21 2:17 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm	[REDACTED]	1	NULL
10/3/21 2:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:17 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:17 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm	[REDACTED]	1	NULL
10/3/21 2:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:22 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:24 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm	[REDACTED]	1	NULL
10/3/21 2:27 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature	[REDACTED]	1	NULL
10/3/21 2:27 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature	[REDACTED]	1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 2:27 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 2:27 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 2:27 PM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1 NULL
10/3/21 2:27 PM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm			1 NULL
10/3/21 2:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 2:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 2:27 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 2:27 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 2:27 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 2:27 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 2:27 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 2:27 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 2:27 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1
10/3/21 2:32 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 2:34 PM	UNACK_ALM	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm			1
10/3/21 2:34 PM	UNACK_ALM	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure			1
10/3/21 2:34 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 2:34 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 2:34 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 2:34 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 2:34 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 2:34 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 2:34 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 2:34 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 2:34 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 2:34 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 2:34 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 2:34 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 2:34 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 2:34 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 2:34 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 2:34 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 2:34 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 2:34 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 2:34 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 2:34 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 2:34 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 2:34 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 2:34 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 2:34 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 2:34 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 2:34 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 2:37 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 2:37 PM	UNACK_ALM	U35_SDFSLO_000	SDFSLO_000 : Fail to Crank	[REDACTED]	1	[REDACTED]
10/3/21 2:38 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 2:38 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 2:38 PM	ACK_RTN	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/3/21 2:38 PM	ACK	50_ALM_CEMS_Priority_2	CEMS Priority #2 Alarm		1	NULL
10/3/21 2:38 PM	ACK_RTN	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	NULL
10/3/21 2:38 PM	ACK	50_ALM_Sat_NP10A_Dsl_Switch_Fail	NP10A Diesel Switch Failure		1	NULL
10/3/21 2:38 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 2:38 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 2:38 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 2:38 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 2:38 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 2:38 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 2:39 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 2:47 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 [REDACTED]
10/3/21 2:47 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 2:47 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	NULL
10/3/21 2:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 2:47 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 2:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 2:47 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 2:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 2:47 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 2:47 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 2:47 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 2:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 2:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 2:47 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm	[REDACTED]	1	[REDACTED]
10/3/21 2:53 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 2:57 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 [REDACTED]
10/3/21 2:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 2:57 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 2:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 2:57 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 2:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 2:57 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 2:57 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 2:57 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 2:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 2:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 3:02 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 3:07 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 [REDACTED]
10/3/21 3:07 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:07 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 3:07 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 3:07 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 3:07 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 3:07 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 3:07 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 3:07 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 3:07 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 3:07 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 3:07 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 3:07 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 3:07 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 3:07 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 3:07 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/3/21 3:07 PM	ACK	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1 NULL
10/3/21 3:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 3:07 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 3:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 3:07 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 3:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 3:07 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 3:07 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 3:07 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 3:07 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 3:07 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 3:07 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 3:07 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 3:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 3:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 3:07 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm			1
10/3/21 3:12 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 3:17 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 3:17 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 3:17 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1 NULL
10/3/21 3:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 3:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 3:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 3:17 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 3:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 3:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 3:17 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 3:17 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 3:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:17 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 3:22 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 3:26 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/3/21 3:26 PM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	
10/3/21 3:26 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/3/21 3:26 PM	UNACK_ALM	14_ALM_Atmos_Comm_Fail_PS_PL	Atmos Communications Failure to Beta PS PLC 5		500	
10/3/21 3:27 PM	UNACK_ALM	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	
10/3/21 3:27 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 3:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:27 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:27 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:27 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:27 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:27 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/3/21 3:27 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/3/21 3:27 PM	ACK_RTN	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	NULL
10/3/21 3:27 PM	ACK	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	NULL
10/3/21 3:27 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 3:27 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 3:27 PM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 3:27 PM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 3:27 PM	ACK_RTN	14_ALM_Atmos_Comm_Fail_PS_PL	Atmos Communications Failure to Beta PS PLC 5		500	NULL
10/3/21 3:27 PM	ACK	14_ALM_Atmos_Comm_Fail_PS_PL	Atmos Communications Failure to Beta PS PLC 5		500	NULL
10/3/21 3:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:27 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:27 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/3/21 3:28 PM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	
10/3/21 3:28 PM	UNACK_ALM	10_ALM_PS_Omni_Comm	OMNI Pump Station Communication Failure		1	
10/3/21 3:28 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/3/21 3:28 PM	UNACK_ALM	14_ALM_Atmos_Comm_Fail_PS_PL	Atmos Communications Failure to Beta PS PLC 5		500	
10/3/21 3:32 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 3:37 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 3:37 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:37 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 3:37 PM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 3:37 PM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 3:37 PM	ACK_RTN	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	NULL
10/3/21 3:37 PM	ACK	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	NULL
10/3/21 3:37 PM	ACK_RTN	14_ALM_Atmos_Comm_Fail_PS_PL	Atmos Communications Failure to Beta PS PLC 5		500	NULL
10/3/21 3:37 PM	ACK	14_ALM_Atmos_Comm_Fail_PS_PL	Atmos Communications Failure to Beta PS PLC 5		500	NULL
10/3/21 3:37 PM	ACK_RTN	10_ALM_PS_Omni_Comm	OMNI Pump Station Communication Failure		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:37 PM	ACK	10_ALM_PS_Omni_Comm	OMNI Pump Station Communication Failure			1 NULL
10/3/21 3:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 3:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 3:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 3:37 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 3:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 3:37 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 3:37 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/3/21 3:37 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/3/21 3:37 PM	ACK_RTN	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly			1 NULL
10/3/21 3:37 PM	ACK	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly			1 NULL
10/3/21 3:37 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 3:37 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 3:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:37 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 3:42 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 3:47 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 3:47 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:47 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 3:47 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:47 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 3:47 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:47 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 3:47 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:47 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 3:47 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:47 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 3:47 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:47 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 3:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:47 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 3:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:47 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 3:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:47 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 3:47 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 3:47 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 3:47 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 3:47 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 3:47 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 3:47 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 3:47 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 3:47 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 3:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 3:52 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 3:57 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 3:57 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 3:57 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 3:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/3/21 3:57 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/3/21 3:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1 NULL	
10/3/21 3:57 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1 NULL	
10/3/21 3:57 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1 NULL	
10/3/21 3:57 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1 NULL	
10/3/21 3:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 3:57 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 4:02 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 4:07 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1
10/3/21 4:07 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1 NULL	
10/3/21 4:07 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1 NULL	
10/3/21 4:07 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1 NULL	
10/3/21 4:07 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1 NULL	
10/3/21 4:07 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1 NULL	
10/3/21 4:07 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1 NULL	
10/3/21 4:07 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1 NULL	
10/3/21 4:07 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1 NULL	
10/3/21 4:07 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1 NULL	
10/3/21 4:07 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1 NULL	
10/3/21 4:07 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1 NULL	
10/3/21 4:07 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1 NULL	
10/3/21 4:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/3/21 4:07 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1 NULL	
10/3/21 4:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1 NULL	
10/3/21 4:07 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1 NULL	
10/3/21 4:07 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1 NULL	
10/3/21 4:07 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1 NULL	
10/3/21 4:07 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 4:07 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 4:07 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 4:07 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 4:07 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 4:07 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 4:07 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL
10/3/21 4:07 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour		1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 4:07 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 4:12 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 4:17 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 [REDACTED]
10/3/21 4:17 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 4:17 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 4:17 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:17 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 4:17 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:17 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 4:17 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:17 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 4:17 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:17 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 4:17 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:17 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 4:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:17 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 4:17 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 4:17 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:17 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 4:17 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.	[REDACTED]	1	[REDACTED]
10/3/21 4:17 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure	[REDACTED]	1	[REDACTED]
10/3/21 4:17 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure	[REDACTED]	1	[REDACTED]
10/3/21 4:17 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature	[REDACTED]	1	[REDACTED]
10/3/21 4:17 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed	[REDACTED]	1	[REDACTED]
10/3/21 4:17 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed	[REDACTED]	1	[REDACTED]
10/3/21 4:17 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 NULL
10/3/21 4:17 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 NULL
10/3/21 4:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 4:17 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 4:22 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position	[REDACTED]	1	[REDACTED]
10/3/21 4:27 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS	[REDACTED]	1	[REDACTED]
10/3/21 4:27 PM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly	[REDACTED]	1	[REDACTED]
10/3/21 4:37 PM	UNACK_ALM	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 24 Hour	[REDACTED]	1 [REDACTED]
10/3/21 4:37 PM	ACK_RTN	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 4:37 PM	ACK	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 4:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:37 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 4:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 4:37 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 4:37 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:37 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 4:37 PM	ACK_RTN	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly			1 NULL
10/3/21 4:37 PM	ACK	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly			1 NULL
10/3/21 4:37 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/3/21 4:37 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS			1 NULL
10/3/21 4:37 PM	ACK_RTN	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni		Eu_Elly Leak Detect 24 Hour	1 NULL
10/3/21 4:37 PM	ACK	20_ALM_LDS_Omni_24_Hr	Alarm -- From Omni		Eu_Elly Leak Detect 24 Hour	1 NULL
10/3/21 4:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 4:37 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 4:37 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%			1
10/3/21 4:42 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1
10/3/21 4:44 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm			40
10/3/21 4:44 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 4:44 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 4:44 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 4:44 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position			1 NULL
10/3/21 4:44 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 4:44 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 4:44 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 4:44 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1 NULL
10/3/21 4:44 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 4:44 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1 NULL
10/3/21 4:44 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 4:44 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1 NULL
10/3/21 4:44 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 4:44 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1 NULL
10/3/21 4:44 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 4:44 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1 NULL
10/3/21 4:44 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 4:44 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1 NULL
10/3/21 4:44 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1
10/3/21 4:44 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1
10/3/21 4:44 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.			1
10/3/21 4:44 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure			1
10/3/21 4:44 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed			1
10/3/21 4:44 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed			1
10/3/21 4:44 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure			1
10/3/21 4:44 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature			1
10/3/21 4:44 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 4:44 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position			1 NULL
10/3/21 4:44 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 4:44 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1 NULL
10/3/21 4:44 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position			1

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 4:44 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 4:49 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 5:17 PM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	
10/3/21 5:17 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/3/21 5:17 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/3/21 5:17 PM	UNACK_ALM	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	
10/3/21 5:17 PM	UNACK_ALM	14_ALM_Atmos_Comm_Fail_PS_PL	Atmos Communications Failure to Beta PS PLC 5		500	
10/3/21 5:44 PM	ACK_RT	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 5:44 PM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 5:44 PM	ACK_RT	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	NULL
10/3/21 5:44 PM	ACK	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	NULL
10/3/21 5:44 PM	ACK_RT	14_ALM_Atmos_Comm_Fail_PS_PL	Atmos Communications Failure to Beta PS PLC 5		500	NULL
10/3/21 5:44 PM	ACK	14_ALM_Atmos_Comm_Fail_PS_PL	Atmos Communications Failure to Beta PS PLC 5		500	NULL
10/3/21 5:44 PM	ACK_RT	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 5:44 PM	ACK	30_ALM_TankLvL_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	NULL
10/3/21 5:44 PM	ACK_RT	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:44 PM	ACK	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	NULL
10/3/21 5:44 PM	ACK_RT	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:44 PM	ACK	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	NULL
10/3/21 5:44 PM	ACK_RT	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:44 PM	ACK	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	NULL
10/3/21 5:44 PM	ACK_RT	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/3/21 5:44 PM	ACK	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	NULL
10/3/21 5:44 PM	ACK_RT	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	NULL
10/3/21 5:44 PM	ACK	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	NULL
10/3/21 5:44 PM	ACK_RT	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 5:44 PM	ACK	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	NULL
10/3/21 5:44 PM	ACK_RT	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:44 PM	ACK	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	NULL
10/3/21 5:44 PM	ACK_RT	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:44 PM	ACK	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	NULL
10/3/21 5:44 PM	ACK_RT	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:44 PM	ACK	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	NULL
10/3/21 5:44 PM	ACK_RT	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:44 PM	ACK	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	NULL
10/3/21 5:44 PM	ACK_RT	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:44 PM	ACK	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	NULL
10/3/21 5:44 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 5:44 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 5:44 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 5:44 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 5:44 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 5:44 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 5:44 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 5:44 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 5:44 PM	UNACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 5:49 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 6:14 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/3/21 6:14 PM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	
10/3/21 6:14 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/3/21 6:14 PM	UNACK_ALM	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	
10/3/21 6:40 PM	UNACK_ALM	50_ALM_CEMS_Pilot_B_Low_Flare	CEMS Pilot B Low Flare Alarm		1	
10/3/21 6:47 PM	ACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 6:47 PM	ACK_ALM	U35_SDFSLO_000	SDFSLO_000 : Fail to Crank		1	
10/3/21 6:47 PM	ACK_ALM	U36_ALM_039	ALM_039 : PT341: Fuel Gas Header Pressure LowLow		2	
10/3/21 6:47 PM	ACK_ALM	50_ALM_CEMS_Pilot_B_Low_Flare	CEMS Pilot B Low Flare Alarm		1	
10/3/21 6:47 PM	ACK_ALM	30_ALM_TankLvl_Low_S06	Alarm -- S06 Tank Level Low < 30%		1	
10/3/21 6:47 PM	ACK_ALM	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	
10/3/21 6:47 PM	ACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/3/21 6:47 PM	ACK_ALM	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	
10/3/21 6:47 PM	ACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/3/21 6:47 PM	ACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 6:47 PM	ACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 6:47 PM	ACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 6:47 PM	ACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 6:47 PM	ACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 6:47 PM	ACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 6:47 PM	ACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 6:47 PM	ACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 6:47 PM	ACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 6:47 PM	ACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 6:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 6:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 6:47 PM	ACK_RTN	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 6:47 PM	ACK_RTN	10_ALM_Comm_Fail_to_EllyLDS_PL	Communications Failure from Beta PS to Elly_LDS		1	
10/3/21 6:47 PM	ACK_RTN	10_ALM_Comm_Failure_to_Elly_PL	Communications Failure from Beta PS to Elly		1	
10/3/21 6:47 PM	ACK_RTN	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 6:47 PM	ACK_RTN	50_ALM_CEMS_Pilot_B_Low_Flare	CEMS Pilot B Low Flare Alarm		1	
10/3/21 6:47 PM	ACK_RTN	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 6:47 PM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/3/21 6:47 PM	ACK_RTN	14_ALM_Atmos_Comm_Fail_PS_Omni	Atmos Communications to Beta PS Omni Failure		1	
10/3/21 6:47 PM	ACK_RTN	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 6:47 PM	ACK_RTN	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 6:47 PM	ACK_RTN	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 6:47 PM	ACK_RTN	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 6:47 PM	ACK_RTN	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 6:47 PM	ACK_RTN	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 6:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V540	Beta PS Valve V540 Failed to Reach Position		1	
10/3/21 6:47 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V520	Beta PS Valve V520 Failed to Reach Position		1	
10/3/21 6:47 PM	UNACK_ALM	91_Alm_V02B_Water_Vlv_100_Pos	Warning--V02B Water Out Valve Opened Over 90% for 10 sec.		1	
10/3/21 6:47 PM	UNACK_ALM	91_Alm_TrainB_FWKO_Press_Lo	Alarm--Train B FWKO Low Pressure		1	
10/3/21 6:47 PM	UNACK_ALM	91_Alm_V01B_Water_Vlv_Pos	Warning--V01B Water Out Valve Closed		1	
10/3/21 6:47 PM	UNACK_ALM	91_Alm_V01B_Oil_Vlv_Pos	Warning--V01B Oil Out Valve Closed		1	
10/3/21 6:47 PM	UNACK_ALM	91_Alm_TrainB_Treat_Press_Lo	Alarm--Train B Treater Low Pressure		1	
10/3/21 6:47 PM	UNACK_ALM	91_Alm_TrainB_X04B_Temp_Low	Alarm--Train B Emul Heater X04B Low Temperature		1	
10/3/21 6:47 PM	UNACK_ALM	85_ALM_TestTreatA_Gas_Low_Press	PIC V03A Low Pressure Alarm		1	
10/3/21 6:47 PM	UNACK_ALM	40_ALM_Palace_Low_Press	Ellen Palace Low Pressurization Alarm		40	
10/3/21 6:52 PM	UNACK_ALM	10_ALM_Valve_PositionFail_V530	Beta PS Valve V530 Failed to Reach Position		1	
10/3/21 7:08 PM	UNACK_ALM	10_ALM_Comm_Fail_to_EllyLDS_PLC	Communications Failure from Beta PS to Elly_LDS		1	
10/3/21 7:08 PM	UNACK_ALM	10_ALM_Comm_Failure_to_Elly_PLC	Communications Failure from Beta PS to Elly		1	
10/3/21 7:13 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/3/21 8:15 PM	UNACK_ALM	14_ALM_Atmos_Comm_Fail_PS_PLC	Atmos Communications Failure to Beta PS PLC 5		500	
10/3/21 11:05 PM	UNACK_ALM	U35_ALM_039	ALM_039 : PT341: Fuel Gas Header Pressure LowLow		2	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 5:43 AM	UNACK ALM	10 ALM Leak Detect From Atmos	Signal from Atmos -- LEAK DETECTED			1 [REDACTED]
10/2/21 5:59 AM	ACK RTN	10 ALM Leak Detect From Atmos	Signal from Atmos -- LEAK DETECTED			1 NULL
10/2/21 5:59 AM	ACK	10 ALM Leak Detect From Atmos	Signal from Atmos -- LEAK DETECTED			1 NULL
10/2/21 5:59 AM	UNACK ALM	10 ALM Leak Detect From Atmos	Signal from Atmos -- LEAK DETECTED			1 [REDACTED]
10/2/21 7:01 AM	ACK RTN	14 ALM Atmos Leak Detected	Atmos -- LEAK DETECTED			1 NULL
10/2/21 7:01 AM	ACK	14 ALM Atmos Leak Detected	Atmos -- LEAK DETECTED			1 NULL
10/2/21 7:01 AM	ACK RTN	10 ALM Leak Detect From Atmos	Signal from Atmos -- LEAK DETECTED			1 NULL
10/2/21 7:01 AM	ACK	10 ALM Leak Detect From Atmos	Signal from Atmos -- LEAK DETECTED			1 NULL

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/2/21 8:47 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:47 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8:47 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8:47 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8 57 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8 57 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8 57 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8 57 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 8 57 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 8 57 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9 07 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 9 07 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9 07 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 9 07 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 9 07 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9 07 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:17 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 9:17 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:17 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 9:17 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 9:17 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:17 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:27 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:27 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:27 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:37 PM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:37 PM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 9:38 PM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:38 PM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/2/21 9:38 PM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 9:38 PM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/2/21 9:46 PM	ACK_RTN	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	
10/2/21 10 03 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/2/21 10 05 PM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1 NULL	
10/2/21 10 05 PM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1 NULL	
10/2/21 11:28 PM	UNACK_ALM	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	
10/2/21 11:37 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	
10/2/21 11 50 PM	ACK_RTN	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1 NULL	
10/2/21 11 50 PM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1 NULL	
10/3/21 3:27 AM	UNACK_ALM	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/3/21 3:27 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/3/21 3:27 AM	ACK_RTN	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/3/21 3:27 AM	ACK	20_ALM_LDS_Omni_10_MIN	Alarm -- From Omni	Eu_Elly Leak Detect 10 Minute		1 NULL
10/3/21 3:27 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/3/21 3:27 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/3/21 3:37 AM	UNACK_ALM	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/3/21 3:37 AM	ACK_RTN	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/3/21 3:37 AM	ACK	20_ALM_LDS_Omni_1_Hr	Alarm -- From Omni	Eu_Elly Leak Detect 1 Hour		1 NULL
10/3/21 3:42 AM	ACK_RTN	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1 NULL	
10/3/21 3:42 AM	ACK	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1 NULL	
10/3/21 4:04 AM	UNACK_ALM	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	
10/3/21 4:25 AM	ACK_ALM	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	
10/3/21 4:35 AM	ACK_RTN	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	
10/3/21 5:11 AM	UNACK_ALM	U36_ALM_041	ALM_041 : SPARE		2	
10/3/21 5:14 AM	ACK_RTN	U36_ALM_041	ALM_041 : SPARE		2 NULL	
10/3/21 5:14 AM	ACK	U36_ALM_041	ALM_041 : SPARE		2 NULL	
10/3/21 5:51 AM	UNACK_ALM	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	
10/3/21 5:51 AM	ACK_ALM	24_Elly_BPV_Pipeline_Press_Lo	Elly BPV Pipeline Pressure Low Alarm		1	

EventStamp	AlarmState	TagName	Description	Operator	Priority	UserFullName
10/3/21 6:47 PM	ACK	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm		1	NULL
10/3/21 7:13 PM	UNACK_ALM	11_ALM_Ship_Read_PS	Shipping Read From Pump Station Alarm	██████████	1	██████████