

Factual Report – Attachment 3 FAA Technical Operations Log

AIR TRAFFIC CONTROL

DCA19FA089

Details

Log Record Information

Log ID 2023726003 Record Status C Audit/Seq No Audit Logs ▼

Event Type N/A

Start Date 03/04/2019 22:55z **Created Date** 03/05/2019 01:58z Mod Date 03/05/2019 01:58z

SAL Sync Date 03/05/2019 01:39z

Coord Required False

Cat/Suppl/MAC 3//

> End Date 03/05/2019 00:05z 0 Days 1 Hrs 10 Mins Duration

Mod By <u>christopher.lundstrom@faa.gov</u>

Location Information

Fac ID PQI SvcArea/Dir Eastern Fac Type LOC ATOW Location PRESQUE ISLE, ME <u>WEP44</u> Arpt/Rwy -/01 ATOW Desc BANGOR B SSC Work Area NAVAID

Fac Desc LOCALIZER

Log Summary Information

No summary information available

Comments A

1 Comments

Date Name Comment 03/05/2019 01:58:39z CHRISTOPHER LUNDSTROM

Found facility operating within normal parameters with the exception of radiated ground check signals. Ground check readings at edge of course and centerline indicate a course shift into the 150hz side, possibly caused by large snow pack and snow banks in the vicinity of the localizer

antenna array.

Related Logs ▼