

MEMORANDUM FOR RECORD

Timothy W. Monville Sr. Air Safety Investigator Eastern Region

Date: 6/21/2023 NTSB Accident Number: ERA23FA067

Medical and Pathological Information:

An autopsy of the pilot was performed by the Wake Forest Baptist Medical Center, Winston-Salem, North Carolina. The cause of death was multiple blunt force injuries.