

MEMORANDUM FOR RECORD

Michael J. Folkerts Aviation Accident Investigator Central Region

NTSB Accident Number: CEN21FA299

An autopsy of the pilot was performed by the Iowa Office of the State Medical Examiner, Ankeny, Iowa. The cause of death was thermal injuries and smoke inhalation.