

MEMORANDUM FOR RECORD

Aaron Sauer Sr. Air Safety Investigator Central Region

Date: 04/06/22 NTSB Accident Number: CEN22FA109

An autopsy of the pilot was performed by the Clinical Laboratory of the Black Hills, Rapid City, South Dakota, which listed the cause of death as blunt trauma injury sustained in a plane crash.

MEMORANDUM OF RECORD