

Career Employee Discipline Report

SHUSTER, LOUIS - [REDACTED]

This Report comes from one Data Source: **TIMS is Blue**

DISP DATE	LOCATION	ASSGN/TRN	RULE	DISCIPLINE DESCRIPTION	OFCR
11/25/2008	Nsr2.0	BX22	104	START MINOR - Failure to ensure switch was line for movement resulting in run through switch on 11/21/08 while assigned to BX22. AH-Counseled.	[REDACTED]
01/16/2009	Cd182.5	BR28		START MINOR - Riding shove move through close clearance on 12/19/08 while serving as crew member on BR28. AH-Counseled.	[REDACTED]
05/13/2009	Bedford	327	1100C	START MINOR - Released handbrake from the ground on 4/22/09 while assigned as crew member on 327. AH-Counseled.	[REDACTED]
03/07/2011	Cd 197	BX18		Waiver - START SERIOUS 10 Days deferred suspension. Failure to have proper clearance when walking around the end of standing equipment on 2/21/11 while serving as crew membr on BX18.	[REDACTED]
05/06/2019	Cleveland, Oh	CX21		Investigation - Start Serious, 10 Day Deferred Suspension - Failure to properly and/or safely perform your duties when you made repeated attempts to operate a hand throw switch on April 14, 2019 at approximately 5:10 PM in the vicinity of Cleveland Terminal, while you were serving as Conductor on assignment CX21.	
06/01/2019	Cleveland, Oh	CX01		Signed Waiver - Start Minor - Failure to notify your engineer prior to dismounting moving equipment on May 8, 2019 at approximately 10:10 AM in the vicinity of Cleveland Terminal, while you were serving as Conductor on Train CX01.	
06/01/2019	Cleveland, Oh	CX01		Signed Waiver - Start Serious, 14 Day Actual Suspension - Causing intentional delay to Carrier operations at various locations throughout your tour of duty on May 9, 2019, while serving as crewmembers on Train CX01-09 on duty at 6:30 AM, in the vicinity of Rockport Yard, Cleveland, Ohio. First knowledge of this incident occurred on May 10, 2019.	
06/08/2020	Cleveland, Oh	CF17	HM2-T.4	START Minor - Failure to possess and update position-in-train documentation at approximately 1:30 PM on December 27, 2019, while serving as foreman on assignment CF17 in the vicinity of Cleveland Ohio.	[REDACTED]
07/15/2020	Cleveland Term	CR01	1100 (f)	START Minor - Failure to properly transport brake stick in the collapsed and locked position at approximately 1:00 PM on July 8, 2020, while serving as conductor on assignment CR01 in the vicinity of Cleveland Terminal.	[REDACTED]
07/22/2020			919	Failure to maintain an acceptable work record for the period of April 26, 2020 through June 26, 2020. 7/22/20 - Letter of Reprimand.	[REDACTED]

Career Employee Discipline Report

SHUSTER, LOUIS - [REDACTED]

This Report comes from one Data Source: **TIMS is Blue**

DISP DATE	LOCATION	ASSGN/TRN	RULE	DISCIPLINE DESCRIPTION	OFCR
05/03/2022				LOC-Miss Call Step 1-This is to confirm conversation concerning your non-compliance with Safety & General Conduct Rules 920 when you missed your call on 04/21/2022.	[REDACTED]
01/24/2023	Rockport Yard	C69B1		START Minor - failure to comply with switch-derail flag test, per bulletined instructions KSOP-019.	[REDACTED]