



The reported wind at the time of the accident was from 080 degrees at 9 knots, gusting to 22 knots. The pilot was landing on runway 17R. The maximum demonstrated crosswind component was 19 knots.