

## **RECORD OF CONVERSATION**

Eleazar Nepomuceno Air Safety Investigator General Aviation Accident Division

Date: 10/1/2020 Person Contacted: Chad Miller (Director of Maintenance) NTSB Accident Number: WPR20CA298

## Narrative:

The following is a synopsis of the information provided by the Director of Maintenance (DOM) in a telephone conversation on this date:

- The DOM reported that there were no preimpact mechanical failures or malfunctions that would have precluded normal operation.
- He further stated that the sheared inner tube valve was consistent with the loss of directional control.