

RECORD OF <input checked="" type="checkbox"/> VISIT <input type="checkbox"/> CONFERENCE OR <input type="checkbox"/> TELEPHONE CALL		TIME 10:30 AM	DATE 08/20/2019
NAME (S) OF PERSON (S) CONTACTED OR IN CONFERENCE AND LOCATION		ROUTING	
		SYMBOL	INITIALS
Inspection by Inspectors Brian Lord and Keith Rittenberry at Burns			
Municipal Airport (KBNO)			
SUBJECT Inspection of glider N112AV			
DIGEST			
Inspectors Inspectors Brian Lord and Keith Rittenberry traveled to burns Municipal Airport			
to inspect N122AV glider damaged in an accident 7/17/2019. Inspection of the aircraft as			
follows:			
Aircraft was substantially damaged. All major portions of the aircraft was accounted for.			
The wing attachment pin was located in multiple pieces. One section was embedded in the			
wing spar at the alignment hole. Inspection of the control system showed no anomalies not			
related to the aircraft accident.			
CONCLUSION, ACTION TAKEN, OR REQUIRED			
Additional photos supplied by the Harney County Sheriffs Office substantiated that the			
aircraft was intact before impact. No anomalies appeared in the photos as for the aircraft			
itself however the photo's indicate the tow rope was not kept tight during the launch,			
reducing forward momentum and causing an eventual stall. The crash was amplified by the tow			
rope becoming tight as the aircraft rolled left, driving the aircraft into the ground.			
DATE 08/20/2019	TITLE ASI Edwin Brian Lord	SIGNATURE 	