

Elliott Simpson  
Senior Aviation Accident Investigator  
WPR-AS

**Date:** June 27, 2022

**Subject:** WPR22FA229 Kerrville Aviation FBO Video Camera

The security camera video that faced south to the ramp of Kerrville Aviation was reviewed, and the following was observed. The recorded date was June 25, 2022. Technical difficulties prevented copying of the file. The video was not continuous, but appeared to record specific movement, therefore only sporadic events were recorded. The recording did not show the airplane taxiing away from the ramp.

*1734 - Pilot enters the airplane, then appears to walk around, and perform a preflight inspection.*

*1742:30 - Passenger boards the airplane.*

*1743:30 - Pilot boards the airplane.*

*1747:30 - Propeller turns, engine does not start.*

*1748:20 - Propeller turns, engine does not start.*

*1748:50 - Propeller turns, engine does not start.*

*1749:38 - Propeller turns, engine does not start.*

*1750:11 - Propeller turns, engine does not start.*

*1751:52 - Door opens, then closes.*

*1751:18 - Propeller turns, engine does not start.*

1752:29 - Propeller turns, engine does not start.

1753:04 - Propeller turns, engine does not start.

1754:25 - Propeller turns, engine does not start.

1755:14 - Propeller turns, engine does not start.

1755:51 - Propeller turns, engine does not start.

1756:02 - Propeller turns, engine does not start.

1757:00 - Pilot gets out of the airplane and appears to open the left then right fuel filler caps.

1800 - Pilot gets back into airplane and then restart engine attempt.

1801 - Propeller turns, engine does not start.

1801:45 - Propeller turns, engine does not start.

1802:15 - Propeller turns, engine does not start.

1802:32 - Engine starts.

1802:39 - Video ends.