



NATIONAL TRANSPORTATION SAFETY BOARD
Central Region - Denver, Colorado

Record of Telephone Conversation
Person Interviewed: Tony Onesti
Date: February 28, 2019

Mr. Onesti stated that the pilot encountered an autopilot issue about 3 months before the accident. The pilot recounted to Mr. Onesti that he was at 15,000 ft with the autopilot on when the airplane nosed over and descended rapidly in a stalled condition. The pilot as able to recover, though the details of the recovery were not available. The pilot then took the airplane in for maintenance to fix the issue and during a flight before the holiday, it was understood that the problem was fixed.

Jennifer S. Rodi
National Transportation Safety Board
Senior Air Safety Investigator