

Friday, Feb. 23, 2018-3534 Espanola Dr. (Explosion at Home reported)

- 06:38 a.m.-Female neighbor (English speaker) residing near 3534 Espanola Drive calls 911 to report that a home across from her house situated at 3533 Espanola Dr. has exploded. Separate 911 call handled includes a frantic woman (English speaker) reporting that she also heard an explosion near her home. Multiple calls handled by 911 including one placed by a Spanish speaking female who was reporting a house on fire. Two other callers (English speakers) called to report that other incidents involving fires or explosions had occurred in their neighborhood and that they thought there were problems with the gas lines. Fire Dispatcher T. Murphy notified Atmos that there were multiple homes that may be on fire in the vicinity where the explosion was reported.
- 6:38 Engine 35 En route and on location at 06:44 along with other first alarm companies (En 43, En 30 and Truck 41)
- 06:39 Fire dispatcher reports that all units are en route and that multiple 911 calls have been placed to report the emergency.
- 06:42 Gas Utility summoned to the scene
- 06:44-45 Engine 43 officer's size up included that he was viewing a one story house with much structural damage. Fire Dispatcher advised that multiple homes were reported to have been damaged as well (this was attributed to miscommunication between 911 callers and 911 call handlers). Engine 43 requests 3 ambulances to their location. Battalion Chief (09) asks while en route if the gas company has been summoned-Fire Dispatcher acknowledges that this has happened.
- 06:45-Battalion 7 reports out with size up of single story home with a lot of structural damage but no visible fire or smoke.
- 06:48 Electric utility summoned to the scene

FIRE INVESTIGATION REPORT

DALLAS FIRE-RESCUE DEPARTMENT
Fire Investigation and Explosive Ordnance Disposal Division

1551 Baylor Street #500
Dallas, Texas 75226
Phone Number (214) 670-4312
Fax Number (214) 670-4650

Council District: 8
Census Tract: 09802
Zip Code: 75220

COPY

Date: 02/23/2018	Time of Alarm: 06:38	District/Shift: 7/C	Mapsc0: 23-V
Incident Number: 2018049283		Investigator (s): Westbrook/Gardner	
Address: 3534 Espanola Dr			
Apartment / Suite Number:	Exposure:	Same Building:	
Business Name:			

Property Owner: [REDACTED]	Rep:
Occupant:	Rep:

Type

Structure <input checked="" type="checkbox"/>	1 Story W/F Single Family Dwelling	Construction Type III
Non-Structure <input type="checkbox"/>		
Criminal Attempt <input type="checkbox"/>	Terroristic Threat <input type="checkbox"/>	False Alarm <input type="checkbox"/>
Injury <input checked="" type="checkbox"/>	Number of injuries 4	Death <input checked="" type="checkbox"/> Number of deaths 1
Multiple Alarm	Select one:	Out Taps 00:44
Vehicle <input type="checkbox"/>	Year Make Model	State/License Number VIN
Classification <u>Undetermined</u>		

Fire Loss Information

	Building / Vehicle	Contents
Loss Estimate	81,580	15000
Estimated Value	81,580	15000
Insurance Company		
Description		Comments
Right of Entry/Chain of Custody	Exigent Circumstances	
Gas	Yes	
Electric	Yes	
DFR Notified	911 Caller	
First Responder	EN43	

Assigned FBR Entered NFIRS Entered Completed Sup. Review _____

FIRE INVESTIGATION REPORT

INCIDENT # 2018049283

Evidence: No	Photos: Yes	Supplement: No
Previous Fires: No	Drug Involved: No	Homeless: No

Sprinklers: No	Type: Choose One: Activated: Choose One:	Operational: Yes <input type="checkbox"/> No <input type="checkbox"/> N/A <input type="checkbox"/> # of Heads
Fire Alarm System: Yes <input type="checkbox"/> No <input type="checkbox"/> Unk. <input checked="" type="checkbox"/> How many: (including non-working)	Type:	# of working smoke alarms:
Operational: Yes <input type="checkbox"/> No <input type="checkbox"/> Unk. <input checked="" type="checkbox"/> N/A <input type="checkbox"/>	Location: Unknown	
Number of occupants at home at time of fire: 5	Ages of occupants: 36,43,78,15,12	
Did the smoke detector warn occupants? Yes <input type="checkbox"/> No <input type="checkbox"/> Unk. <input checked="" type="checkbox"/> N/A <input type="checkbox"/>	Did the smoke detector aid in escape? Yes <input type="checkbox"/> No <input type="checkbox"/> Unk. <input checked="" type="checkbox"/> N/A <input type="checkbox"/>	
Exits Obstructed: Yes <input type="checkbox"/> No <input type="checkbox"/> Unk. <input checked="" type="checkbox"/> N/A <input type="checkbox"/> If Yes, How?		
Burglar Bars: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Installed Correctly? Yes <input type="checkbox"/> No <input type="checkbox"/> N/A <input checked="" type="checkbox"/>	

Narrative:

EN43 was dispatched to the listed location for a structure fire. Upon arrival they responded out with major damage to the structure, but no fire. After investigation conducted by EN 43, it was found that there had been an explosion at the home and five members of the family were extracted and transported to the hospital for treatment. Investigators 684 & 685 were requested to the scene. However, 684 & 685 were not able to enter the structure due to the advisement of the Incident Commander and the safety of the structure. Utilities supplied to the home were gas and electricity and both were confirmed to be operational at the structure. Oncor and Atmos were on location during the entire incident. A rough sketch was made of the exterior by investigators and indicated that the bulk of the damage was sustained to the Delta/Alpha corner of the structure. Exterior photos show that due to the explosion, the brick exterior on the Alpha/Delta corner was blown off and the exterior wall were blown out on the Delta Side. The roof structure on the same side was damaged and in a collapsed state. The Bravo side had the walls blown out as well, and the Charlie side was still pretty much in tact with the blast pushing out the bottom of the structure. An additional sketch of the interior was made by the son, and it annotated the heater and the stove, both gas fed appliances, were located in the center of the home. The sketch also indicated that this was a two bedroom, two bath structure with two members of the family sleeping in the living area of the home where the bulk of the damage was sustained. The family members in this area of the home received the brunt of the injuries from the blast. The dad stated that everyone in the home was asleep when the explosion took place and were awakened to fallen debris and insulation. The previous evening, the father and son stated that they heard a loud pop noise in the general area of the kitchen, searched the area and did not find anything. Because of the unknown factors regarding this incident and two previous incidents noted below, evacuation procedures were conducted by Emergency Response personnel to include several street blocks north and south of the listed address. Due to the inability to access the location and adequately eliminate all possible ignition sources, this fire will be classified at this time as undetermined.

Prior to this incident, there were two previous fires in the immediate area that were similar in nature. The first such fire took place on February 20, 2018 at approximately 05:49 am at 3527 Durango Dr. where five family were affected and two were injured with one person transported to Parkland with second degree burns to the face. The second fire took place on February 22, 2018 at approximately 10:21 am at 3515 Durango Dr. with one person injured. He drove himself to the hospital. He noted to investigators that he was experiencing problems with his gas line to his stove.

SIGNIFICANT FIRE INCIDENT REPORT

DALLAS FIRE-RESCUE DEPARTMENT

FIRE INVESTIGATION & E.O.D.

(214) 670-4312 FAX: (214) 670-4650

Date: 02/23/2018 Alarm Times: 1st 06:38 2th 3th 4th 5th 6th 7th Out 00:44 Taps

DFR #: 2018049283 Location: 3534 Espanola Dr. Investigator: Westbrook/Gardner

Type of Incident / Description of Property: 1 Story W/F Single Family Dwelling

Name of Business or Property:

Owner / Occupant: [REDACTED]

Cause of the Fire: Undetermined

Fire Loss: Building: 81,580 Content: 15,000 Total: 96,580

Departmental Resources: Fire Fighting Equipment (Companies): 35 Firefighters: 59

	Yes	No	Unk	
Smoke Detectors?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	If yes, type
Installed Correctly?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	If no, explain
Operational?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	If no, explain
Warned Occupants?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	If no, explain
Aided Escape?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	If no, explain
Sprinkler System?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Operational? Yes <input type="checkbox"/> No <input type="checkbox"/> Unk. <input type="checkbox"/>
Additional Information?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Description of Incident:

EN-43 was dispatched to the listed location for a structure fire. Upon arrival they responded out with major damage to the structure, but no fire. After investigation conducted by EN 43, it was found that there had been an explosion at the home and five members of the family were extracted and transported to the hospital for treatment. Investigators 684 & 685 were requested to the scene. However, 684 & 685 were not able to enter the structure due to the advisement of the Incident Commander and the safety of the structure. Utilities supplied to the home were gas and electricity and both were confirmed to be operational at the structure. Oncor and Amos were on location during the entire incident. A rough sketch was made of the exterior by investigators and indicated that the bulk of the damage was sustained to the Delta Alpha corner of the structure. Exterior photos show that due to the explosion, the brick exterior on the Alpha Delta corner was blown off and the exterior wall were blown out on the Delta Side. The roof structure on the same side was damaged and in a collapsed state. The Bravo side had the walls blown out as well, and the Charlie side was still pretty much in tact with the blast pushing out the bottom of the structure. An additional sketch of the interior was made by the son, and it annotated the heater and the stove, both gas fed appliances, were located in the center of the home. The sketch also indicated that this was a two bedroom, two bath structure with two members of the family sleeping in the living area of the home where the bulk of the damage was sustained. The family members in this area of the home received the brunt of the injuries from the blast. The dad stated that everyone in the home was asleep when the explosion took place and were awakened to fallen debris and insulation. The previous evening, the father and son stated that they heard a loud pop noise in the general area of the kitchen, searched the area and did not find anything. Because of the unknown factors regarding this incident and two previous incidents noted below, evacuation procedures were conducted by Emergency Response personnel to include several street blocks north and south of the listed address. Due to the inability to access the location and adequately eliminate all possible ignition sources, this fire will be classified at this time as undetermined.

Prior to this incident, there were two previous fires in the immediate area that were similar in nature. The first such fire took place on February 20, 2018 at approximately 05:49 am at 3527 Durango Dr. where five family were affected and two were injured with one person transported to Parkland with second degree burns to the face. The second fire took place on February 22, 2018 at approximately 10:21 am at 3515 Durango Dr. with one person injured. He drove himself to the hospital. He noted to investigators that he was experiencing problems with his gas line to his stove.

Injuries/Deaths Yes No Unk. If Yes, continue on second page

This release authorized by _____

INJURIES / DEATHS

Name	C / F	Injury Type or Fatality	Transported by and taken where Pronounced where and time
██████████	<input checked="" type="checkbox"/> / <input type="checkbox"/>	Cuts and Bruises	R42 to Parkland Hosp 7:01am
██████████	<input checked="" type="checkbox"/> / <input type="checkbox"/>	Cuts and Bruises	RE47 to Parkland Hosp 7:21am
██████████	<input checked="" type="checkbox"/> / <input type="checkbox"/>	Minor Abrasions	RE30 to Parkland Hosp 7:21am
██████████	<input checked="" type="checkbox"/> / <input type="checkbox"/>	<u>Fractured foot</u>	RE37 to Parkland Hosp 7:10am
██████████	<input checked="" type="checkbox"/> / <input type="checkbox"/>	<u>Fatality</u>	RE43 to Children's Hosp 6:51am
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____
_____	<input type="checkbox"/> / <input type="checkbox"/>	_____	_____

Can names be released? ^{TBD}

This release authorized by _____

CASUALTY REPORT

INCIDENT NUMBER 2018049283

WITNESS #1 OBSERVATIONS (NAME, ADDRESS, PHONE NUMBER)

Dad, [REDACTED], 3534 Espanola Dr. heard a boom and woke up to fallen debris on top of his body.

WITNESS #2 OBSERVATIONS (NAME, ADDRESS, PHONE NUMBER)

Son, [REDACTED], awakened by the blast. He was instrumental in getting everyone out of the house.

NARRATIVE:

A minor explosion took place at the residence. The family was asleep at the time of the explosion and were awakened by falling debris. There were five family members at home and all were able to escape and were transported to Parkland and Children's hospital where one member of the family expired due to injuries sustained in the blast. The listed member sustained severe internal injuries and was pronounced dead at the hospital. SW

Incident Detail Report

Data Source: Data Warehouse
 Incident Status: Closed
 Incident number: 2018049283
 Case Numbers:
 Incident Date: 2/23/2018 06:38:02
 Report Generated: 2/27/2018 11:41:15

Incident Information

Incident Type:	STRUCTURE FIRE A(WORKING)	Alarm Level:	1
Priority:	Emergency	Problem:	99 - Structure Fire Working
Determinant:		Agency:	Fire
Base Response#:	02232018-0067338	Jurisdiction:	Dallas Fire
Confirmation#:		Division:	Dallas Fire
Taken By:	GILCREASE, SONNY W	Battalion:	Dallas Fire
Response Area:	DAL	Response Plan:	*DFR-A BOX(WORKING)
Disposition:		Command Ch:	
Cancel Reason:		Primary TAC:	
Incident Status:	Closed	Secondary TAC:	
Certification:		Delay Reason (if any):	
Longitude:	96860336	Latitude:	32868327

Incident Location

Location Name:	County:
Address:	DALLAS
Apartment:	Location Type:
Building:	LARGA DR/EL CENTRO DR
City, State, Zip:	Map Reference:
Dallas TX 75220	23-V

Call Receipt

Caller Name:	GONZALEZ,O
Method Received:	Telephone
Caller Type:	
Call Back Phone:	(214) 358-4809
Caller Location:	3523 ESPANOLA DR

Time Stamps

Description	Date	Time	User	Elapsed Times	Description	Time
Phone Pickup	2/23/2018	06:38:01				
1st Key Stroke	2/23/2018	06:38:03			Received to In Queue	00:00:11
In Waiting Queue	2/23/2018	06:38:13			Call Taking	00:03:13
Call Taking Complete	2/23/2018	06:41:15	GILCREASE, SONNY W		In Queue to 1st Assign	00:00:03
1st Unit Assigned	2/23/2018	06:38:16			Call Received to 1st Assign	00:00:15
1st Unit Enroute	2/23/2018	06:38:41			Assigned to 1st Enroute	00:00:25.8
1st Unit Arrived	2/23/2018	06:42:36			Enroute to 1st Arrived	00:03:54.5
Closed	2/24/2018	00:44:19	Mobile2		Incident Duration	18:06:18

Resources Assigned

Unit	Primary Flag	Assigned	Disposition	Enroute	Staged	Arrived	Delay At Patient Avail	Complete	Odm. Enroute	Odm. Arrived	Cancel Reason
EN35	N	06:38:16		06:39:11		06:44:17		11:54:28			
EN43	N	06:38:16		06:38:50		06:44:51		11:45:46			
EN30	N	06:38:16		06:39:19		06:45:34		11:49:03			
TR41	N	06:38:16		06:38:41		06:45:34		10:12:10			
TR11	N	06:38:16	Reassign FIRE					06:39:04			Swap
BC07	N	06:38:16		06:39:26		06:52:13		19:19:59			
BC09	N	06:38:16		06:38:58		06:45:58		23:39:59			
TR43	N	06:39:04		06:39:10		06:43:07		11:54:12			
RE43	N	06:39:20		06:39:24		06:42:36		07:24:38			
RE42	N	06:44:04		06:44:49		06:52:26		07:54:41			
RE11	N	06:44:04	Reassign FIRE	06:45:27				06:45:47			Swap
RE37	N	06:44:04		06:45:24		06:55:53		08:03:39			
782	N	06:45:01		06:46:20		06:54:16		11:52:00			
RE47	N	06:45:47		06:45:54		06:52:21		08:02:51			
684	N	06:53:11		07:05:34		07:28:33		08:51:29			
685	N	06:53:11		07:05:49		07:28:45		11:35:24			
RE30	N	06:59:54		07:01:34		07:09:08		08:06:34			
RE01	N	07:01:11		07:01:45		07:16:07		13:46:12			
780	N	07:02:17		07:02:17		07:08:02		14:12:35			
885	N	07:05:35		07:08:29		07:08:29		07:08:32			
806	N	07:07:25		07:08:17		07:24:47		08:52:01			
881	N	07:08:43		07:12:40		08:16:51		16:23:09			
EN42	N	07:08:57		07:10:25		07:28:32		07:50:23			
EN02	N	07:08:57		07:10:29		07:16:53		07:59:39			
EN41	N	07:08:57		07:09:23		07:16:42		07:52:08			
678	N	08:54:29				09:06:41		11:34:02			
659	N	08:54:44				09:06:41		11:34:01			
601	N	08:55:08				09:06:41		11:34:01			
EN42	N	09:40:17		09:41:37		09:48:00		11:57:10			
896	N	09:41:22		10:01:15		10:20:06		13:54:34			
806	N	09:56:10		09:56:16		09:56:16		12:48:09			
897	N	11:12:18		11:12:22		11:40:31		14:02:42			
US19	N	11:46:11		11:48:53		12:07:34		13:13:29			
	N	13:02:09		13:02:41		13:18:50		14:26:36			
	N	14:10:25		14:12:35		14:52:54		16:55:46			
	N	16:32:50		16:34:28		17:09:08		21:56:33			
	N	18:11:51				18:11:54		22:51:43			
RE28	Y	21:36:37		21:38:49		21:55:29		00:44:19			

RE44 N 23:50:04 Reassign FIRE 23:50:18 23:50:29 Swap

Personnel Assigned

Unit	Name
EN35	[REDACTED]
EN43	[REDACTED]
EN30	[REDACTED]
TR41	[REDACTED]
TR11	[REDACTED]
BC07	[REDACTED]
BC09	[REDACTED]
TR43	[REDACTED]
RE43	[REDACTED]
RE11	[REDACTED]
RE37	[REDACTED]
782	[REDACTED]
RE47	[REDACTED]
684	[REDACTED]
RE30	[REDACTED]
RE01	[REDACTED]
780	[REDACTED]
806	[REDACTED]
EN42	[REDACTED]
EN02	[REDACTED]
EN41	[REDACTED]
EN42	[REDACTED]
806	[REDACTED]
RE20	[REDACTED]
RE70	[REDACTED]
RE28	[REDACTED]
RE44	[REDACTED]

Pre-Scheduled Information
No Pre-Scheduled Information

Transports

Unit	Location/Address	City	Patient	Mode	Protocol	Mileage	Depart	Arrived	Complete
RE43	CHILDRENS MED CTR DALLAS/1935 MEDICAL DISTRICT DR	Dallas		Priority 3	Code 1	0.0/ 0.0/ 0.0	06:51:51	07:01:46	07:24:38
RE42	PARKLAND HOSP/5200 HARRY HINES BLVD	Dallas		Priority 3	Code 1	0.0/ 0.0/ 0.0	07:01:21	07:16:24	07:54:41
RE37	PARKLAND HOSP/5200 HARRY HINES BLVD	Dallas		Priority 3	Code 1	0.0/ 0.0/ 0.0	07:10:19	07:19:54	08:03:39
RE47	PARKLAND HOSP/5200 HARRY HINES BLVD	Dallas		Priority 3	Code 1	0.0/ 0.0/ 0.0	07:12:04	07:24:49	08:02:51
RE30	PARKLAND HOSP/5200 Harry Hines Blvd	Dallas		Priority 3	Code 1	0.0/ 0.0/ 0.0	07:21:20	07:37:21	08:06:34

Transport Legs
No Transports Information

Comments

Date	Time	User	Type	Conf.	Comments
2/23/2018	06:37:55	SYS	Response		[3] [Appended, 06:39:02] [1] Multiple Response Areas found. Response Area Choices: 526,536
2/23/2018	06:38:19	PAGINGSERICE	Response		[1] Paging Groups Notified:1-11 (98) GROUP
2/23/2018	06:38:38	031410	Response		[2] house poss blew up per the caller thats all she has
2/23/2018	06:39:02	115624	Response		[4] Duplicate call appended to incident at 06:39:02
2/23/2018	06:39:05	093104	Response		[5] RECEIVING MULTIPLE CALLS
2/23/2018	06:39:11	PAGINGSERICE	Response		[6] Paging Groups Notified:1-11 (99) GROUP
2/23/2018	06:39:12	093104	Response		[8] [Page] Problem changed from 98 - Structure Fire Reported to 99 - Structure Fire Working by Fire [Shared]
2/23/2018	06:39:12	093104	Response		[7] Multi-Agency Police Incident #: 18-0326546
2/23/2018	06:39:14	115624	Response		[9] ANOTHER CALLER 214 662 3817 REPORTING SAME [Shared]
2/23/2018	06:39:22	PAGINGSERICE	Response		[10] Paging Groups Notified:1-11 (99) GROUP [Shared]
2/23/2018	06:39:32	115127	Response		[11] ANNOUNCED [Shared]
2/23/2018	06:39:45	055396	Response		[12] ALSO GOT THE ADDRESS OF 3534 ESPANOLA [Shared]
2/23/2018	06:40:16	115127	Response		[13] ANNOUNCED [Shared]
2/23/2018	06:40:24	121478	Response		[14] ANOTHER CALLER 469.446.6899 REPORTING SAME. STATED THERE ARE MULTIPLE PEOPLE INSIDE HOME. [Shared]
2/23/2018	06:40:27	115624	Response		[15] Duplicate call appended to incident at 06:40:27 [Shared]
2/23/2018	06:41:38	115127	Response		[16] NOTIFIED A510 [Shared]
2/23/2018	06:42:09	093104	Response		[17] Duplicate call appended to incident at 06:42:09 [Shared]
2/23/2018	06:43:16	046518	Response		[18] (be adv while waiting with caller for dfd to pick; she was talking to someone inthe background; she stated that "something is wrong with the gas lines; this is the 3rd house) fyi. [Shared]
2/23/2018	06:44:05	PAGINGSERICE	Response		[19] Paging Groups Notified:1-11 (99) GROUP [Shared]
2/23/2018	06:44:26	115127	Response		[20] [Notification] [Police]-TR43 - IS DPD NEEDED CODE 3 [Shared]
2/23/2018	06:44:43	115127	Response		[21] [Notification] [Police]-A510 - CODE 3 RESPONSE [Shared]
2/23/2018	06:44:47	115624	Response		[22] ANOTHER CALLER 469-446-6899 STATED ATMOS ENERGY WAS REPORTING PROBLEMS AT A HOUSE ON DURANGO ST. [Shared]
2/23/2018	06:44:53	115127	Response		[23] NOTIFIED RADIO RM SGT (VS) [Shared]
2/23/2018	06:45:04	PAGINGSERICE	Response		[24] Paging Groups Notified:1-11 (99) GROUP [Shared]
2/23/2018	06:46:01	115127	Response		[25] A542 - ATMOS IS ALREADY AT LOC [Shared]
2/23/2018	06:46:48	115127	Response		[26] [Notification] [Police]-A542 - REDUCE TO CODE 1 [Shared]
2/23/2018	06:52:53	115127	Response		[27] A553 - CORRECT ADDRESS IS 3534 ESPANOLA [Shared]
2/23/2018	06:53:08	115127	Response		[28] ** UPDATED ADDRESS ** [Shared]

2/23/2018	06:57:40	093104	Response	[29] STREETS NOTIFIED [Shared]
2/23/2018	06:59:56	PAGINGSERICE	Response	[30] Paging Groups Notified:1-11 (99) GROUP [Shared]
2/23/2018	07:01:12	PAGINGSERICE	Response	[31] Paging Groups Notified:1-11 (99) GROUP [Shared]
2/23/2018	07:04:07	012443	Response	[32] *****ALL RESCUES STAGING ESPANOLA AT EL CENTRO ***** [Shared]
2/23/2018	07:08:59	PAGINGSERICE	Response	[33] Paging Groups Notified:1-11 (99) GROUP [Shared]
2/23/2018	07:11:36	012443	Response	[34] *****EN42, EN02,EN41 STAGING IS AT CONTRAIL @ DURANGO ***** [Shared]
2/23/2018	07:14:33	012443	Response	[35] ***** CORRECTION 2ND IN ENGINE COMPANY STAGING IS AT DURANGO @ EL CENTRO ***** [Shared]
2/23/2018	07:20:15	031410	Response	[36] DART is sending 2 buses to the location // 1 bus is coming immediately and another bus will be sent as soon as it becomes available. Advise if it is not needed and we can turn it back [Shared]
2/23/2018	07:29:44	012443	Response	[37] Duplicate incident created: 2018049306 [Shared]
2/23/2018	07:51:21	007466	Response	[38] [Page] STREETS IS HAVING DIFFICULTY FINDING A SUPERVISOR TO CALL 807.....THEY ARE LOOKING FOR A GOOD PHONE NUMBER AND WILL CONTACT US AS SOON AS THEY FIND ONE [Shared]
2/23/2018	07:53:40	Ladzinski, James E	Response	[39] RO'S MADE CONTACT WITH COMP WHO STATED THAT SHE JUST HAD A VERBAL ALTERCATION WITH A CUSTOMER. COMP STATED THAT SHE DOES NOT NEED ANY POLICE ASSISTANCE AT THIS TIME. NFI [Shared]
2/23/2018	07:54:00	Ladzinski, James E	Response	[40] DISREGARD LAST LINE [Shared]
2/23/2018	08:01:03	115127	Response	[41] A510 NEED UNIT TO MARGA / ESPINOLA [Shared]
2/23/2018	08:01:09	115127	Response	[42] E561 WILL TAKE THAT SPOT [Shared]
2/23/2018	08:01:29	115127	Response	[43] A510 - TO LARGA / MONTANA [Shared]
2/23/2018	08:30:38	Salomon, David A	Response	[44] bwc 6362 and 9641 [Shared]
2/23/2018	08:44:05	115127	Response	[46] B542 - PLEASE LET DFR KNOW THAT CITIZENS ARE QUESTIONING WHO WILL ADVISE THEM WHEN THEY ARE ABLE TO RETURN TO THEIR HOMES - PLEASE GET A CONTACT NUMBER SO THAT B542 CAN GIVE IT TO THE CITIZENS [Shared]
2/23/2018	08:44:05	115127	Response	[45] Multi-Agency Service Desk Incident #: 0017295-18
2/23/2018	08:50:35	6513	Response	[47] 469-323-5684 OR 5685.....PER FIRE DISPATCH THEY PROBABLY WILL NOT BE ALLOWED BACK IN TODAY, BUT THEY CAN ALWAYS GO TO THE COMMAND POST OUT THERE AND ASK QUESTIONS [Shared]
2/23/2018	08:50:43	6513	Response	[48] [Service Desk] has closed their incident [0017295-18]
2/23/2018	09:37:03	089972	Response	[49] [Page] DISD notified and they are sending a police unit out [Shared]
2/23/2018	09:40:19	PAGINGSERICE	Response	[50] Paging Groups Notified:1-11 (99) GROUP [Shared]
2/23/2018	09:45:37	089972	Response	[51] [Page] EOC notified to call bc07 by cell [Shared]
2/23/2018	10:08:04	Clayton, Thomas J	Response	[52] THE 2ND DART BUS HAS BEEN SENT TO THE STEPHEN C. FOSTER ELEMENTARY SCHOOL LOCATED AT 3700 CLOVER LN IN DALLAS TX. TO CONTACT THAT BUS DRIVER FOR ANY RELOCATION WOULD REQUIRE CONTACTING DART DISPATCH OR DIRECT CONTACT FROM ANOTHER DART BUS DRIVER. [Shared]
2/23/2018	10:12:49	Salomon, David A	Response	[53] bwc 6362 and 9641 [Shared]
2/23/2018	10:23:19	056748	Response	[54] Duplicate incident created: 2018049400 [Shared]
2/23/2018	11:02:33	6006	Response	[55] FIRE IS NOTIFYING THE RED CROSS PER FIRE [Shared]
2/23/2018	11:12:16	6006	Response	[56] EVACUEES MAY BE DIRECTED TO THE DART BUS AT ESPANOLA AND EL CENTRO [Shared]
2/23/2018	11:18:32	6006	Response	[57] FIRE COMMAND POST IS AT THE ADDRESS 3534 ESPANOLA DR [Shared]
2/23/2018	11:20:43	021252	Response	[58] [Page] FOSTER ELEMENTARY EVACUATED 1120 [Shared]
2/23/2018	11:20:48	6006	Response	[59] PERIMETER OFFICERS BLOCKING IF A RESIDENT NEEDS MEDICAL EQUIPMENT FIRE WILL ESCORT THEM IN . [Shared]
2/23/2018	11:21:43	6006	Response	[60] WALNUT HILL RECREATION CENTER (SHELTER) IS SETTING UP WILL NOT BE READY TILL NOON. [Shared]
2/23/2018	11:51:21	Clayton, Thomas J	Response	[61] THE ADDRESS OF THE WALNUT HILL RECREATION CENTER IS 10011 MIDWAY RD. IT IS AT THE NW CORNER OF WALNUT HILL AND MIDWAY... THIS WILL BE THE SHELTER LOCATION STARTING AT 12 NOON. [Shared]
2/23/2018	11:58:01	Clayton, Thomas J	Response	[62] LAST INFO ON MEDIA IS THAT THEY ARE NOW TO BE DIRECTED TO THE FIRE COMMAND POST AT THE CALLSHEET LOCATION [Shared]
2/23/2018	12:07:46	806	Response	[63] [Shared]
2/23/2018	12:10:52	089972	Response	[64] [Page] en 35 getting gas odor as far as Bowman st. Espanola command please communicate w/them to advise if further evacuation is necessary [Shared]
2/23/2018	12:44:26	Clayton, Thomas J	Response	[65] ATMOS ENERGY EMERGENCY # IF GAS IS SMELLED - 866-322-8667 [Shared]
2/23/2018	12:50:01	Clayton, Thomas J	Response	[66] WALNUT HILL REC CENTER # 214-670-7112 AND TEMPORARY SHELTER [Shared]
2/23/2018	12:53:55	Clayton, Thomas J	Response	[67] THE ONLY # WE HAVE SO FAR FOR CITIZENS TO CALL AND FIND OUT IF IT IS SAFE TO RETURN TO THEIR HOMES IS THE SHELTER AT THE WALNUT HILL REC CENTER WHICH IS 214-670-7112. IF THE SHELTER IS OPEN IT IS NOT SAFE TO RETURN TO THEIR HOMES. IF THE SHELTER IS CLOSED THEN IT IS SAFE TO RETURN TO THEIR HOMES. AT THIS TIME IT IS UNKNOWN HOW LONG THE EVACUATION WILL BE FOR. [Shared]
2/23/2018	13:02:11	PAGINGSERICE	Response	[68] Paging Groups Notified:1-11 (99) GROUP [Shared]
2/23/2018	13:40:10	Clayton, Thomas J	Response	[69] DFR CHIEF MATTHEWS SAID THAT DFR PIO JASON EVANS WILL BE TWEETING UPDATES ON THE FIRE DEPT TWITTER ACCOUNT AND THAT MIGHT HELP KEEP CITIZENS INFORMED ON UPDATES. [Shared]
2/23/2018	13:45:13	115127	Response	[70] C530 - NEED ADDITIONAL UNIT TO BLOCK OFF ALMAZAN/EL RITO [Shared]
2/23/2018	13:45:48	Clayton, Thomas J	Response	[71] CONTACTED THE ATMOS ENERGY EMERGENCY LINE AND ATTEMPTED TO GET A PHONE # TO HELP ADVISE CUSTOMERS AND CITIZENS WHEN IT WILL BE SAFE TO RETURN HOME FROM THE EVACUATION. ALSO AS A CUSTOMER SERVICE LINE TO ANSWER PEOPLES QUESTIONS RELATED TO THE INCIDENT AND GIVE THEM GUIDANCE FOR SHELTER, FOOD, ETC. R/O IS STILL AWAITING A RESPONSE. [Shared]
2/23/2018	13:55:50	BC09	Response	[72] ATMOS is working on setting up a 1800 number for affected residents. In addition they are printing flyers fore fire/police to hand out to residents as they come home this evening. [Shared]
2/23/2018	14:06:41	007466	Response	[73] SECONDARY EVAC ON BOLIVAR COMPLETE [Shared]
2/23/2018	14:12:24	007466	Response	[74] CMD VAN ADDED....MEET AT WEBB CHAPEL STORY [Shared]
2/23/2018	14:21:12	007466	Response	[75] DART MAY CLEAR SCENE [Shared]
2/23/2018	14:26:01	007466	Response	[76] [Page] COMMAND CENTER NOW AT THE CARNIVAL PARKING LOT @ WEBB CHAPEL/STOREY.....SECONDARY SWEEP OF THE ENTIRE NEIGHBORHOOD

Date	Time	Incident ID	Response	Description
2/23/2018	14:28:27	114064	Response	COMPLETE, POLICE POSTED ON THE PERIMETER [Shared]
2/23/2018	14:43:34	113077	Response	[77] WEBB CHAPEL AND STORY / NO ENTRY ZONE [Shared]
2/23/2018	14:48:05	113077	Response	[78] D560 NEEDS BARRICADES AT BOLIVAR/EL RITO DR [Shared]
2/23/2018	14:49:15	113077	Response	[79] D568 >> i need one more barricade at Marsh and Bolivar [Shared]
2/23/2018	14:49:16	113077	Response	[80] Multi-Agency Service Desk Incident #: 0017386-18
2/23/2018	14:50:12	Clayton, Thomas J	Response	[81] NOTIFY STREETS AND LET THEM KNOW MORE BARRICADES ARE NEEDED OR HAVE THERE DISPATCHER LET THE PERSON OUT THERE KNOW TO GO TO LOCATIONS LISTED BELOW [Shared]
2/23/2018	14:58:30	065642	Response	[82] NO BWC BY 6153 [Shared]
2/23/2018	15:00:40	10970	Response	[83] 1-800-817-8090 IS NO TO CALL ATMOS FOR DISPLACED PERSONS AFFECTED BY GAS LEAK [Shared]
2/23/2018	15:02:02	Clayton, Thomas J	Response	[84] STREETS NOTIFIED TO BRING MORE BARRICADES [Shared]
2/23/2018	15:02:28	113077	Response	[85] ATMOS ENERGY NEVER CALLED BACK WITH A # FOR CITIZENS. R/O GAVE STATION # TO CONTACT AS R/O IS GOING ON A 66. [Shared]
2/23/2018	15:06:59	10970	Response	[86] C530 AT ALMAZON AND EL RITO DR [Shared]
2/23/2018	15:26:55	Sambola, Walter A	Response	[87] [Service Desk] has closed their incident [0017386-18]
2/23/2018	15:34:23	113077	Response	[88] C539 POSTED AT ALMAZON AND EL RITO DR [Shared]
2/23/2018	15:46:12	Saldana Jr, Juan M	Response	[89] C556 HEADED TO MIDWAY AND WALNUT NEAR THE REC CENTER [Shared]
2/23/2018	15:53:45	Sato, Joe	Response	[90] C554 POSTED AT EL CENTRO AND FONTANA DR [Shared]
2/23/2018	15:58:35	Ford, Paul	Response	[91] C534 posted 9647 LARGA/ GASPAS [Shared]
2/23/2018	16:13:58	Allen, Lindsey N	Response	[92] c552 marsh/lespanola [Shared]
2/23/2018	16:25:19	Rivera, Domingo	Response	[93] d663 posted at marsh/durango [Shared]
2/23/2018	16:26:55	065642	Response	[94] F534 Bolivar at Marsh [Shared]
2/23/2018	16:35:16	065642	Response	[95] WALNUT HILL REC CENTER IS LOCATED AT 10011 MIDWAY RD. [Shared]
2/23/2018	16:43:18	Sambola, Walter A	Response	[96] RE70 PLEASE RESPOND TO THE WALNUT HILL REC CENTER TO STAND BY FOR ANY POTENTIAL MEDICAL NEEDS OF EVACUEES COMING THROUGH THE CENTER. ATMOS IS GIVING VOUCHERS FOR HOTEL ROOMS AND MEALS. [Shared]
2/23/2018	17:24:00	PadillaLugo, Ariel D	Response	[97] C539 RELOCATED PER C502 TO EL RITO DR AND BOLIVAR. [Shared]
2/23/2018	17:25:11	Rocha, Gretchen M	Response	[98] F433 NIXON / CORTEZ [Shared]
2/23/2018	17:32:26	115645	Response	[99] c447 North Side of Cortez/ Marsh intersection [Shared]
2/23/2018	17:34:05	Valarezo, Rachel A	Response	[100] OPERATING NOW ON CH12 [Shared]
2/23/2018	17:38:30	115645	Response	[101] c425 east side of marsh at bolivar [Shared]
2/23/2018	17:41:50	Saldana Jr, Juan M	Response	[102] C552 RESIDENT AT 3703 DAVILLA WANTS HOUSE CHECKED BY DFR [Shared]
2/23/2018	17:49:00	Saldana Jr, Juan M	Response	[103] C554 RESIDENT AT 3703 DAVILLA WANTS HOUSE CHECKED BY DFR. PET IS INSIDE A ROOM WITH A PORTABLE HEATER ALL DAY [Shared]
2/23/2018	18:06:45	Valarezo, Rachel A	Response	[104] C554 DISREGARD THE ADDRESS OF 3704 DAVILA. C554 NEEDS THE ADDRESS OF 3630 FONTANA DR [Shared]
2/23/2018	18:06:59	Valarezo, Rachel A	Response	[105] COMMAND POST ADDRESS: 9655 WEBB CHAPEL ROAD LARGA/WEBB CHAPEL [Shared]
2/23/2018	18:24:55	F525	Response	[106] ROAMING ELEMENTS: F525/F526 [Shared]
2/23/2018	18:25:32	Evans, Melanie R	Response	[107] Requested Case Number(s) issued for Dallas Police: 039389-2018 requested by F525. [Shared]
2/23/2018	19:18:35	065642	Response	[108] F525- CASE NUMBER 039389-2018 PROPRTY [Shared]
2/23/2018	19:46:16	119998	Response	[109] SECONDARY EVACUATION COMPLETE IN SECONDARY AREA [Shared]
2/23/2018	20:09:50	Saldana Jr, Juan M	Response	[110] C552 WHITE SUV INSDE PERIMTER 3600 ESPANOLA SB ON EL CENTRO [Shared]
2/23/2018	21:36:38	PAGINGSERVICE	Response	[111] C554 FLAGGED DOWN BY DFR STATED THEY OBSERVED AN UNKNOWN RACE MALE. DARK HOODIE WALKING WB ON DURANGO OR CORTEZ WITH A BAGPACK [Shared]
2/23/2018	23:50:05	PAGINGSERVICE	Response	[112] Paging Groups Notified:1-11 (99) GROUP [Shared]
2/24/2018	00:43:41	Mobile1	Response	[113] Paging Groups Notified:1-11 (99) GROUP [Shared]
				[114] [Police] has closed their incident [18-0326546]

Address Changes

Date	Time	Location/Address	User
2/23/2018	07:11:44	/ 3523 Espanola Dr	JLC

Priority Changes

No Priority Changes

Alarm Level Changes

Date	Time	User	Change to Alarm
2/23/2018	06:38:16	AD	1
2/23/2018	06:39:20	MW	1
2/23/2018	06:44:04	JLC	1
2/23/2018	06:45:01	TAM	1
2/23/2018	06:59:54	JLC	1
2/23/2018	07:01:11	JLC	1
2/23/2018	07:08:57	JLC	1
2/23/2018	09:40:17	RVS	1
2/23/2018	13:02:09	JLO	1
2/23/2018	21:36:37	RPE	1
2/23/2018	23:50:04	RPE	1

Activity Log

Date	Time	Radio	Activity	Location	Log Entry	User
2/23/2018	06:38:02		Sector Change		From Sector No Sector to Sector 660	031410
2/23/2018	06:38:13		Incident in Waiting Queue			
2/23/2018	06:38:13		ANI/ALI Statistics		INT Insert:Feb 23 2018 06:38:02 / INT SendNP:Feb 23 2018 06:38:01 / WS RecvNP:Feb 23 2018 06:38:01 / WS Process:Feb 23 2018 06:38:13	031410
2/23/2018	06:38:13		Incident Priority Change		Incident priority changed from <none> to Emergency	031410
2/23/2018	06:38:14		Waiting Pending Incident Time Warning		Waiting Pending Incident Time Warning timer expired	
2/23/2018	06:38:16	TR11	Assgn	3523 Espanola Dr	Response Number (02232018-0067342)	AUTODISPATCH
2/23/2018	06:38:16	EN35	Assgn	3523 Espanola Dr	Response Number (02232018-0067338)	AUTODISPATCH
2/23/2018	06:38:16	TR41	Assgn	3523 Espanola Dr	Response Number (02232018-0067341)	AUTODISPATCH
2/23/2018	06:38:16	EN43	Assgn	3523 Espanola Dr	Response Number (02232018-0067339)	AUTODISPATCH

2/23/2018	06:38:16	EN30	Assgn	3523 Espanola Dr	Response Number (02232018-0067340)	AUTODISPATCH
2/23/2018	06:38:16	BC07	Assgn	3523 Espanola Dr	Response Number (02232018-0067343)	AUTODISPATCH
2/23/2018	06:38:16	BC09	Assgn	3523 Espanola Dr	Response Number (02232018-0067344)	AUTODISPATCH
2/23/2018	06:38:16		Incident Timer Clear		Incident Timer Cleared	
2/23/2018	06:38:17		Automatic Dispatch		Automatic Dispatch Successful for DYNAMIC- *DFR-A BOX(REPORTED) - Alarm level 1	AUTODISPATCH
2/23/2018	06:38:41	TR41	Enr	3523 Espanola Dr	Responding From = W NORTHWEST HWYUNNAMED STREET	TR41
2/23/2018	06:38:49		Read Incident		Incident 667 was Marked as Read.	093104
2/23/2018	06:38:49		Read Comment		Comment for Incident 667 was Marked as Read.	093104
2/23/2018	06:38:50	EN43	Enr	3523 Espanola Dr	Responding From = LOMBARDY LNABERNATHY AVE	EN43
2/23/2018	06:38:58	BC09	Enr	3523 Espanola Dr	Responding From = ENVOY CTW MOCKINGBIRD LN	BC09
2/23/2018	06:39:02		Duplicate Call Warning		Duplicate Call Warning - New call appended to incident	115624
2/23/2018	06:39:03		Read Comment		Comment for Incident 667 was Marked as Read.	115624
2/23/2018	06:39:03	TR11	ReAssign Vehicle	3523 Espanola Dr	ReAssign Reason: Swap	012443
2/23/2018	06:39:04	TR43	Assgn	3523 Espanola Dr	Response Number (02232018-0067346)	012443
2/23/2018	06:39:04		ReAssign Response	3523 Espanola Dr	Clearing Primary Vehicle Flag	012443
2/23/2018	06:39:10	TR43	Enr	3523 Espanola Dr	Responding From = HARRY HINES BLVD/LOMBARDY LN	TR43
2/23/2018	06:39:11		MultiAgencyResponse		A Change in the Problem from 99 - Structure Fire Working to 99 - Structure Fire Working has resulted in the recommendation of the following additional agencies Police	093104
2/23/2018	06:39:11	EN35	Enr	3523 Espanola Dr	Responding From = WALNUT HILL LNUNNAMED STREET	EN35
2/23/2018	06:39:12		MultiAgencyResponse		Generated Inc: Police Inc#18-0326546	093104
2/23/2018	06:39:12		MultiAgencyResponse		The following additional Agencies have been sent because of a Problem/Nature change:Police	093104
2/23/2018	06:39:12		Read Comment		Comment for Incident 667 was Marked as Read.	046518
2/23/2018	06:39:13		Remove Waiting Pending Incident Warning		Removing Waiting Pending Incident Time Warning timer expired	
2/23/2018	06:39:14		UserAction		User clicked Exit/Save	115624
2/23/2018	06:39:15		UserAction		User clicked Reconfigure	093104
2/23/2018	06:39:17		Reconfigure Response		The following unit(s) is (are) recommended for assignment: EN35 (00:02:29),EN43 (00:02:47),EN30 (00:05:39),TR43 (00:03:52),TR41 (00:06:46),BC07 (00:02:31),BC09 (00:06:57),RE43 (00:03:58)	093104
2/23/2018	06:39:19	EN30	Enr	3523 Espanola Dr	Responding From = ZODIAC LNDAIRY MILK LN	EN30
2/23/2018	06:39:20	RE43	Assgn	3523 Espanola Dr	Response Number (02232018-0067347)	093104
2/23/2018	06:39:21		UserAction		User clicked Exit/Save	093104
2/23/2018	06:39:24	RE43	Enr	3523 Espanola Dr	Responding From = LOMBARDY LNABERNATHY AVE	RE43
2/23/2018	06:39:26	BC07	Enr	3523 Espanola Dr	Responding From = WALNUT HILL LNUNNAMED STREET	BC07
2/23/2018	06:39:46		UserAction		User clicked Exit/Save	055396
2/23/2018	06:39:50	TR41	Route Deviation	W NORTHWEST HWYUNNAMED STREET	Unit TR41 deviated from original driving directions route	TR41
2/23/2018	06:40:03		Read Comment		Comment for Incident 667 was Marked as Read.	012443
2/23/2018	06:41:07	EN43	Route Deviation	LARGA DR	Unit EN43 deviated from original driving directions route	EN43
2/23/2018	06:41:15		UserAction		User clicked Exit/Save	031410
2/23/2018	06:42:09		Duplicate Call Warning		Duplicate Call Warning - New call appended to incident	093104
2/23/2018	06:42:09		Read Comment		Comment for Incident 667 was Marked as Read.	093104
2/23/2018	06:42:12		UserAction		User clicked Exit/Save	093104
2/23/2018	06:42:36	RE43	At Scene	3523 Espanola Dr		RE43
2/23/2018	06:42:58		UserAction		User clicked Exit/Save	055396
2/23/2018	06:43:07	TR43	At Scene	3523 Espanola Dr		TR43
2/23/2018	06:43:50		UserAction		User clicked Add Resource	012443
2/23/2018	06:43:50		Read Comment		Comment for Incident 667 was Marked as Read.	055396
2/23/2018	06:43:57		VisiCAD Recommendation		RE42: 00:06:43, RE11: 00:10:54, RE37: 00:11:34, RE01: 00:12:20, RE08: 00:13:54,	012443
2/23/2018	06:43:59		UserAction		User Accepted RE42	
2/23/2018	06:43:59		Add Resources		The following unit(s) is (are) recommended for assignment: RE42 (00:06:43)	012443
2/23/2018	06:44:02		UserAction		User Accepted RE11	
2/23/2018	06:44:02		Add Resources		The following unit(s) is (are) recommended for assignment: RE11 (00:10:54)	012443
2/23/2018	06:44:02		UserAction		User Accepted RE37	
2/23/2018	06:44:02		Add Resources		The following unit(s) is (are) recommended for assignment: RE37 (00:11:34)	012443
2/23/2018	06:44:04	RE37	Assgn	3523 Espanola Dr	Response Number (02232018-0067352)	012443
2/23/2018	06:44:04	RE11	Assgn	3523 Espanola Dr	Response Number (02232018-0067351)	012443
2/23/2018	06:44:04	RE42	Assgn	3523 Espanola Dr	Response Number (02232018-0067350)	012443
2/23/2018	06:44:17	EN35	At Scene	3523 Espanola Dr		EN35
2/23/2018	06:44:26		Read Comment		Comment for Incident 667 was Marked as Read.	085032
2/23/2018	06:44:29		Read Comment		Comment for Incident 667 was Marked as	118185

2/23/2018	06:44:32		UserAction		Read.	055396
2/23/2018	06:44:43		Read Comment		User clicked Exit/Save Comment for Incident 667 was Marked as Read.	093104
2/23/2018	06:44:47		UserAction		User clicked Add Resource	055396
2/23/2018	06:44:49	RE42	Enr	3523 Espanola Dr	Responding From = STA 42	RE42
2/23/2018	06:44:51	EN43	At Scene	3523 Espanola Dr		012443
2/23/2018	06:44:52		Read Comment		Comment for Incident 667 was Marked as Read.	034562
2/23/2018	06:44:56		VisiCAD Recommendation		782: 00:06:30, 780: 00:15:32, 781: 00:19:36, 784: 00:20:09, 783: 00:22:47, User Accepted 782	055396
2/23/2018	06:44:59		UserAction		The following unit(s) is (are) recommended for assignment: 782 (00:06:30)	055396
2/23/2018	06:44:59		Add Resources		Response Number (02232018-0067354)	055396
2/23/2018	06:45:01	782	Assgn	3523 Espanola Dr	User clicked Exit/Save	055396
2/23/2018	06:45:04		UserAction		Comment for Incident 667 was Marked as Read.	115127
2/23/2018	06:45:09		Read Comment		Responding From = GREENVILLE AVE\UNNAMED STREET	RE37
2/23/2018	06:45:24	RE37	Enr	3523 Espanola Dr	Responding From = CEDAR SPRINGS RD\REAGAN ST	RE11
2/23/2018	06:45:27	RE11	Enr	3523 Espanola Dr	User clicked Exit/Save	034562
2/23/2018	06:45:32		UserAction			EN30
2/23/2018	06:45:34	EN30	At Scene	3523 Espanola Dr		TR41
2/23/2018	06:45:34	TR41	At Scene	3523 Espanola Dr		TR41
2/23/2018	06:45:34	RE47	Assgn	3523 Espanola Dr	Response Number (02232018-0067357)	034562
2/23/2018	06:45:47	RE11	ReAssign Vehicle	3523 Espanola Dr	ReAssign Reason: Swap	034562
2/23/2018	06:45:47	RE47	ReAssign Response	3523 Espanola Dr	Clearing Primary Vehicle Flag	034562
2/23/2018	06:45:54	RE47	Enr	3523 Espanola Dr	Responding From = JOHN W CARPENTER ACRD NB\JOHN W CARPENTER FWY NB	RE47
2/23/2018	06:45:58	BC09	At Scene	3523 Espanola Dr		BC09
2/23/2018	06:46:05		UserAction		User clicked Exit/Save	115127
2/23/2018	06:46:11		Read Comment		Comment for Incident 667 was Marked as Read.	119914
2/23/2018	06:46:20	782	Enr	3523 Espanola Dr	Responding From = NORTHAVEN RD\MIDWAY RD	012443
2/23/2018	06:46:49		Read Comment		Comment for Incident 667 was Marked as Read.	085032
2/23/2018	06:49:25		UserAction		User clicked Exit/Save	031410
2/23/2018	06:49:34		UserAction		User clicked Exit/Save	055396
2/23/2018	06:49:37		UserAction		User clicked Exit/Save	012443
2/23/2018	06:51:51	RE43	To Fac	1935 MEDICAL DISTRICT DR [CHILDRENS MED CTR DALLAS]	Transport Priority - Priority 3; Protocol - Code 1	RE43
2/23/2018	06:52:13	BC07	At Scene	3523 Espanola Dr		012443
2/23/2018	06:52:21	RE47	At Scene	3523 Espanola Dr		RE47
2/23/2018	06:52:26	RE42	At Scene	3523 Espanola Dr		RE42
2/23/2018	06:53:00		Read Comment		Comment for Incident 667 was Marked as Read.	055396
2/23/2018	06:53:11	684	Assgn	3523 Espanola Dr	Response Number (02232018-0067358)	012443
2/23/2018	06:53:11	685	Assgn	3523 Espanola Dr	Response Number (02232018-0067359)	012443
2/23/2018	06:54:16	782	At Scene	3523 Espanola Dr		782
2/23/2018	06:54:21		UserAction		User clicked Exit/Save	055396
2/23/2018	06:55:02		Read Comment		Comment for Incident 667 was Marked as Read.	046518
2/23/2018	06:55:12		Incident Late		Active incident marked as late	
2/23/2018	06:55:50		UserAction		User clicked Exit/Save	046518
2/23/2018	06:55:53	RE37	At Scene	3523 Espanola Dr		RE37
2/23/2018	06:55:53		Incident Late		Active incident marked as late	
2/23/2018	06:58:04		UserAction		User clicked Exit/Save	093104
2/23/2018	06:59:47		UserAction		User selected Add Additional Resources from PowerLine	012443
2/23/2018	06:59:49		VisiCAD Recommendation		RE30: 00:06:48, RE01: 00:12:20, RE08: 00:13:54, RE45: 00:14:46, RE28: 00:14:50, User Accepted RE30	012443
2/23/2018	06:59:53		UserAction		The following unit(s) is (are) recommended for assignment: RE30 (00:06:48)	012443
2/23/2018	06:59:53		Add Resources		Response Number (02232018-0067365)	012443
2/23/2018	06:59:54	RE30	Assgn	3523 Espanola Dr	User selected Add Additional Resources from PowerLine	012443
2/23/2018	07:01:02		UserAction		RE01: 00:12:20, RE08: 00:13:54, RE45: 00:14:46, RE28: 00:14:50, RE03: 00:15:00, User Accepted RE01	012443
2/23/2018	07:01:05		VisiCAD Recommendation		The following unit(s) is (are) recommended for assignment: RE01 (00:12:20)	012443
2/23/2018	07:01:10		UserAction		Response Number (02232018-0067366)	012443
2/23/2018	07:01:10		Add Resources		Transport Priority - Priority 3; Protocol - Code 1	RE42
2/23/2018	07:01:11	RE01	Assgn	3523 Espanola Dr		
2/23/2018	07:01:21	RE42	To Fac	5200 HARRY HINES BLVD [PARKLAND HOSP] 3523 Espanola Dr	Responding From = ZODIAC LN\DAIRY MILK LN	RE30
2/23/2018	07:01:34	RE30	Enr	3523 Espanola Dr	Active incident marked as late	
2/23/2018	07:01:34		Incident Late		Responding From = IRVING BLVD\TURTLE CREEK BLVD	RE01
2/23/2018	07:01:45	RE01	Enr	3523 Espanola Dr	Active incident marked as late	
2/23/2018	07:01:46		Incident Late			
2/23/2018	07:01:46	RE43	At Fac	1935 MEDICAL DISTRICT DR [CHILDRENS MED CTR DALLAS]		RE43
2/23/2018	07:02:17	780	Assgn	3523 Espanola Dr	Response Number (02232018-0067367)	012443
2/23/2018	07:02:46		Read Comment		Comment for Incident 667 was Marked as Read.	012443

2/23/2018	07:04:11		UserAction		User clicked Exit/Save	012443
2/23/2018	07:04:27	RE01	Route Deviation	N STEMMONS SERV NBIN STEMMONS ACRD NB 3523 Espanola Dr	Unit RE01 deviated from original driving directions route	RE01
2/23/2018	07:05:34	684	Enr		Responding From = DAWSON ST\CHESTNUT ST	684
2/23/2018	07:05:35	885	Assgn	3523 Espanola Dr	Response Number (02232018-0067368)	012443
2/23/2018	07:05:35		Incident Late		Active incident marked as late	
2/23/2018	07:05:46		Incident Late		Active incident marked as late	
2/23/2018	07:05:49	685	Enr	3523 Espanola Dr	Responding From = E R L THORNTON FWY	685
2/23/2018	07:07:25	806	Assgn	3523 Espanola Dr	Response Number (02232018-0067370)	012443
2/23/2018	07:08:02	780	Enr	3523 Espanola Dr	Responding From = DAWSON ST\CHESTNUT ST	780
2/23/2018	07:08:05		Incident Late		Active incident marked as late	
2/23/2018	07:08:17	806	Enr	3523 Espanola Dr	Responding From = GREENVILLE AVE\UNNAMED STREET	806
2/23/2018	07:08:19		Incident Late		Active incident marked as late	
2/23/2018	07:08:29	885	Enr	3523 Espanola Dr	Responding From = ADMIN	021252
2/23/2018	07:08:32	885	Clear	3523 Espanola Dr		021252
2/23/2018	07:08:42		Read Comment		Comment for Incident 667 was Marked as Read.	012443
2/23/2018	07:08:43	881	Assgn	3523 Espanola Dr	Response Number (02232018-0067371)	021252
2/23/2018	07:08:43	RE01	Unit Backed up	3523 Espanola Dr	Backed up with 881 - Response Priority	021252
2/23/2018	07:08:47		UserAction		User clicked Add Resource	012443
2/23/2018	07:08:53		VisiCAD Recommendation		EN42: 00:06:33, EN02: 00:07:26, EN41: 00:07:26, EN47: 00:07:58, EN01: 00:12:01, User Accepted EN42	012443
2/23/2018	07:08:54		UserAction		The following unit(s) is (are) recommended for assignment: EN42 (00:06:33)	012443
2/23/2018	07:08:54		Add Resources		User Accepted EN02	
2/23/2018	07:08:55		UserAction		The following unit(s) is (are) recommended for assignment: EN02 (00:07:26)	012443
2/23/2018	07:08:55		Add Resources		User Accepted EN41	
2/23/2018	07:08:55		UserAction		The following unit(s) is (are) recommended for assignment: EN41 (00:07:26)	012443
2/23/2018	07:08:57	EN02	Assgn	3523 Espanola Dr	Response Number (02232018-0067373)	012443
2/23/2018	07:08:57	EN41	Assgn	3523 Espanola Dr	Response Number (02232018-0067374)	012443
2/23/2018	07:08:57	EN42	Assgn	3523 Espanola Dr	Response Number (02232018-0067372)	012443
2/23/2018	07:09:08	RE30	At Scene	3523 Espanola Dr		RE30
2/23/2018	07:09:23	EN41	Enr	3523 Espanola Dr	Responding From = NORTHAVEN RD\MIDWAY RD	EN41
2/23/2018	07:10:19	RE37	To Fac	5200 HARRY HINES BLVD [PARKLAND HOSP]	Transport Priority - Priority 3; Protocol - Code 1	RE37
2/23/2018	07:10:25	EN42	Enr	3523 Espanola Dr	Responding From = W MOCKINGBIRD LN\UNNAMED STREET	EN42
2/23/2018	07:10:29	EN02	Enr	3523 Espanola Dr	Responding From = MIDWAY RD\NORTHAVEN RD	EN02
2/23/2018	07:10:36	780	Route Deviation	DAWSON ST\CHESTNUT ST	Unit 780 deviated from original driving directions	780
2/23/2018	07:10:44		Incident Late		Active incident marked as late	
2/23/2018	07:11:47		Address Update		Address Update Accepted by User Inc#: 2018049283	012443
2/23/2018	07:11:48		Read Comment		Comment for Incident 667 was Marked as Read.	012443
2/23/2018	07:12:04	RE47	To Fac	5200 HARRY HINES BLVD [PARKLAND HOSP]	Transport Priority - Priority 3; Protocol - Code 1	RE47
2/23/2018	07:12:40	881	Enr	3534 ESPANOLA DR	Responding From = ADMIN	012443
2/23/2018	07:15:34		Read Comment		Comment for Incident 667 was Marked as Read.	031410
2/23/2018	07:16:07	RE01	At Scene	3534 ESPANOLA DR		RE01
2/23/2018	07:16:24	RE42	At Fac	5200 HARRY HINES BLVD [PARKLAND HOSP]		RE42
2/23/2018	07:16:42	EN41	At Scene	3534 ESPANOLA DR		EN41
2/23/2018	07:16:53	EN02	At Scene	3534 ESPANOLA DR		EN02
2/23/2018	07:19:54	RE37	At Fac	5200 HARRY HINES BLVD [PARKLAND HOSP]		RE37
2/23/2018	07:21:20	RE30	To Fac	1935 MEDICAL DISTRICT DR [CHILDRENS MED CTR DALLAS]	Transport Priority - Priority 3; Protocol - Code 1	RE30
2/23/2018	07:22:02		UserAction		User clicked Exit/Save	012443
2/23/2018	07:22:17		Read Comment		Comment for Incident 667 was Marked as Read.	079054
2/23/2018	07:23:40		UserAction		User clicked Exit/Save	079054
2/23/2018	07:24:38	RE43	Clear	3534 ESPANOLA DR		RE43
2/23/2018	07:24:47	806	At Scene	3534 ESPANOLA DR		806
2/23/2018	07:24:49	RE47	At Fac	5200 HARRY HINES BLVD [PARKLAND HOSP]		RE47
2/23/2018	07:24:53		UserAction		User clicked Exit/Save	007466
2/23/2018	07:28:05		UserAction		User clicked Exit/Save	018802
2/23/2018	07:28:32	EN42	At Scene	3534 ESPANOLA DR		012443
2/23/2018	07:28:33	684	At Scene	3534 ESPANOLA DR		684
2/23/2018	07:28:42	780	At Scene	3534 ESPANOLA DR		012443
2/23/2018	07:28:45	685	At Scene	3534 ESPANOLA DR		685
2/23/2018	07:29:58		UserAction		User clicked Exit/Save	021252
2/23/2018	07:31:01	RE30	Change Tx Destination	PARKLAND HOSP	Tx Destination Changed from 1935 MEDICAL DISTRICT DR to 5200 Harry Hines Blvd	034017
2/23/2018	07:37:21	RE30	At Fac	5200 Harry Hines Blvd [PARKLAND HOSP]		RE30
2/23/2018	07:37:29		Read Comment		Comment for Incident 667 was Marked as Read.	007466

2/23/2018	07:38:31		UserAction		User clicked Exit/Save	007466
2/23/2018	07:50:23	EN42	Clear	3534 ESPANOLA DR	(Response Viewer)	EN42
2/23/2018	07:51:21		Notify Comment		Comment for Incident 667 was Marked as Read.	106177
2/23/2018	07:51:21		Read Comment			
2/23/2018	07:52:08	EN41	Clear	3534 ESPANOLA DR		EN41
2/23/2018	07:52:54		UserAction		User clicked Exit/Save	007466
2/23/2018	07:54:41	RE42	Clear	3534 ESPANOLA DR		RE42
2/23/2018	07:59:39	EN02	Clear	3534 ESPANOLA DR		EN02
2/23/2018	08:02:17		UserAction		User clicked Exit/Save	031410
2/23/2018	08:02:51	RE47	Clear	3534 ESPANOLA DR		RE47
2/23/2018	08:03:39	RE37	Clear	3534 ESPANOLA DR		RE37
2/23/2018	08:06:34	RE30	Clear	3534 ESPANOLA DR		RE30
2/23/2018	08:16:51	881	At Scene	3534 ESPANOLA DR		056748
2/23/2018	08:20:40		Read Comment		Comment for Incident 667 was Marked as Read.	021252
2/23/2018	08:20:43		Load Times		Depart Scene Time: 06:51:51, Arrive Destination Time: 07:01:46	021252
2/23/2018	08:20:43		Load Times		Depart Scene Time: 07:01:21, Arrive Destination Time: 07:16:24	021252
2/23/2018	08:20:43		Load Times		Depart Scene Time: 07:10:19, Arrive Destination Time: 07:19:54	021252
2/23/2018	08:20:43		Load Times		Depart Scene Time: 07:12:04, Arrive Destination Time: 07:24:49	021252
2/23/2018	08:20:57		UserAction		Depart Scene Time: 07:21:20, Arrive Destination Time: 07:37:21	021252
2/23/2018	08:26:07		UserAction		User clicked Exit/Save	007466
2/23/2018	08:48:49		Read Comment		Comment for Incident 667 was Marked as Read.	079054
2/23/2018	08:51:29	684	Clear	3534 ESPANOLA DR		684
2/23/2018	08:52:01	806	Clear	3534 ESPANOLA DR		806
2/23/2018	08:54:29	678	Assgn	3534 ESPANOLA DR	Response Number (02232018-0067479)	089972
2/23/2018	08:54:44	659	Assgn	3534 ESPANOLA DR	Response Number (02232018-0067480)	089972
2/23/2018	08:55:08	601	Assgn	3534 ESPANOLA DR	Response Number (02232018-0067481)	089972
2/23/2018	08:56:30		Incident Late		Active incident marked as late	
2/23/2018	08:59:16		UserAction		User clicked Exit/Save	079054
2/23/2018	09:02:25		UserAction		User clicked Exit/Save	065642
2/23/2018	09:06:41	601	At Scene	3534 ESPANOLA DR		056748
2/23/2018	09:06:41	659	At Scene	3534 ESPANOLA DR		056748
2/23/2018	09:06:41	678	At Scene	3534 ESPANOLA DR		056748
2/23/2018	09:10:16		Read Comment		Comment for Incident 667 was Marked as Read.	034562
2/23/2018	09:10:35		UserAction		User clicked Exit/Save	034562
2/23/2018	09:11:01		UserAction		User clicked Exit/Save	034562
2/23/2018	09:15:36		UserAction		User clicked Exit/Save	019654
2/23/2018	09:16:37		UserAction		User clicked Exit/Save	019654
2/23/2018	09:21:54	782	Route Deviation	ESPANOLA DRIEL CENTRO DR	Unit 782 deviated from original driving directions route	
2/23/2018	09:37:03		Notify Comment		(Response Viewer)	
2/23/2018	09:37:03		Read Comment		Comment for Incident 667 was Marked as Read.	056748
2/23/2018	09:37:34		UserAction		User clicked Exit/Save	089972
2/23/2018	09:39:53		UserAction		User selected Add Additional Resources from PowerLine	056748
2/23/2018	09:40:13		VisiCAD Recommendation		EN42: 00:05:21, EN02: 00:06:11, EN41: 00:07:21, EN47: 00:08:01, EN11: 00:10:34, User Accepted EN42	056748
2/23/2018	09:40:15		UserAction		The following unit(s) is (are) recommended for assignment: EN42 (00:05:21)	056748
2/23/2018	09:40:15		Add Resources		Response Number (02232018-0067529)	056748
2/23/2018	09:40:17	EN42	Assgn	3534 ESPANOLA DR	Backed up with 896 - Response Priority	034017
2/23/2018	09:41:22	EN35	Unit Backed up	3534 ESPANOLA DR	Response Number (02232018-0067534)	034017
2/23/2018	09:41:22	896	Assgn	3534 ESPANOLA DR	Responding From = W MOCKINGBIRD	EN42
2/23/2018	09:41:37	EN42	Enr	3534 ESPANOLA DR	LNAIRDROME DR	
2/23/2018	09:41:52		UserAction		User clicked Exit/Save	034562
2/23/2018	09:43:23		Incident Late		Active incident marked as late	
2/23/2018	09:45:17		Read Comment		Comment for Incident 667 was Marked as Read.	089972
2/23/2018	09:45:36		Read Comment		Comment for Incident 667 was Marked as Read.	122119
2/23/2018	09:45:37		Notify Comment		(Response Viewer)	
2/23/2018	09:46:04		UserAction		User clicked Exit/Save	089972
2/23/2018	09:48:00	EN42	At Scene	3534 ESPANOLA DR		EN42
2/23/2018	09:48:04		Incident Late		Active incident marked as late	
2/23/2018	09:56:10	806	Assgn	3534 ESPANOLA DR	Response Number (02232018-0067543)	056748
2/23/2018	09:56:16	806	Enr	3534 ESPANOLA DR	Status bypassed by user due to allowable status change	806
2/23/2018	09:56:16	806	Enr	3534 ESPANOLA DR	Responding From = ESPANOLA DRIEL CENTRO DR	806
2/23/2018	09:56:16	806	At Scene	3534 ESPANOLA DR		806
2/23/2018	09:56:18		Incident Late		Active incident marked as late	
2/23/2018	10:01:15	896	Enr	3534 ESPANOLA DR	Responding From = STA 28	056748
2/23/2018	10:12:10	TR41	Clear	3534 ESPANOLA DR		TR41
2/23/2018	10:20:06	896	At Scene	3534 ESPANOLA DR		021252
2/23/2018	10:28:05		Read Comment		Comment for Incident 667 was Marked as Read.	021252
2/23/2018	10:31:02		UserAction		User clicked Exit/Save	021252
2/23/2018	10:41:57		UserAction		User clicked Exit/Save	100758
2/23/2018	10:45:58		UserAction		User clicked Exit/Save	110624

2/23/2018	10:53:33		UserAction		User clicked Exit/Save	021252
2/23/2018	11:02:35		UserAction		User clicked Exit/Save	110624
2/23/2018	11:07:15		Read Comment		Comment for Incident 667 was Marked as Read.	110624
2/23/2018	11:09:14		UserAction		User clicked Exit/Save	056748
2/23/2018	11:10:55		UserAction		User clicked Exit/Save	110624
2/23/2018	11:12:18	897	Assgn	3534 ESPANOLA DR	Response Number (02232018-0067626)	056748
2/23/2018	11:12:22	897	Enr	3534 ESPANOLA DR	Responding From = STA 28	056748
2/23/2018	11:20:23		Read Comment		Comment for Incident 667 was Marked as Read.	021252
2/23/2018	11:20:42		Read Comment		Comment for Incident 667 was Marked as Read.	106177
2/23/2018	11:20:43		Read Comment		Comment for Incident 667 was Marked as Read.	110624
2/23/2018	11:20:43		Notify Comment		(Response Viewer)	
2/23/2018	11:20:52		UserAction		User clicked Exit/Save	021252
2/23/2018	11:34:01	601	Clear	3534 ESPANOLA DR		021252
2/23/2018	11:34:01	659	Clear	3534 ESPANOLA DR		021252
2/23/2018	11:34:02	678	Clear	3534 ESPANOLA DR		021252
2/23/2018	11:35:24	685	Clear	3534 ESPANOLA DR		685
2/23/2018	11:40:31	897	At Scene	3534 ESPANOLA DR		056748
2/23/2018	11:41:41		Read Comment		Comment for Incident 667 was Marked as Read.	021252
2/23/2018	11:42:02		UserAction		User clicked Add Resource	021252
2/23/2018	11:42:28		UserAction		User clicked Exit/Save	021252
2/23/2018	11:42:38		UserAction		User selected Add Additional Resources from PowerLine	021252
2/23/2018	11:42:41		VisiCAD Recommendation		US19: 00:17:06, US33: 00:19:34,	021252
2/23/2018	11:45:46	EN43	Clear	3534 ESPANOLA DR		EN43
2/23/2018	11:46:11	US19	Assgn	3534 ESPANOLA DR	Response Number (02232018-0067653)	112235
2/23/2018	11:47:06		UserAction		User clicked Exit/Save	101117
2/23/2018	11:48:12		Incident Late		Active incident marked as late	
2/23/2018	11:48:53	US19	Enr	3534 ESPANOLA DR	Responding From = STA 19	US19
2/23/2018	11:49:03	EN30	Clear	3534 ESPANOLA DR		EN30
2/23/2018	11:52:00	782	Clear	3534 ESPANOLA DR		782
2/23/2018	11:54:12	TR43	Clear	3534 ESPANOLA DR		TR43
2/23/2018	11:54:28	EN35	Clear	3534 ESPANOLA DR		EN35
2/23/2018	11:57:10	EN42	Clear	3534 ESPANOLA DR		EN42
2/23/2018	12:05:28		Read Comment		Comment for Incident 667 was Marked as Read.	079054
2/23/2018	12:06:50		UserAction		User clicked Exit/Save	079054
2/23/2018	12:07:34	US19	At Scene	3534 ESPANOLA DR		US19
2/23/2018	12:09:28		Read Comment		Comment for Incident 667 was Marked as Read.	089972
2/23/2018	12:10:52		Notify Comment		(Response Viewer)	
2/23/2018	12:10:52		Read Comment		Comment for Incident 667 was Marked as Read.	053831
2/23/2018	12:11:55		UserAction		User clicked Exit/Save	089972
2/23/2018	12:16:06		UserAction		User clicked Exit/Save	101117
2/23/2018	12:20:48		Premise History Access		Premise History Viewed	101117
2/23/2018	12:22:09		UserAction		User clicked Exit/Save	101117
2/23/2018	12:26:18		UserAction		User clicked Exit/Save	089972
2/23/2018	12:28:09		UserAction		User clicked Exit/Save	101117
2/23/2018	12:48:09	806	Clear	3534 ESPANOLA DR		806
2/23/2018	12:59:45		Read Comment		Comment for Incident 667 was Marked as Read.	065642
2/23/2018	12:59:49		Load Times		Depart Scene Time: 06:51:51, Arrive Destination Time: 07:01:46	065642
2/23/2018	12:59:49		Load Times		Depart Scene Time: 07:01:21, Arrive Destination Time: 07:16:24	065642
2/23/2018	12:59:49		Load Times		Depart Scene Time: 07:10:19, Arrive Destination Time: 07:19:54	065642
2/23/2018	12:59:49		Load Times		Depart Scene Time: 07:12:04, Arrive Destination Time: 07:24:49	065642
2/23/2018	12:59:49		Load Times		Depart Scene Time: 07:21:20, Arrive Destination Time: 07:37:21	065642
2/23/2018	13:01:16		UserAction		User clicked Add Resource	065642
2/23/2018	13:01:25		VisiCAD Recommendation		RE42: 00:06:41, RE30: 00:06:51, RE47: 00:08:13, RE11: 00:10:52, RE20: 00:12:42,	065642
2/23/2018	13:02:07		UserAction		User Accepted RE20	
2/23/2018	13:02:07		Add Resources		The following unit(s) is (are) recommended for assignment: RE20 (00:12:42)	065642
2/23/2018	13:02:09	RE20	Assgn	3534 ESPANOLA DR	Response Number (02232018-0067720)	065642
2/23/2018	13:02:10		UserAction		User clicked Exit/Save	065642
2/23/2018	13:02:41	RE20	Enr	3534 ESPANOLA DR	Responding From = HARVEST HILL	RE20
2/23/2018	13:13:29	US19	Clear	3534 ESPANOLA DR		US19
2/23/2018	13:18:50	RE20	At Scene	3534 ESPANOLA DR		RE20
2/23/2018	13:29:20		Read Comment		Comment for Incident 667 was Marked as Read.	065642
2/23/2018	13:34:49		UserAction		User clicked Exit/Save	065642
2/23/2018	13:46:12	RE01	Clear	3534 ESPANOLA DR		101117
2/23/2018	13:54:34	896	Clear	3534 ESPANOLA DR		007466
2/23/2018	14:02:42	897	Clear	3534 ESPANOLA DR		007466
2/23/2018	14:06:07		Read Comment		Comment for Incident 667 was Marked as Read.	007466
2/23/2018	14:06:42		UserAction		User clicked Exit/Save	007466
2/23/2018	14:10:25	825	Assgn	3534 ESPANOLA DR	Response Number (02232018-0067782)	007466
2/23/2018	14:11:30		Read Comment		Comment for Incident 667 was Marked as Read.	007466

2/23/2018	14:12:26		Incident Late		Active incident marked as late	
2/23/2018	14:12:35	825	Enr	3534 ESPANOLA DR	Responding From = STA 06	007466
2/23/2018	14:12:35	780	Clear	3534 ESPANOLA DR		780
2/23/2018	14:14:49		UserAction		User clicked Exit/Save	007466
2/23/2018	14:20:26		Read Comment		Comment for Incident 667 was Marked as Read.	007466
2/23/2018	14:21:15		UserAction		User clicked Exit/Save	007466
2/23/2018	14:24:35		Read Comment		Comment for Incident 667 was Marked as Read.	007466
2/23/2018	14:26:01		Notify Comment		(Response Viewer)	
2/23/2018	14:26:01		Read Comment		Comment for Incident 667 was Marked as Read.	122756
2/23/2018	14:26:36	RE20	Clear	3534 ESPANOLA DR		RE20
2/23/2018	14:26:57		UserAction		User clicked Exit/Save	007466
2/23/2018	14:52:54	825	At Scene	3534 ESPANOLA DR		007466
2/23/2018	14:55:01		Read Comment		Comment for Incident 667 was Marked as Read.	065642
2/23/2018	14:57:05		UserAction		User clicked Exit/Save	007466
2/23/2018	15:00:20		UserAction		User clicked Exit/Save	065642
2/23/2018	15:01:16		Read Comment		Comment for Incident 667 was Marked as Read.	065642
2/23/2018	15:09:57		Read Comment		Comment for Incident 667 was Marked as Read.	101117
2/23/2018	15:10:00		Load Times		Depart Scene Time: 06:51:51, Arrive Destination Time: 07:01:46	101117
2/23/2018	15:10:00		Load Times		Depart Scene Time: 07:01:21, Arrive Destination Time: 07:16:24	101117
2/23/2018	15:10:00		Load Times		Depart Scene Time: 07:10:19, Arrive Destination Time: 07:19:54	101117
2/23/2018	15:10:00		Load Times		Depart Scene Time: 07:12:04, Arrive Destination Time: 07:24:49	101117
2/23/2018	15:10:00		Load Times		Depart Scene Time: 07:21:20, Arrive Destination Time: 07:37:21	101117
2/23/2018	15:10:13		UserAction		User clicked Exit/Save	065642
2/23/2018	15:10:56		UserAction		User clicked Exit/Save	101117
2/23/2018	16:18:42		Read Comment		Comment for Incident 667 was Marked as Read.	065642
2/23/2018	16:23:09	881	Clear	3534 ESPANOLA DR		007466
2/23/2018	16:26:22		UserAction		User clicked Exit/Save	007466
2/23/2018	16:32:50		Read Incident		Incident 667 was Marked as Read.	065642
2/23/2018	16:32:50	RE70	Assgn	3534 ESPANOLA DR	Response Number (02232018-0067922)	065642
2/23/2018	16:32:54		Read Comment		Comment for Incident 667 was Marked as Read.	065642
2/23/2018	16:34:28	RE70	Enr	3534 ESPANOLA DR	Responding From = N GRIFFIN ST\ROSS AVE	RE70
2/23/2018	16:35:17		UserAction		User clicked Exit/Save	065642
2/23/2018	16:55:46	825	Clear	3534 ESPANOLA DR		065642
2/23/2018	17:06:12		Read Comment		Comment for Incident 667 was Marked as Read.	065642
2/23/2018	17:09:08	RE70	At Scene	3534 ESPANOLA DR		RE70
2/23/2018	17:21:01		UserAction		User clicked Exit/Save	071236
2/23/2018	17:33:09		UserAction		User clicked Exit/Save	065642
2/23/2018	17:45:03		Read Comment		Comment for Incident 667 was Marked as Read.	089972
2/23/2018	17:58:28		Read Comment		Comment for Incident 667 was Marked as Read.	089972
2/23/2018	18:02:29		UserAction		User clicked Exit/Save	089972
2/23/2018	18:11:51	825	Assgn	3534 ESPANOLA DR	Response Number (02232018-0068039)	065642
2/23/2018	18:11:54	825	At Scene	3534 ESPANOLA DR		065642
2/23/2018	18:13:28		Read Comment		Comment for Incident 667 was Marked as Read.	065642
2/23/2018	18:19:00		UserAction		User clicked Exit/Save	065642
2/23/2018	18:30:31		Read Comment		Comment for Incident 667 was Marked as Read.	065642
2/23/2018	18:31:28		UserAction		User clicked Exit/Save	065642
2/23/2018	19:18:39		Read Comment		Comment for Incident 667 was Marked as Read.	065642
2/23/2018	19:18:43		UserAction		User clicked Exit/Save	065642
2/23/2018	19:19:59	BC07	Clear	3534 ESPANOLA DR		BC07
2/23/2018	19:59:24		Read Comment		Comment for Incident 667 was Marked as Read.	065642
2/23/2018	19:59:30		Load Times		Depart Scene Time: 06:51:51, Arrive Destination Time: 07:01:46	065642
2/23/2018	19:59:30		Load Times		Depart Scene Time: 07:01:21, Arrive Destination Time: 07:16:24	065642
2/23/2018	19:59:30		Load Times		Depart Scene Time: 07:10:19, Arrive Destination Time: 07:19:54	065642
2/23/2018	19:59:30		Load Times		Depart Scene Time: 07:12:04, Arrive Destination Time: 07:24:49	065642
2/23/2018	19:59:30		Load Times		Depart Scene Time: 07:21:20, Arrive Destination Time: 07:37:21	065642
2/23/2018	20:00:05		UserAction		User clicked Exit/Save	065642
2/23/2018	21:01:45		Read Comment		Comment for Incident 667 was Marked as Read.	065642
2/23/2018	21:03:16		UserAction		User clicked Exit/Save	065642
2/23/2018	21:03:21		UserAction		User clicked Exit/Save	065642
2/23/2018	21:06:35		UserAction		User clicked Exit/Save	021252
2/23/2018	21:27:29		UserAction		User selected Add Additional Resources from PowerLine	021252
2/23/2018	21:27:33		VisiCAD Recommendation		RE37: 00:12:35, RE28: 00:14:48, RE03: 00:14:58, RE04: 00:15:02, RE55: 00:15:04,	021252

2/23/2018	21:35:38		UserAction			User selected Add Additional Resources from PowerLine	021252
2/23/2018	21:35:41		VisiCAD Recommendation			RE30: 00:05:48, RE28: 00:14:48, RE03: 00:14:58, RE04: 00:15:02, RE55: 00:15:04, User Accepted RE28	021252
2/23/2018	21:36:31		UserAction			The following unit(s) is (are) recommended for assignment: RE28 (00:14:48)	021252
2/23/2018	21:36:31		Add Resources			Response Number (02232018-0068262)	021252
2/23/2018	21:36:37	RE28	Assgn	3534 ESPANOLA DR		Active incident marked as late	021252
2/23/2018	21:38:38		Incident Late			Responding From = GREENVILLE AVE\UNNAMED STREET	021252
2/23/2018	21:38:49	RE28	Enr	3534 ESPANOLA DR			021252
2/23/2018	21:55:29	RE28	At Scene	3534 ESPANOLA DR			RE28
2/23/2018	21:56:33	RE70	Clear	3534 ESPANOLA DR			021252
2/23/2018	22:51:43	825	Clear	3534 ESPANOLA DR			065642
2/23/2018	23:39:59	BC09	Clear	3534 ESPANOLA DR			BC09
2/23/2018	23:49:46		UserAction			User selected Add Additional Resources from PowerLine	021252
2/23/2018	23:49:49		VisiCAD Recommendation			RE37: 00:12:35, RE44: 00:12:41, RE08: 00:13:51, RE29: 00:14:02, RE06: 00:16:49, User Accepted RE44	021252
2/23/2018	23:50:03		UserAction			The following unit(s) is (are) recommended for assignment: RE44 (00:12:41)	021252
2/23/2018	23:50:03		Add Resources			Response Number (02232018-0068426)	021252
2/23/2018	23:50:04	RE44	Assgn	3534 ESPANOLA DR		Responding From = N STEMMONS FWY NB\N STEMMONS ACRD NB	RE44
2/23/2018	23:50:18	RE44	Enr	3534 ESPANOLA DR		ReAssign Reason: Swap	065642
2/23/2018	23:50:29	RE44	ReAssign Vehicle	3534 ESPANOLA DR		Clearing Primary Vehicle Flag	065642
2/23/2018	23:50:29		ReAssign Response	3534 ESPANOLA DR		Comment for Incident 667 was Marked as Read.	055396
2/24/2018	00:07:16		Read Comment			Depart Scene Time: 06:51:51, Arrive Destination Time: 07:01:46	055396
2/24/2018	00:07:19		Load Times			Depart Scene Time: 07:01:21, Arrive Destination Time: 07:16:24	055396
2/24/2018	00:07:19		Load Times			Depart Scene Time: 07:10:19, Arrive Destination Time: 07:19:54	055396
2/24/2018	00:07:19		Load Times			Depart Scene Time: 07:12:04, Arrive Destination Time: 07:24:49	055396
2/24/2018	00:07:19		Load Times			Depart Scene Time: 07:21:20, Arrive Destination Time: 07:37:21	055396
2/24/2018	00:08:29		UserAction			User clicked Exit/Save	055396
2/24/2018	00:44:19	RE28	Clear	3534 ESPANOLA DR			RE28
2/24/2018	00:44:20	RE28	Response Closed	3534 ESPANOLA DR		Response Disposition:	RE28
2/24/2018	04:57:53		Read Comment			Comment for Incident 667 was Marked as Read.	089972
2/24/2018	04:58:04		Load Times			Depart Scene Time: 06:51:51, Arrive Destination Time: 07:01:46	089972
2/24/2018	04:58:04		Load Times			Depart Scene Time: 07:01:21, Arrive Destination Time: 07:16:24	089972
2/24/2018	04:58:04		Load Times			Depart Scene Time: 07:10:19, Arrive Destination Time: 07:19:54	089972
2/24/2018	04:58:04		Load Times			Depart Scene Time: 07:12:04, Arrive Destination Time: 07:24:49	089972
2/24/2018	04:58:04		Load Times			Depart Scene Time: 07:21:20, Arrive Destination Time: 07:37:21	089972
2/24/2018	05:02:41		UserAction			User clicked Exit/Save	089972

Edit Log

Date	Time	Field	Changed From	Changed To	Reason	Table	Workstation	User
2/23/2018	06:38:02	Longitude	0	96860601	Entry Verified	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:02	Latitude	0	32868271	Entry Verified	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:02	City		Dallas	Updated City	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:02	Address	3523 ESPANOLA DR	3523 ESPANOLA DR	Entry Verified	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:02	ResponsePlanType	0	0	(Response Viewer)	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:02	Response_Area		DAL	(Response Viewer)	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:02	Battalion		Dallas Fire	(Response Viewer)	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:02	Division		Dallas Fire	(Response Viewer)	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:02	Jurisdiction		Dallas Fire	(Response Viewer)	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:02	Address	(Blank)	3523 ESPANOLA DR	New Entry	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:02	Call_Back_Phone		(214) 358-4809	(Response Viewer)	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:13	Priority_Number	0	1		Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:13	Priority_Description		Emergency		Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:13	Problem		98 - Structure Fire	(Response Viewer)	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:15	MethodOfCallRcvd		Telephone	(Response Viewer)	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:15	Map_Info		23-V		Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:15	Pickup_Map_Info		23-V		Response_Transports	CADDFRF281B031410	
2/23/2018	06:38:15	Caller_Building		350001	Polygon Lookup	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:38:49	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF280B093104	
2/23/2018	06:38:49	Read Call	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF280B093104	
2/23/2018	06:39:03	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CAD911CT350 115624	

2/23/2018	06:39:11	Incident_Type	STRUCTURE FIRE A (REPORTED)	STRUCTURE FIRE A (WORKING)	(Response Viewer)	Response_Master_Incident	CADDFRF280B093104
2/23/2018	06:39:11	Response_Plan	*DFR-A BOX (REPORTED)	*DFR-A BOX (WORKING)	(Response Viewer)	Response_Master_Incident	CADDFRF280B093104
2/23/2018	06:39:11	RespReconfigState	0	1	Response reconfigure needed	Response_Master_Incident	CADDFRF280B093104
2/23/2018	06:39:11	Problem	98 - Structure Fire Reported	99 - Structure Fire Working	(Response Viewer)	Response_Master_Incident	CADDFRF280B093104
2/23/2018	06:39:12	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF290B055396
2/23/2018	06:39:12	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT358 119914
2/23/2018	06:39:12	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF281B031410
2/23/2018	06:39:12	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT347 046518
2/23/2018	06:39:13	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF284B101097
2/23/2018	06:39:13	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF283B012443
2/23/2018	06:39:13	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT343 053831
2/23/2018	06:39:14	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT312 085032
2/23/2018	06:39:16	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT344 118185
2/23/2018	06:40:03	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF283B012443
2/23/2018	06:42:09	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF280B093104
2/23/2018	06:42:56	Date_Time		Feb 23 2018 06:42:56	*Notified - Gas Utility	Response_User_TimeStamp	CADDFRF290B055396
2/23/2018	06:43:50	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF290B055396
2/23/2018	06:44:25	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF290B055396
2/23/2018	06:44:25	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	APCAD105 DFRAPIUSER
2/23/2018	06:44:25	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT347 046518
2/23/2018	06:44:25	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF281B031410
2/23/2018	06:44:26	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF282B034562
2/23/2018	06:44:26	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT343 053831
2/23/2018	06:44:26	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT312 085032
2/23/2018	06:44:29	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT344 118185
2/23/2018	06:44:43	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF282B034562
2/23/2018	06:44:43	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF290B055396
2/23/2018	06:44:43	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT347 046518
2/23/2018	06:44:43	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF280B093104
2/23/2018	06:44:43	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF281B031410
2/23/2018	06:44:43	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT358 119914
2/23/2018	06:44:43	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	APCAD105 DFRAPIUSER
2/23/2018	06:44:44	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT312 085032

2/23/2018	06:44:44	Read Comment	False	True	Notification Window)	Response_Master_Incident	CAD911CT343	053831
2/23/2018	06:44:44	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF283B012443	
2/23/2018	06:44:46	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT344	118185
2/23/2018	06:44:52	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF282B034562	
2/23/2018	06:45:09	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDPDPCHO	115127
2/23/2018	06:46:11	Read Comment	False	True	(Recall Window)	Response_Master_Incident	CAD911CT358	119914
2/23/2018	06:46:48	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF290B055396	
2/23/2018	06:46:48	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF289B034562	
2/23/2018	06:46:48	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT358	119914
2/23/2018	06:46:48	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF282B034562	
2/23/2018	06:46:48	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	06:46:48	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT347	046518
2/23/2018	06:46:48	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	APCAD105	DFRAPIUSER
2/23/2018	06:46:49	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT312	085032
2/23/2018	06:46:51	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT344	118185
2/23/2018	06:48:26	Date_Time		Feb 23 2018 06:48:26	*Notified - Electric Utility	Response_User_TimeStamp	CADDFRF290B055396	
2/23/2018	06:53:00	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF290B055396	
2/23/2018	06:55:02	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CAD911CT347	046518
2/23/2018	07:02:46	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF283B012443	
2/23/2018	07:08:42	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF283B012443	
2/23/2018	07:11:44	Address	3523 Espanola Dr	3534 ESPANOLA DR	Update Address Form	Response_Master_Incident	CADDFRF283B012443	
2/23/2018	07:11:44	Map_Info	23-V		Powerline Command	Response_Master_Incident	CADDFRF283B012443	
2/23/2018	07:11:44	Longitude	96860601	96860336	Powerline Command	Response_Master_Incident	CADDFRF283B012443	
2/23/2018	07:11:44	Latitude	32868271	32868327	Powerline Command	Response_Master_Incident	CADDFRF283B012443	
2/23/2018	07:11:44	Address	3523 Espanola Dr	3534 ESPANOLA DR	Powerline Command	Response_Master_Incident	CADDFRF283B012443	
2/23/2018	07:11:45	Map_Info		23-V		Response_Master_Incident	CADDFRF283B012443	
2/23/2018	07:11:45	Pickup_Map_Info		23-V		Response_Transports	CADDFRF283B012443	
2/23/2018	07:11:45	Caller_Building	350001	350001	Polygon Lookup	Response_Master_Incident	CADDFRF283B012443	
2/23/2018	07:11:48	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF283B012443	
2/23/2018	07:15:34	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF281B031410	
2/23/2018	07:22:17	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF285B079054	
2/23/2018	07:31:01	Address	1935 MEDICAL DISTRICT DR	5200 Harry Hines Blvd		Response_Transports	CADDFRF282B034017	
2/23/2018	07:31:01	Address	1935 MEDICAL DISTRICT DR	5200 Harry Hines Blvd		Response_Transports	CADDFRF282B034017	
2/23/2018	07:31:01	Address	1935 MEDICAL DISTRICT DR	5200 Harry Hines Blvd		Response_Transports	CADDFRF282B034017	
2/23/2018	07:31:01	Address	1935 MEDICAL DISTRICT DR	5200 Harry Hines Blvd		Response_Transports	CADDFRF282B034017	
2/23/2018	07:31:01	Address	1935 MEDICAL DISTRICT DR	5200 Harry Hines Blvd		Response_Transports	CADDFRF282B034017	
2/23/2018	07:37:29	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF287B007466	
2/23/2018	07:51:21	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT311	106177
2/23/2018	07:51:22	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF285B079054	

2/23/2018	07:51:22	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF284B021252
2/23/2018	07:51:22	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident APCAD105 DFRAPIUSER
2/23/2018	07:51:22	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT356 117963
2/23/2018	07:51:22	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF283B055396
2/23/2018	07:51:22	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT347 046518
2/23/2018	07:51:22	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT363 100758
2/23/2018	07:51:22	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF281B031410
2/23/2018	07:51:22	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT359 116768
2/23/2018	07:51:23	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT364 110341
2/23/2018	07:51:23	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF289B034562
2/23/2018	07:51:23	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT336 116762
2/23/2018	08:20:40	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF284B021252
2/23/2018	08:48:49	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF285B079054
2/23/2018	09:10:16	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF289B034562
2/23/2018	09:37:02	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT347 046518
2/23/2018	09:37:03	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF284B019654
2/23/2018	09:37:03	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT363 100758
2/23/2018	09:37:03	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF283B056748
2/23/2018	09:37:03	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT336 116762
2/23/2018	09:37:03	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT356 117963
2/23/2018	09:37:04	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF285B079054
2/23/2018	09:45:17	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF287B089972
2/23/2018	09:45:36	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT367 122119
2/23/2018	09:45:37	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF286B070211
2/23/2018	09:45:37	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF281B034017
2/23/2018	10:28:05	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF287B021252
2/23/2018	11:02:26	Field_Data		RED CROSS IS NEEDED UNKOWN NUMBERS	RED CROSS PAGE	Response_User_Data_FieldCADDFRF288B110624 s
2/23/2018	11:07:15	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF288B110624
2/23/2018	11:20:23	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF287B021252
2/23/2018	11:20:42	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT311 106177
2/23/2018	11:20:43	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF288B110624
2/23/2018	11:20:43	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF283B056748
2/23/2018	11:20:43	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF290B112235

2/23/2018	11:20:44	Read Comment	False	True	Notification Window)	Response_Master_Incident CAD911CT312 085032
2/23/2018	11:20:44	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF285B079054
2/23/2018	11:20:44	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF280B035761
2/23/2018	11:20:44	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT336 116762
2/23/2018	11:41:41	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF287B021252
2/23/2018	12:05:28	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF285B079054
2/23/2018	12:09:28	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF283B089972
2/23/2018	12:10:52	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT343 053831
2/23/2018	12:10:52	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF289B034562
2/23/2018	12:10:53	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF287B021252
2/23/2018	12:10:53	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT364 110341
2/23/2018	12:10:53	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF284B070211
2/23/2018	12:10:53	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT347 046518
2/23/2018	12:10:53	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident APCAD105 DFRAPIUSER
2/23/2018	12:10:53	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT358 116768
2/23/2018	12:10:53	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT356 117963
2/23/2018	12:10:53	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF285B079054
2/23/2018	12:10:53	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF286B007466
2/23/2018	12:10:54	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT367 122119
2/23/2018	12:59:45	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF280B065642
2/23/2018	13:29:20	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF280B065642
2/23/2018	14:06:07	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF283B007466
2/23/2018	14:11:30	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF283B007466
2/23/2018	14:20:26	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF283B007466
2/23/2018	14:24:35	Read Comment	False	True	(Response Viewer)	Response_Master_Incident CADDFRF283B007466
2/23/2018	14:26:00	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT311 106177
2/23/2018	14:26:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF287B089972
2/23/2018	14:26:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF290B021252
2/23/2018	14:26:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT361 122742
2/23/2018	14:26:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CADDFRF289B034562
2/23/2018	14:26:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT364 110341
2/23/2018	14:26:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT362 122756
2/23/2018	14:26:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident CAD911CT336 116762

Date	Time	Action	Is Read	Is Deleted	Notification Window	Response	Master	Incident
2/23/2018	14:26:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF285B	079054
2/23/2018	14:26:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT343	122090
2/23/2018	14:26:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	APCAD105	DFRAPIUSER
2/23/2018	14:26:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT367	122119
2/23/2018	14:26:01	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF280B	065642
2/23/2018	14:26:02	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT363	100758
2/23/2018	14:26:02	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CADDFRF282B	101117
2/23/2018	14:26:02	Read Comment	False	True	(Comment Notification Window)	Response_Master_Incident	CAD911CT346	121758
2/23/2018	14:55:01	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF280B	065642
2/23/2018	15:01:16	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF280B	065642
2/23/2018	15:09:57	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF282B	101117
2/23/2018	16:18:42	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF280B	065642
2/23/2018	16:32:50	Read Call	False	True	(Powerline Unit Alert)	Response_Master_Incident	CADDFRF280B	065642
2/23/2018	16:32:54	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF280B	065642
2/23/2018	17:06:12	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF280B	065642
2/23/2018	17:45:03	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF283B	089972
2/23/2018	17:58:28	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF283B	089972
2/23/2018	18:13:28	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF280B	065642
2/23/2018	18:30:31	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF280B	065642
2/23/2018	19:18:39	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF283B	065642
2/23/2018	19:59:24	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF280B	065642
2/23/2018	21:01:45	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF283B	065642
2/24/2018	00:07:16	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF290B	055396
2/24/2018	04:57:53	Read Comment	False	True	(Response Viewer)	Response_Master_Incident	CADDFRF280B	089972

Custom Time Stamps
Description
 *Notified - Gas Utility
 *Notified - Electric Utility

Date	Time	User
2/23/2018	06:42:56	055396
2/23/2018	06:48:26	055396

Custom Data Fields
Description
 RED CROSS PAGE

Data	User
RED CROSS IS NEEDED	110624
UNKOWN NUMBERS	

Attachments
No Attachment

INCIDENT OBJECTIVES (ICS 202)

1. Incident Name: <i>Espanola Command</i>	2. Operational Period: Date From: <i>2-23-18</i> Date To: <i>2-24-18</i> Time From: <i>1800</i> Time To: <i>0600</i>											
3. Objective(s): 1.) Primary Evacuation of st the North Side of Bolivar and the South Side of Carter between Marsh and Mixon. This area is referred to as Division 2. 2.) Secondary Evacuation and Search of Division 2. 3.) Transportation of citizen with FD escort to retrieve necessary items from the evacuation zone.												
4. Operational Period Command Emphasis: Maintain a operational perimeter ^{outside} in the evacuations zone. Control the flow of citizens into and out of the evacuation area.												
General Situational Awareness Make command aware of any concerns when working in the assigned area.												
5. Site Safety Plan Required? Yes <input type="checkbox"/> No <input type="checkbox"/> Approved Site Safety Plan(s) Located at:												
6. Incident Action Plan (the items checked below are included in this Incident Action Plan): <table style="width: 100%; border: none;"> <tr> <td><input type="checkbox"/> ICS 203</td> <td><input type="checkbox"/> ICS 207</td> <td rowspan="5" style="vertical-align: top;"> Other Attachments: <input type="checkbox"/> _____ <input type="checkbox"/> _____ <input type="checkbox"/> _____ <input type="checkbox"/> _____ </td> </tr> <tr> <td><input type="checkbox"/> ICS 204</td> <td><input type="checkbox"/> ICS 208</td> </tr> <tr> <td><input type="checkbox"/> ICS 205</td> <td><input type="checkbox"/> Map/Chart</td> </tr> <tr> <td><input type="checkbox"/> ICS 205A</td> <td><input type="checkbox"/> Weather Forecast/Tides/Currents</td> </tr> <tr> <td><input type="checkbox"/> ICS 206</td> <td></td> </tr> </table>		<input type="checkbox"/> ICS 203	<input type="checkbox"/> ICS 207	Other Attachments: <input type="checkbox"/> _____ <input type="checkbox"/> _____ <input type="checkbox"/> _____ <input type="checkbox"/> _____	<input type="checkbox"/> ICS 204	<input type="checkbox"/> ICS 208	<input type="checkbox"/> ICS 205	<input type="checkbox"/> Map/Chart	<input type="checkbox"/> ICS 205A	<input type="checkbox"/> Weather Forecast/Tides/Currents	<input type="checkbox"/> ICS 206	
<input type="checkbox"/> ICS 203	<input type="checkbox"/> ICS 207	Other Attachments: <input type="checkbox"/> _____ <input type="checkbox"/> _____ <input type="checkbox"/> _____ <input type="checkbox"/> _____										
<input type="checkbox"/> ICS 204	<input type="checkbox"/> ICS 208											
<input type="checkbox"/> ICS 205	<input type="checkbox"/> Map/Chart											
<input type="checkbox"/> ICS 205A	<input type="checkbox"/> Weather Forecast/Tides/Currents											
<input type="checkbox"/> ICS 206												
7. Prepared by: Name: <i>M. Meador</i> Position/Title: <i>BC/Incident Com</i> Signature:												
8. Approved by Incident Commander: Name: <i>Michael Meador</i> Signature:												
ICS 202	IAP Page _____	Date/Time: <i>2-24-18 0200</i>										